

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Abbey Park H.S.	HB164	12	2019-06-06	Serena Romito	Nov-19	Degraded caulking around window . Degraded caulking around door
Abbey Park H.S.	HB163		2019-06-06	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door
Abbey Park H.S.	HB108		2019-06-06	Serena Romito	Nov-19	NSMOMO
Abbey Park H.S.	HB177		2019-06-06	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile due to roof leak
Abbey Park H.S.	HBL213		2019-06-06	Serena Romito	Nov-19	NSMOMO
Abbey Park H.S.	HBL227		2019-06-06	Serena Romito	Nov-19	NSMOMO
Abbey Park H.S.	HB043		2019-06-06	Serena Romito	Nov-19	NSMOMO
Abbey Park H.S.	HB131		2019-06-06	Serena Romito	Nov-19	Level 4. Impacted drywall and rotted subfloor with lifting vinyl floor tiles. Damaged flashing N side. Screw holes under window . Degraded door caulking . Lifting vinyl floor tiles and rotted subfloor near windows
Abbey Park H.S.	HB072		2019-06-06	Serena Romito	Nov-19	Level 4 . Impacted drywall on E and N Wall under windows . Degraded caulking around windows
Abbey Park H.S.	HB053		2019-06-06	Serena Romito	Nov-19	Degraded Caulking around windows . Degraded Caulking around HVAC Louvre
Abbey Park H.S.	HB206		2019-06-06	Serena Romito	Nov-19	NSMOMO
Abbey Park H.S.	HBL224		2019-06-06	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HBL239	11	2019-05-27	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HBL238		2019-05-27	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HBL237		2019-05-27	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HBL236		2019-05-27	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile due to roof leak . Degraded caulking around door
Alton Village P.S.	HBL235		2019-05-27	Serena Romito	Nov-19	Rotted door frame
Alton Village P.S.	HBL234		2019-05-27	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HB037		2019-05-27	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HB140		2019-05-27	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HBL247		2019-05-27	Serena Romito	Nov-19	NSMOMO
Alton Village P.S.	HBL225		2019-05-27	Serena Romito	Nov-19	Level 1 . Two water stained ceiling tiles and water above vapor barrier
Alton Village P.S.	HB068		2019-05-27	Serena Romito	Nov-19	Level 1 . Wet drywall beneath AC unit
Anne J. MacArthur P.S.	HBL215	11	2019-05-07	Serena Romito	Nov-19	NSMOMO
Anne J. MacArthur P.S.	HB026		2019-05-07	Serena Romito	Nov-19	Damaged lintel above door . Damaged fascia and roof flashing (S) . Degraded caulking around ac line penetration (S) . ~10 damaged floor tiles
Anne J. MacArthur P.S.	HBL,214		2019-05-08	Serena Romito	Nov-19	Degraded caulking around 3 windows . Degraded caulking around door
Anne J. MacArthur P.S.	HB071		2019-05-08	Serena Romito	Nov-19	Level 3 . Mould growth and suspect moisture under North window to height of sill . Gaps in cladding at bottom of door . Cracked caulking around windows . Cracked and degraded caulking around door
Anne J. MacArthur P.S.	HB174		2019-05-08	Serena Romito	Nov-19	Level 1 . One water stained ceiling tile and water staining on drywall in ceiling space near Wall mounted ac unit . Detaching SE metal corner . Screw holes near door . Detaching SW downspout . Degraded caulking around HVAC louvre
Anne J. MacArthur P.S.	HBL202		2019-05-08	Serena Romito	Nov-19	NSMOMO
Anne J. MacArthur P.S.	HBL203		2019-05-08	Serena Romito	Nov-19	NSMOMO
Anne J. MacArthur P.S.	HBL204		2019-05-08	Serena Romito	Nov-19	NSMOMO
Anne J. MacArthur P.S.	HBL205		2019-05-08	Serena Romito	Nov-19	NSMOMO
Anne J. MacArthur P.S.	HBL232		2019-05-08	Serena Romito	Nov-19	NSMOMO

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Anne J. MacArthur P.S.	HBL233		2019-05-08	Serena Romito	Nov-19	Level 1 . Suspect moisture in one ceiling tile and on three batts of insulation . Screw holes on three window frames
Boyne P.S.	HBL257	12	2019-05-07	Serena Romito	Nov-19	NSMOMO
Boyne P.S.	HB028		2019-05-07	Serena Romito	Nov-19	Detaching sheathing (S) . Detaching metal corner (SW) . Degraded caulking around windows . Degraded caulking around door
Boyne P.S.	HBL241		2019-05-07	Serena Romito	Nov-19	NSMOMO
Boyne P.S.	HBL110		2019-05-07	Serena Romito	Nov-19	Degraded caulking around windows
Boyne P.S.	HBL252		2019-05-07	Serena Romito	Nov-19	Level 1 . One water stained ceiling tile . One water stained ceiling tile (level 1)
Boyne P.S.	HBL254		2019-05-07	Serena Romito	Nov-19	NSMOMO
Boyne P.S.	HB015		2019-05-07	Serena Romito	Nov-19	Separation of caulking around door . Hole in sheathing (S side)
Boyne P.S.	HBL226		2019-05-07	Serena Romito	Nov-19	NSMOMO
Boyne P.S.	HBL251		2019-05-07	Serena Romito	Nov-19	NSMOMO
Boyne P.S.	HBL253		2019-05-07	Serena Romito	Nov-19	NSMOMO
Boyne P.S.	HB152		2019-05-07	Serena Romito	Nov-19	Degraded caulking between fascia boards and roof (S side) . Missing caulking between for frame and flashing . Degraded caulking around conduit (S side) . ~5 broken vinyl floor tiles
Boyne P.S.	HB179		2019-05-07	Serena Romito	Nov-19	Level 2 . Screw holes in metal corner (NW) and under windows . Damaged fascia board and roof flashing (W) . Missing number plate above door . Degraded caulking around HVAC louvre . Mould odour near wet drywall under West window . Mould present behind base
Bruce T. Lindley P.S.	HB166	1	2019-06-04	Serena Romito	Nov-19	Level 2 . Mould on drywall under W window . Screw holes D side . Degraded caulking around windows . Degraded caulking around door
Bruce Trail P.S.	HB032	17	2019-05-14	Serena Romito	Nov-19	Screw holes on metal corners N side . Degraded caulking around conduits N side
Bruce Trail P.S.	HBL228		2019-05-14	Serena Romito	Nov-19	NSMOMO
Bruce Trail P.S.	HBL229		2019-05-14	Serena Romito	Nov-19	NSMOMO
Bruce Trail P.S.	HBL231		2019-05-14	Serena Romito	Nov-19	NSMOMO
Bruce Trail P.S.	HBL230		2019-05-14	Serena Romito	Nov-19	NSMOMO
Bruce Trail P.S.	HB115		2019-05-14	Serena Romito	Nov-19	~20 damaged vinyl floor tiles
Bruce Trail P.S.	HBL105		2019-05-14	Serena Romito	Nov-19	NSMOMO
Bruce Trail P.S.	HB062		2019-05-14	Serena Romito	Nov-19	Damaged fascia board and roof flashing W side . Degraded caulking around windows . Degraded caulking around door . Degraded caulking around HVAC louvre . Damaged Gable louvre W end
Bruce Trail P.S.	HB114		2019-05-14	Serena Romito	Nov-19	Screw holes near door . Degraded caulking around door
Bruce Trail P.S.	HB046		2019-05-14	Serena Romito	Nov-19	Screw holes near door . Degraded caulking around windows . Degraded caulking around door . Wasp nest in ceiling space above door . Damaged drywall near door
Bruce Trail P.S.	HB110		2019-05-14	Serena Romito	Nov-19	Level 3 . Mould growth and suspect moisture on drywall under windows . Missing downspout SW side . Degraded caulking around windows . Degraded caulking around HVAC louvre
Bruce Trail P.S.	HB103		2019-05-14	Serena Romito	Nov-19	Degraded caulking around windows. Screw holes near windows . Degraded caulking around door
Bruce Trail P.S.	HB075		2019-05-14	Serena Romito	Nov-19	Screw holes NW corner . Rotted wooden window frames
Bruce Trail P.S.	HB181		2019-05-14	Serena Romito	Nov-19	Level 1 . Two water stained ceiling tiles due to roof leak . Gap between fascia boards w side . Degraded caulking around Condit W side
Bruce Trail P.S.	HBL107		2019-05-14	Serena Romito	Nov-19	Hole in sheathing West side
Bruce Trail P.S.	HBL262		2019-05-14	Serena Romito	Nov-19	NSMOMO

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Bruce Trail P.S.	HBL206		2019-05-14	Serena Romito	Nov-19	Screw holes SE corner . Degraded caulking around door
Captain R. Wilson P.S.	HB047	4	2019-06-20	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door
Captain R. Wilson P.S.	HB106		2019-06-20	Serena Romito	Nov-19	Level 1 . Water stained ceiling tiles due to roof leak . Degraded caulking around windows . Degraded caulking around HVAC louver . Soft flooring and broken vinyl floor tiles near centre seam
Captain R. Wilson P.S.	HB065		2019-06-20	Serena Romito	Nov-19	Degraded caulking and rotted window frames
Captain R. Wilson P.S.	HB014		2019-06-20	Serena Romito	Nov-19	Detaching downspout
Charles R. Beaudoin P.S.	HBL100	2	2019-06-13	Serena Romito	Nov-19	NSMOMO
Charles R. Beaudoin P.S.	HBL101		2019-06-13	Serena Romito	Nov-19	NSMOMO
Chris Hadfield P.S.	Rm a6	10	2019-05-15	Serena Romito	Nov-19	Level 1 . Wet drywall window sills on East wall due to degraded window caulking . Hole in drywall behind door
Chris Hadfield P.S.	Rm a7		2019-05-15	Serena Romito	Nov-19	NSMOMO
Chris Hadfield P.S.	Rm a8		2019-05-15	Serena Romito	Nov-19	Degraded caulking around S window
Chris Hadfield P.S.	Rm a9		2019-05-15	Serena Romito	Nov-19	Degraded concrete below East wall . Degraded caulking around windows
Chris Hadfield P.S.	Rm a10		2019-05-15	Serena Romito	Nov-19	Level 1. Wet drywall window sills due to degraded window caulking. Degraded concrete below East wall . Degraded caulking around windows
Chris Hadfield P.S.	Rm a1		2019-05-15	Serena Romito	Nov-19	NSMOMO
Chris Hadfield P.S.	Rm a2		2019-05-15	Serena Romito	Nov-19	Degraded caulking around south window
Chris Hadfield P.S.	Rm a3		2019-05-15	Serena Romito	Nov-19	Degraded caulking around south window
Chris Hadfield P.S.	Rm a4		2019-05-15	Serena Romito	Nov-19	NSMOMO
Chris Hadfield P.S.	Rm a5		2019-05-15	Serena Romito	Nov-19	NSMOMO
Craig Kielburger S.S.	HB073	10	2019-06-11	Serena Romito	Nov-19	Level 3 . Impacted drywall due to degraded window caulking and rotted frame . Degraded caulking around windows. Rotted window frames . Degraded caulking around door
Craig Kielburger S.S.	HB143		2019-06-11	Serena Romito	Nov-19	Screw holes E and W side . Degraded caulking around windows . Degraded caulking around door
Craig Kielburger S.S.	HB133		2019-06-11	Serena Romito	Nov-19	Screw holes E side . Degraded caulking around windows . Degraded caulking around door
Craig Kielburger S.S.	HB203		2019-06-11	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door
Craig Kielburger S.S.	HB134		2019-06-11	Serena Romito	Nov-19	NSMOMO
Craig Kielburger S.S.	HB057		2019-06-11	Serena Romito	Nov-19	Screw holes in window frames
Craig Kielburger S.S.	HB113		2019-06-11	Serena Romito	Nov-19	Damaged sheathing under door
Craig Kielburger S.S.	HB125		2019-06-11	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door
Craig Kielburger S.S.	HBL084		2019-06-11	Serena Romito	Nov-19	NSMOMO
Craig Kielburger S.S.	HB056		2019-06-11	Serena Romito	Nov-19	NSMOMO
E.J. James P.S.	HB121	3	2019-05-30	Serena Romito	Nov-19	Degraded caulking around S window
E.J. James P.S.	HB111		2019-05-30	Serena Romito	Nov-19	NSMOMO
E.J. James P.S.	HB061		2019-05-30	Serena Romito	Nov-19	Level 2 . Mould growth on drywall beneath N window
Emily Carr P.S.	HB084	4	2019-06-17	Serena Romito	Nov-19	Mouse droppings and staining on top of ceiling tiles
Emily Carr P.S.	HBL008		2019-06-17	Serena Romito	Nov-19	NSMOMO
Emily Carr P.S.	HBL217		2019-06-17	Serena Romito	Nov-19	Missing number plate
Emily Carr P.S.	HB147		2019-06-17	Serena Romito	Nov-19	Detaching downspout
Escarpment View P.S.	HBL081	11	2019-05-13	Serena Romito	Nov-19	NSMOMO
Escarpment View P.S.	HBL082		2019-05-13	Serena Romito	Nov-19	NSMOMO

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Escarpment View P.S.	HBL083		2019-05-13	Serena Romito	Nov-19	NSMOMO
Escarpment View P.S.	HBL088		2019-05-13	Serena Romito	Nov-19	NSMOMO
Escarpment View P.S.	HBL089		2019-05-13	Serena Romito	Nov-19	Grate detached from front of indoor HVAC unit
Escarpment View P.S.	HB144		2019-05-13	Serena Romito	Nov-19	~20 damaged vinyl floor tiles
Escarpment View P.S.	HB005		2019-05-13	Serena Romito	Nov-19	Level 1 . Drywall with suspect moisture on North Wall near centre seam . Degraded caulking around south window . Screw hole in HVAC louver . ~20 damaged vinyl floor tiles
Escarpment View P.S.	HB089		2019-05-13	Serena Romito	Nov-19	Level 3 . Mould growth on drywall and suspect moisture on drywall and wood sheathing due to screw holes and degraded caulking on window frames . Degraded caulking and screw holes on window frames
Escarpment View P.S.	HBL104		2019-05-13	Serena Romito	Nov-19	Water staining on top of vapor barrier sporadically throughout . ~15 damaged vinyl floor tiles
Escarpment View P.S.	HBL103		2019-05-13	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door
Escarpment View P.S.	HBL090		2019-05-13	Serena Romito	Nov-19	NSMOMO
Ethel Gardiner P.S.	HB049	4	2019-05-16	Serena Romito	Nov-19	Level 1 . Three water stained ceiling tiles due to roof leak . Degraded caulking around door
Ethel Gardiner P.S.	HBL212		2019-05-16	Serena Romito	Nov-19	NSMOMO
Ethel Gardiner P.S.	HBL207		2019-05-16	Serena Romito	Nov-19	Degraded caulking around windows
Ethel Gardiner P.S.	HBL263		2019-05-16	Serena Romito	Nov-19	Degraded caulking around East window
E.W. Foster P.S.	HB189	1	2019-05-16	Serena Romito	Nov-19	Level 2 . Mould growth and suspect moisture on drywall due to degraded door caulking and screw holes . Screw holes near door . Degraded caulking around door
Florence Meares P.S.	HB139	1	2019-05-09	Serena Romito	Nov-19	Damaged West fascia board . Degraded caulking around East window
Dr. Frank J. Hayden S.S.	HB151	12	2019-05-09	Serena Romito	Nov-19	Level 1 . One water stained ceiling tile . Screw holes S wall and NW corner
Dr. Frank J. Hayden S.S.	HB059		2019-05-09	Serena Romito	Nov-19	Degraded caulking around door
Dr. Frank J. Hayden S.S.	HB120		2019-05-09	Serena Romito	Nov-19	Level 1 . One water stained ceiling tile due to roof leak . Missing caulking around door
Dr. Frank J. Hayden S.S.	HB172		2019-05-09	Serena Romito	Nov-19	Missing caulking at top of windows . Missing caulking around door
Dr. Frank J. Hayden S.S.	HB092		2019-05-09	Serena Romito	Nov-19	Level 1 . One water stained ceiling tile due to roof leak . Degraded caulking around top of windows
Dr. Frank J. Hayden S.S.	HB010		2019-05-09	Serena Romito	Nov-19	Gap between fascia boards N side . Degraded caulking around door
Dr. Frank J. Hayden S.S.	HBL256		2019-05-09	Serena Romito	Nov-19	NSMOMO
Dr. Frank J. Hayden S.S.	HBL210		2019-05-09	Serena Romito	Nov-19	NSMOMO
Dr. Frank J. Hayden S.S.	HBL255		2019-05-09	Serena Romito	Nov-19	Screw holes S side
Dr. Frank J. Hayden S.S.	HBL211		2019-05-09	Serena Romito	Nov-19	NSMOMO
Dr. Frank J. Hayden S.S.	HB137		2019-05-09	Serena Romito	Nov-19	Level 1 . Two water stained ceiling tiles due to roof leak . Cracked caulking around south window . Missing caulking around door . Screw holes in HVAC louver
Dr. Frank J. Hayden S.S.	HB207		2019-05-09	Serena Romito	Nov-19	Missing caulking at top of windows . Missing caulking around conduit penetration
Garth Webb S.S.	HB091	8	2019-06-20	Serena Romito	Nov-19	Degraded caulking around windows, door, conduits, and cut in sheathing
Garth Webb S.S.	HB135		2019-06-20	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile due to roof leak . Degraded caulking around windows
Garth Webb S.S.	HB100		2019-06-20	Serena Romito	Nov-19	Level 1 . Three water stained ceiling tiles due to roof leak . Degraded caulking around windows . Degraded caulking around door . Degraded caulking around HVAC louver
Garth Webb S.S.	HB076		2019-06-20	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile due to roof leak
Garth Webb S.S.	HB052		2019-06-20	Serena Romito	Nov-19	NSMOMO
Garth Webb S.S.	HB090		2019-06-20	Serena Romito	Nov-19	NSMOMO
Garth Webb S.S.	HB045		2019-06-20	Serena Romito	Nov-19	Screw holes and missing panel joint cover W side . Degraded caulking around windows and door

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Garth Webb S.S.	HB038		2019-06-20	Serena Romito	Nov-19	NSMOMO
Gladys Spears P.S.	HB 158	1	2019-05-15	Evan Faubert	Nov-19	Missing east Gable flashing..
Glen Williams P.S.	HB184	2	2019-05-16	Serena Romito	Nov-19	Level 2 . Mould growth on backside of drywall in inspection port under North window
Glen Williams P.S.	HB178		2019-05-16	Serena Romito	Nov-19	Level 1 . Drywall with suspect moisture under West window . Gap in caulking W window
Glenview P.S.	HB148	2	2019-05-14	Evan Faubert	Nov-19	NSMOMO
Glenview P.S.	HB. 122		2019-05-14	Evan Faubert	Nov-19	Visible space in center beam north wall. . Visible gap on north wall center beam.
Hawthorne Village P.S.	RM301	17	2019-06-04	Serena Romito	Nov-19	Degraded caulking at Wall panel junctions
Hawthorne Village P.S.	Rm302		2019-06-04	Serena Romito	Nov-19	NSMOMO
Hawthorne Village P.S.	Rm303		2019-06-04	Serena Romito	Nov-19	Degraded caulking at Wall panel junctions
Hawthorne Village P.S.	Rm,304		2019-06-04	Serena Romito	Nov-19	Degraded caulking at Wall panel junctions
Hawthorne Village P.S.	Rm305		2019-06-04	Serena Romito	Nov-19	Degraded caulking at Wall panel
Hawthorne Village P.S.	Rm306		2019-06-04	Serena Romito	Nov-19	Degraded caulking at Wall panels
Hawthorne Village P.S.	Rm307		2019-06-04	Serena Romito	Nov-19	NSMOMO
Hawthorne Village P.S.	Rm308		2019-06-04	Serena Romito	Nov-19	NSMOMO
Hawthorne Village P.S.	Rm309		2019-06-04	Serena Romito	Nov-19	NSMOMO
Hawthorne Village P.S.	Rm310		2019-06-04	Serena Romito	Nov-19	Degraded caulking at Wall panel
Hawthorne Village P.S.	HB162		2019-06-04	Serena Romito	Nov-19	Detaching skirting S side . Detaching downspout E side . Degraded caulking around Condit S side
Hawthorne Village P.S.	HB013		2019-06-04	Serena Romito	Nov-19	Detaching downspout W side
Hawthorne Village P.S.	HB136		2019-06-04	Serena Romito	Nov-19	Level 2 . Mould on drywall under N window . Detaching skirting N side . Exposed wood fascia board N side . Degraded caulking around door
Hawthorne Village P.S.	HB036		2019-06-04	Serena Romito	Nov-19	Degraded caulking around door
Hawthorne Village P.S.	HB035		2019-06-04	Serena Romito	Nov-19	Detached vent cover in skirting S side
Hawthorne Village P.S.	HB034		2019-06-04	Serena Romito	Nov-19	NSMOMO
Hawthorne Village P.S.	HB155		2019-06-04	Serena Romito	Nov-19	Degraded caulking around N window
Irma Coulson P.S.	HBL246	15	2019-05-22	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door . Missing baseboards East wall
Irma Coulson P.S.	HBL245		2019-05-22	Serena Romito	Nov-19	Detaching skirting North side . Screw holes NW corner
Irma Coulson P.S.	HBL244		2019-05-22	Serena Romito	Nov-19	NSMOMO
Irma Coulson P.S.	HB142		2019-05-22	Serena Romito	Nov-19	Level 1 . 3 water stained ceiling tiles and water on vapor barrier due to roof leak. Wet drywall around unused door on S wall . Screw holes NW corner . Degraded caulking around door . Degraded caulking between fascia boards W side
Irma Coulson P.S.	HBL242		2019-05-22	Serena Romito	Nov-19	NSMOMO
Irma Coulson P.S.	HBL243		2019-05-22	Serena Romito	Nov-19	Missing downspout connection SE . Degraded caulking around windows . Degraded caulking around door . Holes in drywall S wall near unused door
Irma Coulson P.S.	HB195		2019-05-22	Serena Romito	Nov-19	Level 2 . Suspect moisture on exterior sheathing under W window. Mould growth on drywall cutout in inspection port . Screw holes in various areas . Degraded caulking around windows . Degraded caulking around door . Fallen insulation in two areas
Irma Coulson P.S.	HB149		2019-05-22	Serena Romito	Nov-19	Level 3 . Mould growth on drywall beneath windows. One water stained ceiling tile . Degraded caulking around windows and door and HVAC louvre and AC conduit penetration
Irma Coulson P.S.	HB196		2019-05-22	Serena Romito	Nov-19	Degraded caulking around door and windows
Irma Coulson P.S.	HB081		2019-05-22	Serena Romito	Nov-19	Damaged roof flashing W side

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Irma Coulson P.S.	HB150		2019-05-22	Serena Romito	Nov-19	Level 2 . Drywall with suspect moisture and mould growth on surface of HVAC unit
Irma Coulson P.S.	HB204		2019-05-22	Serena Romito	Nov-19	Degraded caulking around windows and doors and HVAC louvre
Irma Coulson P.S.	HBL111		2019-05-22	Serena Romito	Nov-19	Degraded caulking around windows
Irma Coulson P.S.	HB146		2019-05-22	Serena Romito	Nov-19	Degraded caulking around door
Irma Coulson P.S.	HB009		2019-05-22	Serena Romito	Nov-19	Degraded caulking around windows and door
Iroquois Ridge H.S.	HB145	6	2019-06-12	Serena Romito	Nov-19	Gap between metal sheathing and plywood W side . Screw holes W and E sides
Iroquois Ridge H.S.	HB088		2019-06-12	Serena Romito	Nov-19	NSMOMO
Iroquois Ridge H.S.	HB202		2019-06-12	Serena Romito	Nov-19	Level 4 . Impacted drywall. Cause unknown due to no access on exterior . ~15 damaged vinyl floor tiles
Iroquois Ridge H.S.	HB070		2019-06-12	Serena Romito	Nov-19	Level 3 . Impacted drywall beneath window and wall mounted AC unit . Degraded caulking around windows and one rotted window frame . ~50 damaged vinyl floor tiles
Iroquois Ridge H.S.	HB209		2019-06-12	Serena Romito	Nov-19	Level 2 . Impacted drywall due to window leaks . Degraded caulking around windows
Iroquois Ridge H.S.	HBL264		2019-06-12	Serena Romito	Nov-19	NSMOMO
James W. Hill P.S.	HB050	4	2019-05-30	Serena Romito	Nov-19	NSMOMO
James W. Hill P.S.	HB086		2019-05-30	Serena Romito	Nov-19	NSMOMO
James W. Hill P.S.	HB099		2019-05-30	Serena Romito	Nov-19	Degraded caulking around door
James W. Hill P.S.	HB176		2019-05-30	Serena Romito	Nov-19	NSMOMO
John T. Tuck P.S.	HB 165	9	2019-05-15	Evan Faubert	Nov-19	NSMOMO
John T. Tuck P.S.	HBL216		2019-05-15	Evan Faubert	Nov-19	Level 1 . Water stained ceiling tile and vapor barrier. NE corner. . Water stained ceiling tile and vapor barrier from possible roof leak. NE corner . Stained vapor barrier. NE corner
John T. Tuck P.S.	HBL221		2019-05-15	Evan Faubert	Nov-19	Level 1 . Stained ceiling tile NW corner . Stained ceiling tile NW corner.
John T. Tuck P.S.	HB156		2019-05-15	Evan Faubert	Nov-19	NSMOMO
John T. Tuck P.S.	HB 064		2019-05-15	Evan Faubert	Nov-19	NSMOMO
John T. Tuck P.S.	HBL 219		2019-05-15	Evan Faubert	Nov-19	NSMOMO
John T. Tuck P.S.	HB 157		2019-05-15	Evan Faubert	Nov-19	Door closer remains missing. . Caulking at South mechanical equipment remains poor.
John T. Tuck P.S.	HB 173		2019-05-15	Evan Faubert	Nov-19	Inspection ports are not open to sheathing..
John T. Tuck P.S.	HBL 220		2019-05-15	Evan Faubert	Nov-19	NSMOMO
John W. Boich P.S.	HBL108	2	2019-06-17	Serena Romito	Nov-19	NSMOMO
John W. Boich P.S.	HBL109		2019-06-17	Serena Romito	Nov-19	NSMOMO
Joshua Creek P.S.	HB085	4	2019-05-30	Serena Romito	Nov-19	NSMOMO
Joshua Creek P.S.	HB011		2019-05-30	Serena Romito	Nov-19	Screw holes in window frames
Joshua Creek P.S.	HB077		2019-05-30	Serena Romito	Nov-19	Damaged sheathing N side . Screw holes on W window frame
Joshua Creek P.S.	HB160		2019-05-30	Serena Romito	Nov-19	Damaged fascia board and roof flashing W side . Degraded caulking around HVAC louvre
J.W. Singleton Ed. Ctre.	HB003	5	2019-06-17	Serena Romito	Nov-19	Degraded caulking W side
J.W. Singleton Ed. Ctre.	HB118		2019-06-17	Serena Romito	Nov-19	NSMOMO
J.W. Singleton Ed. Ctre.	HB117		2019-06-17	Serena Romito	Nov-19	NSMOMO
J.W. Singleton Ed. Ctre.	HB161		2019-06-17	Serena Romito	Nov-19	NSMOMO
J.W. Singleton Ed. Ctre.	HB119		2019-06-17	Serena Romito	Nov-19	Degraded caulking around window E side
Kilbride P.S.	HB074	1	2019-06-04	Serena Romito	Nov-19	Level 2 . Mould on drywall under East window. Two water stained ceiling tiles
Maple Grove P.S.	HB 130	2	2019-05-15	Evan Faubert	Nov-19	NSMOMO

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Maple Grove P.S.	HB 159		2019-05-15	Evan Faubert	Nov-19	Missing flashing at fascia north gable . Hole in metal exterior sheathing. North side near unused door.
Milton District H.S.	HB001	5	2019-06-11	Serena Romito	Nov-19	Missing caulking around windows. . Missing caulking around door . Missing caulking around HVAC louvre . Missing number plate
Milton District H.S.	HBL223		2019-06-11	Serena Romito	Nov-19	NSMOMO
Milton District H.S.	HB041		2019-06-11	Serena Romito	Nov-19	NSMOMO
Milton District H.S.	HB093		2019-06-11	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door . Degraded caulking at ceiling centre seam. Daylight visible
Milton District H.S.	HB154		2019-06-11	Serena Romito	Nov-19	Level 2 . Impacted drywall beneath West window . Damaged floor/Wall flashing under West window . Degraded caulking around windows . Degraded caulking around door . Degraded caulking around conduit West side
Munn's P.S.	HBL 001	2	2019-06-05	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile . Degraded caulking around windows . Degraded caulking around door
Munn's P.S.	HBL002		2019-06-05	Serena Romito	Nov-19	NSMOMO
New Central P.S.	HB 079	2	2019-05-15	Evan Faubert	Nov-19	NSMOMO
New Central P.S.	HB 104		2019-05-15	Evan Faubert	Nov-19	Caulking remains poor on conduit on West exterior.
Oakville Trafalgar H.S.	Rm189a	11	2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm189b		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm190		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm191		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm192		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm193		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm194		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm195		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm196		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm197		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oakville Trafalgar H.S.	Rm198		2019-06-13	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HBL086	19	2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HBL009		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HBL258		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HBL080		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HBL005		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HBL085		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HBL261		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HB128		2019-05-29	Serena Romito	Nov-19	Level 1 . Damp sill plate in inspection port under E window . Degraded caulking around door . Missing caulking around hangers W side . ~ 20 damaged vinyl floor tiles . Damp sill plate in inspection port under E window
Oodenawi P.S.	HB094		2019-05-29	Serena Romito	Nov-19	Level 2 . Mould growth and suspect moisture on drywall in inspection port under East window. North cladding damaged under door and near HVAC louvre . Degraded caulking around windows. Daylight visible from inside . Missing inspection port cover South wall
Oodenawi P.S.	HB096		2019-05-29	Serena Romito	Nov-19	Screw holes NE corner . Damaged caulking W window
Oodenawi P.S.	HB067		2019-05-29	Serena Romito	Nov-19	Level 1 . One water stained ceiling tile due to roof leak . Screw holes, degraded caulking and damaged window frames

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
Oodenawi P.S.	HB044		2019-05-29	Serena Romito	Nov-19	Damaged roof Gable flashing W side
Oodenawi P.S.	HBL248		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HB177		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HB175		2019-05-29	Serena Romito	Nov-19	Screw holes N side . Damaged fascia board N side. Degraded caulking around door . Degraded caulking around HVAC louvre
Oodenawi P.S.	HB058		2019-05-29	Serena Romito	Nov-19	Degraded caulking around windows and damaged window frames . Holes in soffit N side
Oodenawi P.S.	HB101		2019-05-29	Serena Romito	Nov-19	Damaged corner flashing NE corner
Oodenawi P.S.	HBL260		2019-05-29	Serena Romito	Nov-19	NSMOMO
Oodenawi P.S.	HB080		2019-05-30	Serena Romito	Nov-19	NSMOMO
Orchard Park P.S.	HB040	1	2019-06-20	Serena Romito	Nov-19	NSMOMO
Palermo P.S.	HB087	3	2019-06-20	Serena Romito	Nov-19	NSMOMO
Palermo P.S.	HB168		2019-06-20	Serena Romito	Nov-19	Hole in sheathing and detaching metal corner N side
Palermo P.S.	HB167		2019-06-20	Serena Romito	Nov-19	Level 1 . Two water stained ceiling tiles due to roof leak . Missing caulking around conduit
Pauline Johnson P.S.	HB 024	3	2019-05-14	Evan Faubert	Nov-19	NSMOMO
Pauline Johnson P.S.	HBL222		2019-05-14	Evan Faubert	Nov-19	Repair degrade caulking around windows
Pauline Johnson P.S.	HB 102		2019-05-14	Evan Faubert	Nov-19	NSMOMO
Pilgrim Wood P.S.	HB006	4	2019-06-12	Serena Romito	Nov-19	Level 1 . The water stained ceiling tiles due to roof leaks and water trapped in vapor barrier
Pilgrim Wood P.S.	HB123		2019-06-12	Serena Romito	Nov-19	Level 3 . Impacted drywall due to window leaks . Degraded caulking around windows
Pilgrim Wood P.S.	HBL087		2019-06-12	Serena Romito	Nov-19	Missing number plate
Pilgrim Wood P.S.	HBL267		2019-06-12	Serena Romito	Nov-19	Missing number plate
Pineland P.S.	HB 069	1	2019-05-15	Evan Faubert	Nov-19	Missing caulking at South window exterior
P.L. Robertson P.S.	HBL265	12	2019-05-08	Serena Romito	Nov-19	NSMOMO
P.L. Robertson P.S.	HBL259		2019-05-08	Serena Romito	Nov-19	NSMOMO
P.L. Robertson P.S.	HBL091		2019-05-08	Serena Romito	Nov-19	NSMOMO
P.L. Robertson P.S.	HB039		2019-05-08	Serena Romito	Nov-19	NSMOMO
P.L. Robertson P.S.	HB051		2019-05-08	Serena Romito	Nov-19	NSMOMO
P.L. Robertson P.S.	HBL266		2019-05-08	Serena Romito	Nov-19	NSMOMO
P.L. Robertson P.S.	HB004		2019-05-08	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around door
P.L. Robertson P.S.	HB027		2019-05-08	Serena Romito	Nov-19	Level 1 . Three water damaged ceiling tiles due to roof leaks
P.L. Robertson P.S.	HB022		2019-05-13	Serena Romito	Nov-19	Degraded caulking around windows
P.L. Robertson P.S.	HB016		2019-05-13	Serena Romito	Nov-19	Degraded caulking around door
P.L. Robertson P.S.	HB030		2019-05-13	Serena Romito	Nov-19	Degraded caulking around door
P.L. Robertson P.S.	HB021		2019-05-13	Serena Romito	Nov-19	NSMOMO
Post's Corners P.S.	HBL218	4	2019-06-12	Serena Romito	Nov-19	Missing number plate
Post's Corners P.S.	HB129		2019-06-12	Serena Romito	Nov-19	NSMOMO
Post's Corners P.S.	HB180		2019-06-12	Serena Romito	Nov-19	NSMOMO
Post's Corners P.S.	HBL102		2019-06-12	Serena Romito	Nov-19	~10 damaged/missing vinyl floor tiles . NSMOMO
River Oaks P.S.	HB008	6	2019-06-05	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile due to roof leak . Degraded caulking around door . Degraded caulking around conduits
River Oaks P.S.	HB033		2019-06-05	Serena Romito	Nov-19	NSMOMO
River Oaks P.S.	HB208		2019-06-05	Serena Romito	Nov-19	Level 1 . Two water stained ceiling tiles due to roof leak . Bees in inspection port

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
River Oaks P.S.	HBL106		2019-06-05	Serena Romito	Nov-19	NSMOMO
River Oaks P.S.	HBL014		2019-06-05	Serena Romito	Nov-19	Level 1 . One water stained ceiling tile
River Oaks P.S.	HBL015		2019-06-05	Serena Romito	Nov-19	Two soft boards on walkway
Robert Baldwin P.S.	HBL079	1	2019-05-15	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile due to roof leak . NW block water damaged from downspout. Screw holes in HVAC louvre . Downspout pointed at block foundation . Degraded caulking around HVAC louvre
Sam Sherratt P.S.	HB127	5	2019-05-16	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile due to roof leak . Screw holes in sheathing on South and West walls . Detaching downspout SW corner . Degraded caulking around windows . Degraded caulking around door
Sam Sherratt P.S.	HB066		2019-05-16	Serena Romito	Nov-19	Holes in sheathing about conduit and mechanical penetrations N side. Hole in sheathing W side . Screw holes each corner . Detaching downspout SW corner
Sam Sherratt P.S.	HB082		2019-05-16	Serena Romito	Nov-19	Level 1 . Three water stained ceiling tiles due to roof leak
Sam Sherratt P.S.	HB083		2019-05-16	Serena Romito	Nov-19	NSMOMO
Sam Sherratt P.S.	HBL099		2019-05-16	Serena Romito	Nov-19	NSMOMO
Sheridan P.S.	HB132	1	2019-06-18	Serena Romito	Nov-19	Screw holes W and N side. Hole in sheathing near door . Degraded caulking around door and N window . ~40 damaged vinyl floor tiles
Tiger Jeet Singh P.S.	HB029	9	2019-05-21	Serena Romito	Nov-19	Level 1 . Four water stained ceiling tiles due to roof leak . Screw holes NE NW SE corners . E fascia board not fastened. No flashing between fascia boards and roofing E and W side . Missing Wall flashing under HVAC louvre . Missing caulking around E wind
Tiger Jeet Singh P.S.	HBL098		2019-05-21	Serena Romito	Nov-19	NSMOMO
Tiger Jeet Singh P.S.	HBL013		2019-05-21	Serena Romito	Nov-19	SE corner screw holes . Degraded caulking E window
Tiger Jeet Singh P.S.	HB116		2019-05-21	Serena Romito	Nov-19	Level 1 . Water stained ceiling tile . Degraded caulking around windows . Degraded caulking around door . Degraded caulking around HVAC louvre
Tiger Jeet Singh P.S.	HB187		2019-05-21	Serena Romito	Nov-19	Degraded caulking around door . Inspection panels glued shut
Tiger Jeet Singh P.S.	HB095		2019-05-21	Serena Romito	Nov-19	Degraded caulking around centre and right window
Tiger Jeet Singh P.S.	HB126		2019-05-21	Serena Romito	Nov-19	Degraded caulking around door . Degraded caulking around conduit
Tiger Jeet Singh P.S.	HB063		2019-05-21	Serena Romito	Nov-19	Level 1 . Four water stained ceiling tiles due to roof leak . Degraded caulking around windows . Degraded caulking around door
Tiger Jeet Singh P.S.	HB109		2019-05-21	Serena Romito	Nov-19	Missing downspout SE corner . Degraded caulking around right window . Degraded caulking around HVAC louvre
Tom Thompson P.S.	HB 012	7	2019-05-14	Evan Faubert	Nov-19	NSMOMO
Tom Thompson P.S.	HB 141		2019-05-14	Evan Faubert	Nov-19	NSMOMO
Tom Thompson P.S.	HB 124		2019-05-14	Evan Faubert	Nov-19	NSMOMO
Tom Thompson P.S.	HB 031		2019-05-14	Evan Faubert	Nov-19	NSMOMO
Tom Thompson P.S.	HB 105		2019-05-14	Evan Faubert	Nov-19	NSMOMO
Tom Thompson P.S.	HB 098		2019-05-14	Evan Faubert	Nov-19	NSMOMO
Tom Thompson P.S.	HB169		2019-05-14	Evan Faubert	Nov-19	NSMOMO
West Oak P.S.	Rm01	7	2019-06-18	Serena Romito	Nov-19	Degraded caulking around windows and split caulking between exterior wall panels
West Oak P.S.	Rm02		2019-06-18	Serena Romito	Nov-19	Split caulking between exterior wall panels
West Oak P.S.	Rm03		2019-06-18	Serena Romito	Nov-19	Split caulking between exterior wall panels
West Oak P.S.	Rm04		2019-06-18	Serena Romito	Nov-19	Degraded caulking around HVAC louvre . Split caulking between exterior wall panels
West Oak P.S.	Rm05		2019-06-18	Serena Romito	Nov-19	Split caulking between exterior wall panels

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
West Oak P.S.	Rm06		2019-06-18	Serena Romito	Nov-19	Hole in skirting . Hole in sheathing . Degraded caulking around windows . Split caulking between exterior wall panels
West Oak P.S.	HB107		2019-06-18	Serena Romito	Nov-19	NSMOMO
W.H. Morden P.S.	HB097	10	2019-06-05	Serena Romito	Nov-19	Level 3 . Mould growth on drywall SW corner due to roof leak . Sink holes in asphalt . Majority of skirting removed . Screw holes and detaching screw W side . Degraded caulking around windows . Hole in sheathing S side . Water above vapor barrier SW cor
W.H. Morden P.S.	HB199		2019-06-05	Serena Romito	Nov-19	Degraded caulking around windows . Degraded caulking around Condit
W.H. Morden P.S.	HB200		2019-06-05	Serena Romito	Nov-19	Detaching metal corners . ~30 damaged vinyl floor tiles
W.H. Morden P.S.	HBL006		2019-06-05	Serena Romito	Nov-19	NSMOMO
W.H. Morden P.S.	HBL249		2019-06-05	Serena Romito	Nov-19	NSMOMO
W.H. Morden P.S.	HBL250		2019-06-05	Serena Romito	Nov-19	NSMOMO
W.H. Morden P.S.	HBL201		2019-06-05	Serena Romito	Nov-19	NSMOMO
W.H. Morden P.S.	HB055		2019-06-05	Serena Romito	Nov-19	Degraded caulking around windows. One y rotted window frame . Degraded caulking around door. Missing flashing above door
W.H. Morden P.S.	HB138		2019-06-05	Serena Romito	Nov-19	NSMOMO
W.H. Morden P.S.	HBL007		2019-06-05	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (North Campus)	HBL092	5	2019-06-12	Serena Romito	Nov-19	Detached downspout N side
White Oaks S.S. (North Campus)	HBL093		2019-06-12	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (North Campus)	HBL094		2019-06-12	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (North Campus)	HBL095		2019-06-12	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (North Campus)	HB060		2019-06-12	Serena Romito	Nov-19	Level 2 . Mould growth on drywall and water stained ceiling tile due to roof leak . Degraded caulking around door . Degraded caulking around condensate line . Water staining on vapor barrier near HVAC unit
White Oaks S.S. (South Campus)	HB153	13	2019-06-18	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (South Campus)	HB112		2019-06-18	Serena Romito	Nov-19	Level 3 . Impacted drywall beneath windows . Degraded caulking around windows
White Oaks S.S. (South Campus)	HB201		2019-06-18	Serena Romito	Nov-19	Level 3 . Impacted drywall on S wall likely due to gap in sheathing on SE corner and possible leak from wall mounted AC unit
White Oaks S.S. (South Campus)	HB078		2019-06-18	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (South Campus)	HB205		2019-06-18	Serena Romito	Nov-19	Degraded caulking around windows
White Oaks S.S. (South Campus)	HB023		2019-06-18	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (South Campus)	HB054		2019-06-18	Serena Romito	Nov-19	Level 1. Three water stained ceiling tiles due to roof leaks. Screw holes all corners
White Oaks S.S. (South Campus)	HBL016		2019-06-18	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (South Campus)	HBL017		2019-06-18	Serena Romito	Nov-19	NSMOMO

Portable Classroom Preventative Maintenance Inspection No. 108

School	Portable Number	Portables on Site	Round 108 Inspection Date	Pinchin Inspector	Proposed Round 109 Inspection Date	Comments from Round 107 Inspection
White Oaks S.S. (South Campus)	HBL018		2019-06-18	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (South Campus)	HB042		2019-06-18	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (South Campus)	HBL096		2019-06-18	Serena Romito	Nov-19	NSMOMO
White Oaks S.S. (South Campus)	HBL097		2019-06-18	Serena Romito	Nov-19	NSMOMO
W.I. Dick P.S.	HB183	3	2019-05-15	Serena Romito	Nov-19	Hole in drywall near door
W.I. Dick P.S.	HB007		2019-05-22	Serena Romito	Nov-19	NSMOMO
W.I. Dick P.S.	HB002		2019-05-22	Serena Romito	Nov-19	Level 3 . Mould growth and suspect moisture on drywall under East window . Degraded caulking around windows . ~10 damaged vinyl floor tiles