

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
Abbey Park H.S.	HB043	12	2019-11-27	Evan Faubert	May 2020	Screw holes in SE corner flashing.
Abbey Park H.S.	HBI227		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HBI213		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HB177		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HB072		2019-11-27	Evan Faubert	May 2020	Screw holes NW and corner flashing. Gap in SE fascia board.
Abbey Park H.S.	HB131		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HB053		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HB206		2019-11-27	Evan Faubert	May 2020	NE downspout heavily damaged.
Abbey Park H.S.	HBI224		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HB164		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HB163		2019-11-27	Evan Faubert	May 2020	NSMOMO
Abbey Park H.S.	HB108		2019-11-27	Evan Faubert	May 2020	NSMOMO
Alton Village P.S.	HBL235	11	2019-12-10	Erin Kulikowski	May 2020	Rotted Door Frame
Alton Village P.S.	HBL239		2019-12-10	Erin Kulikowski	May 2020	NSMOMO
Alton Village P.S.	HBL238		2019-12-10	Erin Kulikowski	May 2020	Degraded caulking outside at corners of windows
Alton Village P.S.	HBL237		2019-12-10	Erin Kulikowski	May 2020	Degraded caulking outside on window corners
Alton Village P.S.	HB037		2019-12-10	Erin Kulikowski	May 2020	NSMOMO
Alton Village P.S.	HB140		2019-12-10	Erin Kulikowski	May 2020	NSMOMO
Alton Village P.S.	HBL247		2019-12-10	Erin Kulikowski	May 2020	Degraded caulking outside in corner of windows
Alton Village P.S.	HB068		2019-12-10	Erin Kulikowski	May 2020	Level 1. Wet drywall beneath AC unit
Alton Village P.S.	HBL225		2019-12-10	Erin Kulikowski	May 2020	NSMOMO
Alton Village P.S.	HBL236		2019-12-10	Erin Kulikowski	May 2020	Caulking coming off of outside of door
Alton Village P.S.	HBL234		2019-12-10	Erin Kulikowski	May 2020	Degraded caulking on outside of windows
Anne J MacArthur P.S.	HBL215	8	2019-11-12	Serena Romito	May 2020	NSMOMO
Anne J MacArthur P.S.	HBL214		2019-11-12	Serena Romito	May 2020	NSMOMO
Anne J MacArthur P.S.	HBL204		2019-11-22	Serena Romito	May 2020	NSMOMO
Anne J MacArthur P.S.	HBL203		2019-11-22	Serena Romito	May 2020	NSMOMO
Anne J MacArthur P.S.	HBL202		2019-11-22	Serena Romito	May 2020	NSMOMO
Anne J MacArthur P.S.	HBL233		2019-11-22	Serena Romito	May 2020	NSMOMO
Anne J MacArthur P.S.	HBL232		2019-11-22	Serena Romito	May 2020	NSMOMO
Anne J MacArthur P.S.	HBL205		2019-11-22	Serena Romito	May 2020	Level 1 . Four water stained ceiling tiles due to roof leak
Boyne P.S.	HBL251	12	2019-11-19	Serena Romito	May 2020	NSMOMO
Boyne P.S.	HBL253		2019-11-19	Serena Romito	May 2020	NSMOMO
Boyne P.S.	HB152		2019-11-19	Serena Romito	May 2020	Degraded Caulking around door and between fascia boards. ~10 damaged vinyl floor tiles
Boyne P.S.	HBL252		2019-11-19	Serena Romito	May 2020	Detaching baseboard under Window
Boyne P.S.	HBL254		2019-11-19	Serena Romito	May 2020	NSMOMO
Boyne P.S.	HBL257		2019-11-19	Serena Romito	May 2020	NSMOMO
Boyne P.S.	HB015		2019-11-19	Serena Romito	May 2020	Degraded Caulking around door
Boyne P.S.	HB179		2019-11-19	Serena Romito	May 2020	Missing number plate above door
Boyne P.S.	HBL110		2019-11-19	Serena Romito	May 2020	NSMOMO
Boyne P.S.	HBL241		2019-11-19	Serena Romito	May 2020	NSMOMO
Boyne P.S.	HB028		2019-11-19	Serena Romito	May 2020	Detaching metal corner SW

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
Boyne P.S.	HBL226		2019-11-19	Serena Romito	May 2020	NSMOMO
Bruce T Lindley P.S.	HB166	1	2019-12-11	Erin Kulikowski	May 2020	Level 1 . Degraded caulking around door. Level 1 Remediation: wet drywall beneath west window
Bruce Trail P.S.	HBL228	17	2019-11-22	Serena Romito	May 2020	NSMOMO
Bruce Trail P.S.	HBL229		2019-11-22	Serena Romito	May 2020	NSMOMO
Bruce Trail P.S.	HBL231		2019-11-22	Serena Romito	May 2020	NSMOMO
Bruce Trail P.S.	HBL230		2019-11-22	Serena Romito	May 2020	One damaged / missing vinyl floor tile
Bruce Trail P.S.	HBL105		2019-11-22	Serena Romito	May 2020	~5 damaged vinyl floor tiles
Bruce Trail P.S.	HBL107		2019-11-22	Serena Romito	May 2020	NSMOMO
Bruce Trail P.S.	HBL262		2019-11-22	Serena Romito	May 2020	NSMOMO
Bruce Trail P.S.	HBL206		2019-11-22	Serena Romito	May 2020	NSMOMO
Bruce Trail P.S.	HB032		2019-11-25	Serena Romito	May 2020	Screw holes N side. Degraded Caulking around conduit N side
Bruce Trail P.S.	HB115		2019-11-25	Serena Romito	May 2020	Degraded Caulking around door. Screw holes near door
Bruce Trail P.S.	HB114		2019-11-25	Serena Romito	May 2020	Screw holes near door
Bruce Trail P.S.	HB062		2019-11-25	Serena Romito	May 2020	Degraded Caulking around windows
Bruce Trail P.S.	HB181		2019-11-25	Serena Romito	May 2020	NSMOMO
Bruce Trail P.S.	HB075		2019-11-25	Serena Romito	May 2020	Rotted window frames
Bruce Trail P.S.	HB103		2019-11-25	Serena Romito	May 2020	Degraded Caulking around door and windows
Bruce Trail P.S.	HB046		2019-11-25	Serena Romito	May 2020	Degraded Caulking around windows. Wasp nest in ceiling space above door. Majority of access panels nailed shut and unable to be opened
Bruce Trail P.S.	HB110		2019-11-25	Serena Romito	May 2020	Degraded Caulking around windows. Missing downspout near door
Captain R. Wilson P.S.	HB047	5	2019-12-17	Erin Kulikowski	May 2020	Caulking is missing from one conduit on left side. Down spout is coming off of eavestrough. Screw holes in sheathing to the right of the front door
Captain R. Wilson P.S.	HBL217		2019-12-17	Erin Kulikowski	May 2020	Degraded caulking at HVAC louvres
Captain R. Wilson P.S.	HB014		2019-12-17	Erin Kulikowski	May 2020	Downspout at back of portable is detaching
Captain R. Wilson P.S.	HB065		2019-12-17	Erin Kulikowski	May 2020	Rotted wood window frames and degraded caulking
Captain R. Wilson P.S.	HB106		2019-12-17	Erin Kulikowski	May 2020	HVAC louvre degraded caulking, holes in door and frame, soft tiles against back wall
Chris Hadfield P.S.	RM01	10	2019-12-03	Serena Romito	May 2020	NSMOMO
Chris Hadfield P.S.	RM02		2019-12-03	Serena Romito	May 2020	NSMOMO
Chris Hadfield P.S.	RM03		2019-12-03	Serena Romito	May 2020	NSMOMO
Chris Hadfield P.S.	RM04		2019-12-03	Serena Romito	May 2020	NSMOMO
Chris Hadfield P.S.	RM05		2019-12-03	Serena Romito	May 2020	Level 1 . Wet drywall window still under N window due to separating window Caulking
Chris Hadfield P.S.	RM06		2019-12-03	Serena Romito	May 2020	Degraded Caulking around N window
Chris Hadfield P.S.	RM07		2019-12-03	Serena Romito	May 2020	NSMOMO
Chris Hadfield P.S.	RM08		2019-12-03	Serena Romito	May 2020	Degraded Caulking E window
Chris Hadfield P.S.	RM09		2019-12-03	Serena Romito	May 2020	NSMOMO
Chris Hadfield P.S.	RM10		2019-12-03	Serena Romito	May 2020	NSMOMO
Craig Keilburger P.S.	HB133	9	2019-12-18	Erin Kulikowski	May 2020	Degraded caulking around the windows. Screw holes in east side of cladding.
Craig Keilburger P.S.	HB203		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking on the door, windows and HVAC louvre. Screw holes on the east side of cladding and in the door. Door is not sealed properly; air gap at the bottom.
Craig Keilburger P.S.	HB134		2019-12-19	Erin Kulikowski	May 2020	Level 1 . 1 water stained ceiling tile.
Craig Keilburger P.S.	HB057		2019-12-18	Erin Kulikowski	May 2020	Screw holes in cladding and window frames. Degraded caulking around windows and HVAC louvre

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
Craig Keilburger P.S.	HB125		2019-12-18	Erin Kulikowski	May 2020	Level 1 . 3 water stained ceiling tiles due to mouse droppings . Level 1 remediation: 3 water stained ceiling tiles due to mouse droppings. Insulation will need to be replaced. Bee hive in corner of ceiling. Degraded caulking around windows, door and HVAC
Craig Keilburger P.S.	HB113		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking around door and conduits. Damaged sheathing to the bottom right of the door.
Craig Keilburger P.S.	HBL084		2019-12-18	Erin Kulikowski	May 2020	Degraded window caulking
Craig Kielburger P.S.	HB073		2019-12-18	Erin Kulikowski	May 2020	Caulking around window frame is degraded. Wall corner is coming off of portable. Screw holes in cladding at the front of the portable.
Craig Kielburger P.S.	HB143		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking around windows, door and HVAC louvre. Baseboard in the portable is coming off of the all. Screw holes in east and west side of the cladding
E.J. James P.S.	HB061	3	2019-11-12	Evan Faubert	May 2020	Level 1 . Moisture detected below East Window 1 sqft
E.J. James P.S.	HB121		2019-11-12	Evan Faubert	May 2020	NSMOMO
E.J. James P.S.	HB111		2019-11-12	Evan Faubert	May 2020	NSMOMO
Emily Carr P.S.	HB084	4	2019-11-23	Evan Faubert	May 2020	NSMOMO
Emily Carr P.S.	HB040		2019-11-23	Evan Faubert	May 2020	Hole in west gable soffit. Numerous missing screws in NE cladding Portable under renovations.
Emily Carr P.S.	HB008		2019-11-23	Evan Faubert	May 2020	Missing flashing at N gable. Degraded caulking at NE conduit. Missing screws at N on E cladding. Under renovation.
Emily Carr P.S.	HBI008		2019-11-23	Evan Faubert	May 2020	NSMOMO
Escarpment View P.S.	HBL090	12	2019-11-18	Serena Romito	May 2020	NSMOMO
Escarpment View P.S.	HBL104		2019-11-18	Serena Romito	May 2020	Sporadic water staining on top of vapour barrier. ~15 damaged vinyl floor tiles
Escarpment View P.S.	HB144		2019-11-18	Serena Romito	May 2020	Level 3 . Mould growth on drywall on North wall near door and on drywall beneath south window. . Degraded Caulking around HVAC louvre . Ripped and peeling drywall covering throughout . ~20 damaged vinyl floor tiles . Damaged corner flashing at NE corne
Escarpment View P.S.	HB089		2019-11-18	Serena Romito	May 2020	Damaged sheathing under N window. Damaged Caulking around HVAC louvre
Escarpment View P.S.	HB005		2019-11-18	Serena Romito	May 2020	Screw hole in HVAC louvre. Degraded Caulking around S window. Eaves trough leaking onto S window
Escarpment View P.S.	HBL083		2019-11-18	Serena Romito	May 2020	NSMOMO
Escarpment View P.S.	HBL082		2019-11-18	Serena Romito	May 2020	NSMOMO
Escarpment View P.S.	HBL081		2019-11-18	Serena Romito	May 2020	Degraded Caulking around windows
Escarpment View P.S.	HBL089		2019-11-18	Serena Romito	May 2020	NSMOMO
Escarpment View P.S.	HB056		2019-11-18	Serena Romito	May 2020	NSMOMO
Escarpment View P.S.	HBL088		2019-11-18	Serena Romito	May 2020	NSMOMO
Escarpment View P.S.	HBL103		2019-11-18	Serena Romito	May 2020	NSMOMO
Ethel Gardiner P.S.	HB049	5	2019-12-09	Serena Romito	May 2020	Level 1 . One water stained ceiling tile due to roof leak
Ethel Gardiner P.S.	HBL212		2019-12-09	Serena Romito	May 2020	NSMOMO
Ethel Gardiner P.S.	HBL207		2019-12-09	Serena Romito	May 2020	NSMOMO
Ethel Gardiner P.S.	HBL263		2019-12-09	Serena Romito	May 2020	NSMOMO
Ethel Gardiner P.S.	HBL101		2019-12-09	Serena Romito	May 2020	Level 1 . Water stained ceiling tile due to roof leak
E. W. Foster P.S.	HB189	1	2019-12-11	Serena Romito	May 2020	Gap between fascia boards both sides. Gap in flashing N window
Falgarwood P.S.	HB147	1	2019-12-17	Erin Kulikowski	May 2020	Level 1 . 1 water stained ceiling tile at front of classroom . Level 1 Remediation: 1 Water stained ceiling tile

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
Florence Meares P.S.	HBL100	3	2019-12-10	Erin Kulikowski	May 2020	Degraded caulking on outside of windows
Florence Meares P.S.	HB139		2019-12-10	Erin Kulikowski	May 2020	NSMOMO
Florence Meares P.S.	HB069		2019-12-10	Erin Kulikowski	May 2020	Damaged down spout
Dr. Frank Hayden S.S.	HB151	9	2019-12-05	Serena Romito	May 2020	Level 3 . Impacted drywall under S window. One water stained ceiling tile . Damaged eve near door . Degraded Caulking around windows . Degraded Caulking around HVAC louvre . Damaged gable vent S side . Damaged vapour barrier SE side
Dr. Frank Hayden S.S.	HB059		2019-12-05	Serena Romito	May 2020	Degraded Caulking around door and N window
Dr. Frank Hayden S.S.	HB120		2019-12-05	Serena Romito	May 2020	No caulking around door
Dr. Frank Hayden S.S.	HB172		2019-12-05	Serena Romito	May 2020	Degraded Caulking around door
Dr. Frank Hayden S.S.	HB092		2019-12-05	Serena Romito	May 2020	NSMOMO
Dr. Frank Hayden S.S.	HB010		2019-12-05	Serena Romito	May 2020	Degraded Caulking around door and windows
Dr. Frank Hayden S.S.	HBL256		2019-12-05	Serena Romito	May 2020	NSMOMO
Dr. Frank Hayden S.S.	HB137		2019-12-05	Serena Romito	May 2020	Level 1 . Water stained ceiling tile near the door caused by condensation off of refrigeration line . Degraded caulking around door and south window
Dr. Frank Hayden S.S.	HB207		2019-12-05	Serena Romito	May 2020	NSMOMO
Garth Webb S.S	HB038	8	2019-12-16	Erin Kulikowski	May 2020	NSMOMO
Garth Webb S.S	HB045		2019-12-16	Erin Kulikowski	May 2020	No down spout . Wall flashing at seams are exposed. Down spout is missing. Flashing at corners is damaged. Drywall at seams in interior is exposed. Electrical panel has damaged drywall around it. Wallpaper is peeling on side with windows.
Garth Webb S.S	HB076		2019-12-16	Erin Kulikowski	May 2020	Eavestrough falling off side of portable
Garth Webb S.S	HB052		2019-12-16	Erin Kulikowski	May 2020	NSMOMO
Garth Webb S.S	HB090		2019-12-16	Erin Kulikowski	May 2020	Downspout is coming off of eavestrough . Degraded caulking . Hole in the floor at the end of the classroom . Degraded caulking at door, down spout coming apart from eavestrough, hole in the floor at the back of the classroom
Garth Webb S.S	HB091		2019-12-16	Erin Kulikowski	May 2020	Degraded caulking around door, windows and conduits. Screw holes in sheathing. Missing parts of floor tiles with exposed wood. Exterior corners of portable is damaged.
Garth Webb S.S	HB135		2019-12-16	Erin Kulikowski	May 2020	Floor tiles at door falling off and wood is exposed.
Garth Webb S.S	HB100		2019-12-16	Erin Kulikowski	May 2020	NSMOMO
Gladys Spears P.S.	HB158	1	2019-11-19	Evan Faubert	May 2020	NSMOMO
Glen Williams P.S.	HB178	2	2019-12-11	Serena Romito	May 2020	NSMOMO
Glen Williams P.S.	HB184		2019-12-11	Serena Romito	May 2020	NSMOMO
Glenview P.S.	HB148	2	2019-12-11	Erin Kulikowski	May 2020	NSMOMO
Glenview P.S.	HB122		2019-12-11	Erin Kulikowski	May 2020	NSMOMO
Hawthorne Village P.S.	RM301	16	2019-12-18	Erin Kulikowski	May 2020	NSMOMO
Hawthorne Village P.S.	RM302		2019-12-18	Erin Kulikowski	May 2020	NSMOMO
Hawthorne Village P.S.	RM303		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at wall junction.
Hawthorne Village P.S.	RM304		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at wall junction
Hawthorne Village P.S.	RM307		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at wall junction
Hawthorne Village P.S.	RM308		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at wall junction
Hawthorne Village P.S.	RM309		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at wall junction
Hawthorne Village P.S.	RM310		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at wall junction
Hawthorne Village P.S.	HB162		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking around door and windows. Missing downspout.
Hawthorne Village P.S.	HB013		2019-12-18	Erin Kulikowski	May 2020	Missing downspout
Hawthorne Village P.S.	HB136		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking around windows.

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
Hawthorne Village P.S.	HB035		2019-12-18	Erin Kulikowski	May 2020	NSMOMO
Hawthorne Village P.S.	HB034		2019-12-18	Erin Kulikowski	May 2020	NSMOMO
Hawthorne Village P.S.	HB036		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking around the door.
Hawthorne Village P.S.	RM305		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at wall junction
Hawthorne Village P.S.	RM306		2019-12-18	Erin Kulikowski	May 2020	Degraded caulking at the wall junction
Irma Coulson P.S.	HBL243	15	2019-12-19	Erin Kulikowski	May 2020	Degraded window and door caulking
Irma Coulson P.S.	HBL242		2019-12-19	Erin Kulikowski	May 2020	NSMOMO
Irma Coulson P.S.	HB142		2019-12-19	Erin Kulikowski	May 2020	NSMOMO
Irma Coulson P.S.	HB195		2019-12-19	Erin Kulikowski	May 2020	Cladding deteriorating beneath door
Irma Coulson P.S.	HB149		2019-12-19	Erin Kulikowski	May 2020	Level 1 . 1 water stained ceiling tile . Level 1 remediation: 1 water stained ceiling tile. Degraded door caulking and door seal is damaged.
Irma Coulson P.S.	HB196		2019-12-19	Erin Kulikowski	May 2020	Degraded caulking around windows
Irma Coulson P.S.	HB009		2019-12-19	Erin Kulikowski	May 2020	Degraded caulking around door and windows
Irma Coulson P.S.	HB146		2019-12-19	Erin Kulikowski	May 2020	Degraded caulking around door
Irma Coulson P.S.	HBL111		2019-12-19	Erin Kulikowski	May 2020	Degraded caulking around the windows
Irma Coulson P.S.	HB204		2019-12-19	Erin Kulikowski	May 2020	Level 1 . One water stained ceiling tile . Level 1 remediation: one water stained ceiling tile. Degraded caulking around door, windows and HVAC louvre.
Irma Coulson P.S.	HB150		2019-12-19	Erin Kulikowski	May 2020	NSMOMO
Irma Coulson P.S.	HB081		2019-12-19	Erin Kulikowski	May 2020	Screw holes in cladding to the right of the door
Irma Coulson P.S.	HBL244		2019-12-19	Erin Kulikowski	May 2020	NSMOMO
Irma Coulson P.S.	HBL245		2019-12-19	Erin Kulikowski	May 2020	NSMOMO
Irma Coulson P.S.	HBL246		2019-12-19	Erin Kulikowski	May 2020	Degraded caulking on door, windows, HVAC louvre and conduits
Iroquois Ridge H.S.	HB209	6	2019-11-13	Evan Faubert	May 2020	NSMOMO
Iroquois Ridge H.S.	HB070		2019-11-13	Evan Faubert	May 2020	Degraded caulking around window frames and one rotten window frame.
Iroquois Ridge H.S.	HB202		2019-11-13	Evan Faubert	May 2020	Missing casters at Southwest corner
Iroquois Ridge H.S.	HB145		2019-11-13	Evan Faubert	May 2020	Missing fasteners on North East northwest and south west corners
Iroquois Ridge H.S.	HB088		2019-11-13	Evan Faubert	May 2020	Wasp Nest in North East Ceiling Space
Iroquois Ridge H.S.	HBL264		2019-11-13	Evan Faubert	May 2020	NSMOMO
J.W Singleton ED. CTR.	HB119	4	2019-12-11	Erin Kulikowski	May 2020	Level 1 . Level 1 Remediation: 1 water stained ceiling tile in room adjacent to the entry
J.W Singleton ED. CTR.	HB003		2019-12-23	Erin Kulikowski	May 2020	NSMOMO
J.W Singleton ED. CTR.	HB117		2019-12-23	Erin Kulikowski	May 2020	Level 1 . Water impacted drywall under window on right side . Level 1 Remediation: wet drywall beneath window to the right side. Approx. 2 square feet.
J.W. Singleton ED. CTR.	HB118		2019-12-11	Erin Kulikowski	May 2020	NSMOMO
James W. Hill P.S.	HB050	6	2019-11-12	Evan Faubert	May 2020	NSMOMO
James W. Hill P.S.	HB086		2019-11-12	Evan Faubert	May 2020	NSMOMO
James W. Hill P.S.	HB099		2019-11-12	Evan Faubert	May 2020	NSMOMO
James W. Hill P.S.	HB176		2019-11-12	Evan Faubert	May 2020	NSMOMO
James W. Hill P.S.	HB080		2019-11-12	Evan Faubert	May 2020	NSMOMO
James W. Hill P.S.	HB107		2019-11-12	Evan Faubert	May 2020	NSMOMO
John T. Tuck P.S.	HBL219	10	2019-11-11	Serena Romito	May 2020	NSMOMO
John T. Tuck P.S.	HBL220		2019-11-11	Serena Romito	May 2020	NSMOMO
John T. Tuck P.S.	HB156		2019-11-11	Serena Romito	May 2020	NSMOMO

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
John T. Tuck P.S.	HB064		2019-11-11	Serena Romito	May 2020	NSMOMO
John T. Tuck P.S.	HB165		2019-11-11	Serena Romito	May 2020	Degraded Caulking around door
John T. Tuck P.S.	HBL216		2019-11-11	Serena Romito	May 2020	NSMOMO
John T. Tuck P.S.	HBL221		2019-11-11	Serena Romito	May 2020	Level 1 . Water stained ceiling tile N corner
John T. Tuck P.S.	HB169		2019-11-11	Serena Romito	May 2020	NSMOMO
John T. Tuck P.S.	HB157		2019-11-11	Serena Romito	May 2020	NSMOMO
John T. Tuck P.S.	HB173		2019-11-11	Serena Romito	May 2020	Degraded Caulking around door
John W. Boich P.S.	HBL109	1	2019-12-16	Erin Kulikowski	May 2020	NSMOMO
Joshua Creek P.S.	HB085	5	2019-11-13	Evan Faubert	May 2020	NSMOMO
Joshua Creek P.S.	HB077		2019-11-13	Evan Faubert	May 2020	NSMOMO
Joshua Creek P.S.	HB161		2019-11-13	Evan Faubert	May 2020	Moved from JW singleton. Being renovated.
Joshua Creek P.S.	HB155		2019-11-13	Evan Faubert	May 2020	Moved from Frank Hayden. Being renovated.
Joshua Creek P.S.	HB011		2019-11-13	Evan Faubert	May 2020	NSMOMO
Killbride P.S.	HB074	1	2019-11-12	Serena Romito	May 2020	NSMOMO
Maple Grove P.S.	HB130	2	2019-11-12	Evan Faubert	May 2020	NSMOMO
Maple Grove P.S.	HB159		2019-11-12	Evan Faubert	May 2020	NSMOMO
Milton District H.S.	HB001	5	2019-11-18	Serena Romito	May 2020	Missing number plate. Missing Caulking around door, Windows, and HVAC louvre
Milton District H.S.	HBL223		2019-11-18	Serena Romito	May 2020	NSMOMO
Milton District H.S.	HB041		2019-11-18	Serena Romito	May 2020	NSMOMO
Milton District H.S.	HB093		2019-11-18	Serena Romito	May 2020	Degraded Caulking around door, Windows and HVAC louvre
Milton District H.S.	HB154		2019-11-18	Serena Romito	May 2020	Level 2 . Impacted drywall beneath W window
Montclair	HBL255	1	2019-11-23	Evan Faubert	May 2020	Mislisted as at Posts Corners. Degraded caulking at HVAC exhaust, door bottom plate and NE conduit
Munn's P.S.		2	2019-11-23	Evan Faubert	May 2020	NSMOMO
Munn's P.S.			2019-11-23	Evan Faubert	May 2020	NSMOMO
New Central P.S.	HB079	2	2019-11-12	Evan Faubert	May 2020	East Seam panel loose/removed
New Central P.S.	HB104		2019-11-12	Evan Faubert	May 2020	Level 1 . 2 sqft of wet drywall at baseboard level. W wall . Conduit holes uncaulked SW . 2 sqft of wet drywall at baseboard level. W wall . 2 sqft of wet drywall at baseboard level. W wall . Conduit holes uncaulked SW
Oakville Trafalgar H.S.	RM190	11	2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM191		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM192		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM193		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM194		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM195		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM196		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM189A		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM197		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM198		2019-11-13	Evan Faubert	May 2020	NSMOMO
Oakville Trafalgar H.S.	RM189B		2019-11-13	Evan Faubert	May 2020	NSMOMO

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
Oodenawi P.S.	HB175	18	2019-11-24	Evan Faubert	May 2020	Level 1 . Level 1. 1 water stained ceiling tile north end. Water staining, outside organic debris animal droppings present on and above vapour barrier. Hole in vapor barrier. Damaged fascia board N side.
Oodenawi P.S.	HB058		2019-11-24	Evan Faubert	May 2020	Hole at NW corner soffit joint.
Oodenawi P.S.	HB101		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HBL260		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HB171		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HB096		2019-11-24	Evan Faubert	May 2020	Damaged NE corner flashing and screw holes.
Oodenawi P.S.	HB094		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HB128		2019-11-24	Evan Faubert	May 2020	Missing caulking from hangers. Degraded caulking on conduit W side
Oodenawi P.S.	HB044		2019-11-24	Evan Faubert	May 2020	Missing screws south side. Missing inspection port covers on both west and east inspection ports.
Oodenawi P.S.	HB067		2019-11-24	Evan Faubert	May 2020	Damaged window frames from screw holes.
Oodenawi P.S.	HBL261		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HBL085		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HBL005		2019-11-24	Serena Romito	May 2020	NSMOMO
Oodenawi P.S.	HBL080		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HBL258		2019-11-24	Evan Faubert	May 2020	Exterior screw holes in cladding above door
Oodenawi P.S.	HBL009		2019-11-24	Evan Faubert	May 2020	NSMOMO
Oodenawi P.S.	HBL086		2019-11-24	Evan Faubert	May 2020	Missing ID label
Oodenawi P.S.	HBL248		2019-11-24	Evan Faubert	May 2020	Missing ID label
Palermo P.S.	HB167	3	2019-11-23	Evan Faubert	May 2020	Level 1 Water stained ceiling tile and damaged vapor barrier at North East corner. Damaged corner flashing and detached downspout at NE corner
Palermo P.S.	HB168		2019-11-23	Evan Faubert	May 2020	Level 1. Water stained ceiling tile and damaged vapour barrier.SE corner.
Palermo P.S.	HB087		2019-11-23	Evan Faubert	May 2020	NSMOMO
Pauline Johnson P.S.	HB024	3	2019-11-11	Serena Romito	May 2020	NSMOMO
Pauline Johnson P.S.	HBL222		2019-11-11	Serena Romito	May 2020	NSMOMO
Pauline Johnson P.S.	HB102		2019-11-11	Serena Romito	May 2020	NSMOMO
Pilgrim Woods P.S.	HB123	5	2019-12-16	Erin Kulikowski	May 2020	NSMOMO
Pilgrim Woods P.S.	HB006		2019-12-16	Erin Kulikowski	May 2020	NSMOMO
Pilgrim Woods P.S.	HBL087		2019-12-16	Erin Kulikowski	May 2020	Degraded caulking around both windows.
Pilgrim Woods P.S.	HBL267		2019-12-16	Erin Kulikowski	May 2020	NSMOMO
Pilgrim Woods P.S.	HBL007		2019-12-16	Erin Kulikowski	May 2020	Degraded caulking around both windows.
P. L. Robertson P.S.	HBL265	12	2019-11-12	Serena Romito	May 2020	NSMOMO
P. L. Robertson P.S.	HBL259		2019-11-12	Serena Romito	May 2020	NSMOMO
P. L. Robertson P.S.	HBL091		2019-11-12	Serena Romito	May 2020	NSMOMO
P. L. Robertson P.S.	HB039		2019-11-12	Serena Romito	May 2020	NSMOMO
P. L. Robertson P.S.	HB051		2019-11-12	Serena Romito	May 2020	Level 1 . Water stained ceiling tile under center beam
P. L. Robertson P.S.	HBL266		2019-11-12	Serena Romito	May 2020	NSMOMO
P. L. Robertson P.S.	HB004		2019-11-12	Serena Romito	May 2020	Degraded Caulking around door
P. L. Robertson P.S.	HB027		2019-11-12	Serena Romito	May 2020	Broken window near door
P. L. Robertson P.S.	HB021		2019-11-12	Serena Romito	May 2020	Detaching downspout N corner
P. L. Robertson P.S.	HB030		2019-11-12	Serena Romito	May 2020	NSMOMO

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
P. L. Robertson P.S.	HB016		2019-11-12	Serena Romito	May 2020	NSMOMO
P. L. Robertson P.S.	HB022		2019-11-12	Serena Romito	May 2020	NSMOMO
Post's Corners P.S.	HBL268	9	2019-11-23	Evan Faubert	May 2020	Missing name plate
Post's Corners P.S.	HBL102		2019-11-23	Evan Faubert	May 2020	Broken window frame in door
Post's Corners P.S.	HB180		2019-11-23	Evan Faubert	May 2020	Missing down spout NW corner. Damaged drywall south wall. Prevalent Burnt odour in unit
Post's Corners P.S.	HB129		2019-11-23	Evan Faubert	May 2020	NSMOMO
Post's Corners P.S.	HBL006		2019-11-23	Evan Faubert	May 2020	NSMOMO
Post's Corners P.S.	HBL218		2019-11-23	Evan Faubert	May 2020	Missing outside name plate.
Post's Corners P.S.	HBL211		2019-11-23	Evan Faubert	May 2020	NSMOMO
Post's Corners P.S.	HBL255		2019-11-23	Evan Faubert	May 2020	NSMOMO. Mislisted as Montclair.
Post's Corners P.S.	HBL269		2019-11-23	Evan Faubert	May 2020	Missing name plate
River Oaks P.S.	HBL014	5	2019-11-21	Evan Faubert	May 2020	NSMOMO
River Oaks P.S.	HBL106		2019-11-21	Evan Faubert	May 2020	NSMOMO
River Oaks P.S.	HB208		2019-11-21	Evan Faubert	May 2020	Level 1 . Two water stained ceiling tiles due to roof leak. NE corner. Beehive in NE inspection port.
River Oaks P.S.	HB033		2019-11-21	Evan Faubert	May 2020	Missing exterior cladding on west seam.
River Oaks P.S.	HBL015		2019-11-21	Evan Faubert	May 2020	NSMOMO
Sam Sherratt P.S.	HB082	5	2019-11-25	Serena Romito	May 2020	Level 1 . Three water stained ceiling tiles due to roof leak
Sam Sherratt P.S.	HB083		2019-11-25	Serena Romito	May 2020	Level 1 . One water stained ceiling tile due to roof leak
Sam Sherratt P.S.	HBL099		2019-11-25	Serena Romito	May 2020	NSMOMO
Sam Sherratt P.S.	HB066		2019-11-25	Serena Romito	May 2020	NSMOMO
Sam Sherratt P.S.	HB127		2019-11-25	Serena Romito	May 2020	NSMOMO
Sheridan P.S.	HB132	1	2019-12-17	Erin Kulikowski	May 2020	Degraded caulking around door. Missing tiles where cabinet used to be at front of classroom left corner
Tiger Jeet Singh P.S.	HB126	11	2019-11-27	Serena Romito	May 2020	NSMOMO
Tiger Jeet Singh P.S.	HB063		2019-11-27	Serena Romito	May 2020	NSMOMO
Tiger Jeet Singh P.S.	HB109		2019-11-27	Serena Romito	May 2020	Missing drywall strapping near door
Tiger Jeet Singh P.S.	HB095		2019-11-27	Serena Romito	May 2020	NSMOMO
Tiger Jeet Singh P.S.	HB187		2019-11-27	Serena Romito	May 2020	Level 2 . Impacted drywall under right window due to degraded window Caulking . Degraded Caulking around windows
Tiger Jeet Singh P.S.	HB116		2019-11-27	Serena Romito	May 2020	Level 1 . Wet drywall under window . Degraded Caulking around windows
Tiger Jeet Singh P.S.	HBL108		2019-11-27	Serena Romito	May 2020	Missing drywall strapping near door under window
Tiger Jeet Singh P.S.	HBL013		2019-11-27	Serena Romito	May 2020	NSMOMO
Tiger Jeet Singh P.S.	HBL098		2019-11-27	Serena Romito	May 2020	NSMOMO
Tiger Jeet Singh P.S.	HB029		2019-11-27	Serena Romito	May 2020	NSMOMO
Tiger Jeet Singh P.S.	HBL079		2019-11-27	Serena Romito	May 2020	NSMOMO
Tom Thomson P.S.	HB141	6	2019-12-11	Erin Kulikowski	May 2020	NSMOMO
Tom Thomson P.S.	HB098		2019-12-11	Erin Kulikowski	May 2020	Degraded caulking around outside of doors, windows and air vent
Tom Thomson P.S.	HB105		2019-12-11	Erin Kulikowski	May 2020	Caulking around door cracking. No insulation in ceiling
Tom Thomson P.S.	HB031		2019-12-11	Erin Kulikowski	May 2020	Degraded caulking at bottom of door
Tom Thomson P.S.	HB124		2019-12-11	Erin Kulikowski	May 2020	NSMOMO
Tom Thomson P.S.	HB012		2019-12-11	Erin Kulikowski	May 2020	Level 1 . Damaged down spout. Level 1 remediation: 2 water stained ceiling tiles due to condensation



Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
Viola Desmond P.S.	HBL284	18	2019-12-11	Serena Romito	May 2020	Water staining on top of vapour barrier. Missing name plate
Viola Desmond P.S.	HBL282		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL276		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL278		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL281		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL280		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL279		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL287		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL285		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL286		2019-12-12	Serena Romito	May 2020	Missing number plate.
Viola Desmond P.S.	HBL283		2019-12-12	Serena Romito	May 2020	Level 1 . Water stained ceiling tile due to roof leak . Missing number plate.
Viola Desmond P.S.	HBL277		2019-12-12	Serena Romito	May 2020	Level 1 . Water stained ceiling tiles due to roof leaks . Missing number plate.
Viola Desmond P.S.	HBL270		2019-12-17	Erin Kulikowski	May 2020	Missing number plate
Viola Desmond P.S.	HBL271		2019-12-17	Erin Kulikowski	May 2020	Missing number plate
Viola Desmond P.S.	HBL272		2019-12-17	Erin Kulikowski	May 2020	Missing number plate
Viola Desmond P.S.	HBL273		2019-12-17	Erin Kulikowski	May 2020	Missing number plate
Viola Desmond P.S.	HBL274		2019-12-17	Erin Kulikowski	May 2020	Missing number plate
Viola Desmond P.S.	HBL275		2019-12-17	Erin Kulikowski	May 2020	Missing number plate
West Oak P.S.	RM01	6	2019-11-27	Evan Faubert	May 2020	NSMOMO
West Oak P.S.	RM02		2019-11-27	Evan Faubert	May 2020	NSMOMO
West Oak P.S.	RM03		2019-11-27	Evan Faubert	May 2020	NSMOMO
West Oak P.S.	RM04		2019-11-27	Evan Faubert	May 2020	NSMOMO
West Oak P.S.	RM05		2019-11-27	Evan Faubert	May 2020	NSMOMO
West Oak P.S.	RM06		2019-11-27	Evan Faubert	May 2020	NSMOMO
W.H. Morden P.S.	HB055	7	2019-11-19	Evan Faubert	May 2020	Degraded caulking around windows. One rotted window frame. Missing flashing above door. Wasp nest located above door.
W.H. Morden P.S.	HB138		2019-11-19	Evan Faubert	May 2020	NSMOMO
W.H. Morden P.S.	HBL249		2019-11-19	Evan Faubert	May 2020	NSMOMO
W.H. Morden P.S.	HBL250		2019-11-19	Evan Faubert	May 2020	NSMOMO
W.H. Morden P.S.	HBL201		2019-11-19	Evan Faubert	May 2020	NSMOMO
W.H. Morden P.S.	HB200		2019-11-19	Evan Faubert	May 2020	Missing fasteners at both west corners.
W.H. Morden P.S.	HB199		2019-11-19	Evan Faubert	May 2020	Hole in exterior cladding below HVAC intake. South side
White Oaks North H.S.	HBL092	5	2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks North H.S.	HBL093		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks North H.S.	HBL094		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks North H.S.	HBL095		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks North H.S.	HB060		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HB078	13	2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HB205		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HB023		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HB153		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HB112		2019-11-21	Evan Faubert	May 2020	Downspout off at me corner. Degraded caulking at door
White Oaks South H.S.	HB201		2019-11-21	Evan Faubert	May 2020	NSMOMO

Portable Classroom Preventative Inspection No. 109

School	Portable Number	Portables on Site	Round 109 Inspection Date	Pinchin Inspector	Proposed Round 110 Inspection Date	Comments from Round 109 Inspection
White Oaks South H.S.	HBL018		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HBL017		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HBL016		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HB054		2019-11-21	Evan Faubert	May 2020	Missing fasteners south and west side of portable. Missing northeast inspection port cover.
White Oaks South H.S.	HBL096		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HBL097		2019-11-21	Evan Faubert	May 2020	NSMOMO
White Oaks South H.S.	HB042		2019-11-21	Evan Faubert	May 2020	NSMOMO
W.I. Dick P.S.	HB007	3	2019-12-09	Serena Romito	May 2020	Degraded Caulking around door
W.I. Dick P.S.	HB002		2019-12-09	Serena Romito	May 2020	Damaged downspout rear side
W.I. Dick P.S.	HB183		2019-12-09	Serena Romito	May 2020	NSMOMO
<b>Total Number of Portables</b>		353				

<b>Notes:</b>
Scheduled inspection date subject to change due to availability of manpower and the facility.
<b>N.S.M.O.M.O. =</b> No Suspect Mould Or Moisture Observed