

Portable Classroom Preventative Inspection 110

School	Portable Number	Portables on Site	Round 110 Inspection Date	Pinchin Inspector	Proposed Round 111 Inspection Date	Comments from Round 110 Inspection
Abbey Park H.S.	HB177	12	2020-03-16	Evan Faubert	Jun-20	NSMOMO
Abbey Park H.S.	HBL213		2020-03-17	Evan Faubert	Jun-20	Screw holes above door. Holes in drywall at N and W walls
Abbey Park H.S.	HBL227		2020-03-17	Evan Faubert	Jun-20	NSMOMO
Abbey Park H.S.	HB043		2020-03-17	Evan Faubert	Jun-20	Level 1. Water stained ceiling tile NE corner where penetrating pipe is located. Screw holes in door and SE, NE, NW corner flashing.
Abbey Park H.S.	HB131		2020-03-17	Evan Faubert	Jun-20	NSMOMO
Abbey Park H.S.	HB072		2020-03-17	Evan Faubert	Jun-20	Gap in NE fascia board
Abbey Park H.S.	HB053		2020-03-17	Evan Faubert	Jun-20	Level 4. Mould detected on drywall below both windows
Abbey Park H.S.	HB206		2020-03-17	Evan Faubert	Jun-20	NSMOMO
Abbey Park H.S.	HBL224		2020-03-17	Evan Faubert	Jun-20	NSMOMO
Abbey Park H.S.	HB164		2020-03-17	Evan Faubert	Jun-20	Delaminating caulking below windows.Unsecure cladding below E window.
Abbey Park H.S.	HB163		2020-03-17	Evan Faubert	Jun-20	Gap in caulking in east conduit.
Abbey Park H.S.	HB108		2020-03-17	Evan Faubert	Jun-20	NSMOMO
Alton Village P.S.	HBL236	11	2020-03-18	Erin Kulikowski	Jun-20	Caulking separating around door
Alton Village P.S.	HBL235		2020-03-18	Erin Kulikowski	Jun-20	Rotted wooden door frame; caulking starting to separate.
Alton Village P.S.	HBL234		2020-03-18	Erin Kulikowski	Jun-20	Caulking around window corners are separating
Alton Village P.S.	HBL239		2020-03-18	Erin Kulikowski	Jun-20	NSMOMO
Alton Village P.S.	HBL238		2020-03-18	Erin Kulikowski	Jun-20	Caulking separating around windows
Alton Village P.S.	HBL237		2020-03-18	Erin Kulikowski	Jun-20	Caulking separating around windows
Alton Village P.S.	HBL247		2020-03-18	Erin Kulikowski	Jun-20	Caulking separating at corners of windows
Alton Village P.S.	HB140		2020-03-18	Erin Kulikowski	Jun-20	NSMOMO
Alton Village P.S.	HB037		2020-03-18	Erin Kulikowski	Jun-20	NSMOMO
Alton Village P.S.	HB068		2020-03-18	Erin Kulikowski	Jun-20	Missing caulking above HVAC louvre. Pest droppings present in the inspection ports.
Alton Village P.S.	HBL225		2020-03-18	Erin Kulikowski	Jun-20	Caulking on bottom of the door deteriorating. Conduit missing caulking
Anne J MacArthur P.S.	HBL202	9	2020-03-18	Serena Romito	Jun-20	NSMOMO
Anne J MacArthur P.S.	HBL204		2020-03-18	Serena Romito	Jun-20	NSMOMO
Anne J MacArthur P.S.	HBL214		2020-03-18	Serena Romito	Jun-20	NSMOMO
Anne J MacArthur P.S.	HBL215		2020-03-18	Serena Romito	Jun-20	NSMOMO
Anne J MacArthur P.S.	HBL203		2020-04-17	Evan Faubert	Jun-20	NSMOMO
Anne J. MacArthur P.S.	HBL233		2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Anne J. MacArthur P.S.	HBL232		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around windows.
Anne J. MacArthur P.S.	HBL205		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around window. Damaged downspout.
Anne J. MacArthur P.S.	HB174		2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Boyne P.S.	HBL251	12	2020-03-16	Serena Romito	Jun-20	NSMOMO
Boyne P.S.	HBL253		2020-03-16	Serena Romito	Jun-20	NSMOMO
Boyne P.S.	HB152		2020-03-16	Serena Romito	Jun-20	Degraded Caulking around door and between fascia boards. Lifting vinyl floor tiles throughout.
Boyne P.S.	HBL252		2020-03-16	Serena Romito	Jun-20	NSMOMO
Boyne P.S.	HBL254		2020-03-16	Serena Romito	Jun-20	NSMOMO
Boyne P.S.	HB015		2020-03-16	Serena Romito	Jun-20	Degraded Caulking and detaching sheathing around door
Boyne P.S.	HBL226		2020-03-16	Serena Romito	Jun-20	NSMOMO
Boyne P.S.	HB028		2020-03-16	Serena Romito	Jun-20	Wasp nest in ceiling space north corner. Degraded Caulking around windows, HVAC louvre, and windows
Boyne P.S.	HBL241		2020-03-16	Serena Romito	Jun-20	Level 1. Water stained ceiling tile due to roof leak
Boyne P.S.	HBL110		2020-03-16	Serena Romito	Jun-20	Railing loose and detached from wall . NSMOMO
Boyne P.S.	HBL257		2020-03-16	Serena Romito	Jun-20	NSMOMO
Boyne P.S.	HB179		2020-03-16	Serena Romito	Jun-20	Missing number plate above door
Bruce T. Lindley P.S.	HB166	1	2020-03-17	Erin Kulikowski	Jun-20	Level 1. Wet drywall beneath west window . Level 1- wet drywall beneath west window approximately 1 ft square left side. Degraded window caulking
Bruce Trail P.S.	HB032	17	2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HBL228		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HBL229		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HBL231		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HBL230		2020-03-20	Serena Romito	Jun-20	Three damaged vinyl floor tiles near the door
Bruce Trail P.S.	HB115		2020-03-20	Serena Romito	Jun-20	Degraded Caulking around door. Screw holes by door
Bruce Trail P.S.	HBL105		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HB062		2020-03-20	Serena Romito	Jun-20	Degraded Caulking around door and windows
Bruce Trail P.S.	HB114		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HB046		2020-03-20	Serena Romito	Jun-20	Degraded Caulking around windows. Wasp nest in ceiling space above door
Bruce Trail P.S.	HB110		2020-03-20	Serena Romito	Jun-20	Level 1. Wet drywall around windows . Degraded Caulking around door and windows. Missing downspout near door
Bruce Trail P.S.	HB103		2020-03-20	Serena Romito	Jun-20	Degraded Caulking around door and windows
Bruce Trail P.S.	HB075		2020-03-20	Serena Romito	Jun-20	Degraded Caulking around windows and rotted window frames. Degraded Caulking around door
Bruce Trail P.S.	HB181		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HBL107		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HBL262		2020-03-20	Serena Romito	Jun-20	NSMOMO
Bruce Trail P.S.	HBL206		2020-03-20	Serena Romito	Jun-20	Level 1. Wet drywall under window . Degraded Caulking around windows
Captain R Wilson P.S.	HB047	5	2020-03-16	Evan Faubert	Jun-20	Screw holes in cladding near door
Captain R Wilson P.S.	HB106		2020-03-16	Evan Faubert	Jun-20	Screw holes in door and door frame.
Captain R Wilson P.S.	HB065		2020-03-16	Evan Faubert	Jun-20	NSMOMO
Captain R Wilson P.S.	HB014		2020-03-16	Evan Faubert	Jun-20	Detached downspout.
Captain R Wilson P.S.	HBL217		2020-03-16	Evan Faubert	Jun-20	Screw holes NE and SE cladding corners. Hole at NE top conduit.
Chris Hadfield P.S	RM03	10	2020-03-10	Serena Romito	Jun-20	Hole in Caulking on East window
Chris Hadfield P.S	RM03		2020-03-10	Serena Romito	Jun-20	NSMOMO
Chris Hadfield P.S	RM04		2020-03-10	Serena Romito	Jun-20	NSMOMO
Chris Hadfield P.S	RM05		2020-03-10	Serena Romito	Jun-20	NSMOMO

Portable Classroom Preventative Inspection 110

School	Portable Number	Portables on Site	Round 110 Inspection Date	Pinchin Inspector	Proposed Round 111 Inspection Date	Comments from Round 110 Inspection
Chris Hadfield P.S	RM07		2020-03-10	Serena Romito	Jun-20	NSMOMO
Chris Hadfield P.S	RM08		2020-03-10	Serena Romito	Jun-20	Spilt Caulking around north window
Chris Hadfield P.S	RM09		2020-03-10	Serena Romito	Jun-20	NSMOMO
Chris Hadfield P.S	RM10		2020-03-10	Serena Romito	Jun-20	NSMOMO
Chris Hadfield P.S.	RM01		2020-03-10	Serena Romito	Jun-20	NSMOMO
Chris Hadfield P.S.	RM02		2020-03-10	Serena Romito	Jun-20	NSMOMO
Craig Keilburger S.S.	HB073	9	2020-03-18	Serena Romito	Jun-20	Screw holes front elevation. Rotted window frames with degraded Caulking around both windows
Craig Keilburger S.S.	HB143		2020-03-18	Serena Romito	Jun-20	Degraded Caulking around windows, HVAC louvre, and door. Screw holes in east and west side of cladding
Craig Keilburger S.S.	HB133		2020-03-18	Serena Romito	Jun-20	Degraded Caulking around windows. Screw holes front elevation
Craig Keilburger S.S.	HB203		2020-03-18	Serena Romito	Jun-20	Degraded Caulking around windows, HVAC louvre, and door. Damaged / missing door sweep and weather stripping around door
Craig Keilburger S.S.	HB057		2020-03-18	Serena Romito	Jun-20	Degraded Caulking around door, Windows and HVAC louvre. Screw holes near door
Craig Keilburger S.S.	HB113		2020-03-18	Serena Romito	Jun-20	Degraded Caulking around door
Craig Keilburger S.S.	HB134		2020-03-18	Serena Romito	Jun-20	NSMOMO
Craig Keilburger S.S.	HB125		2020-03-18	Serena Romito	Jun-20	Degraded Caulking around door, Windows and HVAC louvre
Craig Keilburger S.S.	HBL084		2020-03-18	Serena Romito	Jun-20	Damaged downspout rear elevation
Dr. Frank J. Hayden S.S.	HB059	9	2020-03-18	Erin Kulikowski	Jun-20	Degraded caulking around door and windows. Pest droppings present in ceiling insulation.
Dr. Frank J. Hayden S.S.	HB120		2020-03-18	Erin Kulikowski	Jun-20	Degraded caulking around door
Dr. Frank J. Hayden S.S.	HB172		2020-03-18	Erin Kulikowski	Jun-20	Degraded caulking around door
Dr. Frank J. Hayden S.S.	HB092		2020-03-18	Erin Kulikowski	Jun-20	NSMOMO
Dr. Frank J. Hayden S.S.	HB010		2020-03-18	Erin Kulikowski	Jun-20	Level 1 . 1 water stained ceiling tile above HVAC . Level 1: 1 water stained ceiling tile above HVAC unit. Degraded caulking around windows and doors.
Dr. Frank J. Hayden S.S.	HBL256		2020-03-18	Erin Kulikowski	Jun-20	Degrading caulking around windows.
Dr. Frank J. Hayden S.S.	HB137		2020-03-18	Erin Kulikowski	Jun-20	Level 1 . 1 water stained ceiling tile . Level 1: 1 water stained ceiling tile
Dr. Frank J. Hayden S.S.	HB207		2020-03-18	Erin Kulikowski	Jun-20	NSMOMO
Dr. Frank J. Hayden S.S.	HB151		2020-03-18	Erin Kulikowski	Jun-20	NSMOMO
E.J. James P.S.	HB111	3	2020-03-20	Erin Kulikowski	Jun-20	Separating caulking around door frame
E.J James P.S.	HB061		2020-03-20	Erin Kulikowski	Jun-20	Degraded caulking around windows
E.J James P.S.	HB121		2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
E.W. Foster P.S.	HB189	1	2020-03-10	Serena Romito	Jun-20	Gap between fascia boards both ends
Emily Carr P.S.	HBL008	4	2020-03-16	Evan Faubert	Jun-20	NSMOMO
Emily Carr P.S.	HB008		2020-03-16	Evan Faubert	Jun-20	Level 1 . Stained ceiling tiles . 2 water stained ceiling tiles N and W. West centre roof beam is rusted. Screw Holes in NE cladding and at NW flashing. Degraded caulking at NW conduit.
Emily Carr P.S.	HB040		2020-03-16	Evan Faubert	Jun-20	Level 1 . Water stained ceiling tile . Gap in north gable soffit. Screw holes in NE and NW corners. Water stained ceiling tile at NW corner.
Emily Carr P.S.	HB084		2020-03-16	Evan Faubert	Jun-20	NSMOMO
Escarpment View P.S.	HBL090	12	2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HBL103		2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HBL104		2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HB144		2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HB005		2020-03-05	Serena Romito	Jun-20	Screw hole in HVAC louvre. Degraded Caulking around south window
Escarpment View P.S.	HB089		2020-03-05	Serena Romito	Jun-20	Level 1 . Wet drywall beneath north window. . Degraded Caulking north window. Degraded Caulking along centre beam
Escarpment View P.S.	HBL083		2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HBL082		2020-03-05	Serena Romito	Jun-20	Degraded Caulking around windows
Escarpment View P.S.	HBL081		2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HB056		2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HBL088		2020-03-05	Serena Romito	Jun-20	NSMOMO
Escarpment View P.S.	HBL089		2020-03-05	Serena Romito	Jun-20	NSMOMO
Ethel Gardiner P.S.	HBL101	5	2020-03-10	Serena Romito	Jun-20	Disconnected down spout front elevation
Ethel Gardiner P.S.	HBL263		2020-03-10	Serena Romito	Jun-20	NSMOMO
Ethel Gardiner P.S.	HBL207		2020-03-10	Serena Romito	Jun-20	NSMOMO
Ethel Gardiner P.S.	HBL212		2020-03-10	Serena Romito	Jun-20	NSMOMO
Ethel Gardiner P.S.	HB049		2020-03-10	Serena Romito	Jun-20	Missing downspout rear elevation
Falgarwood P.S.	HB147	1	2020-03-18	Evan Faubert	Jun-20	NSMOMO
Florence Meares P.S.	HB069	3	2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around windows and conduits. Downspout is damaged
Florence Meares P.S.	HBL100		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around windows
Florence Meares P.S.	HB139		2020-03-17	Erin Kulikowski	Jun-20	NSMOMO
Garth Webb S.S.	HB090	8	2020-03-16	Evan Faubert	Jun-20	Missing screws at NW corner cladding.
Garth Webb S.S.	HB100		2020-03-16	Evan Faubert	Jun-20	Conduit and screw holes in east cladding.
Garth Webb S.S.	HB135		2020-03-16	Evan Faubert	Jun-20	Busted floor tiles at door.
Garth Webb S.S.	HB091		2020-03-16	Evan Faubert	Jun-20	Screw holes at northeast cladding near door.
Garth Webb S.S.	HB045		2020-03-16	Evan Faubert	Jun-20	Degraded caulking at NE window and at door. Screw holes at NE and SE corner flashing
Garth Webb S.S.	HB038		2020-03-16	Evan Faubert	Jun-20	Level 2 . Mould on bottom of drywall and wall paper below west window. Multiple damaged/missing floor tiles near door and ac unit. Degraded caulking at door. Missing caulking at SE conduits.
Garth Webb S.S.	HB052		2020-03-16	Evan Faubert	Jun-20	NSMOMO
Garth Webb S.S.	HB076		2020-03-16	Evan Faubert	Jun-20	NSMOMO
Gladys Spears P.S.	HB158	1	2020-03-16	Evan Faubert	Jun-20	Missing west seam gable flashing on exterior
Glen Williams P.S.	HB184	2	2020-03-10	Serena Romito	Jun-20	Level 1 . Wet drywall due to window leaks . Degraded Caulking around windows
Glen Williams P.S.	HB178		2020-03-10	Serena Romito	Jun-20	Degraded Caulking around window near door
Glenview P.S.	HB122	2	2020-03-17	Erin Kulikowski	Jun-20	Degrading caulking around conduits
Glenview P.S.	HB148		2020-03-17	Erin Kulikowski	Jun-20	NSMOMO

Portable Classroom Preventative Inspection 110

School	Portable Number	Portables on Site	Round 110 Inspection Date	Pinchin Inspector	Proposed Round 111 Inspection Date	Comments from Round 110 Inspection
Hawthorne Village P.S.	HB162	16	2020-03-18	Serena Romito	Jun-20	Degraded Caulking around window to left of HVAC louvre . One damaged gable louvre . Damaged drywall beneath window to right of HVAC unit
Hawthorne Village P.S.	HB013		2020-03-18	Serena Romito	Jun-20	NSMOMO
Hawthorne Village P.S.	HB136		2020-03-18	Serena Romito	Jun-20	NSMOMO
Hawthorne Village P.S.	HB035		2020-03-18	Serena Romito	Jun-20	NSMOMO
Hawthorne Village P.S.	HB036		2020-03-18	Serena Romito	Jun-20	Damaged downspout front elevation
Hawthorne Village P.S.	HB034		2020-03-18	Serena Romito	Jun-20	NSMOMO
Hawthorne Village P.S.	RM301		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM302		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM303		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM304		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM307		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM308		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM309		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM310		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM305		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Hawthorne Village P.S.	RM306		2020-04-17	Evan Faubert	Jun-20	Degraded caulking at wall junction
Irma Coulson P.S.	HB195	15	2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Irma Coulson P.S.	HB149		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around HVAC Louvre. Holes in cladding above door.
Irma Coulson P.S.	HB196		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around HVAC louvre
Irma Coulson P.S.	HBL243		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around door and windows. Rotted wet plywood on the base of the portable at the downspout. Down spout at the back of the portable is not connected to the eavestrough
Irma Coulson P.S.	HBL242		2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Irma Coulson P.S.	HB142		2020-03-19	Erin Kulikowski	Jun-20	Pest droppings in ceiling insulation
Irma Coulson P.S.	HB009		2020-03-19	Erin Kulikowski	Jun-20	Screw holes in door. Cracking caulking around windows.
Irma Coulson P.S.	HB146		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around door. Holes in cladding a NE end.
Irma Coulson P.S.	HBL111		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around windows
Irma Coulson P.S.	HB204		2020-03-19	Erin Kulikowski	Jun-20	No caulking around HVAC. Inspection port under north east window has a hole in the exterior wall under the cladding, sunlight is visible.
Irma Coulson P.S.	HB150		2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Irma Coulson P.S.	HB081		2020-03-19	Erin Kulikowski	Jun-20	Screw holes in the door and on the front of the portable.
Irma Coulson P.S.	HBL244		2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Irma Coulson P.S.	HBL245		2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Irma Coulson P.S.	HBL246		2020-03-19	Erin Kulikowski	Jun-20	Degraded caulking around door and windows
Iroquois Ridge H.S.	HBL264	6	2020-03-19	Evan Faubert	Jun-20	NSMOMO
Iroquois Ridge H.S.	HB145		2020-03-19	Evan Faubert	Jun-20	Screw holes in SE and NE corner cladding. Missing skirting at SE corner.
Iroquois Ridge H.S.	HB088		2020-03-19	Evan Faubert	Jun-20	Wasp nest in NE ceiling space.
Iroquois Ridge H.S.	HB202		2020-03-19	Evan Faubert	Jun-20	Cut in vapour barrier above ceiling tile and near air vent.
Iroquois Ridge H.S.	HB070		2020-03-19	Evan Faubert	Jun-20	Rotted window frame on west window.
Iroquois Ridge H.S.	HB209		2020-03-19	Evan Faubert	Jun-20	Missing strapping at south seam. Daylight visible at seam. Open vapor barrier at NE corner. Daylight and pest droppings visible.
J W Singleton ED. CTR.	HB003	4	2020-04-20	Evan Faubert	Jun-20	NSMOMO
J W Singleton ED. CTR.	HB117		2020-04-20	Evan Faubert	Jun-20	NSMOMO
J W Singleton ED. CTR.	HB118		2020-04-20	Serena Romito	Jun-20	NSMOMO
J W Singleton ED. CTR.	HB119		2020-04-20	Evan Faubert	Jun-20	NSMOMO
James W. Hill P.S.	HB107	6	2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
James W. Hill P.S.	HB176		2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
James W. Hill P.S.	HB099		2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
James W. Hill P.S.	HB080		2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
James W. Hill P.S.	HB086		2020-03-20	Erin Kulikowski	Jun-20	Level 1 . Damp drywall to full height from W corner to the fire alarm . Level 1 remediation: damp drywall (.8% moisture) full height from west corner to fire alarm.
James W. Hill P.S.	HB050		2020-03-20	Erin Kulikowski	Jun-20	Level 1 . Damp drywall to full height from west corner to the right of door frame . Level 1 remediation: damp drywall (0.6%) to full height from west corner to the right of door frame. No caulking around the one conduit.
John T. Tuck P.S.	HBL220	10	2020-03-17	Erin Kulikowski	Jun-20	Caulking missing around conduit. Caulking starting to degrade on windows
John T. Tuck P.S.	HB173		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around door and gable louvre
John T. Tuck P.S.	HB157		2020-03-17	Erin Kulikowski	Jun-20	Caulking on door and windows starting to degrade and separate
John T. Tuck P.S.	HB156		2020-03-17	Erin Kulikowski	Jun-20	NSMOMO
John T. Tuck P.S.	HB064		2020-03-17	Erin Kulikowski	Jun-20	Rotted wooden door frame
John T. Tuck P.S.	HBL219		2020-03-17	Erin Kulikowski	Jun-20	Caulking separating on windows
John T. Tuck P.S.	HB165		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking below windows and around the conduits
John T. Tuck P.S.	HBL221		2020-03-17	Erin Kulikowski	Jun-20	NSMOMO
John T. Tuck P.S.	HBL216		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around windows
John T. Tuck P.S.	HB169		2020-03-17	Erin Kulikowski	Jun-20	NSMOMO
John W. Boich P.S.	HBL109	1	2020-03-17	Erin Kulikowski	Jun-20	NSMOMO
Joshua Creek P.S.	HB161	5	2020-03-20	Evan Faubert	Jun-20	NSMOMO
Joshua Creek P.S.	HB155		2020-03-20	Evan Faubert	Jun-20	NSMOMO
Joshua Creek P.S.	HB077		2020-03-20	Evan Faubert	Jun-20	NSMOMO
Joshua Creek P.S.	HB011		2020-03-20	Evan Faubert	Jun-20	NSMOMO
Joshua Creek P.S.	HB085		2020-03-20	Evan Faubert	Jun-20	NSMOMO
Killbride P.S.	HB074	1	2020-03-04	Serena Romito	Jun-20	NSMOMO
Maple Grove P.S.	HB130	2	2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Maple Grove P.S.	HB159		2020-03-19	Erin Kulikowski	Jun-20	Caulking starting to crack around windows. Downspout is damaged.
Milton District H.S.	HB154	5	2020-03-18	Erin Kulikowski	Jun-20	Degrading caulking around windows, door, HVAC louvre and conduits. Pest dropping present in ceiling insulation
Milton District H.S.	HB093		2020-03-18	Erin Kulikowski	Jun-20	Degraded caulking around door, windows and HVAC louvre. Holes in cladding on SE wall; plywood exposed.

Portable Classroom Preventative Inspection 110

School	Portable Number	Portables on Site	Round 110 Inspection Date	Pinchin Inspector	Proposed Round 111 Inspection Date	Comments from Round 110 Inspection
Milton District H.S.	HB041		2020-03-18	Erin Kulikowski	Jun-20	Degraded caulking around HVAC louvre and conduits.
Milton District H.S.	HBL223		2020-03-18	Erin Kulikowski	Jun-20	Degraded caulking around the door
Milton District H.S.	HB001		2020-03-18	Erin Kulikowski	Jun-20	Missing caulking around doors, windows and HVAC louvre. Exposed plywood on NW wall
Montclair	HBL210	1	2020-04-17	Evan Faubert	Jun-20	Miss listed as HBL255. Degraded caulking at HVAC. Degraded caulking at NW conduit.
Munn's P.S.	HBL001	2	2020-03-17	Evan Faubert	Jun-20	Damaged NW corner flashing.
Munn's P.S.	HBL002		2020-03-17	Evan Faubert	Jun-20	NSMOMO
New Central P.S.	HB104	2	2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
New Central P.S.	HB079		2020-03-19	Erin Kulikowski	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM190	11	2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM191		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM192		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM193		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM194		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM195		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM196		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM197		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM198		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM189a		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oakville Trafalgar H.S.	RM189b		2020-04-15	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB058	18	2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB101		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HBL260		2020-03-19	Evan Faubert	Jun-20	Missing caulking at NW conduit penetrations.
Oodenawi P.S.	HB171		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB175		2020-03-19	Evan Faubert	Jun-20	Evidence of pest droppings on top of vapour barrier throughout.
Oodenawi P.S.	HBL048		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB096		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB094		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB128		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB044		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HB067		2020-03-19	Evan Faubert	Jun-20	Wooden Walkway plank is offset
Oodenawi P.S.	HBL086		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HBL261		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HBL085		2020-03-19	Evan Faubert	Jun-20	Degraded caulking at top of HVAC
Oodenawi P.S.	HBL005		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HBL080		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HBL258		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Oodenawi P.S.	HBL009		2020-03-19	Evan Faubert	Jun-20	NSMOMO
P.L. Robertson P.S.	HBL265	12	2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HBL259		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HBL091		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HB039		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HB051		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HBL266		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HB022		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HB016		2020-03-04	Serena Romito	Jun-20	Degraded Caulking around door
P.L. Robertson P.S.	HB030		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HB021		2020-03-04	Serena Romito	Jun-20	Damaged downspout front elevation. Missing flashing on HVAC louvre.
P.L. Robertson P.S.	HB027		2020-03-04	Serena Romito	Jun-20	NSMOMO
P.L. Robertson P.S.	HB004		2020-03-04	Serena Romito	Jun-20	Degraded Caulking around door and HVAC louvre.
Palermo P.S.	HB087	3	2020-03-16	Evan Faubert	Jun-20	NSMOMO
Palermo P.S.	HB167		2020-03-16	Evan Faubert	Jun-20	Small hole in NW drywall and SE drywall walls.
Palermo P.S.	HB168		2020-03-16	Evan Faubert	Jun-20	NSMOMO
Pauline Johnson P.S.	HB102	3	2020-03-17	Erin Kulikowski	Jun-20	Caulking separating on windows and gable louvre. Holes in the cladding on both sides of the door.
Pauline Johnson P.S.	HBL222		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around windows
Pauline Johnson P.S.	HB024		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around gable louvre and conduits. Holes in cladding on NW wall
Pilgrim Woods P.S.	HBL007	5	2020-03-17	Evan Faubert	Jun-20	NSMOMO
Pilgrim Woods P.S.	HB123		2020-03-17	Evan Faubert	Jun-20	Missing down spout and screw holes in cladding at NE corner.
Pilgrim Woods P.S.	HB006		2020-03-17	Evan Faubert	Jun-20	Screw holes at SW corner cladding.
Pilgrim Woods P.S.	HBL087		2020-03-17	Evan Faubert	Jun-20	Missing ID plate
Pilgrim Woods P.S.	HBL267		2020-03-17	Evan Faubert	Jun-20	Missing ID Plate
Posts Corners P.S.	HBL006	9	2020-03-19	Evan Faubert	Jun-20	NSMOMO
Posts Corners P.S.	HBL102		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Posts Corners P.S.	HB180		2020-03-19	Evan Faubert	Jun-20	Missing downspout at NW corner.
Posts Corners P.S.	HB129		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Posts Corners P.S.	HBL255		2020-03-19	Evan Faubert	Jun-20	Screw holes in cladding NW corner cladding and door. Miss listed to be at Montclair
Posts Corners P.S.	HBL211		2020-03-19	Evan Faubert	Jun-20	Missing caulking on top of HVAC
Posts Corners P.S.	HBL268		2020-03-19	Evan Faubert	Jun-20	Missing ID plate
Posts Corners P.S.	HBL218		2020-03-19	Evan Faubert	Jun-20	NSMOMO
Posts Corners P.S.	HBL269		2020-04-20	Evan Faubert	Jun-20	Missing Id tag
River Oaks P.S.	HBL014	5	2020-03-17	Evan Faubert	Jun-20	NSMOMO
River Oaks P.S.	HBL015		2020-03-16	Evan Faubert	Jun-20	Missing down spout, torn cladding at NE Corner
River Oaks P.S.	HB208		2020-03-17	Evan Faubert	Jun-20	Repair work done on vapour barrier. Missing exterior cladding at east portable seam.

Portable Classroom Preventative Inspection 110

School	Portable Number	Portables on Site	Round 110 Inspection Date	Pinchin Inspector	Proposed Round 111 Inspection Date	Comments from Round 110 Inspection
River Oaks P.S.	HBL106		2020-03-17	Evan Faubert	Jun-20	NSMOMO
River Oaks P.S.	HB033		2020-03-17	Evan Faubert	Jun-20	Missing caulking in holes from conduits. NE and NW corners.
Sam Sherratt P.S.	HB082	5	2020-03-12	Serena Romito	Jun-20	Level 1 . Three water stained ceiling tiles due to roof leak or condensation
Sam Sherratt P.S.	HB083		2020-03-12	Serena Romito	Jun-20	Level 1 . Four water stained ceiling tiles due to roof leak or condensation
Sam Sherratt P.S.	HBL099		2020-03-12	Serena Romito	Jun-20	NSMOMO
Sam Sherratt P.S.	HB066		2020-03-12	Serena Romito	Jun-20	NSMOMO
Sam Sherratt P.S.	HB127		2020-03-12	Serena Romito	Jun-20	NSMOMO
Sheridan P.S.	HB132	1	2020-03-18	Evan Faubert	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HB126	11	2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HB063		2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HB109		2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HB095		2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HB187		2020-03-12	Serena Romito	Jun-20	Degraded Caulking around door due to loose door frame. Degraded Caulking along centre beam
Tiger Jeet Singh P.S.	HB116		2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HBL108		2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HBL013		2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HBL098		2020-03-12	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HB029		2020-03-16	Serena Romito	Jun-20	NSMOMO
Tiger Jeet Singh P.S.	HBL079		2020-03-16	Serena Romito	Jun-20	NSMOMO
Tom Thomson P.S.	HB098	6	2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around windows, doors, HVAC louvre and conduits.
Tom Thomson P.S.	HB105		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around windows
Tom Thomson P.S.	HB031		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around door
Tom Thomson P.S.	HB124		2020-03-17	Erin Kulikowski	Jun-20	Degraded caulking around conduits
Tom Thomson P.S.	HB012		2020-03-17	Erin Kulikowski	Jun-20	Level 1 . 6 water stained ceiling tiles . Level 1 Remediation: 6 water stained ceiling tiles due to condensation. Degraded caulking around HVAC louvre and damaged down spout
Tom Thomson P.S.	HB141		2020-03-17	Erin Kulikowski	Jun-20	NSMOMO
Viola Desmond P.S.	HBL284	18	2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL283		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL282		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL287		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL286		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL285		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL279		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL280		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL281		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL276		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL277		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL278		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL272		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL271		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL270		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL275		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL274		2020-03-17	Serena Romito	Jun-20	NSMOMO
Viola Desmond P.S.	HBL273		2020-03-17	Serena Romito	Jun-20	NSMOMO
W.H Morden P.S.	HB199	7	2020-03-20	Erin Kulikowski	Jun-20	Degraded caulking around windows
W.H. Morden P.S.	HB200		2020-03-20	Erin Kulikowski	Jun-20	Holes in cladding by the door and the south west corner. Cladding is coming off of wall under window; underneath cladding is exposed. Degraded caulking around HVAC louvre.
W.H. Morden P.S.	HBL250		2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
W.H. Morden P.S.	HBL249		2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
W.H. Morden P.S.	HB138		2020-03-20	Erin Kulikowski	Jun-20	Pest droppings in ceiling insulation
W.H. Morden P.S.	HB055		2020-03-20	Erin Kulikowski	Jun-20	NSMOMO
W.H. Morden P.S.	HBL201		2020-04-17	Evan Faubert	Jun-20	Key doesn't open portable. No deficiencies on exterior.
West Oak P.S.	RM 1	6	2020-04-20	Evan Faubert	Jun-20	NSMOMO
West Oak P.S.	RM 2		2020-04-20	Evan Faubert	Jun-20	NSMOMO
West Oak P.S.	RM 3		2020-04-20	Evan Faubert	Jun-20	NSMOMO
West Oak P.S.	RM 4		2020-04-21	Evan Faubert	Jun-20	NSMOMO
West Oak P.S.	RM 5		2020-04-20	Evan Faubert	Jun-20	NSMOMO
West Oak P.S.	RM 6		2020-04-20	Evan Faubert	Jun-20	NSMOMO
White Oaks North H.S.	HB060	5	2020-03-20	Evan Faubert	Jun-20	Hole in W skirting.
White Oaks North H.S.	HBL095		2020-03-20	Evan Faubert	Jun-20	Degraded caulking at top of north door.
White Oaks North H.S.	HBL094		2020-03-20	Evan Faubert	Jun-20	NSMOMO
White Oaks North H.S.	HBL093		2020-03-20	Evan Faubert	Jun-20	Hole in SW skirting
White Oaks North H.S.	HBL092		2020-03-20	Evan Faubert	Jun-20	NSMOMO
White Oaks South H.S.	HBL018	13	2020-03-20	Evan Faubert	Jun-20	NSMOMO
White Oaks South H.S.	HBL017		2020-03-20	Evan Faubert	Jun-20	NSMOMO
White Oaks South H.S.	HBL016		2020-03-20	Evan Faubert	Jun-20	NSMOMO
White Oaks South H.S.	HB054		2020-03-20	Evan Faubert	Jun-20	Screw holes in SE, SW, NW cladding and flashing.
White Oaks South H.S.	HBL096		2020-03-20	Evan Faubert	Jun-20	NSMOMO
White Oaks South H.S.	HBL097		2020-03-20	Evan Faubert	Jun-20	Missing caulking on top of door
White Oaks South H.S.	HB042		2020-03-20	Evan Faubert	Jun-20	Missing caulking at both windows.Missing strapping at S seam
White Oaks South H.S.	HB023		2020-03-20	Evan Faubert	Jun-20	Missing view grate for portable alley
White Oaks South H.S.	HB205		2020-03-20	Evan Faubert	Jun-20	NSMOMO
White Oaks South H.S.	HB078		2020-03-20	Evan Faubert	Jun-20	NSMOMO

Portable Classroom Preventative Inspection 110

School	Portable Number	Portables on Site	Round 110 Inspection Date	Pinchin Inspector	Proposed Round 111 Inspection Date	Comments from Round 110 Inspection
White Oaks South H.S.	HB201		2020-03-20	Evan Faubert	Jun-20	Screw holes in cladding at SW corner near door.
White Oaks South H.S.	HB112		2020-03-20	Evan Faubert	Jun-20	Level 1 . Water stained ceiling tile at north seam. Damaged vapour barrier . Degraded caulking around HVAC.Down spout detached from NW corner
White Oaks South H.S.	HB153		2020-03-20	Evan Faubert	Jun-20	NSMOMO
WI Dick P.S.	HB007	3	2020-03-12	Serena Romito	Jun-20	NSMOMO
WI Dick P.S.	HB002		2020-03-12	Serena Romito	Jun-20	Degraded Caulking around window near door and between centre beams
WI Dick P.S.	HB183		2020-03-12	Serena Romito	Jun-20	Missing downspout front elevation. Missing Caulking around condensate drain pipe below HVAC louvre. Missing door sweep.