

Portable Classroom Preventative Inspection Round 111

School	Portable Number	Portables on Site	Round 111 Inspection Date	Pinchin Inspector	Proposed Round 112 Inspection Date	Comments from Round 111 Inspection
Abbey Park HS	HBO43	12	2020-06-19	Evan Faubert	Sep-20	Screwholes in NE SE and SW corner flashing
Abbey Park HS	HBL227		2020-06-19	Evan Faubert	Sep-20	Gap in NE corner skirting. Screwholes in exterior cladding left of door.
Abbey Park HS	HBL213		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Abbey Park HS	HB206		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Abbey Park HS	HBL224		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Abbey Park HS	HB164		2020-06-19	Evan Faubert	Sep-20	Bird nest in broken louvre
Abbey Park HS	HB163		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Abbey Park HS	HB108		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Abbey Park HS	HB131		2020-06-19	Evan Faubert	Sep-20	Screw holes in exterior cladding below W window.
Abbey Park HS	HB177		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Abbey Park HS	HB072		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Abbey Park HS	HB053		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Alton Village PS	HBL239	11	2020-06-11	Evan Faubert	Sep-20	NSMOMO
Alton Village PS	HBL238		2020-06-11	Evan Faubert	Sep-20	Caulking separating at windows.
Alton Village PS	HBL237		2020-06-11	Evan Faubert	Sep-20	Caulking separating at windows.
Alton Village PS	HBL247		2020-06-11	Evan Faubert	Sep-20	NSMOMO
Alton Village PS	HB140		2020-06-11	Evan Faubert	Sep-20	NSMOMO
Alton Village PS	HB037		2020-06-11	Evan Faubert	Sep-20	NSMOMO
Alton Village PS	HB068		2020-06-11	Evan Faubert	Sep-20	Level 1. Water stained ceiling tile and vapour barrier at NE corner.
Alton Village PS	HBL225		2020-06-11	Evan Faubert	Sep-20	Level 1. Water stained ceiling tile and vapour barrier at north side of portable.
Alton Village PS	HBL236		2020-06-11	Evan Faubert	Sep-20	NSMOMO
Alton Village PS	HBL235		2020-06-11	Evan Faubert	Sep-20	NSMOMO
Alton Village PS	HBL234		2020-06-11	Evan Faubert	Sep-20	NSMOMO
Anne J MacArthur P.S.	HBL202	9	2020-07-08	Erin Kulikowski	Sep-20	Caulking starting to crack and separate at HVAC louvre and conduits.
Anne J MacArthur P.S.	HBL203		2020-07-08	Erin Kulikowski	Sep-20	Door is rusty and rotting at the bottom
Anne J MacArthur P.S.	HBL204		2020-07-08	Erin Kulikowski	Sep-20	Caulking starting to crack around windows
Anne J MacArthur P.S.	HBL215		2020-07-08	Erin Kulikowski	Sep-20	Caulking around windows starting to crack. Holes in cladding on NW corner
Anne J MacArthur P.S.	HBL205		2020-07-08	Erin Kulikowski	Sep-20	NSMOMO
Anne J MacArthur P.S.	HB232		2020-07-08	Erin Kulikowski	Sep-20	NSMOMO
Anne J MacArthur P.S.	HBL233		2020-07-08	Erin Kulikowski	Sep-20	NSMOMO
Anne J MacArthur P.S.	HB174		2020-07-08	Erin Kulikowski	Sep-20	Caulking starting to crack around HVAC louvre. Hole in cladding on SW side between louvres. Damaged downspout. Holes in cladding by clamps near conduits. Caulking separating around AC unit
Anne J MacArthur P.S.	HBL214		2020-07-08	Erin Kulikowski	Sep-20	Caulking around conduits starting to separate. Holes in cladding on SW corner
Boyne	HBL251	12	2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HBL253		2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HB152		2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HB015		2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HBL254		2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HBL252		2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HB179		2020-06-30	Serena Romito	Sep-20	Missing number plate on portable
Boyne	HBL257		2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HBL110		2020-06-30	Serena Romito	Sep-20	NSMOMO
Boyne	HBL241		2020-06-30	Serena Romito	Sep-20	Level 1. Water stained ceiling tile due to roof leak
Boyne	HB028		2020-06-30	Serena Romito	Sep-20	Hole in drywall to right of door
Boyne	HBL226		2020-06-30	Serena Romito	Sep-20	Musty odour coming from hvac unit
Bruce T Lindley	HB166	1	2020-06-11	Evan Faubert	Sep-20	Screw holes in exterior cladding on all four corners
Bruce Trail P.S.	HBL206	16	2020-07-07	Erin Kulikowski	Sep-20	Degraded caulking at bottom of door
Bruce Trail P.S.	HBL262		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HBL107		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HB181		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HB075		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HB110		2020-07-07	Erin Kulikowski	Sep-20	Caulking starting to crack around SE window
Bruce Trail P.S.	HB046		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HB114		2020-07-07	Erin Kulikowski	Sep-20	Caulking starting to crack around bottom of door frame. Hole in sheathing to left of door.
Bruce Trail P.S.	HB062		2020-07-07	Erin Kulikowski	Sep-20	Degraded caulking around windows
Bruce Trail P.S.	HBL105		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HB115		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HBL231		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HBL230		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HBL228		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Bruce Trail P.S.	HBL229		2020-07-07	Erin Kulikowski	Sep-20	Degraded caulking around windows and HVAC louvre
Bruce Trail P.S.	HB103		2020-07-07	Erin Kulikowski	Sep-20	NSMOMO
Captain R Wilson PS	HB014	6	2020-06-18	Evan Faubert	Sep-20	Pest droppings on floor SW corner
Captain R Wilson PS	HBL217		2020-06-18	Evan Faubert	Sep-20	Missing caulking around exterior louvre. Directional spout missing
Captain R Wilson PS	HB065		2020-06-18	Evan Faubert	Sep-20	Vandalism to east exterior cladding and seam flashing. Daylight visible from interior.
Captain R Wilson PS	HB106		2020-06-18	Evan Faubert	Sep-20	Degraded caulking at east centre interior seam. Lifting floor tiles.
Captain R Wilson PS	HB047		2020-06-18	Evan Faubert	Sep-20	NSMOMO
Captain R Wilson PS	HB084		2020-06-18	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM02	10	2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM01		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM03		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM04		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM05		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM06		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM07		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM08		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM09		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Chris Hadfield P.S.	RM10		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Craig Keilburger	HB125	9	2020-06-23	Serena Romito	Sep-20	NSMOMO
Craig Keilburger	HB073		2020-06-23	Serena Romito	Sep-20	Level 1. Two water stained ceiling tiles due to roof leak. Wet drywall near front door
Craig Keilburger	HB143		2020-06-23	Serena Romito	Sep-20	NSMOMO
Craig Keilburger	HB133		2020-06-23	Serena Romito	Sep-20	Level 1. Wet drywall near hvac unit, possibly due to leak from condensate line
Craig Keilburger	HB203		2020-06-23	Serena Romito	Sep-20	AC unit on rear elevation improperly seated/ daylight visible
Craig Keilburger	HB134		2020-06-23	Serena Romito	Sep-20	NSMOMO
Craig Keilburger	HB057		2020-06-23	Serena Romito	Sep-20	Damaged eaves trough and downspout rear elevation. Hole in sheathing rear elevation
Craig Keilburger	HB113		2020-06-23	Serena Romito	Sep-20	NSMOMO
Craig Keilburger	HBL084		2020-06-26	Serena Romito	Sep-20	NSMOMO

Portable Classroom Preventative Inspection Round 111

School	Portable Number	Portables on Site	Round 111 Inspection Date	Pinchin Inspector	Proposed Round 112 Inspection Date	Comments from Round 111 Inspection
Dr. Frank Hayden	HB151	9	2020-06-18	Evan Faubert	Sep-20	Missing caulking at conduit at SE corner Damaged grilles in south Louvres. Compromised vapour barrier at south Louvre opening. Wasp nest at SE louvre
Dr. Frank Hayden	HB207		2020-06-18	Evan Faubert	Sep-20	Exterior screen broken on south window
Dr. Frank Hayden	HB137		2020-06-18	Evan Faubert	Sep-20	Missing caulking around exterior louvre
Dr. Frank Hayden	HB092		2020-06-18	Evan Faubert	Sep-20	NSMOMO
Dr. Frank Hayden	HB172		2020-06-18	Evan Faubert	Sep-20	NSMOMO
Dr. Frank Hayden	HB120		2020-06-18	Evan Faubert	Sep-20	NSMOMO
Dr. Frank Hayden	HB059		2020-06-18	Evan Faubert	Sep-20	Level 1: On ceiling tiles, pest urine. Caulking delaminating on both exterior windows
Dr. Frank Hayden	HBL256		2020-06-18	Evan Faubert	Sep-20	NSMOMO
Dr. Frank Hayden	HB010		2020-06-18	Evan Faubert	Sep-20	NSMOMO
E.W. Foster P.S.	HB189	1	2020-07-07	Erin Kulikowski	Sep-20	Cracking caulking around conduits
EJ James	HB121	3	2020-06-04	Evan Faubert	Sep-20	NSMOMO
EJ James	HB061		2020-06-04	Evan Faubert	Sep-20	NSMOMO
EJ James	HB111		2020-06-04	Evan Faubert	Sep-20	Caulking degraded at HVAC exterior.
Emily Carr PS	HB084	4	2020-06-18	Evan Faubert	Sep-20	NSMOMO
Emily Carr PS	HBL008		2020-06-18	Evan Faubert	Sep-20	NSMOMO
Emily Carr PS	HB008		2020-06-18	Evan Faubert	Sep-20	Separated caulking at NE conduit. Door sill plate is detached and separating.
Emily Carr PS	HB040		2020-06-18	Evan Faubert	Sep-20	Gap in north gable roof soffit.
Escarment View	HB089	12	2020-06-01	Serena Romito	Sep-20	Degraded Caulking around door and window near door and HVAC louvre and centre beam. Damaged siding / degraded Caulking around north window
Escarment View	HB005		2020-06-01	Serena Romito	Sep-20	NSMOMO
Escarment View	HB144		2020-06-01	Serena Romito	Sep-20	Degraded Caulking around HVAC louvre
Escarment View	HBL083		2020-06-01	Serena Romito	Sep-20	NSMOMO
Escarment View	HBL089		2020-06-01	Serena Romito	Sep-20	NSMOMO
Escarment View	HBL088		2020-06-01	Serena Romito	Sep-20	NSMOMO
Escarment View	HB056		2020-06-01	Serena Romito	Sep-20	Screw holes near door and North side. Degraded Caulking around windows and damaged framing on middle window. Damaged sheathing near door. Degraded Caulking around door. Two missing / damaged ceiling tiles with cut vapour barrier.
Escarment View	HBL090		2020-06-02	Serena Romito	Sep-20	NSMOMO
Escarment View	HBL103		2020-06-02	Serena Romito	Sep-20	NSMOMO
Escarment View	HBL104		2020-06-02	Serena Romito	Sep-20	NSMOMO
Escarment View	HBL081		2020-06-02	Serena Romito	Sep-20	NSMOMO
Escarment View	HBL082		2020-06-02	Serena Romito	Sep-20	NSMOMO
Ethel Gardiner	HB049	5	2020-06-22	Serena Romito	Sep-20	Degraded Caulking around door
Ethel Gardiner	HBL101		2020-06-22	Serena Romito	Sep-20	NSMOMO
Ethel Gardiner	HBL263		2020-06-22	Serena Romito	Sep-20	NSMOMO
Ethel Gardiner	HBL207		2020-06-22	Serena Romito	Sep-20	NSMOMO
Ethel Gardiner	HBL212		2020-06-22	Serena Romito	Sep-20	NSMOMO
Falgarwood P.S.	HB147	1	2020-07-06	Erin Kulikowski	Sep-20	Degraded caulking around both windows and conduits.
Florence Meares PS	HB069	3	2020-06-15	Evan Faubert	Sep-20	Unfilled conduit holes in exterior cladding at SE corner. Holes in exterior cladding at entrance
Florence Meares PS	HBL100		2020-06-15	Evan Faubert	Sep-20	NSMOMO
Florence Meares PS	HB139		2020-06-15	Evan Faubert	Sep-20	NSMOMO
Garth Webb SS	HB090	8	2020-06-19	Evan Faubert	Sep-20	NSMOMO
Garth Webb SS	HB076		2020-06-19	Evan Faubert	Sep-20	Conduit hole in cladding at SW corner. Screw holes in cladding at SE corner. Missing inspection port cover NE corner.
Garth Webb SS	HB052		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Garth Webb SS	HB045		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Garth Webb SS	HB038		2020-06-19	Evan Faubert	Sep-20	Degraded caulking at both windows and door. Missing caulking at SE conduit.
Garth Webb SS	HB100		2020-06-19	Evan Faubert	Sep-20	Screw holes in SE corner flashing.
Garth Webb SS	HB135		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Garth Webb SS	HB091		2020-06-19	Evan Faubert	Sep-20	Degraded caulking at NW window. Missing caulking at louvers. Degraded caulking at ceiling center seam.
Gladys Spears PS	HB158	1	2020-05-29	Evan Faubert	Sep-20	NSMOMO
Glen Williams	HB184	2	2020-06-22	Serena Romito	Sep-20	Degraded Caulking around patch on rear elevation
Glen Williams	HB178		2020-06-22	Serena Romito	Sep-20	NSMOMO
Glenview PS	HB148	2	2020-05-28	Evan Faubert	Sep-20	NSMOMO
Glenview PS	HB122		2020-05-28	Evan Faubert	Sep-20	Missing caulking at conduits and hole in NW cladding.
Hawthorne Village P.S.	HB136	17	2020-07-08	Erin Kulikowski	Sep-20	1. 7 water stained ceiling tiles . Level 1 mould remediation. 7 water stained ceiling tiles due to condensation from HVAC line. Water staining on floor beneath HVAC unit. Floor tiles lifting around HVAC unit as well.
Hawthorne Village P.S.	HB013		2020-07-08	Erin Kulikowski	Sep-20	NSMOMO
Hawthorne Village P.S.	HB162		2020-07-08	Erin Kulikowski	Sep-20	To the left of the Door frame rotten. Holes in cladding by downspout in front of portable. Caulking around conduits are separating
Hawthorne Village P.S.	HB036		2020-07-14	Evan Faubert	Sep-20	Screw holes at N corner
Hawthorne Village P.S.	HB034		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Hawthorne Village P.S.	HB035		2020-07-14	Evan Faubert	Sep-20	Screw holes at N corner
Hawthorne Village P.S.	RM305		2020-07-14	Evan Faubert	Sep-20	Degraded caulking at corner wall seam.
Hawthorne Village P.S.	RM310		2020-07-14	Evan Faubert	Sep-20	Degraded caulking at wall seam
Hawthorne Village P.S.	RM309		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Hawthorne Village P.S.	RM308		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Hawthorne Village P.S.	RM307		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Hawthorne Village P.S.	RM306		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Hawthorne Village P.S.	RM305		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Hawthorne Village P.S.	RM304		2020-07-14	Evan Faubert	Sep-20	NSMOMO
Hawthorne Village P.S.	RM303		2020-07-14	Evan Faubert	Sep-20	Degraded caulking at wall joints
Hawthorne Village P.S.	RM302		2020-07-14	Evan Faubert	Sep-20	Degraded caulking at wall joints
Hawthorne Village P.S.	RM301		2020-07-14	Evan Faubert	Sep-20	Degraded caulking at wall joints
Irma Coulson	HBL246	15	2020-07-07	Serena Romito	Sep-20	Degraded Caulking around door
Irma Coulson	HBL245		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HBL244		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HB142		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HBL242		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HBL243		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HB195		2020-07-07	Serena Romito	Sep-20	Missing downspout rear elevation
Irma Coulson	HB149		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HB196		2020-07-07	Serena Romito	Sep-20	10 broken floor tiles
Irma Coulson	HB150		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HB204		2020-07-07	Serena Romito	Sep-20	Level 1. Wet drywall due to unknown water infiltration
Irma Coulson	HB081		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HB009		2020-07-07	Serena Romito	Sep-20	NSMOMO
Irma Coulson	HB146		2020-07-07	Serena Romito	Sep-20	NSMOMO

Portable Classroom Preventative Inspection Round 111

School	Portable Number	Portables on Site	Round 111 Inspection Date	Pinchin Inspector	Proposed Round 112 Inspection Date	Comments from Round 111 Inspection
Irma Coulson	HBL111		2020-07-07	Serena Romito	Sep-20	NSMOMO
Iroquois Ridge HS	HB209	6	2020-07-16	Evan Faubert	Sep-20	NSMOMO
Iroquois Ridge HS	HB070		2020-07-16	Evan Faubert	Sep-20	Level 1 . Water stained ceiling tile at NE corner. Denatured caulking on top of exterior HVAC louvre.
Iroquois Ridge HS	HB202		2020-07-16	Evan Faubert	Sep-20	Level 1 . Water stained ceiling tile near NW roof seam.
Iroquois Ridge HS	HBL264		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Iroquois Ridge HS	HB088		2020-07-16	Evan Faubert	Sep-20	Level 2 Mould Remediation. Mold growth on vapor barrier and ceiling insulation at NE ceiling
Iroquois Ridge HS	HB145		2020-07-16	Evan Faubert	Sep-20	NSMOMO
J W Singleton	HB119	4	2020-06-11	Evan Faubert	Sep-20	Separating caulking at door frame. Missing caulking at north conduit.
J W Singleton	HB118		2020-06-11	Evan Faubert	Sep-20	NSMOMO
J W Singleton	HB117		2020-06-11	Evan Faubert	Sep-20	Level 1 . Water stained ceiling tile at entrance.
J W Singleton	HB003		2020-06-11	Evan Faubert	Sep-20	NSMOMO
James W Hill	HB050	6	2020-06-04	Evan Faubert	Sep-20	Missingcaulking at E corner conduit.
James W Hill	HB086		2020-06-04	Evan Faubert	Sep-20	Screw holes in cladding near door.
James W Hill	HB107		2020-06-04	Evan Faubert	Sep-20	Many screw holes on NW cladding wall and at E corner
James W Hill	HB176		2020-06-04	Evan Faubert	Sep-20	NSMOMO
James W Hill	HB099		2020-06-04	Evan Faubert	Sep-20	NSMOMO
James W Hill	HB080		2020-06-04	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HB169	10	2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HB165		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HBL216		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HBL221		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HB064		2020-05-28	Evan Faubert	Sep-20	Rotted Wooden door frame
John T Tuck PS	HB156		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HBL219		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HBL220		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HB157		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John T Tuck PS	HB173		2020-05-28	Evan Faubert	Sep-20	NSMOMO
John W Boich	HBL109	1	2020-06-18	Evan Faubert	Sep-20	NSMOMO
Joshua Creek P.S.	HB161	5	2020-07-06	Erin Kulikowski	Sep-20	Damaged eavestrough at back of portable
Joshua Creek P.S.	HB155		2020-07-06	Erin Kulikowski	Sep-20	Degraded caulking around NW window and HVAC louvre
Joshua Creek P.S.	HB077		2020-07-06	Erin Kulikowski	Sep-20	NSMOMO
Joshua Creek P.S.	HB011		2020-07-06	Erin Kulikowski	Sep-20	NSMOMO
Joshua Creek P.S.	HB085		2020-07-06	Erin Kulikowski	Sep-20	NSMOMO
Killbride P.S.	HB074	1	2020-07-14	Evan Faubert	Sep-20	NSMOMO
Maplegrove	HB159	2	2020-06-04	Evan Faubert	Sep-20	Missing roof / wall gable cap at NE side.
Maplegrove	HB130		2020-06-04	Evan Faubert	Sep-20	NSMOMO
Milton District HS	HB001	5	2020-06-01	Serena Romito	Sep-20	NSMOMO
Milton District HS	HBL223		2020-06-01	Serena Romito	Sep-20	Degraded Caulking around door and middle window
Milton District HS	HB041		2020-06-01	Serena Romito	Sep-20	Degraded Caulking around conduits
Milton District HS	HB093		2020-06-01	Serena Romito	Sep-20	NSMOMO
Milton District HS	HB154		2020-06-01	Serena Romito	Sep-20	NSMOMO
Montclair P.S.	HBL210	1	2020-07-06	Erin Kulikowski	Sep-20	Caulking starting to crack around HVAC louvre .
Munn's P.S.	HBL001	2	2020-07-06	Erin Kulikowski	Sep-20	NSMOMO
Munn's P.S.	HBL002		2020-07-06	Erin Kulikowski	Sep-20	NSMOMO
New Central	HB079	2	2020-06-04	Evan Faubert	Sep-20	Screw holes on cladding at NE and SE corners
New Central	HB104		2020-06-04	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM189B	11	2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM190		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM191		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM192		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM193		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM189A		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM194		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM195		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM196		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM197		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oakville Trafalgar HS	RM198		2020-07-16	Evan Faubert	Sep-20	NSMOMO
Oodenawi P.S.	HB096	16	2020-07-10	Erin Kulikowski	Sep-20	Screw holes in door
Oodenawi P.S.	HB094		2020-07-10	Erin Kulikowski	Sep-20	NSMOMO
Oodenawi P.S.	HB128		2020-07-10	Erin Kulikowski	Sep-20	NSMOMO
Oodenawi P.S.	HB044		2020-07-10	Erin Kulikowski	Sep-20	NSMOMO
Oodenawi P.S.	HB067		2020-07-10	Erin Kulikowski	Sep-20	NSMOMO
Oodenawi P.S.	HBL086		2020-07-10	Erin Kulikowski	Sep-20	Caulking starting to crack around windows.
Oodenawi P.S.	HBL248		2020-07-10	Erin Kulikowski	Sep-20	Caulking around windows starting to crack
Oodenawi P.S.	HB171		2020-07-10	Erin Kulikowski	Sep-20	Bottom of door frame is rotted and rusty
Oodenawi P.S.	HB175		2020-07-10	Erin Kulikowski	Sep-20	NSMOMO
Oodenawi P.S.	HB058		2020-07-10	Erin Kulikowski	Sep-20	1 . Wet floor tiles around door . Level 1 mould remediation. 14 water impacted floor tiles by door due to rotten door frame. First 2 rows of tiles from SE corner to NW and 7 tiles in from SE corner to N.
Oodenawi P.S.	HB101		2020-07-10	Erin Kulikowski	Sep-20	NSMOMO
Oodenawi P.S.	HBL260		2020-07-10	Erin Kulikowski	Sep-20	NSMOMO
Oodenawi P.S.	HBL085		2020-07-10	Erin Kulikowski	Sep-20	Prepped for moving
Oodenawi P.S.	HBL080		2020-07-17	Erin Kulikowski	Sep-20	Prepped for moving
Oodenawi P.S.	HBL005		2020-07-10	Erin Kulikowski	Sep-20	Prepped for moving
Oodenawi P.S.	HBL258		2020-07-10	Erin Kulikowski	Sep-20	Prepped for moving
Palermo	HB168	3	2020-06-19	Evan Faubert	Sep-20	NSMOMO
Palermo	HB167		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Palermo	HB087		2020-06-19	Evan Faubert	Sep-20	NSMOMO
Pauline Johnson PS	HB102	3	2020-05-28	Evan Faubert	Sep-20	Caulking separating at gable Louvre and windows. Holes in cladding near both sides of door.
Pauline Johnson PS	HBL222		2020-05-28	Evan Faubert	Sep-20	Degraded caulking around windows.
Pauline Johnson PS	HB024		2020-05-28	Evan Faubert	Sep-20	Degraded caulking around gable louvre and conduits Holes in cladding on NW wall.
Pilgrim Woods	HBL267	5	2020-07-03	Evan Faubert	Sep-20	Missing id plate
Pilgrim Woods	HBL007		2020-07-03	Evan Faubert	Sep-20	NSMOMO/ prepped for transfer
Pilgrim Woods	HB123		2020-07-03	Evan Faubert	Sep-20	Prepped for transfer.
Pilgrim Woods	HB006		2020-07-03	Evan Faubert	Sep-20	Missing seam external cladding on both sides.
Pilgrim Woods	HBL087		2020-07-03	Evan Faubert	Sep-20	Missing id plate
PL Robertson	HBL091	12	2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HBL259		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HBL265		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HBL266		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HB051		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HB039		2020-06-02	Serena Romito	Sep-20	NSMOMO

Portable Classroom Preventative Inspection Round 111

School	Portable Number	Portables on Site	Round 111 Inspection Date	Pinchin Inspector	Proposed Round 112 Inspection Date	Comments from Round 111 Inspection
PL Robertson	HB022		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HB016		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HB030		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HB021		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HB027		2020-06-02	Serena Romito	Sep-20	NSMOMO
PL Robertson	HB004		2020-06-02	Serena Romito	Sep-20	NSMOMO
Posts Corners P.S.	HBL102	9	2020-07-09	Erin Kulikowski	Sep-20	Caulking separating at bottom of door
Posts Corners P.S.	HB180		2020-07-09	Erin Kulikowski	Sep-20	NSMOMO
Posts Corners P.S.	HB129		2020-07-09	Erin Kulikowski	Sep-20	Damaged downspout and loose connection
Posts Corners P.S.	HBL006		2020-07-09	Erin Kulikowski	Sep-20	NSMOMO
Posts Corners P.S.	P5		2020-07-09	Erin Kulikowski	Sep-20	1 . 3 water stained ceiling tiles . Level 1 mould remediation. 3 water stained ceiling tiles due to condensation on HVAC vents and a hole in the exterior east wall. Window caulking is starting to crack as well.
Posts Corners P.S.	HBL255		2020-07-09	Erin Kulikowski	Sep-20	NSMOMO
Posts Corners P.S.	HBL211		2020-07-09	Erin Kulikowski	Sep-20	Damaged eavestrough at SE corner. Screw holes in door.
Posts Corners P.S.	P7		2020-07-09	Erin Kulikowski	Sep-20	1 . 2 water stained ceiling tiles . Level 1 mould remediation. 2 water stained ceiling tiles due to condensation on HVAC ducts.
Posts Corners P.S.	P6		2020-07-09	Erin Kulikowski	Sep-20	NSMOMO
River Oaks P.S.	HBL015	5	2020-07-09	Erin Kulikowski	Sep-20	No caulking around conduits and screw holes in cladding by conduits
River Oaks P.S.	HBL014		2020-07-09	Erin Kulikowski	Sep-20	Caulking around windows starting to crack. Damaged downspout. Screw holes in cladding on N side
River Oaks P.S.	HBL106		2020-07-09	Erin Kulikowski	Sep-20	Portable Under construction. No caulking around conduits
River Oaks P.S.	HB208		2020-07-09	Erin Kulikowski	Sep-20	1 . 2 water stained ceiling tiles . Level 1 mould remediation. 2 water stained ceiling tiles due to roof leak. Portable under construction. Cladding on E and W side not secured properly.
River Oaks P.S.	HB033		2020-07-09	Erin Kulikowski	Sep-20	Portable under construction. Holes in cladding where hand rail used to be. Cladding not secured properly on E and W side of portable
Sam Sherratt	HB082	5	2020-06-02	Serena Romito	Sep-20	NSMOMO
Sam Sherratt	HB083		2020-06-02	Serena Romito	Sep-20	NSMOMO
Sam Sherratt	HBL099		2020-06-02	Serena Romito	Sep-20	NSMOMO
Sam Sherratt	HB066		2020-06-02	Serena Romito	Sep-20	NSMOMO
Sam Sherratt	HB127		2020-06-02	Serena Romito	Sep-20	NSMOMO
Sheridan P.S.	HB132	1	2020-07-09	Erin Kulikowski	Sep-20	Caulking starting to crack around door
Tiger Jeet Singh	HBL108	11	2020-06-18	Serena Romito	Sep-20	NSMOMO
Tiger Jeet Singh	HBL013		2020-06-18	Serena Romito	Sep-20	NSMOMO
Tiger Jeet Singh	HBL098		2020-06-18	Serena Romito	Sep-20	NSMOMO
Tiger Jeet Singh	HB116		2020-06-22	Serena Romito	Sep-20	NSMOMO
Tiger Jeet Singh	HB187		2020-06-22	Serena Romito	Sep-20	Level 2 . Moisture and mould growth on drywall beneath S window due to degraded Caulking and damaged window frame . Degraded Caulking around windows
Tiger Jeet Singh	HB095		2020-06-22	Serena Romito	Sep-20	Degraded Caulking around door and windows
Tiger Jeet Singh	HB126		2020-06-22	Serena Romito	Sep-20	NSMOMO
Tiger Jeet Singh	HB063		2020-06-22	Serena Romito	Sep-20	Level 1 . Wet drywall beneath N window due to window leak. . Degraded Caulking around windows
Tiger Jeet Singh	HB109		2020-06-22	Serena Romito	Sep-20	NSMOMO
Tiger Jeet Singh	HB029		2020-06-22	Serena Romito	Sep-20	NSMOMO
Tiger Jeet Singh	HBL079		2020-06-22	Serena Romito	Sep-20	NSMOMO
Tom Tompson PS	HB031	6	2020-05-28	Evan Faubert	Sep-20	Degraded caulking at door. Hole in soffit SE corner.
Tom Tompson PS	HB098		2020-05-28	Evan Faubert	Sep-20	Degraded caulking around HVAC Louvre, windows and doors and conduits.
Tom Tompson PS	HB105		2020-05-28	Evan Faubert	Sep-20	Degraded caulking around door.
Tom Tompson PS	HB124		2020-05-28	Evan Faubert	Sep-20	NSMOMO
Tom Tompson PS	HB141		2020-05-28	Evan Faubert	Sep-20	Damaged skirting at NE corner
Tom Tompson PS	HB012		2020-05-28	Evan Faubert	Sep-20	Damaged downspout.
Viola Desmond	HBL278	18	2020-06-18	Serena Romito	Sep-20	Cut in vapour barrier S side
Viola Desmond	HBL270		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL271		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL272		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL273		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL274		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL275		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL276		2020-06-18	Serena Romito	Sep-20	Level 1 . Water stained ceiling tile due to condensation
Viola Desmond	HBL277		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL279		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL280		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL281		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL282		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL283		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL284		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL285		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL286		2020-06-18	Serena Romito	Sep-20	NSMOMO
Viola Desmond	HBL287		2020-06-18	Serena Romito	Sep-20	NSMOMO
West Oak PS	RM01	6	2020-07-16	Evan Faubert	Sep-20	NSMOMO
West Oak PS	RM02		2020-07-16	Evan Faubert	Sep-20	NSMOMO
West Oak PS	RM03		2020-07-16	Evan Faubert	Sep-20	NSMOMO
West Oak PS	RM04		2020-07-16	Evan Faubert	Sep-20	NSMOMO
West Oak PS	RM05		2020-07-16	Evan Faubert	Sep-20	NSMOMO
West Oak PS	RM06		2020-07-17	Evan Faubert	Sep-20	NSMOMO
WH Morden	HB055	7	2020-06-04	Evan Faubert	Sep-20	NSMOMO
WH Morden	HBL249		2020-06-04	Evan Faubert	Sep-20	NSMOMO
WH Morden	HBL250		2020-06-04	Evan Faubert	Sep-20	NSMOMO
WH Morden	HBL201		2020-06-04	Evan Faubert	Sep-20	NSMOMO
WH Morden	HB199		2020-06-04	Evan Faubert	Sep-20	NSMOMO
WH Morden	HB200		2020-06-04	Evan Faubert	Sep-20	NSMOMO
WH Morden	HB138		2020-06-04	Evan Faubert	Sep-20	Missing roof/side gable cap at north end joint.
White Oaks North H.S.	HB060	5	2020-07-10	Evan Faubert	Sep-20	Damaged and disjointed eavestroughs on north side
White Oaks North H.S.	HBL092		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks North H.S.	HBL093		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks North H.S.	HBL094		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks North H.S.	HBL095		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HB078	15	2020-07-03	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HB205		2020-07-03	Evan Faubert	Sep-20	Degraded caulking around door
White Oaks South H.S.	HB023		2020-07-03	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HB112		2020-07-03	Evan Faubert	Sep-20	Missing caulking at door cladding seam Degraded caulking at door.
White Oaks South H.S.	HB201		2020-07-03	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HB153		2020-07-03	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HBL009		2020-07-03	Evan Faubert	Sep-20	Recently transferred. Missing seam cladding
White Oaks South H.S.	HBL261		2020-07-03	Evan Faubert	Sep-20	Recently transferred

Portable Classroom Preventative Inspection Round 111

School	Portable Number	Portables on Site	Round 111 Inspection Date	Pinchin Inspector	Proposed Round 112 Inspection Date	Comments from Round 111 Inspection
White Oaks South H.S.	HB042		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HBL097		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HBL016		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HBL017		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HBL018		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HBL096		2020-07-10	Evan Faubert	Sep-20	NSMOMO
White Oaks South H.S.	HB054		2020-07-10	Evan Faubert	Sep-20	NSMOMO
WI Dick P.S.	HB007	3	2020-07-14	Evan Faubert	Sep-20	NSMOMO
WI Dick P.S.	HB002		2020-07-14	Evan Faubert	Sep-20	NSMOMO
WI Dick P.S.	HB183		2020-07-14	Evan Faubert	Sep-20	NSMOMO