

Portable Classroom Preventative Inspection Round 112

School	Portable Number	Portables on Site	Round 112 Inspection Date	Pinchin Inspector	Proposed Round 113 Inspection Date	Comments from Round 112 Inspection
Abbey Park HS	HB108	12	2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HB053		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HB206		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HB164		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HB163		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HB177		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HBL227		2020-09-16	Evan Faubert	Dec-20	Screw holes in exterior cladding left of door
Abbey Park HS	HB043		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HB072		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HB131		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HBL213		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Abbey Park HS	HBL224		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Alton Village P.S.	HBL235	12	2020-09-08	Erin Kulikowski	Dec-20	Caulking separating around door frame.
Alton Village P.S.	HBL234		2020-09-08	Erin Kulikowski	Dec-20	Caulking around conduits are cracking
Alton Village P.S.	HBL239		2020-09-08	Erin Kulikowski	Dec-20	NSMOMO
Alton Village P.S.	HBL238		2020-09-08	Erin Kulikowski	Dec-20	NSMOMO
Alton Village P.S.	HBL237		2020-09-08	Erin Kulikowski	Dec-20	NSMOMO
Alton Village P.S.	HBL236		2020-09-08	Erin Kulikowski	Dec-20	Door frame starting to rot and deteriorate
Alton Village P.S.	HBL247		2020-09-08	Erin Kulikowski	Dec-20	Caulking on top of HVAC louvre is partly done
Alton Village P.S.	HB140		2020-09-08	Erin Kulikowski	Dec-20	Bottom of door frame missing; covered with tuck tape. Hole inside door frame where the lock sits; no cover
Alton Village P.S.	HB037		2020-09-08	Erin Kulikowski	Dec-20	Level 1 Remediation- wet floor tiles (see picture). Water staining on floor is present and floor in front of door is deteriorating.
Alton Village P.S.	HB068		2020-09-08	Erin Kulikowski	Dec-20	Level 1 remediation- 1 water stained ceiling tile in east corner due to pest droppings. Ceiling insulation is full of pest droppings.
Alton Village P.S.	HBL225		2020-09-08	Erin Kulikowski	Dec-20	Level 3 Wet drywall bottom right corner of door. Mould present beneath baseboard approx 12 square feet of mould.
Alton Village P.S.	HB169		2020-09-08	Erin Kulikowski	Dec-20	Screw holes in cladding at east and west corner as well as near the railing at the front door. Hole in the cladding in west corner. No caulking around conduits.
Anne J MacArthur P.S.	HBL215	15	2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL214		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL219		2020-09-09	Serena Romito	Dec-20	Missing skirting near conduits
Anne J MacArthur P.S.	HBL221		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HB111		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HB061		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HB165		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL202		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL203		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL204		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL205		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL232		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL233		2020-09-09	Serena Romito	Dec-20	NSMOMO
Anne J MacArthur P.S.	HBL216		2020-09-09	Serena Romito	Dec-20	Missing number plate
Anne J MacArthur P.S.	HB174		2020-09-09	Serena Romito	Dec-20	Level 1. Wet drywall around door due to damaged flashing beneath door
Boyne P.S.	HB033	15	2020-09-10	Erin Kulikowski	Dec-20	Screw holes in cladding SE And NE wall. Damaged cladding on NE wall.
Boyne P.S.	HB208		2020-09-10	Erin Kulikowski	Dec-20	NSMOMO
Boyne P.S.	HB106		2020-09-10	Erin Kulikowski	Dec-20	Screw holes in cladding south Corner
Boyne P.S.	HBL241		2020-09-10	Erin Kulikowski	Dec-20	Damaged cladding on SW side. Screw holes in cladding W corner.
Boyne P.S.	HB028		2020-09-10	Erin Kulikowski	Dec-20	Caulking starting to separate around door. Damage cladding along S Wall
Boyne P.S.	HBL226		2020-09-10	Erin Kulikowski	Dec-20	NSMOMO
Boyne P.S.	HB179		2020-09-10	Erin Kulikowski	Dec-20	Damaged cladding on SE side
Boyne P.S.	HBL257		2020-09-10	Erin Kulikowski	Dec-20	NSMOMO
Boyne P.S.	HBL110		2020-09-10	Erin Kulikowski	Dec-20	NSMOMO
Boyne P.S.	HBL252		2020-09-10	Erin Kulikowski	Dec-20	Caulking starting to crack around windows
Boyne P.S.	HBL254		2020-09-10	Erin Kulikowski	Dec-20	Caulking starting to crack around windows
Boyne P.S.	HB015		2020-09-10	Erin Kulikowski	Dec-20	NSMOMO
Boyne P.S.	HB152		2020-09-10	Erin Kulikowski	Dec-20	NSMOMO
Boyne P.S.	HBL253		2020-09-10	Erin Kulikowski	Dec-20	Caulking around windows starting to crack
Boyne P.S.	HBL251		2020-09-10	Erin Kulikowski	Dec-20	Caulking around windows starting to crack
Bruce Trail P.S.	HB115	16	2020-09-11	Erin Kulikowski	Dec-20	Degraded caulking around conduits
Bruce Trail P.S.	HBL105		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HB062		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HB114		2020-09-11	Erin Kulikowski	Dec-20	Caulking starting to crack around door
Bruce Trail P.S.	HB046		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HB110		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HB103		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HB075		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HB181		2020-09-11	Erin Kulikowski	Dec-20	Caulking starting to crack around conduits. Screw holes by front door
Bruce Trail P.S.	HBL107		2020-09-11	Erin Kulikowski	Dec-20	Damaged cladding on W side
Bruce Trail P.S.	HBL262		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HBL206		2020-09-11	Erin Kulikowski	Dec-20	Screw holes in S corner
Bruce Trail P.S.	HBL228		2020-09-11	Erin Kulikowski	Dec-20	Caulking around windows starting to crack. Screw holes on E wall
Bruce Trail P.S.	HBL229		2020-09-11	Erin Kulikowski	Dec-20	Caulking partly done around HVAC louvre
Bruce Trail P.S.	HBL231		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Bruce Trail P.S.	HBL230		2020-09-11	Erin Kulikowski	Dec-20	NSMOMO
Captain R Wilson PS	HB014	6	2020-09-18	Evan Faubert	Dec-20	Damaged/unsecure stairs.
Captain R Wilson PS	HBL217		2020-09-18	Evan Faubert	Dec-20	Missing caulking on top of east door.
Captain R Wilson PS	HB087		2020-09-18	Evan Faubert	Dec-20	Screw holes in west door and cladding beside it.
Captain R Wilson PS	HB065		2020-09-18	Evan Faubert	Dec-20	Damaged interior drywall and baseboard at east seam. Missing building envelope at seam. Visible daylight.
Captain R Wilson PS	HB106		2020-09-18	Evan Faubert	Dec-20	NSMOMO
Captain R Wilson PS	HB047		2020-09-18	Evan Faubert	Dec-20	NSMOMO
Chris Hadfield P.S.	HBL266	18	2020-09-24	Erin Kulikowski	Dec-20	Caulking around conduits is missing.
Chris Hadfield P.S.	HB034		2020-09-23	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	HB051		2020-09-23	Erin Kulikowski	Dec-20	Caulking starting to crack on top of HVAC. Hole in cladding on E wall; visible through ceiling space.
Chris Hadfield P.S.	HB168		2020-09-23	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	HB036		2020-09-23	Erin Kulikowski	Dec-20	Caulking around doors starting to crack.
Chris Hadfield P.S.	HB035		2020-09-23	Erin Kulikowski	Dec-20	West, South and East wall have holes in the cladding visible from the ceiling space.
Chris Hadfield P.S.	HBL259		2020-09-23	Erin Kulikowski	Dec-20	NSMOMO

Portable Classroom Preventative Inspection Round 112

School	Portable Number	Portables on Site	Round 112 Inspection Date	Pinchin Inspector	Proposed Round 113 Inspection Date	Comments from Round 112 Inspection
Chris Hadfield P.S.	HBL265		2020-09-23	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA10		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA09		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA08		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA07		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA06		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA05		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA04		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA03		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Chris Hadfield P.S.	RMA02		2020-09-30	Erin Kulikowski	Dec-20	Window caulking is cracking.
Chris Hadfield P.S.	RMA01		2020-09-30	Erin Kulikowski	Dec-20	NSMOMO
Craig Keilburger S.S.	HBL084	15	2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB125		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB113		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB057		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB134		2020-09-23	Serena Romito	Dec-20	Floor tiles throughout curling and lifting
Craig Keilburger S.S.	HB203		2020-09-23	Serena Romito	Dec-20	Approximately half of floor tiles curling and lifting
Craig Keilburger S.S.	HB133		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB143		2020-09-23	Serena Romito	Dec-20	Downspout on front elevation aimed at wall
Craig Keilburger S.S.	HB073		2020-09-23	Serena Romito	Dec-20	Level 1 . Wet drywall due to downspouts aimed at wall
Craig Keilburger S.S.	HB132		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB128		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB147		2020-09-23	Serena Romito	Dec-20	Missing downspout front elevation. About 10 damaged floor tiles
Craig Keilburger S.S.	HBL015		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HBL014		2020-09-23	Serena Romito	Dec-20	NSMOMO
Craig Keilburger S.S.	HB159		2020-09-23	Serena Romito	Dec-20	NSMOMO
Dr. Frank Hayden S.S.	HB059	9	2020-09-08	Erin Kulikowski	Dec-20	No door frame. No caulking on top of HVAC louver.
Dr. Frank Hayden S.S.	HB120		2020-09-08	Erin Kulikowski	Dec-20	Level 3 remediation- wet drywall under north window. Mould present under baseboards and in inspection port. Insulation is wet as well. Approximately 21 sq ft of mould present
Dr. Frank Hayden S.S.	HB172		2020-09-08	Erin Kulikowski	Dec-20	No flashing on top of windows. No caulking around HVAC louver.
Dr. Frank Hayden S.S.	HB092		2020-09-08	Erin Kulikowski	Dec-20	No caulking around HVAC louver
Dr. Frank Hayden S.S.	HB010		2020-09-08	Erin Kulikowski	Dec-20	NSMOMO
Dr. Frank Hayden S.S.	HBL256		2020-09-08	Erin Kulikowski	Dec-20	NSMOMO
Dr. Frank Hayden S.S.	HB207		2020-09-08	Erin Kulikowski	Dec-20	No flashing on top of windows. No caulking around HVAC Louvre.
Dr. Frank Hayden S.S.	HB137		2020-09-08	Erin Kulikowski	Dec-20	No caulking around HVAC louver
Dr. Frank Hayden S.S.	HB151		2020-09-08	Erin Kulikowski	Dec-20	NSMOMO
E.J. James P.S.	HB121	1	2020-09-22	Erin Kulikowski	Dec-20	Level 3 remediation- wet drywall to the right of HVAC at baseboard. Approx 12 sq ft of mould present on drywall paper
E.W. Foster P.S.	HB189	1	2020-09-21	Erin Kulikowski	Dec-20	NSMOMO
Emily Carr P.S.	HB084	4	2020-09-18	Evan Faubert	Dec-20	NSMOMO
Emily Carr P.S.	HB040		2020-09-18	Evan Faubert	Dec-20	Degraded caulking at door, windows and on top of HVAC. Missing wooden foundation block at SW corner.
Emily Carr P.S.	HB008		2020-09-18	Evan Faubert	Dec-20	Broken floor tiles at door.
Emily Carr P.S.	HBL008		2020-09-18	Evan Faubert	Dec-20	NSMOMO
Escarpment View P.S.	HBL090	12	2020-09-23	Serena Romito	Dec-20	NSMOMO
Escarpment View P.S.	HBL103		2020-09-23	Serena Romito	Dec-20	NSMOMO
Escarpment View P.S.	HBL104		2020-09-23	Serena Romito	Dec-20	About 20 damages tiles throughout
Escarpment View P.S.	HB144		2020-09-23	Serena Romito	Dec-20	About 20 damaged tiles
Escarpment View P.S.	HB005		2020-09-23	Serena Romito	Dec-20	NSMOMO
Escarpment View P.S.	HB089		2020-09-23	Serena Romito	Dec-20	Degraded Caulking around window near door. Degraded Caulking along centre beam
Escarpment View P.S.	HBL083		2020-09-23	Serena Romito	Dec-20	Damaged skirting
Escarpment View P.S.	HBL082		2020-09-23	Serena Romito	Dec-20	NSMOMO
Escarpment View P.S.	HBL081		2020-09-23	Serena Romito	Dec-20	NSMOMO
Escarpment View P.S.	HB056		2020-09-23	Serena Romito	Dec-20	NSMOMO
Escarpment View P.S.	HBL088		2020-09-23	Serena Romito	Dec-20	NSMOMO
Escarpment View P.S.	HBL089		2020-09-23	Serena Romito	Dec-20	NSMOMO
Ethel Gardiner P.S.	HBL263	5	2020-09-23	Erin Kulikowski	Dec-20	Caulking around windows starting to crack
Ethel Gardiner P.S.	HBL101		2020-09-23	Erin Kulikowski	Dec-20	NSMOMO
Ethel Gardiner P.S.	HBL207		2020-09-23	Erin Kulikowski	Dec-20	NSMOMO
Ethel Gardiner P.S.	HBL212		2020-09-23	Erin Kulikowski	Dec-20	Hole in cladding on East wall visible from ceiling space. Caulking starting to crack around windows.
Ethel Gardiner P.S.	HB049		2020-09-23	Erin Kulikowski	Dec-20	Screw holes in east corner cladding
Florence Mearns P.S.	HB069	3	2020-09-09	Erin Kulikowski	Dec-20	Holes in cladding on SE Wall
Florence Mearns P.S.	HB139		2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Florence Mearns P.S.	HBL100		2020-09-09	Erin Kulikowski	Dec-20	Air gaps in conduits from ceiling space on E side; needs to be caulked
Garth Webb SS	HBL258	12	2020-09-16	Evan Faubert	Dec-20	NSMOMO
Garth Webb SS	HBL080		2020-09-16	Evan Faubert	Dec-20	Door lock is dysfunctional
Garth Webb SS	HB038		2020-09-16	Evan Faubert	Dec-20	Denatured caulking around HVAC louver
Garth Webb SS	HB076		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Garth Webb SS	HB045		2020-09-16	Evan Faubert	Dec-20	Cracked caulking at north window
Garth Webb SS	HBL085		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Garth Webb SS	HBL005		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Garth Webb SS	HB100		2020-09-16	Evan Faubert	Dec-20	Holes in door and door frame
Garth Webb SS	HB090		2020-09-16	Evan Faubert	Dec-20	Damaged downspout at west corner
Garth Webb SS	HB052		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Garth Webb SS	HB135		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Garth Webb SS	HB091		2020-09-16	Evan Faubert	Dec-20	NSMOMO
Glen Williams P.S.	HB178	2	2020-09-23	Erin Kulikowski	Dec-20	NSMOMO
Glen Williams P.S.	HB184		2020-09-23	Erin Kulikowski	Dec-20	NSMOMO
Glenview P.S.	HB148	2	2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Glenview P.S.	HB122		2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Hawthorne Village P.S.	RM301	13	2020-09-29	Erin Kulikowski	Dec-20	Caulking cracking where wall meets ceiling
Hawthorne Village P.S.	HB136		2020-09-21	Erin Kulikowski	Dec-20	Caulking cracking around windows. No caulking on top of HVAC louver. Screw holes in cladding by front door.
Hawthorne Village P.S.	HB013		2020-09-21	Erin Kulikowski	Dec-20	NSMOMO
Hawthorne Village P.S.	HB162		2020-09-21	Erin Kulikowski	Dec-20	Damaged corner flashing on south and west corner
Hawthorne Village P.S.	RM309		2020-10-29	Erin Kulikowski	Dec-20	Caulking cracking where the wall meets ceiling
Hawthorne Village P.S.	RM308		2020-09-29	Erin Kulikowski	Dec-20	Caulking cracking where wall meets ceiling

Portable Classroom Preventative Inspection Round 112

School	Portable Number	Portables on Site	Round 112 Inspection Date	Pinchin Inspector	Proposed Round 113 Inspection Date	Comments from Round 112 Inspection
Hawthorne Village P.S.	RM307		2020-09-29	Erin Kulikowski	Dec-20	Caulking cracking where wall meets ceiling
Hawthorne Village P.S.	RM306		2020-09-29	Erin Kulikowski	Dec-20	NSMOMO
Hawthorne Village P.S.	RM305		2020-09-29	Erin Kulikowski	Dec-20	Concrete blocks cracked on west wall.
Hawthorne Village P.S.	RM304		2020-09-29	Erin Kulikowski	Dec-20	Concrete block cracking at top of south west wall
Hawthorne Village P.S.	RM303		2020-09-29	Erin Kulikowski	Dec-20	Caulking cracking where wall meets ceiling
Hawthorne Village P.S.	RM302		2020-09-29	Erin Kulikowski	Dec-20	NSMOMO
Hawthorne Village P.S.	RM310		2020-09-29	Erin Kulikowski	Dec-20	Caulking cracking where wall meets ceiling.
Irma Coulson P.S.	HBL111	17	2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB009		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB146		2020-09-16	Serena Romito	Dec-20	12 lifting tiles near HVAC
Irma Coulson P.S.	HB081		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB150		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB204		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HBL244		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HBL245		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HBL246		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HBL243		2020-09-16	Serena Romito	Dec-20	Degraded Caulking around door
Irma Coulson P.S.	HBL242		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB142		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB196		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB149		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB195		2020-09-16	Serena Romito	Dec-20	NSMOMO
Irma Coulson P.S.	HB166		2020-09-16	Serena Romito	Dec-20	Degraded Caulking around door
Irma Coulson P.S.	HB158		2020-09-16	Serena Romito	Dec-20	Level 1 . Three water stained ceiling tiles due to condensation
Iroquois Ridge HS	HB202	6	2020-09-15	Evan Faubert	Dec-20	Holes in NE corner cladding
Iroquois Ridge HS	HB088		2020-09-15	Evan Faubert	Dec-20	Holes in cladding at entrance where staircase was screwed in.
Iroquois Ridge HS	HB145		2020-09-15	Evan Faubert	Dec-20	Window protector not securly fasten to frame. Holes in door
Iroquois Ridge HS	HBL264		2020-09-15	Evan Faubert	Dec-20	NSMOMO
Iroquois Ridge HS	HB209		2020-09-15	Evan Faubert	Dec-20	NSMOMO
Iroquois Ridge HS	HB070		2020-09-15	Evan Faubert	Dec-20	NSMOMO
J.W. Singleton ED Centre	HB003	4	2020-10-01	Erin Kulikowski	Dec-20	NSMOMO
J.W. Singleton ED Centre	HB119		2020-10-01	Erin Kulikowski	Dec-20	Level 1 remediation- wet drywall to the right of east window and a water stained ceiling tile directly above the wet drywall.
J.W. Singleton ED Centre	HB117		2020-10-01	Erin Kulikowski	Dec-20	Level 1 remediation- 1 water stain ceiling tile above door due to roof leak
J.W. Singleton ED Centre	HB118		2020-10-01	Erin Kulikowski	Dec-20	NSMOMO
James W Hill P.S.	HB176	6	2020-09-15	Evan Faubert	Dec-20	NSMOMO
James W Hill P.S.	HB099		2020-09-15	Evan Faubert	Dec-20	NSMOMO
James W Hill P.S.	HB080		2020-09-15	Evan Faubert	Dec-20	NSMOMO
James W Hill P.S.	HB086		2020-09-15	Evan Faubert	Dec-20	Holes in door
James W Hill P.S.	HB050		2020-09-15	Evan Faubert	Dec-20	NSMOMO
James W Hill P.S.	HB107		2020-09-15	Evan Faubert	Dec-20	NSMOMO
John T. Tuck P.S.	HB157	5	2020-09-24	Erin Kulikowski	Dec-20	Level 1 remediation: 1 water stained ceiling tile due to condensation on the HVAC line.
John T. Tuck P.S.	HB173		2020-09-24	Erin Kulikowski	Dec-20	Caulking starting to peel inside of the HVAC louvre.
John T. Tuck P.S.	HBL220		2020-09-24	Erin Kulikowski	Dec-20	No caulking around conduits.
John T. Tuck P.S.	HB064		2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
John T. Tuck P.S.	HB156		2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
Joshua Creek P.S.	HB085	5	2020-09-15	Evan Faubert	Dec-20	NSMOMO
Joshua Creek P.S.	HB161		2020-09-15	Evan Faubert	Dec-20	NSMOMO
Joshua Creek P.S.	HB155		2020-09-15	Evan Faubert	Dec-20	NSMOMO
Joshua Creek P.S.	HB077		2020-09-15	Evan Faubert	Dec-20	NSMOMO
Joshua Creek P.S.	HB011		2020-09-15	Evan Faubert	Dec-20	NSMOMO
Kilbride P.S.	HB074	1	2020-09-10	Erin Kulikowski	Dec-20	NSMOMO
Milton District HS	HBL223	5	2020-09-15	Serena Romito	Dec-20	NSMOMO
Milton District HS	HB041		2020-09-15	Serena Romito	Dec-20	NSMOMO
Milton District HS	HB093		2020-09-15	Serena Romito	Dec-20	Hole in drywall near north window. Approximately 30 damaged vinyl floor tiles throughout
Milton District HS	HB154		2020-09-15	Serena Romito	Dec-20	Hole in drywall north wall. Degraded Caulking around ac line penetration north side.
Milton District HS	HB001		2020-09-15	Serena Romito	Dec-20	Missing baseboards and number plate
Montclair	HBL210	1	2020-09-17	Evan Faubert	Dec-20	Caulking cracked at SW conduits. Screw holes in cladding at SW and NE corners.
Munn's P.S.	HBL001	2	2020-09-22	Erin Kulikowski	Dec-20	Window caulking starting to crack around corners
Munn's P.S.	HBL002		2020-09-22	Erin Kulikowski	Dec-20	NSMOMO
New Central	HB104	2	2020-09-15	Evan Faubert	Dec-20	Damaged cladding at West top gable seam. Missing portable alley screen.
New Central	HB079		2020-09-15	Evan Faubert	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM198	11	2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM190		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM197		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM196		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM195		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM194		2020-09-25	Erin Kulikowski	Dec-20	Middle window needs caulking on bottom
Oakville Trafalgar S.S.	RM193		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM192		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM191		2020-09-25	Erin Kulikowski	Dec-20	Needs caulking around middle window on the bottom
Oakville Trafalgar S.S.	RM189A		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oakville Trafalgar S.S.	RM189B		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
Oodenawi PS	HB094	11	2020-09-11	Evan Faubert	Dec-20	Gap in SW cladding corner
Oodenawi PS	HB067		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HB044		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HB096		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HBL086		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HBL248		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HB171		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HB175		2020-09-11	Evan Faubert	Dec-20	Missing down spout.Holes in cladding were missing downspout should be
Oodenawi PS	HB058		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HBL260		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Oodenawi PS	HB101		2020-09-11	Evan Faubert	Dec-20	Missing downspout and portable alley screen.
P.L Robertson P.S.	HBL091	8	2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
P.L Robertson P.S.	HB039		2020-09-24	Erin Kulikowski	Dec-20	NSMOMO

Portable Classroom Preventative Inspection Round 112

School	Portable Number	Portables on Site	Round 112 Inspection Date	Pinchin Inspector	Proposed Round 113 Inspection Date	Comments from Round 112 Inspection
P.L Robertson P.S.	HB022		2020-09-24	Erin Kulikowski	Dec-20	Caulking around door is peeling off.
P.L Robertson P.S.	HB016		2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
P.L Robertson P.S.	HB030		2020-09-24	Erin Kulikowski	Dec-20	Holes in cladding on west wall visible through ceiling space.
P.L Robertson P.S.	HB021		2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
P.L Robertson P.S.	HB027		2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
P.L Robertson P.S.	HB004		2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
Palermo P.S.	HB167	1	2020-09-22	Erin Kulikowski	Dec-20	NSMOMO
Pauline Johnson P.S.	HB102	3	2020-09-09	Erin Kulikowski	Dec-20	Damaged cladding on SE wall. Cracking caulking around windows and HVAC louvre
Pauline Johnson P.S.	HBL222		2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Pauline Johnson P.S.	HB024		2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Pilgrim Woods P.S.	HB006	3	2020-09-16	Evan Faubert	Dec-20	NSMOMO
Pilgrim Woods P.S.	HBL087		2020-09-16	Evan Faubert	Dec-20	Missing id plate
Pilgrim Woods P.S.	HBL267		2020-09-16	Evan Faubert	Dec-20	Missing id plate
Posts Corners P.S.	HBL007	11	2020-09-11	Evan Faubert	Dec-20	NSMOMO
Posts Corners P.S.	HBL211		2020-09-11	Evan Faubert	Dec-20	Screw holes in door
Posts Corners P.S.	HBL255		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Posts Corners P.S.	HB129		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Posts Corners P.S.	HB180		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Posts Corners P.S.	HBL102		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Posts Corners P.S.	HBL268		2020-09-11	Evan Faubert	Dec-20	Missing id plate
Posts Corners P.S.	HBL269		2020-09-11	Evan Faubert	Dec-20	Missing id plate
Posts Corners P.S.	HB123		2020-09-11	Evan Faubert	Dec-20	Missing caulking above hvac louvre
Posts Corners P.S.	HBL218		2020-09-11	Evan Faubert	Dec-20	Missing exterior id plate
Posts Corners P.S.	HBL006		2020-09-11	Evan Faubert	Dec-20	NSMOMO
Sam Sherratt P.S.	HB032	6	2020-09-16	Serena Romito	Dec-20	Missing railing on walkway. Screw holes in sheathing on both sides of door. Damaged fascia boards east end. Damaged eaves trough rear elevation. Damaged drywall west end. Three missing floor tiles.
Sam Sherratt P.S.	HBL099		2020-09-16	Serena Romito	Dec-20	NSMOMO
Sam Sherratt P.S.	HB083		2020-09-16	Serena Romito	Dec-20	NSMOMO
Sam Sherratt P.S.	HB082		2020-09-16	Serena Romito	Dec-20	NSMOMO
Sam Sherratt P.S.	HB066		2020-09-16	Serena Romito	Dec-20	NSMOMO
Sam Sherratt P.S.	HB127		2020-09-16	Serena Romito	Dec-20	About 20 lifting vinyl floor tiles near door
Tiger Jeet Singh P.S.	HB029	11	2020-09-21	Erin Kulikowski	Dec-20	NSMOMO
Tiger Jeet Singh P.S.	HBL079		2020-09-21	Erin Kulikowski	Dec-20	Degraded caulking around HVAC louvre
Tiger Jeet Singh P.S.	HBL108		2020-09-21	Erin Kulikowski	Dec-20	Screw holes in cladding around back door of portable and in. east corner
Tiger Jeet Singh P.S.	HBL013		2020-09-21	Erin Kulikowski	Dec-20	NSMOMO
Tiger Jeet Singh P.S.	HBL098		2020-09-21	Erin Kulikowski	Dec-20	Caulking around windows starting to crack
Tiger Jeet Singh P.S.	HB095		2020-09-21	Erin Kulikowski	Dec-20	Caulking around windows starting to separate
Tiger Jeet Singh P.S.	HB187		2020-09-21	Erin Kulikowski	Dec-20	NSMOMO
Tiger Jeet Singh P.S.	HB116		2020-09-21	Erin Kulikowski	Dec-20	HVAC louvre is missing some caulking. Damaged downspout
Tiger Jeet Singh P.S.	HB109		2020-09-21	Erin Kulikowski	Dec-20	NSMOMO
Tiger Jeet Singh P.S.	HB063		2020-09-21	Erin Kulikowski	Dec-20	Cladding unsecured under east window and beside door. Window frames are rotting and caulking is degrading.
Tiger Jeet Singh P.S.	HB126		2020-09-21	Erin Kulikowski	Dec-20	NSMOMO
Tom Thomson P.S.	HB141	7	2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Tom Thomson P.S.	HBL109		2020-09-09	Erin Kulikowski	Dec-20	Screw holes in cladding around back door and E corner
Tom Thomson P.S.	HB098		2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Tom Thomson P.S.	HB105		2020-09-09	Erin Kulikowski	Dec-20	Caulking starting to crack around door
Tom Thomson P.S.	HB124		2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Tom Thomson P.S.	HB012		2020-09-09	Erin Kulikowski	Dec-20	Level 1 remediation- 1 waterstained ceiling tile due to condensation from HVAC line
Tom Thomson P.S.	HB031		2020-09-09	Erin Kulikowski	Dec-20	NSMOMO
Viola Desmond P.S.	HBL270	18	2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL271		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL272		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL273		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL274		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL275		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL276		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL277		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL278		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL279		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL280		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL281		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL282		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL283		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL284		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL285		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL286		2020-09-16	Serena Romito	Dec-20	Missing number plate
Viola Desmond P.S.	HBL287		2020-09-16	Serena Romito	Dec-20	Missing number plate
W.H Morden P.S.	HB138	7	2020-09-22	Erin Kulikowski	Dec-20	NSMOMO
W.H Morden P.S.	HB055		2020-09-22	Erin Kulikowski	Dec-20	No caulking around repair patch on cladding on NE wall
W.H Morden P.S.	HBL249		2020-09-22	Erin Kulikowski	Dec-20	NSMOMO
W.H Morden P.S.	HB199		2020-09-22	Erin Kulikowski	Dec-20	NSMOMO
W.H Morden P.S.	HB200		2020-09-22	Erin Kulikowski	Dec-20	NSMOMO
W.H Morden P.S.	HBL201		2020-09-22	Erin Kulikowski	Dec-20	HVAC louvre needs caulking on top
W.H. Morden P.S.	HBL250		2020-09-22	Erin Kulikowski	Dec-20	NSMOMO
W.I Dick P.S.	HB183	3	2020-09-24	Erin Kulikowski	Dec-20	NSMOMO
W.I Dick P.S.	HB002		2020-09-24	Erin Kulikowski	Dec-20	Key wouldn't work; outdoors NSMOMO
W.I Dick P.S.	HB007		2020-09-24	Erin Kulikowski	Dec-20	Key wouldn't work; NSMOMO outside
West Oak P.S.	RM1	6	2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
West Oak P.S.	RM2		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
West Oak P.S.	RM3		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
West Oak P.S.	RM4		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
West Oak P.S.	RM5		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
West Oak P.S.	RM6		2020-09-25	Erin Kulikowski	Dec-20	NSMOMO
White Oaks North H.S.	HB060	5	2020-09-17	Evan Faubert	Dec-20	Damaged eavestroughs on north side
White Oaks North H.S.	HBL092		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks North H.S.	HBL093		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks North H.S.	HBL094		2020-09-17	Evan Faubert	Dec-20	NSMOMO

Portable Classroom Preventative Inspection Round 112

School	Portable Number	Portables on Site	Round 112 Inspection Date	Pinchin Inspector	Proposed Round 113 Inspection Date	Comments from Round 112 Inspection
White Oaks North H.S.	HBL095		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB054	16	2020-09-17	Evan Faubert	Dec-20	Cracked caulking at HVAC louvre. Screw holes in cladding next to door and railing.
White Oaks South H.S.	HBL016		2020-09-17	Evan Faubert	Dec-20	Damaged skirting at SW corner
White Oaks South H.S.	HBL096		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HBL097		2020-09-17	Evan Faubert	Dec-20	Hole in skirting. Wooden board blocking portable alley is unsecure.
White Oaks South H.S.	HB042		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HBL017		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HBL018		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB078		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB205		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB023		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB153		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB112		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB201		2020-09-17	Serena Romito	Dec-20	NSMOMO
White Oaks South H.S.	HBL009		2020-09-17	Evan Faubert	Dec-20	Screwholes in cladding near door and at NE corner
White Oaks South H.S.	HBL261		2020-09-17	Evan Faubert	Dec-20	NSMOMO
White Oaks South H.S.	HB130		2020-09-17	Evan Faubert	Dec-20	Missing top cladding end cap at south end gable.