

Portable Classroom Preventative Inspection Round 113

School	Portable Number	Portables on Site	Round 113 Inspection Date	Pinchin Inspector	Proposed Round 114 Inspection Date	Comments from Round 113 Inspection
Abbey Park H.S.	HB108	12	2020-12-21	Evan Faubert	Mar-21	NSMOMO
Abbey Park H.S.	HBL227		2020-12-21	Evan Faubert	Mar-21	Holes in cladding left of door. Cracked caulking at windows
Abbey Park H.S.	HB043		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at conduits
Abbey Park H.S.	HBL213		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at windows. Broken screen in window.
Abbey Park H.S.	HB177		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at door, windows and hvac louvre. Screwholes left of door.
Abbey Park H.S.	HB072		2020-12-21	Evan Faubert	Mar-21	NSMOMO
Abbey Park H.S.	HB131		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at door. Lifting and cracked floor tiles throughout portable.
Abbey Park H.S.	HB053		2020-12-21	Evan Faubert	Mar-21	NSMOMO
Abbey Park H.S.	HB206		2020-12-21	Evan Faubert	Mar-21	Broken floor tiles present
Abbey Park H.S.	HBL224		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at HVAC louvre and conduits
Abbey Park H.S.	HB164		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at door
Abbey Park H.S.	HB163		2020-12-21	Evan Faubert	Mar-21	NSMOMO
Alton Village P.S.	HBL234	12	2020-12-07	Evan Faubert	Mar-21	Cracked and or missing caulking at windows and conduits.
Alton Village P.S.	HBL235		2020-12-07	Evan Faubert	Mar-21	Caulking separating from door frame.
Alton Village P.S.	HBL236		2020-12-07	Evan Faubert	Mar-21	Wooden door frame is cracked and split in areas.
Alton Village P.S.	HBL237		2020-12-07	Evan Faubert	Mar-21	NSMOMO
Alton Village P.S.	HBL238		2020-12-07	Evan Faubert	Mar-21	NSMOMO
Alton Village P.S.	HBL239		2020-12-07	Evan Faubert	Mar-21	NSMOMO
Alton Village P.S.	HBL247		2020-12-14	Evan Faubert	Mar-21	Cracked and split caulking at windows
Alton Village P.S.	HB140		2020-12-14	Evan Faubert	Mar-21	Bottom of door frame missing and covered with tape. Gap in deadbolt cradle in door.
Alton Village P.S.	HB037		2020-12-14	Evan Faubert	Mar-21	Broken floor tiles at entrance.
Alton Village P.S.	HB068		2020-12-14	Evan Faubert	Mar-21	Level 1 . Water stained ceiling tile, vapor barrier and insulation in east corner.
Alton Village P.S.	HBL225		2020-12-14	Evan Faubert	Mar-21	NSMOMO
Alton Village P.S.	HB169		2020-12-14	Evan Faubert	Mar-21	Screw holes in cladding at east and west corner as well as near the railing at the front door. Hole in the cladding in west corner. No caulking around conduits.
Anne J MacArthur P.S.	HB174	15	2021-01-06	Serena Romito	Mar-21	Degraded Caulking around windows. Around 20 damaged floor tiles
Anne J MacArthur P.S.	HBL221		2021-01-06	Serena Romito	Mar-21	Degraded Caulking around windows
Anne J MacArthur P.S.	HB111		2021-01-06	Serena Romito	Mar-21	Degraded Caulking around door
Anne J MacArthur P.S.	HB061		2021-01-06	Serena Romito	Mar-21	Degraded Caulking around door and windows. Around 5 damaged floor tiles
Anne J MacArthur P.S.	HBL202		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL203		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL204		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL205		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL214		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL215		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL232		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL233		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HB165		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL216		2021-01-05	Serena Romito	Mar-21	NSMOMO
Anne J MacArthur P.S.	HBL219		2021-01-05	Serena Romito	Mar-21	NSMOMO
Boyne P.S.	HB033	15	2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HB208		2021-01-08	Erin Kulikowski	Mar-21	Level 1 remediation: 5 water stained ceiling tiles due to pest urine. Caulking separating above HVAC louvre and there are screw holes in cladding to left of door.
Boyne P.S.	HBL106		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL110		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL241		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HB028		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL226		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HB179		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL257		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL252		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL254		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HB152		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL253		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HBL251		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Boyne P.S.	HB015		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Bruce Trail P.S.	HB115	16	2021-01-12	Evan Faubert	Mar-21	Degraded caulking around conduits.
Bruce Trail P.S.	HBL105		2021-01-12	Evan Faubert	Mar-21	1 broken floor tile.
Bruce Trail P.S.	HB062		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HB114		2021-01-12	Evan Faubert	Mar-21	Caulking cracked around hvac louvre.
Bruce Trail P.S.	HB046		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HB110		2021-01-12	Evan Faubert	Mar-21	Gap in cladding at electrical conduits
Bruce Trail P.S.	HB103		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HB075		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HB181		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HBL107		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HBL262		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HBL206		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HBL228		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HBL229		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HBL231		2021-01-12	Evan Faubert	Mar-21	NSMOMO
Bruce Trail P.S.	HBL230		2021-01-12	Evan Faubert	Mar-21	Split caulking at hvac louvre, conduits and windows.
Captain R Wilson PS	HB047	6	2020-12-18	Evan Faubert	Mar-21	Insufficient caulking in screw holes at staircase railing
Captain R Wilson PS	HB106		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Captain R Wilson PS	HB065		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Captain R Wilson PS	HB014		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Captain R Wilson PS	HB087		2020-12-18	Evan Faubert	Mar-21	Cracked caulking at hvac louvre. Screw holes in East cladding and Corners. Missing floor tile at entrance
Captain R Wilson PS	HBL217		2020-12-18	Evan Faubert	Mar-21	Hole in cladding below windows
Chris Hadfield P.S.	HBL266	18	2021-01-07	Serena Romito	Mar-21	NSMOMO
Chris Hadfield P.S.	HB051		2021-01-07	Erin Kulikowski	Mar-21	Screw holes in cladding to left of door. Caulking starting to separate at to of window. Caulking separated around conduits.
Chris Hadfield P.S.	HB034		2021-01-07	Erin Kulikowski	Mar-21	Degraded caulking around conduits. Damaged cladding under window.

Portable Classroom Preventative Inspection Round 113

School	Portable Number	Portables on Site	Round 113 Inspection Date	Pinchin Inspector	Proposed Round 114 Inspection Date	Comments from Round 113 Inspection
Chris Hadfield P.S.	HB168		2021-01-07	Erin Kulikowski	Mar-21	No caulking around conduit. Screw holes in cladding at SE and NE Corners. 5 ceiling tiles missing.
Chris Hadfield P.S.	HB036		2021-01-07	Erin Kulikowski	Mar-21	1 ceiling tile missing.
Chris Hadfield P.S.	HB035		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	HBL259		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	HBL265		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A10		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A09		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A08		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A07		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A06		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A05		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A04		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A03		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A02		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Chris Hadfield P.S.	RM A01		2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
Craig Keilburger S.S.	HB147	15	2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HB128		2021-01-07	Evan Faubert	Mar-21	Degraded caulking at door frame and hvac louvre. Screwholes in cladding left of door.
Craig Keilburger S.S.	HB159		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HB132		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HBL014		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HBL015		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HB073		2021-01-07	Evan Faubert	Mar-21	Level 2: Suspect moisture on fiberglass insulation vapor barrier and stained ceiling tile from roof leak. Screwholes in cladding at NW corner.
Craig Keilburger S.S.	HB143		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HB133		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HB203		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HB134		2021-01-07	Evan Faubert	Mar-21	Half of floor tiles appear to be lifting at corners.
Craig Keilburger S.S.	HB057		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HB113		2021-01-07	Evan Faubert	Mar-21	Screwholes in cladding above north door.
Craig Keilburger S.S.	HB125		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Craig Keilburger S.S.	HBL084		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Dr. Frank Hayden S.S.	HB059	9	2020-12-14	Evan Faubert	Mar-21	No caulking on top of hvac louvre
Dr. Frank Hayden S.S.	HB120		2020-12-14	Evan Faubert	Mar-21	No caulking on top of hvac louvre
Dr. Frank Hayden S.S.	HB172		2020-12-14	Evan Faubert	Mar-21	No caulking on top of hvac louvre
Dr. Frank Hayden S.S.	HB092		2020-12-14	Evan Faubert	Mar-21	No caulking on top of hvac louvre
Dr. Frank Hayden S.S.	HB010		2020-12-14	Evan Faubert	Mar-21	NSMOMO
Dr. Frank Hayden S.S.	HBL256		2020-12-14	Evan Faubert	Mar-21	NSMOMO
Dr. Frank Hayden S.S.	HB137		2020-12-14	Evan Faubert	Mar-21	No caulking on top of hvac louvre
Dr. Frank Hayden S.S.	HB207		2020-12-14	Evan Faubert	Mar-21	No caulking on top of hvac louvre
Dr. Frank Hayden S.S.	HB151		2020-12-14	Evan Faubert	Mar-21	NSMOMO
E.J. James P.S.	HB121	1	2020-12-14	Erin Kulikowski	Mar-21	Degraded caulking around fan louvre
E.W. Foster P.S.	HB189	1	2021-01-06	Evan Faubert	Mar-21	NSMOMO
Emily Carr P.S.	HBL008	4	2020-12-18	Evan Faubert	Mar-21	NSMOMO
Emily Carr P.S.	HB008		2020-12-18	Evan Faubert	Mar-21	Degraded caulking at NE conduit
Emily Carr P.S.	HB040		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Emily Carr P.S.	HB084		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Escarpment View P.S.	HBL090	12	2020-12-08	Serena Romito	Mar-21	Degraded Caulking around windows
Escarpment View P.S.	HBL103		2020-12-08	Serena Romito	Mar-21	Degraded Caulking around door and windows
Escarpment View P.S.	HBL104		2020-12-08	Serena Romito	Mar-21	About 20 damaged floor tiles throughout
Escarpment View P.S.	HB144		2020-12-08	Serena Romito	Mar-21	About 20 damaged floor tiles throughout
Escarpment View P.S.	HB005		2020-12-08	Serena Romito	Mar-21	Level 1. One water stained ceiling tile near door. Approximately 10 damaged floor tiles. Majority of floor tiles lifting slightly at corners.
Escarpment View P.S.	HB089		2020-12-08	Serena Romito	Mar-21	NSMOMO
Escarpment View P.S.	HBL083		2020-12-08	Serena Romito	Mar-21	NSMOMO
Escarpment View P.S.	HBL082		2020-12-08	Serena Romito	Mar-21	Missing downspout front elevation
Escarpment View P.S.	HBL081		2020-12-08	Serena Romito	Mar-21	NSMOMO
Escarpment View P.S.	HB056		2020-12-08	Serena Romito	Mar-21	Degraded Caulking around door and windows
Escarpment View P.S.	HBL088		2020-12-08	Serena Romito	Mar-21	NSMOMO
Escarpment View P.S.	HBL089		2020-12-08	Serena Romito	Mar-21	NSMOMO
Ethel Gardiner P.S.	HBL101	5	2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Ethel Gardiner P.S.	HBL263		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Ethel Gardiner P.S.	HBL207		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Ethel Gardiner P.S.	HBL212		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Ethel Gardiner P.S.	HB049		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Florence Meares P.S.	HB139	3	2020-12-07	Evan Faubert	Mar-21	NSMOMO
Florence Meares P.S.	HBL100		2020-12-07	Evan Faubert	Mar-21	NSMOMO
Florence Meares P.S.	HB069		2020-12-07	Evan Faubert	Mar-21	Holes in cladding NE corner
Garth Webb SS	HBL258	12	2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HB091		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HB135		2020-12-18	Evan Faubert	Mar-21	Missing caulking at hvac louvre and on top of door
Garth Webb SS	HB100		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HBL005		2020-12-18	Evan Faubert	Mar-21	Denatured caulking at conduits and screwholes in cladding at NE corner
Garth Webb SS	HBL080		2020-12-18	Evan Faubert	Mar-21	Screw holes in east cladding and at NE corner
Garth Webb SS	HB090		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HB038		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HB076		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HB045		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HB052		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Garth Webb SS	HBL009		2020-12-18	Evan Faubert	Mar-21	NSMOMO
Glen Williams P.S.	HB184	2	2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Glen Williams P.S.	HB178		2021-01-08	Erin Kulikowski	Mar-21	NSMOMO
Glenview P.S.	HB148	2	2020-12-12	Evan Faubert	Mar-21	NSMOMO
Glenview P.S.	HB122		2020-12-12	Evan Faubert	Mar-21	NSMOMO
Hawthorne Village P.S.	HB013	13	2021-01-12	Erin Kulikowski	Mar-21	NSMOMO
Hawthorne Village P.S.	HB136		2021-01-12	Erin Kulikowski	Mar-21	NSMOMO
Hawthorne Village P.S.	HB162		2021-01-12	Erin Kulikowski	Mar-21	Caulking separating around conduits
Hawthorne Village P.S.	RM301		2021-01-12	Erin Kulikowski	Mar-21	NSMOMO

Portable Classroom Preventative Inspection Round 113

School	Portable Number	Portables on Site	Round 113 Inspection Date	Pinchin Inspector	Proposed Round 114 Inspection Date	Comments from Round 113 Inspection
Hawthorne Village P.S.	RM302		2021-01-12	Erin Kulikowski	Mar-21	Caulking splitting at wall and ceiling junction. Also splitting at the corners of the walls.
Hawthorne Village P.S.	RM303		2021-01-12	Erin Kulikowski	Mar-21	Caulking splitting at corners of walls.
Hawthorne Village P.S.	RM304		2021-01-12	Erin Kulikowski	Mar-21	Caulking splitting at corners of walls. Also splitting at wall and ceiling. Crack in cement block along top of west wall.
Hawthorne Village P.S.	RM305		2021-01-12	Erin Kulikowski	Mar-21	Caulking splitting at corners of walls. Crack in cement block along top of west wall. Caulking degrading under bulk head by window.
Hawthorne Village P.S.	RM306		2021-01-12	Erin Kulikowski	Mar-21	Caulking splitting at corners of walls. Also splitting at wall and ceiling junction.
Hawthorne Village P.S.	RM307		2021-01-12	Erin Kulikowski	Mar-21	NSMOMO
Hawthorne Village P.S.	RM308		2021-01-12	Erin Kulikowski	Mar-21	NSMOMO
Hawthorne Village P.S.	RM309		2021-01-12	Erin Kulikowski	Mar-21	NSMOMO
Hawthorne Village P.S.	RM310		2021-01-12	Erin Kulikowski	Mar-21	NSMOMO
Irma Coulson P.S.	HBL111	17	2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HB009		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HB146		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HB081		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HB150		2021-01-13	Evan Faubert	Mar-21	1 missing floor tile. Denatured caulking at door.
Irma Coulson P.S.	HB204		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HBL244		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HBL245		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HBL246		2021-01-14	Evan Faubert	Mar-21	Degraded caulking at hvac louvre. Missing conduit cover with exposed wiring.
Irma Coulson P.S.	HBL243		2021-01-14	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HBL242		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HB142		2021-01-14	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HB158		2021-01-14	Evan Faubert	Mar-21	Missing exterior claat south seam. Missing caulking at conduits. Screw holes in cladding left of door.
Irma Coulson P.S.	HB196		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Irma Coulson P.S.	HB149		2021-01-13	Evan Faubert	Mar-21	Denatured caulking at hvac louvre and door frame.
Irma Coulson P.S.	HB166		2021-01-13	Evan Faubert	Mar-21	Screwholes in cladding at right side of door.
Irma Coulson P.S.	HB195		2021-01-13	Evan Faubert	Mar-21	NSMOMO
Iroquois Ridge HS	HBL264	6	2020-12-15	Evan Faubert	Mar-21	Caulking cracked at conduits
Iroquois Ridge HS	HB070		2020-12-15	Evan Faubert	Mar-21	NSMOMO
Iroquois Ridge HS	HB202		2020-12-15	Evan Faubert	Mar-21	Missing caulking on left side of hvac louvre.
Iroquois Ridge HS	HB088		2020-12-15	Evan Faubert	Mar-21	NSMOMO
Iroquois Ridge HS	HB145		2020-12-15	Evan Faubert	Mar-21	NSMOMO
Iroquois Ridge HS	HB209		2020-12-15	Evan Faubert	Mar-21	NSMOMO
J.W. Singleton ED Centre	HB117	4	2020-12-18	Evan Faubert	Mar-21	Level 1 . 1 water stained ceiling tile above door due to roof leak
J.W. Singleton ED Centre	HB003		2020-12-18	Evan Faubert	Mar-21	NSMOMO
J.W. Singleton ED Centre	HB118		2020-12-18	Evan Faubert	Mar-21	NSMOMO
J.W. Singleton ED. Centre	HB119		2020-12-18	Evan Faubert	Mar-21	Level 2 . Moisture and staining of insulation and vapor barrier above east window and stained ceiling tile. Cracked caulking beneath West window.
James W Hill P.S.	HB050	6	2020-12-14	Erin Kulikowski	Mar-21	Caulking cracking around conduits
James W Hill P.S.	HB086		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
James W Hill P.S.	HB080		2020-12-15	Erin Kulikowski	Mar-21	NSMOMO
James W Hill P.S.	HB099		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
James W Hill P.S.	HB176		2020-12-14	Erin Kulikowski	Mar-21	No cladding under door; wood is exposed.
James W Hill P.S.	HB107		2020-12-14	Erin Kulikowski	Mar-21	No cladding under door; wood is exposed. Cladding around where area is exposed is rotting and rusty.
John T. Tuck P.S.	HB157	5	2020-12-12	Evan Faubert	Mar-21	NSMOMO
John T. Tuck P.S.	HB173		2020-12-12	Evan Faubert	Mar-21	NSMOMO
John T. Tuck P.S.	HBL220		2020-12-12	Evan Faubert	Mar-21	NSMOMO
John T. Tuck P.S.	HB156		2020-12-12	Evan Faubert	Mar-21	NSMOMO
John T. Tuck P.S.	HB064		2020-12-12	Evan Faubert	Mar-21	NSMOMO
Joshua Creek P.S.	HB085	5	2021-01-07	Evan Faubert	Mar-21	NSMOMO
Joshua Creek P.S.	HB161		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Joshua Creek P.S.	HB155		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Joshua Creek P.S.	HB077		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Joshua Creek P.S.	HB011		2021-01-07	Evan Faubert	Mar-21	NSMOMO
Kilbride P.S.	HB074	1	2020-12-12	Evan Faubert	Mar-21	NSMOMO
Milton District HS	HB001	5	2020-12-15	Serena Romito	Mar-21	Missing number plate. Damaged soffit above door.
Milton District HS	HBL223		2020-12-15	Serena Romito	Mar-21	Damaged eve trough front elevation
Milton District HS	HB041		2020-12-15	Serena Romito	Mar-21	NSMOMO
Milton District HS	HB093		2020-12-15	Serena Romito	Mar-21	NSMOMO
Milton District HS	HB154		2020-12-15	Serena Romito	Mar-21	Level 2. Impacted drywall beneath window near door.
Montclair	HBL210	1	2021-01-01	Evan Faubert	Mar-21	Damaged downspout
Munn's P.S.	HBL002	2	2021-01-01	Evan Faubert	Mar-21	Degraded caulking at hvac louvre and windows
Munn's P.S.	HBL001		2021-01-01	Evan Faubert	Mar-21	NSMOMO
New Central	HB104	2	2021-01-12	Erin Kulikowski	Mar-21	NSMOMO
New Central	HB079		2021-01-12	Erin Kulikowski	Mar-21	Caulking separating around conduits.
Oakville Trafalgar S.S.	RM190	11	2020-12-14	Erin Kulikowski	Mar-21	Window caulking starting to crack around corners
Oakville Trafalgar S.S.	RM191		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
Oakville Trafalgar S.S.	RM192		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
Oakville Trafalgar S.S.	RM193		2020-12-14	Erin Kulikowski	Mar-21	Caulking starting to crack around window corners
Oakville Trafalgar S.S.	RM194		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
Oakville Trafalgar S.S.	RM189A		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
Oakville Trafalgar S.S.	RM189B		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
Oakville Trafalgar S.S.	RM195		2020-12-14	Erin Kulikowski	Mar-21	Level 1 . 2 water stained ceiling tiles . Level 1 remediation: 2 water stained ceiling tiles due to condensation on water sprinkler line.
Oakville Trafalgar S.S.	RM196		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
Oakville Trafalgar S.S.	RM197		2020-12-14	Erin Kulikowski	Mar-21	Level 1 . 1 water stained ceiling tile . Level 1 remediation: 1 water stained ceiling tile
Oakville Trafalgar S.S.	RM198		2020-12-14	Erin Kulikowski	Mar-21	NSMOMO
Oodenawi PS	HBL086	11	2020-12-21	Evan Faubert	Mar-21	NSMOMO
Oodenawi PS	HB171		2020-12-21	Evan Faubert	Mar-21	NSMOMO
Oodenawi PS	HB175		2020-12-21	Evan Faubert	Mar-21	NSMOMO
Oodenawi PS	HB058		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at hvac louvre and door.
Oodenawi PS	HB101		2020-12-21	Evan Faubert	Mar-21	Damaged downspout
Oodenawi PS	HBL260		2020-12-21	Evan Faubert	Mar-21	Separating caulking at HVAC louvre

Portable Classroom Preventative Inspection Round 113

School	Portable Number	Portables on Site	Round 113 Inspection Date	Pinchin Inspector	Proposed Round 114 Inspection Date	Comments from Round 113 Inspection
Oodenawi PS	HBL248		2020-12-21	Evan Faubert	Mar-21	Missing conduit casing lids. Exposed wires present.
Oodenawi PS	HB044		2020-12-21	Evan Faubert	Mar-21	NSMOMO
Oodenawi PS	HB067		2020-12-21	Evan Faubert	Mar-21	Degraded caulking at hvac louvre
Oodenawi PS	HB094		2020-12-21	Evan Faubert	Mar-21	Holes in NW corner cladding
Oodenawi PS	HB096		2020-12-21	Evan Faubert	Mar-21	NSMOMO
P.L Robertson P.S.	HBL091	8	2021-01-14	Evan Faubert	Mar-21	Denatured caulking at HVAC.
P.L Robertson P.S.	HB039		2021-01-14	Evan Faubert	Mar-21	NSMOMO
P.L Robertson P.S.	HB022		2021-01-14	Evan Faubert	Mar-21	NSMOMO
P.L Robertson P.S.	HB016		2021-01-14	Evan Faubert	Mar-21	NSMOMO
P.L Robertson P.S.	HB030		2021-01-14	Evan Faubert	Mar-21	Holes in outside east cladding. Degraded caulking at hvac louvre.
P.L Robertson P.S.	HB021		2021-01-14	Evan Faubert	Mar-21	NSMOMO
P.L Robertson P.S.	HB027		2021-01-14	Evan Faubert	Mar-21	NSMOMO
P.L Robertson P.S.	HB004		2021-01-14	Evan Faubert	Mar-21	NSMOMO
Palermo P.S.	HB167	1	2020-12-18	Evan Faubert	Mar-21	Screw holes in cladding and missing caulking at conduits at east side of portable
Pauline Johnson P.S.	HB024	3	2020-12-12	Evan Faubert	Mar-21	Broken off caulking at HVAC louvre .
Pauline Johnson P.S.	HBL222		2020-12-12	Evan Faubert	Mar-21	Cracked and split caulking at windows
Pauline Johnson P.S.	HB102		2020-12-12	Evan Faubert	Mar-21	NSMOMO
Pilgrim Woods P.S.	HB006	3	2020-12-21	Evan Faubert	Mar-21	Screwholes in NE cladding. Missing cover for conduit. electrical wire exposed. Lifting and cracked floor tiles.
Pilgrim Woods P.S.	HBL087		2020-12-21	Evan Faubert	Mar-21	Missing id plate
Pilgrim Woods P.S.	HBL267		2020-12-21	Evan Faubert	Mar-21	Missing id plate
Posts Corners P.S.	HBL102	11	2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HB129		2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HBL006		2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HBL218		2021-01-13	Erin Kulikowski	Mar-21	Level 1 . one water stained ceiling tile . Level 1 remediation- one water stained ceiling tile due to dripping water from PVC pipe through wall.
Posts Corners P.S.	HBL255		2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HBL211		2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HBL007		2021-01-13	Erin Kulikowski	Mar-21	Caulking starting to crack around window corners. No caulking around conduits.
Posts Corners P.S.	HB123		2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HB180		2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HBL268		2021-01-13	Erin Kulikowski	Mar-21	NSMOMO
Posts Corners P.S.	HBL269		2021-01-14	Erin Kulikowski	Mar-21	NSMOMO
Sam Sherratt P.S.	HB127	6	2021-01-06	Evan Faubert	Mar-21	NSMOMO
Sam Sherratt P.S.	HB066		2021-01-06	Evan Faubert	Mar-21	Degraded caulking at windows.
Sam Sherratt P.S.	HB082		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Sam Sherratt P.S.	HB083		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Sam Sherratt P.S.	HBL099		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Sam Sherratt P.S.	HB032		2021-01-06	Evan Faubert	Mar-21	Damaged drywall walls at west seam. 3 missing floor tiles. Degraded/split caulking at hvac louvre. Missing caulking at conduits. Gap in west gable fascia and soffit.
Tiger Jeet Singh P.S.	HB095	11	2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HB187		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HB116		2021-01-06	Evan Faubert	Mar-21	Separating caulking at windows.
Tiger Jeet Singh P.S.	HBL108		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HBL079		2021-01-06	Serena Romito	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HB029		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HBL013		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HBL098		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HB109		2021-01-06	Evan Faubert	Mar-21	Degraded caulking at windows.
Tiger Jeet Singh P.S.	HB063		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tiger Jeet Singh P.S.	HB126		2021-01-06	Evan Faubert	Mar-21	NSMOMO
Tom Thomson P.S.	HB012	7	2020-12-12	Evan Faubert	Mar-21	NSMOMO
Tom Thomson P.S.	HB141		2020-12-12	Evan Faubert	Mar-21	Screw holes in cladding at left side of door.
Tom Thomson P.S.	HB031		2020-12-12	Evan Faubert	Mar-21	NSMOMO
Tom Thomson P.S.	HB124		2020-12-12	Evan Faubert	Mar-21	NSMOMO
Tom Thomson P.S.	HB105		2020-12-12	Evan Faubert	Mar-21	Cracked caulking around door frame
Tom Thomson P.S.	HB098		2020-12-12	Evan Faubert	Mar-21	NSMOMO
Tom Thomson P.S.	HBL109		2020-12-12	Evan Faubert	Mar-21	NSMOMO
Viola Desmond P.S.	HBL270	18	2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL271		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL272		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL273		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL274		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL275		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL276		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL277		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL278		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL279		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL280		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL281		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL282		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL283		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL284		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL285		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL286		2020-12-15	Serena Romito	Mar-21	NSMOMO
Viola Desmond P.S.	HBL287		2020-12-15	Serena Romito	Mar-21	NSMOMO
W.H Morden P.S.	HB138	7	2021-01-14	Evan Faubert	Mar-21	NSMOMO
W.H Morden P.S.	HB055		2021-01-14	Evan Faubert	Mar-21	NSMOMO
W.H Morden P.S.	HBL249		2021-01-14	Evan Faubert	Mar-21	NSMOMO
W.H Morden P.S.	HBL201		2021-01-14	Evan Faubert	Mar-21	NSMOMO
W.H Morden P.S.	HB200		2021-01-14	Evan Faubert	Mar-21	NSMOMO
W.H Morden P.S.	HB199		2021-01-14	Evan Faubert	Mar-21	NSMOMO
W.H.Morden P.S.	HBL250		2021-01-14	Evan Faubert	Mar-21	NSMOMO
W.I Dick P.S.	HB183	3	2021-01-07	Erin Kulikowski	Mar-21	NSMOMO
W.I Dick P.S.	HB007		2021-01-07	Erin Kulikowski	Mar-21	Couldn't access portable; key wouldn't work. NSMOMO from outdoors.
W.I Dick P.S.	HB002		2021-01-07	Erin Kulikowski	Mar-21	Couldn't access portable; key wouldn't work. A couple holes in caulking around window.

Portable Classroom Preventative Inspection Round 113

School	Portable Number	Portables on Site	Round 113 Inspection Date	Pinchin Inspector	Proposed Round 114 Inspection Date	Comments from Round 113 Inspection
West Oak P.S.	RM1	6	2020-12-23	Evan Faubert	Mar-21	NSMOMO
West Oak P.S.	RM2		2020-12-23	Evan Faubert	Mar-21	NSMOMO
West Oak P.S.	RM3		2020-12-23	Evan Faubert	Mar-21	NSMOMO
West Oak P.S.	RM4		2020-12-23	Evan Faubert	Mar-21	Degraded caulking at window
West Oak P.S.	RM5		2020-12-23	Evan Faubert	Mar-21	NSMOMO
West Oak P.S.	RM6		2020-12-23	Evan Faubert	Mar-21	Degraded at windows exterior
White Oaks North H.S.	HB060	5	2021-01-01	Evan Faubert	Mar-21	Degraded caulking at hvac louvre.
White Oaks North H.S.	HBL092		2021-01-01	Evan Faubert	Mar-21	Degraded caulking at windows
White Oaks North H.S.	HBL093		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks North H.S.	HBL094		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks North H.S.	HBL95		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HB054	16	2021-01-01	Evan Faubert	Mar-21	Cracked caulking at door
White Oaks South H.S.	HB042		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HBL096		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HBL097		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HBL016		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HBL017		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HBL018		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HB130		2021-01-01	Evan Faubert	Mar-21	Damaged downspout
White Oaks South H.S.	HBL261		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HB078		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HB205		2021-01-01	Evan Faubert	Mar-21	Four Damaged floor tiles in center of portable.
White Oaks South H.S.	HB023		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HB153		2021-01-01	Evan Faubert	Mar-21	Cracked caulking at door
White Oaks South H.S.	HB112		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HB201		2021-01-01	Evan Faubert	Mar-21	NSMOMO
White Oaks South H.S.	HBL085		2021-01-01	Evan Faubert	Mar-21	NSMOMO