

**Portable Classroom Preventative Inspection Round 114**

School	Portable Number	Portables on Site	Round 114 Inspection Date	Pinchin Inspector	Proposed Round 115 Inspection Date	Comments from Round 114 Inspection
Abbey Park H.S.	HB108	12	2021-04-01	Evan Faubert	Jun-21	Missing caulking at conduits.
Abbey Park H.S.	HBL227		2021-04-01	Evan Faubert	Jun-21	Holes in cladding left of door
Abbey Park H.S.	HB043		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Abbey Park H.S.	HBL213		2021-04-01	Evan Faubert	Jun-21	Damaged window screen. Degraded window caulking.
Abbey Park H.S.	HB177		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Abbey Park H.S.	HB072		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Abbey Park H.S.	HB131		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Abbey Park H.S.	HB053		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Abbey Park H.S.	HB206		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Abbey Park H.S.	HBL224		2021-04-01	Evan Faubert	Jun-21	Degraded caulking at HVAC louvre and caulking
Abbey Park H.S.	HB164		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Abbey Park H.S.	HB163		2021-04-01	Serena Romito	Jun-21	NSMOMO
Alton Village P.S.	HBL247	12	2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HB140		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HB037		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HB068		2021-03-04	Erin Kulikowski	Jun-21	Level 1 remediation: 1 water stained ceiling tile due to roof leak
Alton Village P.S.	HBL225		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HB169		2021-03-04	Erin Kulikowski	Jun-21	No caulking around conduits. Screw holes around door and east corner cladding.
Alton Village P.S.	HBL237		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HBL238		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HBL239		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HBL234		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HBL235		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Alton Village P.S.	HBL236		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HBL221	15	2021-03-10	Erin Kulikowski	Jun-21	Flashing above door is missing. Caulking around windows beginning to degrade.
Anne J. MacArthur P.S.	HBL205		2021-03-10	Erin Kulikowski	Jun-21	Caulking cracking around corner of windows
Anne J. MacArthur P.S.	HBL232		2021-03-10	Erin Kulikowski	Jun-21	Caulking cracking around window corners
Anne J. MacArthur P.S.	HBL233		2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HBL202		2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HBL203		2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HBL204		2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HB111		2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HB061		2021-03-10	Erin Kulikowski	Jun-21	Screw holes in cladding on both sides of the door
Anne J. MacArthur P.S.	HB165		2021-03-10	Erin Kulikowski	Jun-21	Screw holes in east corner cladding and to the left of the door
Anne J. MacArthur P.S.	HBL219		2021-03-10	Erin Kulikowski	Jun-21	Caulking is cracking around window corners
Anne J. MacArthur P.S.	HBL216		2021-03-10	Erin Kulikowski	Jun-21	Caulking cracking around window corners
Anne J. MacArthur P.S.	HBL214		2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HB174		2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
Anne J. MacArthur P.S.	HBL215		2021-03-10	Erin Kulikowski	Jun-21	Damaged downspout
Boyne P.S.	HBL106	15	2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HB208		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HB033		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL110		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL241		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HB028		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL226		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL257		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HB179		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL251		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL253		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HB152		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HB015		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL254		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Boyne P.S.	HBL252		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL206	16	2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL262		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL107		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB181		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB075		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB103		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB110		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB046		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB114		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB062		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL105		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HB115		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL231		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL230		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL228		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Bruce Trail P.S.	HBL229		2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Captain R Wilson P.S.	HB047	6	2021-04-01	Evan Faubert	Jun-21	NSMOMO
Captain R Wilson P.S.	HB106		2021-04-01	Evan Faubert	Jun-21	Missing caulking on sides of windows.
Captain R Wilson P.S.	HB065		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Captain R Wilson P.S.	HB014		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Captain R Wilson P.S.	HB087		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Captain R Wilson P.S.	HBL217		2021-04-01	Evan Faubert	Jun-21	NSMOMO
Chris Hadfield P.S.	HBL266	18	2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	HB051		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	HB034		2021-03-12	Erin Kulikowski	Jun-21	No caulking around conduit
Chris Hadfield P.S.	HB036		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	HB168		2021-03-12	Erin Kulikowski	Jun-21	No caulking around conduit. Screw holes in cladding at east corner
Chris Hadfield P.S.	HB035		2021-03-12	Erin Kulikowski	Jun-21	Level 1 remediation: one water stained ceiling tile due to hole in cladding. Hole needs more caulking.
Chris Hadfield P.S.	HBL259		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	HBL265		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A10		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A09		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A08		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A07		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A06		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A05		2021-03-12	Erin Kulikowski	Jun-21	Interior of room inaccessible due to after school program

**Portable Classroom Preventative Inspection Round 114**

School	Portable Number	Portables on Site	Round 114 Inspection Date	Pinchin Inspector	Proposed Round 115 Inspection Date	Comments from Round 114 Inspection
Chris Hadfield P.S.	RM A04		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A03		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A02		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Chris Hadfield P.S.	RM A01		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
Craig Keilburger S.S.	HB128	16	2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Keilburger S.S.	HB113		2021-03-16	Erin Kulikowski	Jun-21	Portable under construction
Craig Kielburger S.S.	HB147		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Kielburger S.S.	HB132		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Kielburger S.S.	HB073		2021-03-15	Erin Kulikowski	Jun-21	Level 1- Wet drywall beneath window
Craig Kielburger S.S.	HB143		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Kielburger S.S.	HB133		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Kielburger S.S.	HB203		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Kielburger S.S.	HB134		2021-03-15	Erin Kulikowski	Jun-21	Level 1 remediation: Wet wood bottom plate of wall in both inspection ports under window.
Craig Kielburger S.S.	HB057		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Kielburger S.S.	HB159		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
Craig Kielburger S.S.	HBL014		2021-03-15	Erin Kulikowski	Jun-21	No caulking around conduit
Craig Kielburger S.S.	HBL015		2021-03-15	Erin Kulikowski	Jun-21	Caulking separating around windows
Craig Kielburger S.S.	HB125		2021-03-16	Erin Kulikowski	Jun-21	Portable under construction
Craig Kielburger S.S.	HBL084		2021-03-16	Erin Kulikowski	Jun-21	Portable under construction
Craig Kielburger S.S.	HB132		2021-03-16	Erin Kulikowski	Jun-21	Portable under construction
Dr. Frank J. Hayden S.S.	HB059	9	2021-03-08	Erin Kulikowski	Jun-21	Separating caulking around conduits. Caulking starting to split around windows. No caulking ontop of HVAC louvres.
Dr. Frank J. Hayden S.S.	HB120		2021-03-08	Erin Kulikowski	Jun-21	Flashing missing above window. No caulking above HVAC louvre.
Dr. Frank J. Hayden S.S.	HB172		2021-03-08	Erin Kulikowski	Jun-21	Flashing missing above window. No caulking above HVAC louvre.
Dr. Frank J. Hayden S.S.	HB092		2021-03-08	Erin Kulikowski	Jun-21	Level 1 remediation: 1 water stained ceiling tile due to condensation on HVAC line. No caulking around HVAC louvre.
Dr. Frank J. Hayden S.S.	HB010		2021-03-08	Erin Kulikowski	Jun-21	Caulking starting to crack around window corners.
Dr. Frank J. Hayden S.S.	HBL256		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Dr. Frank J. Hayden S.S.	HB137		2021-03-08	Erin Kulikowski	Jun-21	Level 1 remediation: 1 water stained ceiling tile due to no caulking around conduit. Caulking starting to crack around HVAC louvre and windows.
Dr. Frank J. Hayden S.S.	HB151		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Dr. Frank J. Hayden S.S.	HB207		2021-03-08	Erin Kulikowski	Jun-21	No flashing above windows. No caulking above HVAC louvre and around HVAC fan line.
E.J. James P.S.	HB121	1	2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
E.W. Foster P.S.	HB189	1	2021-03-16	Erin Kulikowski	Jun-21	NSMOMO
Emily Carr P.S.	HBL008	4	2021-03-10	Evan Faubert	Jun-21	NSMOMO
Emily Carr P.S.	HB008		2021-03-10	Evan Faubert	Jun-21	Loose wooden door sill plate.
Emily Carr P.S.	HB040		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Emily Carr P.S.	HB084		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Escarpment View P.S.	HBL090	12	2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HBL103		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HBL104		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HB144		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HB005		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HB089		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HBL083		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HBL082		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HBL081		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Escarpment View P.S.	HB056		2021-03-17	Erin Kulikowski	Jun-21	Screw holes in cladding at north corner
Escarpment View P.S.	HBL088		2021-03-17	Erin Kulikowski	Jun-21	Caulking starting to crack around window corners
Escarpment View P.S.	HBL089		2021-03-17	Erin Kulikowski	Jun-21	NSMOMO
Ethel Gardiner P.S.	HBL263	5	2021-03-19	Erin Kulikowski	Jun-21	NSMOMO
Ethel Gardiner P.S.	HBL207		2021-03-19	Erin Kulikowski	Jun-21	NSMOMO
Ethel Gardiner P.S.	HBL212		2021-03-19	Erin Kulikowski	Jun-21	No caulking around conduits
Ethel Gardiner P.S.	HBL101		2021-03-19	Erin Kulikowski	Jun-21	NSMOMO
Ethel Gardiner P.S.	HB049		2021-03-19	Erin Kulikowski	Jun-21	NSMOMO
Florence Meares P.S.	HB069	3	2021-03-24	Erin Kulikowski	Jun-21	NSMOMO
Florence Meares P.S.	HBL100		2021-03-24	Erin Kulikowski	Jun-21	NSMOMO
Florence Meares P.S.	HB139		2021-03-24	Erin Kulikowski	Jun-21	NSMOMO
Garth Webb S.S.	HBL258	12	2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HB091		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HB135		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HB100		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HBL005		2021-03-10	Evan Faubert	Jun-21	Denatured caulking at conduits and screwholes in cladding at NE corner
Garth Webb S.S.	HBL080		2021-03-10	Evan Faubert	Jun-21	Screwholes in east cladding at SW corner.
Garth Webb S.S.	HB090		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HB038		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HB076		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HB045		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HB052		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Garth Webb S.S.	HBL009		2021-03-10	Evan Faubert	Jun-21	NSMOMO
Glen Williams P.S.	HB184	2	2021-03-19	Erin Kulikowski	Jun-21	Level 1 remediation: wet drywall beneath window
Glen Williams P.S.	HB178		2021-03-19	Erin Kulikowski	Jun-21	NSMOMO
Glenview P.S.	HB148	2	2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Glenview P.S.	HB122		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	HB162	13	2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	HB013		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	HB136		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM301		2021-03-23	Erin Kulikowski	Jun-21	Crack in cement block at the top of north west wall
Hawthorne Village P.S.	RM302		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM303		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM304		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM305		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM306		2021-03-23	Erin Kulikowski	Jun-21	Crack in concrete at bottom of NE exterior wall.
Hawthorne Village P.S.	RM307		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM308		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM309		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Hawthorne Village P.S.	RM310		2021-03-23	Erin Kulikowski	Jun-21	Crack in cement block at top of east wall. Cracking in concrete exterior wall under bulk head.

**Portable Classroom Preventative Inspection Round 114**

School	Portable Number	Portables on Site	Round 114 Inspection Date	Pinchin Inspector	Proposed Round 115 Inspection Date	Comments from Round 114 Inspection
Irma Coulson P.S.	HBL246	17	2021-03-23	Serena Romito	Jun-21	Degraded caulking around windows and hvac louvre. missing conduit cover with exposed wiring.
Irma Coulson P.S.	HBL245		2021-03-23	Serena Romito	Jun-21	Key doesn't work. Exterior inspection only.
Irma Coulson P.S.	HBL244		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HB142		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HBL242		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HBL243		2021-03-23	Serena Romito	Jun-21	Degraded caulking around windows and door.
Irma Coulson P.S.	HB195		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HB149		2021-03-23	Serena Romito	Jun-21	Degraded caulking around HVAC louvre
Irma Coulson P.S.	HB196		2021-03-23	Serena Romito	Jun-21	Degraded caulking around windows
Irma Coulson P.S.	HB158		2021-03-23	Serena Romito	Jun-21	Missing exterior cladding south seam. Missing caulking at conduits. Screw holes in cladding left of door
Irma Coulson P.S.	HB166		2021-03-23	Serena Romito	Jun-21	Screw holes in cladding at right side of door. Damaged fascia NW side. Strong mould odour possibly related to restricted skirting ventilation.
Irma Coulson P.S.	HB081		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HB150		2021-03-23	Serena Romito	Jun-21	Degraded window caulking
Irma Coulson P.S.	HB204		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HBL111		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HB146		2021-03-23	Serena Romito	Jun-21	NSMOMO
Irma Coulson P.S.	HB009		2021-03-23	Serena Romito	Jun-21	NSMOMO
Iroquois Ridge H.S.	HB145	6	2021-04-05	Erin Kulikowski	Jun-21	Caulking separating around conduits
Iroquois Ridge H.S.	HB088		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
Iroquois Ridge H.S.	HB202		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
Iroquois Ridge H.S.	HB209		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
Iroquois Ridge H.S.	HBL264		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
Iroquois Ridge H.S.	HB070		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
J.W. Singleton ED. CTR.	HB119	4	2021-03-25	Erin Kulikowski	Jun-21	Level 1 remediation: one water stained ceiling tile due to roof leak.
J.W. Singleton ED. CTR.	HB118		2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
J.W. Singleton ED. CTR.	HB117		2021-03-25	Erin Kulikowski	Jun-21	Level 1 - one water stained ceiling tile due to roof leak
J.W. Singleton ED. CTR.	HB003		2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
John T. Tuck P.S.	HBL220	5	2021-03-24	Serena Romito	Jun-21	NSMOMO
John T. Tuck P.S.	HB173		2021-03-24	Erin Kulikowski	Jun-21	Many damaged and lifting floor tiles
John T. Tuck P.S.	HB157		2021-03-24	Erin Kulikowski	Jun-21	NSMOMO
John T. Tuck P.S.	HB156		2021-03-24	Erin Kulikowski	Jun-21	NSMOMO
John T. Tuck P.S.	HB064		2021-03-24	Erin Kulikowski	Jun-21	NSMOMO
James W. Hill P.S.	HB050	6	2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
James W. Hill P.S.	HB086		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
James W. Hill P.S.	HB080		2021-04-05	Erin Kulikowski	Jun-21	Lifting vinyl floor tiles throughout
James W. Hill P.S.	HB099		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
James W. Hill P.S.	HB176		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
James W. Hill P.S.	HB107		2021-04-05	Erin Kulikowski	Jun-21	NSMOMO
Joshua Creek P.S.	HB161	5	2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
Joshua Creek P.S.	HB155		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
Joshua Creek P.S.	HB077		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
Joshua Creek P.S.	HB011		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
Joshua Creek P.S.	HB085		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
Killbide P.S.	HB074	1	2021-03-24	Erin Kulikowski	Jun-21	NSMOMO
Milton District H.S.	HB154	5	2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Milton District H.S.	HB093		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Milton District H.S.	HB041		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Milton District H.S.	HBL223		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Milton District H.S.	HB001		2021-03-09	Erin Kulikowski	Jun-21	NSMOMO
Montclair P.S.	HBL210	1	2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
Munn's P.S.	HBL001	2	2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
Munn's P.S.	HBL002		2021-03-25	Erin Kulikowski	Jun-21	Caulking starting to crack around window corners
New Central P.S.	HB104	2	2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
New Central P.S.	HB079		2021-03-29	Erin Kulikowski	Jun-21	Level 1 remediation: wet vinyl floor tiles present at entrance to door.
Oakville Trafalgar H.S.	RM190	11	2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM191		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM192		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM193		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM194		2021-03-23	Erin Kulikowski	Jun-21	Lifting vinyl floor tiles throughout
Oakville Trafalgar H.S.	RM189A		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM189B		2021-03-23	Erin Kulikowski	Jun-21	Lifting vinyl floor tiles in the middle of room
Oakville Trafalgar H.S.	RM195		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM196		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM197		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oakville Trafalgar H.S.	RM198		2021-03-23	Erin Kulikowski	Jun-21	NSMOMO
Oodenawi P.S.	HB094	11	2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HBL248		2021-03-30	Evan Faubert	Jun-21	Missing conduit casing lids.
Oodenawi P.S.	HB171		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HBL086		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HB175		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HB058		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HB101		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HBL260		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HB044		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HB067		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Oodenawi P.S.	HB096		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Pilgrim Woods P.S.	HB006	3	2021-04-06	Evan Faubert	Jun-21	NSMOMO
Pilgrim Woods P.S.	HBL087		2021-04-06	Evan Faubert	Jun-21	Missing I.D. plate.
Pilgrim Woods P.S.	HBL267		2021-04-06	Evan Faubert	Jun-21	NSMOMO
P.L. Robertson P.S.	HBL091	8	2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
P.L. Robertson P.S.	HB039		2021-03-12	Erin Kulikowski	Jun-21	NSMOMO
P.L. Robertson P.S.	HB022		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
P.L. Robertson P.S.	HB016		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
P.L. Robertson P.S.	HB030		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
P.L. Robertson P.S.	HB021		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
P.L. Robertson P.S.	HB027		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO
P.L. Robertson P.S.	HB004		2021-03-15	Erin Kulikowski	Jun-21	NSMOMO

**Portable Classroom Preventative Inspection Round 114**

School	Portable Number	Portables on Site	Round 114 Inspection Date	Pinchin Inspector	Proposed Round 115 Inspection Date	Comments from Round 114 Inspection
Palermo P.S.	HB167	1	2021-03-10	Evan Faubert	Jun-21	Conduit hole in east exterior cladding where power cable penetrates. Missing caulking at conduits at NE corner.
Pauline Johnson P.S.	HB102	3	2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Pauline Johnson P.S.	HBL222		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Pauline Johnson P.S.	HB024		2021-03-04	Erin Kulikowski	Jun-21	NSMOMO
Posts Corners P.S.	HBL007	11	2021-03-30	Evan Faubert	Jun-21	No caulking around conduits.
Posts Corners P.S.	HBL102		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HB129		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HBL006		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HBL218		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HBL255		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HBL211		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HB123		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HB180		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HBL268		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Posts Corners P.S.	HBL269		2021-03-30	Evan Faubert	Jun-21	NSMOMO
Sam Sherratt P.S.	HB082	6	2021-03-30	Serena Romito	Jun-21	Level 1 - Water stained ceiling tile due to condensation
Sam Sherratt P.S.	HB083		2021-03-30	Serena Romito	Jun-21	Level 1 - Water stained ceiling tile due to condensation
Sam Sherratt P.S.	HB066		2021-03-30	Serena Romito	Jun-21	Key doesn't work. Exterior inspection only. Degraded caulking around windows.
Sam Sherratt P.S.	HB127		2021-03-30	Serena Romito	Jun-21	NSMOMO
Sam Sherratt P.S.	HBL099		2021-03-30	Serena Romito	Jun-21	NSMOMO
Sam Sherratt P.S.	HB032		2021-03-30	Serena Romito	Jun-21	Damaged drywall walls at west seam. 3 missing floor tiles. degraded caulking at hvac louvre and conduits. gap in west gable fascia and soffitt
Tiger Jeet Singh P.S.	HB029	11	2021-03-18	Erin Kulikowski	Jun-21	No caulking around conduits
Tiger Jeet Singh P.S.	HBL079		2021-03-18	Erin Kulikowski	Jun-21	NSMOMO
Tiger Jeet Singh P.S.	HBL108		2021-03-18	Erin Kulikowski	Jun-21	NSMOMO
Tiger Jeet Singh P.S.	HB116		2021-03-18	Erin Kulikowski	Jun-21	Level 1 remediation: one water stained ceiling tile due to pest urine
Tiger Jeet Singh P.S.	HB187		2021-03-18	Erin Kulikowski	Jun-21	NSMOMO
Tiger Jeet Singh P.S.	HB095		2021-03-18	Erin Kulikowski	Jun-21	NSMOMO
Tiger Jeet Singh P.S.	HBL098		2021-03-18	Erin Kulikowski	Jun-21	NSMOMO
Tiger Jeet Singh P.S.	HBL013		2021-03-18	Erin Kulikowski	Jun-21	No caulking around conduits
Tiger Jeet Singh P.S.	HB109		2021-03-18	Erin Kulikowski	Jun-21	NSMOMO
Tiger Jeet Singh P.S.	HB063		2021-03-19	Erin Kulikowski	Jun-21	NSMOMO
Tiger Jeet Singh P.S.	HB126		2021-03-18	Erin Kulikowski	Jun-21	NSMOMO
Tom Thomson P.S.	HB124	7	2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Tom Thomson P.S.	HB031		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Tom Thomson P.S.	HB105		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Tom Thomson P.S.	HBL109		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Tom Thomson P.S.	HB141		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Tom Thomson P.S.	HB012		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Tom Thomson P.S.	HB098		2021-03-08	Erin Kulikowski	Jun-21	NSMOMO
Viola Desmond P.S.	HBL270	18	2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL271		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL272		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL273		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL274		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL275		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL276		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL277		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL278		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL279		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL280		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL281		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL282		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL283		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL284		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL285		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL286		2021-03-08	Serena Romito	Jun-21	NSMOMO
Viola Desmond P.S.	HBL287		2021-03-08	Serena Romito	Jun-21	NSMOMO
W.H. Morden P.S.	HB138	7	2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
W.H. Morden P.S.	HB200		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
W.H. Morden P.S.	HBL201		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
W.H. Morden P.S.	HBL250		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
W.H. Morden P.S.	HB199		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
W.H. Morden P.S.	HBL249		2021-03-29	Erin Kulikowski	Jun-21	NSMOMO
W.H. Morden P.S.	HB055		2021-03-29	Erin Kulikowski	Jun-21	Level 1 remediation: wet vinyl floor tiles. Lifting vinyl floor tiles throughout
W.I Dick P.S.	HB183	3	2021-03-10	Erin Kulikowski	Jun-21	NSMOMO
W.I Dick P.S.	HB007		2021-03-10	Erin Kulikowski	Jun-21	Key wouldn't work. Couldn't get ahold of custodian. Outside good.
W.I Dick P.S.	HB002		2021-03-10	Erin Kulikowski	Jun-21	Key wouldn't work. Could not get ahold of janitor. Outside is good
West Oak P.S.	RM1	6	2021-04-06	Evan Faubert	Jun-21	Split/Degraded caulking between exterior wall veneer panels
West Oak P.S.	RM2		2021-04-06	Evan Faubert	Jun-21	Split/Degraded caulking between exterior wall veneer panels
West Oak P.S.	RM3		2021-04-06	Evan Faubert	Jun-21	Split/Degraded caulking between exterior wall veneer panels
West Oak P.S.	RM4		2021-04-06	Evan Faubert	Jun-21	Split/Degraded caulking between exterior wall veneer panels
West Oak P.S.	RM5		2021-04-06	Evan Faubert	Jun-21	Split/Degraded caulking between exterior wall veneer panels
West Oak P.S.	RM6		2021-04-06	Evan Faubert	Jun-21	Split/Degraded caulking between exterior wall veneer panels
White Oaks N. H.S.	HB060	5	2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
White Oaks N. H.S.	HBL092		2021-03-25	Erin Kulikowski	Jun-21	No caulking around conduits. Caulking around windows starting to crack and separate.
White Oaks N. H.S.	HBL093		2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
White Oaks N. H.S.	HBL094		2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
White Oaks N. H.S.	HBL095		2021-03-25	Erin Kulikowski	Jun-21	NSMOMO
White Oaks South H.S.	HB054	16	2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HB042		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HBL096		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HBL097		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HBL016		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HBL017		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HBL018		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HB130		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HBL261		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HB078		2021-03-22	Serena Romito	Jun-21	NSMOMO

**Portable Classroom Preventative Inspection Round 114**

School	Portable Number	Portables on Site	Round 114 Inspection Date	Pinchin Inspector	Proposed Round 115 Inspection Date	Comments from Round 114 Inspection
White Oaks South H.S.	HB205		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HB023		2021-03-22	Serena Romito	Jun-21	Level 1 - One water stained ceiling tile due to condensation.
White Oaks South H.S.	HB153		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HB112		2021-03-22	Serena Romito	Jun-21	Missing downspout near front door
White Oaks South H.S.	HB201		2021-03-22	Serena Romito	Jun-21	NSMOMO
White Oaks South H.S.	HBL085		2021-03-22	Serena Romito	Jun-21	NSMOMO