

Portable Classroom - Preventative Inspection Round 115

School	Portable Number	Portables on Site	Round 115 Inspection Date	Pinchin Inspector	Proposed Round 116 Inspection Date	Moisture/ Mould found?	Comments from Round 115 Inspection
Abbey Park H.S.	HB164	12	2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1 - Wet floor tiles due to HVAC leaking
Abbey Park H.S.	HB163		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Abbey Park H.S.	HB108		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1 - Water impacted floor tiles due to HVAC leak
Abbey Park H.S.	HB177		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1 - water impacted floor tiles due HVAC leaking.
Abbey Park H.S.	HBL213		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Abbey Park H.S.	HBL227		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1- water impacted floor tiles due to HVAC leak
Abbey Park H.S.	HB043		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Abbey Park H.S.	HB131		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Abbey Park H.S.	HB072		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1- water impacted floor tiles due to HVAC leaking
Abbey Park H.S.	HB053		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Abbey Park H.S.	HB206		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Abbey Park H.S.	HBL224		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Alton Village P.S.	HB169	12	2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Alton Village P.S.	HBL225		2021-06-09	Erin Kulikowski	Sep-21	N	Occupied- online teaching. Rotting cladding at bottom of door frame.
Alton Village P.S.	HB068		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Alton Village P.S.	HB037		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1- wet floor tiles at entrance
Alton Village P.S.	HB140		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1- 1 water stained ceiling tile due to condensation on I beam
Alton Village P.S.	HBL247		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Alton Village P.S.	HBL237		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Alton Village P.S.	HBL238		2021-06-09	Erin Kulikowski	Sep-21	N	Lifting and damaged floor tiles throughout
Alton Village P.S.	HBL239		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Alton Village P.S.	HBL234		2021-06-09	Erin Kulikowski	Sep-21	N	Interior in-accessible - online teaching. Outside of portable NSMOMO
Alton Village P.S.	HBL235		2021-06-09	Erin Kulikowski	Sep-21	N	Rotting cladding beneath door.
Alton Village P.S.	HBL236		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 3- Rotten subfloor, tiles lifted and mould present under floor tiles by HVAC unit
Anne J. MacArthur P.S.	HBL215	15	2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL214		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HB174		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL219		2021-06-23	Erin Kulikowski	Sep-21	Y	Level 1 - Wet floor tile in front of HVAC unit due to HVAC unit leaking.
Anne J. MacArthur P.S.	HBL216		2021-06-23	Erin Kulikowski	Sep-21	N	Cracking caulking around window corners.
Anne J. MacArthur P.S.	HBL221		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HB111		2021-06-23	Erin Kulikowski	Sep-21	N	Screw holes in cladding to right of door.
Anne J. MacArthur P.S.	HB061		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HB165		2021-06-23	Erin Kulikowski	Sep-21	N	Damaged floor tiles along the center of the room.
Anne J. MacArthur P.S.	HBL202		2021-06-23	Erin Kulikowski	Sep-21	N	Portable occupied due to virtual teaching. Damaged downspout
Anne J. MacArthur P.S.	HBL203		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL204		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL205		2021-06-23	Erin Kulikowski	Sep-21	Y	Level 1 - 8 water stained ceiling tiles and wet insulation in ceiling space due to possible roof leak
Anne J. MacArthur P.S.	HBL232		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL233		2021-06-23	Erin Kulikowski	Sep-21	Y	Level 1 - wet floor tiles around HVAC unit due to HVAC unit leaking
Boyne P.S.	HBL106	18	2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HB208		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HB033		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HBL110		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HBL241		2021-06-28	Serena Romito	Sep-21	Y	Level 1 - Water stained ceiling tile.
Boyne P.S.	HB028		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HBL226		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HBL257		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HB179		2021-06-28	Serena Romito	Sep-21	Y	Level 1 - Water stained ceiling tile. Number plate missing.
Boyne P.S.	HBL251		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HBL253		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HB152		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HB015		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HBL254		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	HBL252		2021-06-28	Serena Romito	Sep-21	N	NSMOMO
Boyne P.S.	Unlabeled - South		2021-06-28	Serena Romito	Sep-21	N	Unlabeled portable. Very strong odour from off-gassing of new finishes.
Boyne P.S.	Unlabeled - Centre		2021-06-28	Serena Romito	Sep-21	N	Unlabeled portable. Very strong odour from off-gassing of new finishes.
Boyne P.S.	Unlabeled - North		2021-06-28	Serena Romito	Sep-21	N	Unlabeled portable. Very strong odour from off-gassing of new finishes.
Bruce Trail P.S.	HBL206	16	2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HBL262		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HBL107		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HB075		2021-07-05	Erin Kulikowski	Sep-21	N	Screw holes in cladding at W corner
Bruce Trail P.S.	HB181		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HB103		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO

Portable Classroom - Preventative Inspection Round 115

School	Portable Number	Portables on Site	Round 115 Inspection Date	Pinchin Inspector	Proposed Round 116 Inspection Date	Moisture/ Mould found?	Comments from Round 115 Inspection
Bruce Trail P.S.	HB110		2021-07-05	Erin Kulikowski	Sep-21	Y	Level 1 - water impacted floor tiles around HVAC unit due to HVAC unit leaking
Bruce Trail P.S.	HB046		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HB114		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HB062		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HBL105		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HB115		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HBL231		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HBL230		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HBL228		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Bruce Trail P.S.	HBL229		2021-07-05	Erin Kulikowski	Sep-21	N	NSMOMO
Captain R Wilson PS	HB036	7	2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Captain R. Wilson P.S.	HB047		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Captain R. Wilson P.S.	HB106		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Captain R. Wilson P.S.	HB065		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Captain R. Wilson P.S.	HB014		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Captain R. Wilson P.S.	HBL217		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Captain R. Wilson P.S.	HB087		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Chris Hadfield P.S.	HBL266	18	2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	HB051		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	HB034		2021-06-10	Evan Faubert	Sep-21	N	Holes in both south corners of cladding.
Chris Hadfield P.S.	HB168		2021-06-10	Evan Faubert	Sep-21	N	Open conduit cover.
Chris Hadfield P.S.	HB035		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	HBL259		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	HBL265		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A10		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A09		2021-06-10	Evan Faubert	Sep-21	N	Degraded caulking at exterior windows.
Chris Hadfield P.S.	RM A08		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A07		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A06		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A05		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A04		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A03		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A02		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	RM A01		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Chris Hadfield P.S.	HB036		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB128	16	2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB113		2021-07-02	Evan Faubert	Sep-21	N	Portable under construction.
Craig Kielburger S.S.	HB147		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB132		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB073		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB143		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB133		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB203		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB134		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB057		2021-06-04	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HB159		2021-07-02	Evan Faubert	Sep-21	N	NSMOMO
Craig Kielburger S.S.	HBL014		2021-07-02	Evan Faubert	Sep-21	N	No caulking around conduit.
Craig Kielburger S.S.	HBL015		2021-07-02	Evan Faubert	Sep-21	N	Caulking separating at windows.
Craig Kielburger S.S.	HB125		2021-07-05	Evan Faubert	Sep-21	N	Portable under construction.
Craig Kielburger S.S.	HBL084		2021-07-02	Evan Faubert	Sep-21	N	Portable under construction.
Craig Kielburger S.S.	HB132		2021-07-02	Evan Faubert	Sep-21	N	Portable under construction.
Dr. Frank Hayden S.S.	HB059	9	2021-07-02	Erin Kulikowski	Sep-21	N	NSMOMO
Dr. Frank Hayden S.S.	HB120		2021-07-02	Erin Kulikowski	Sep-21	Y	Level 1- one water stained ceiling tile due to mouse urine.
Dr. Frank Hayden S.S.	HB172		2021-07-02	Erin Kulikowski	Sep-21	N	NSMOMO
Dr. Frank Hayden S.S.	HB092		2021-07-02	Erin Kulikowski	Sep-21	N	Caulking missing on top of HVAC louvre
Dr. Frank Hayden S.S.	HB010		2021-07-02	Erin Kulikowski	Sep-21	Y	Level 2- damp and water damaged floor tiles in front of door. Mould present on drywall wall at left corner of door (2ft)
Dr. Frank Hayden S.S.	HBL256		2021-07-02	Erin Kulikowski	Sep-21	N	NSMOMO
Dr. Frank Hayden S.S.	HB137		2021-07-02	Erin Kulikowski	Sep-21	N	NSMOMO
Dr. Frank Hayden S.S.	HB207		2021-07-02	Erin Kulikowski	Sep-21	N	Damaged window screens
Dr. Frank Hayden S.S.	HB151		2021-07-02	Erin Kulikowski	Sep-21	N	Screw holes in cladding at down spout. Louvres are damaged on south side.
E.J. James P.S.	HB121	1	2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
E.W. Foster P.S.	HB189	1	2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Emily Carr P.S.	HB084	4	2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Emily Carr P.S.	HB040		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Emily Carr P.S.	HB008		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO

Portable Classroom - Preventative Inspection Round 115

School	Portable Number	Portables on Site	Round 115 Inspection Date	Pinchin Inspector	Proposed Round 116 Inspection Date	Moisture/ Mould found?	Comments from Round 115 Inspection
Emily Carr P.S.	HBL008		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Escarpment View P.S.	HBL090	12	2021-06-22	Erin Kulikowski	Sep-21	N	Caulking starting to crack around window corners
Escarpment View P.S.	HBL103		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Escarpment View P.S.	HBL104		2021-06-22	Erin Kulikowski	Sep-21	N	Caulking starting to crack around window corners
Escarpment View P.S.	HB144		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Escarpment View P.S.	HB005		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Escarpment View P.S.	HB089		2021-06-22	Erin Kulikowski	Sep-21	Y	Level 1 - water impacted floor tiles due to HVAC leak.
Escarpment View P.S.	HBL082		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Escarpment View P.S.	HBL081		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Escarpment View P.S.	HB056		2021-06-22	Erin Kulikowski	Sep-21	Y	Level 1: water impacted floor tiles at front entrance to portable.
Escarpment View P.S.	HBL088		2021-06-22	Erin Kulikowski	Sep-21	N	Caulking starting to crack around window corners
Escarpment View P.S.	HBL089		2021-06-22	Erin Kulikowski	Sep-21	N	Damaged downspout
Escarpment View P.S.	HBL083		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Ethel Gardiner P.S.	HB049	5	2021-06-29	Erin Kulikowski	Sep-21	Y	Level 1 remediation - Wet drywall wall at bottom corners of front door.
Ethel Gardiner P.S.	HBL212		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
Ethel Gardiner P.S.	HBL207		2021-06-29	Erin Kulikowski	Sep-21	Y	Level 1 remediation - Wet floor tiles around HVAC unit due to HVAC unit leaking
Ethel Gardiner P.S.	HBL263		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
Ethel Gardiner P.S.	HBL101		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
Florence Meares P.S.	HB069	3	2021-06-04	Erin Kulikowski	Sep-21	N	Caulking degrading around windows
Florence Meares P.S.	HBL100		2021-06-04	Erin Kulikowski	Sep-21	N	NSMOMO
Florence Meares P.S.	HB139		2021-06-04	Erin Kulikowski	Sep-21	N	NSMOMO
Garth Webb S.S.	HBL080	12	2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Garth Webb S.S.	HBL258		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Garth Webb S.S.	HB038		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO - Portable under construction
Garth Webb S.S.	HB045		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO - portable under construction
Garth Webb S.S.	HBL009		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Garth Webb S.S.	HBL005		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Garth Webb S.S.	HB090		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO - portable under construction
Garth Webb S.S.	HB052		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO - portable under construction
Garth Webb S.S.	HB076		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO - portable under construction
Garth Webb S.S.	HB100		2021-06-14	Erin Kulikowski	Sep-21	N	Holes in cladding where conduits are - portable under construction
Garth Webb S.S.	HB135		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO - portable under construction
Garth Webb S.S.	HB091		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO - portable under construction
Glen Williams P.S.	HB184	2	2021-06-29	Erin Kulikowski	Sep-21	Y	Level 1 - wet and water damaged floor tiles at entrance to portable
Glen Williams P.S.	HB178		2021-06-29	Erin Kulikowski	Sep-21	Y	Level 1 remediation - wet roof tile around HVAC unit due to HVAC unit leaking
Glenview P.S.	HB122	2	0000-00-00	Erin Kulikowski	Sep-21	N	Hole in cladding NW corner
Glenview P.S.	HB148		0000-00-00	Erin Kulikowski	Sep-21	N	Screw holes in N and E corner cladding
Hawthorne Village P.S.	RM301	13	2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM302		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM303		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM304		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM305		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM306		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM307		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM308		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM309		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	RM310		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	HB162		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	HB013		2021-06-22	Erin Kulikowski	Sep-21	N	NSMOMO
Hawthorne Village P.S.	HB136		2021-06-22	Erin Kulikowski	Sep-21	Y	Level 3: wet insulation and drywall in inspection port. Wet drywall beneath inspection port. Mould present at baseboards approx. 2 ft ² .
Irma Coulson P.S.	HBL246	17	2021-06-10	Evan Faubert	Sep-21	N	Degraded caulking around windows and HVAC louvre, missing conduit cover with exposed wiring.
Irma Coulson P.S.	HBL245		2021-06-11	Evan Faubert	Sep-21	N	Key doesn't work. Exterior inspection only.
Irma Coulson P.S.	HBL244		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB142		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HBL243		2021-06-11	Evan Faubert	Sep-21	N	Degraded caulking at windows and doors.
Irma Coulson P.S.	HBL242		2021-06-11	Evan Faubert	Sep-21	N	Degraded caulking at HVAC louvre.
Irma Coulson P.S.	HB195		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB149		2021-06-11	Evan Faubert	Sep-21	N	Degraded caulking around HVAC louvre.
Irma Coulson P.S.	HB196		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB158		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB166		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB081		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB150		2021-06-11	Evan Faubert	Sep-21	N	Degraded caulking at door. Screw holes in cladding left of door.
Irma Coulson P.S.	HB204		2021-06-11	Evan Faubert	Sep-21	N	Degraded window caulking.

Portable Classroom - Preventative Inspection Round 115

School	Portable Number	Portables on Site	Round 115 Inspection Date	Pinchin Inspector	Proposed Round 116 Inspection Date	Moisture/ Mould found?	Comments from Round 115 Inspection
Irma Coulson P.S.	HBL111		2021-06-11	Serena Romito	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB146		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Irma Coulson P.S.	HB009		2021-06-11	Evan Faubert	Sep-21	N	NSMOMO
Iroquois Ridge H.S.	HB145	6	2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Iroquois Ridge H.S.	HB088		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Iroquois Ridge H.S.	HB202		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Iroquois Ridge H.S.	HB070		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Iroquois Ridge H.S.	HB209		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Iroquois Ridge H.S.	HB264		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
J.W. Singleton Ed. Ctr.	HB119	4	2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
J.W. Singleton Ed. Ctr.	HB118		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
J.W. Singleton Ed. Ctr.	HB117		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
J.W. Singleton Ed. Ctr.	HB003		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
James W. Hill P.S.	HB050	6	2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
James W. Hill P.S.	HB086		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
James W. Hill P.S.	HB080		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
James W. Hill P.S.	HB099		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
James W. Hill P.S.	HB176		2021-06-14	Erin Kulikowski	Sep-21	Y	Level 1 - water impacted floor tiles at entrance to portable
James W. Hill P.S.	HB107		2021-06-14	Serena Romito	Sep-21	N	NSMOMO
John T. Tuck P.S.	HBL220	5	2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
John T. Tuck P.S.	HB173		2021-06-08	Erin Kulikowski	Sep-21	N	Rotting cladding under door.
John T. Tuck P.S.	HB157		2021-06-08	Erin Kulikowski	Sep-21	N	Portable occupied due to online teaching. Outside of portable NSMOMO
John T. Tuck P.S.	HB156		2021-06-08	Erin Kulikowski	Sep-21	N	Occupied due to online teaching. Cladding under door is rotting.
John T. Tuck P.S.	HB064		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
Joshua Creek P.S.	HB085	5	2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Joshua Creek P.S.	HB011		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Joshua Creek P.S.	HB077		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Joshua Creek P.S.	HB155		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Joshua Creek P.S.	HB161		2021-06-14	Erin Kulikowski	Sep-21	N	Downspout is draining onto wooden support - likely for wood rot to form.
Kilbride P.S.	HB074	1	2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
Milton District H.S.	HB154	5	2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Milton District H.S.	HB093		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Milton District H.S.	HB041		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Milton District H.S.	HBL223		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
Milton District H.S.	HB001		2021-06-23	Erin Kulikowski	Sep-21	N	Missing soffit at front of portable
Montclair P.S.	HBL210	1	2021-06-11	Erin Kulikowski	Sep-21	N	Damaged downspout
Munn's P.S.	HBL001	2	2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Munn's P.S.	HBL002		2021-06-11	Erin Kulikowski	Sep-21	N	Caulking around window corners beginning to crack
New Central P.S.	HB079	2	2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
New Central P.S.	HB104		2021-06-11	Erin Kulikowski	Sep-21	Y	Level 1 - water impacted floor tiles at entrance to portable.
Oakville Trafalgar H.S.	RM190	11	2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM191		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM192		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM193		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM194		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM189A		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM189B		2021-06-14	Erin Kulikowski	Sep-21	Y	Level 1 - Two water stained ceiling tiles due to condensation on sprinkler line
Oakville Trafalgar H.S.	RM195		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM196		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM197		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oakville Trafalgar H.S.	RM198		2021-06-14	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HB058	11	2021-06-15	Erin Kulikowski	Sep-21	N	Rotting wooden door frame
Oodenawi P.S.	HB101		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HBL260		2021-06-15	Erin Kulikowski	Sep-21	N	Caulking around window corners starting to crack
Oodenawi P.S.	HBL248		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HB171		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HB175		2021-06-15	Erin Kulikowski	Sep-21	N	Missing flashing at top of roof on west side. Hole in door visible to indoors.
Oodenawi P.S.	HBL086		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HB067		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HB044		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HB094		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
Oodenawi P.S.	HB096		2021-06-15	Erin Kulikowski	Sep-21	N	NSMOMO
P.L. Robertson P.S.	HB004	8	2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
P.L. Robertson P.S.	HB027		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
P.L. Robertson P.S.	HB021		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
P.L. Robertson P.S.	HB030		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO

Portable Classroom - Preventative Inspection Round 115

School	Portable Number	Portables on Site	Round 115 Inspection Date	Pinchin Inspector	Proposed Round 116 Inspection Date	Moisture/ Mould found?	Comments from Round 115 Inspection
P.L Robertson P.S.	HB016		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
P.L Robertson P.S.	HB022		2021-06-29	Erin Kulikowski	Sep-21	N	NSMOMO
P.L Robertson P.S.	HB039		2021-06-29	Erin Kulikowski	Sep-21	Y	Level 1 remediation - Wet floor tile around HVAC unit due to HVAC leaking. Wet drywall wall to 1 foot in height from left of HVAC unit to inspection port. Wet floor tiles in front of portable entrance.
P.L Robertson P.S.	HBL091		2021-06-29	Erin Kulikowski	Sep-21	N	Screw holes in cladding NW corner
Palermo P.S.	HB167	1	2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Pauline Johnson P.S.	HB024	3	2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1 - Wet and water damaged floor tiles at entrance
Pauline Johnson P.S.	HBL222		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Pauline Johnson P.S.	HB102		2021-06-09	Erin Kulikowski	Sep-21	Y	Level 1 - wet and water damaged floor tiles at entrance
Pilgrim Wood P.S.	HB006	3	2021-06-09	Erin Kulikowski	Sep-21	N	Damaged downspout
Pilgrim Wood P.S.	HBL267		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Pilgrim Wood P.S.	HBL087		2021-06-09	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HBL102	11	2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HB180		2021-06-11	Erin Kulikowski	Sep-21	Y	Level 1 - water impacted floor tiles due to HVAC unit leaking.
Post's Corners P.S.	HB129		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HBL006		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HBL218		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HBL255		2021-06-11	Erin Kulikowski	Sep-21	Y	Level 1 - Water impacted floor tiles in front of HVAC unit due to HVAC unit leaking.
Post's Corners P.S.	HBL211		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HBL007		2021-06-11	Erin Kulikowski	Sep-21	N	Caulking around windows starting to crack.
Post's Corners P.S.	HB123		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HBL269		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Post's Corners P.S.	HBL268		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
Sam Sherratt P.S.	HB082	6	2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Sam Sherratt P.S.	HB083		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Sam Sherratt P.S.	HB066		2021-06-10	Evan Faubert	Sep-21	N	Key doesn't work. Exterior inspection only.
Sam Sherratt P.S.	HB127		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Sam Sherratt P.S.	HBL099		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Sam Sherratt P.S.	HB032		2021-06-10	Evan Faubert	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB029	11	2021-06-24	Erin Kulikowski	Sep-21	N	Portable under construction. Missing cladding on north wall. No skirting around portable and no center metal plate on the floor inside the portable
Tiger Jeet Singh P.S.	HBL079		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HBL108		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HBL013		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HBL098		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB095		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB187		2021-06-24	Erin Kulikowski	Sep-21	Y	Level 1 - wet floor tiles around HVAC unit. Wet drywall wall at baseboards on west wall near HVAC unit. Floor tiles and sub floor are lifting.
Tiger Jeet Singh P.S.	HB116		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB109		2021-06-24	Erin Kulikowski	Sep-21	N	Occupied portable for virtual teaching. Outside of portable NSMOMO
Tiger Jeet Singh P.S.	HB063		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB126		2021-06-24	Erin Kulikowski	Sep-21	N	NSMOMO
Tom Thomson P.S.	HB124	7	2021-06-08	Erin Kulikowski	Sep-21	Y	Level 1 - wet floor tile at entrance and around HVAC unit
Tom Thomson P.S.	HB031		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
Tom Thomson P.S.	HB105		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
Tom Thomson P.S.	HB098		2021-06-08	Erin Kulikowski	Sep-21	N	Screw holes in cladding by stair hand rail
Tom Thomson P.S.	HBL109		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
Tom Thomson P.S.	HB141		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
Tom Thomson P.S.	HB012		2021-06-08	Erin Kulikowski	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL270	18	2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL271		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL272		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL273		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL274		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL275		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL276		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL277		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL278		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL279		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL280		2021-06-10	Serena Romito	Sep-21	Y	Level 1 - Water stained ceiling tile
Viola Desmond P.S.	HBL281		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL282		2021-06-10	Serena Romito	Sep-21	N	Damaged downspout front elevation
Viola Desmond P.S.	HBL283		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL284		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL285		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
Viola Desmond P.S.	HBL286		2021-06-10	Serena Romito	Sep-21	N	NSMOMO

Portable Classroom - Preventative Inspection Round 115

School	Portable Number	Portables on Site	Round 115 Inspection Date	Pinchin Inspector	Proposed Round 116 Inspection Date	Moisture/ Mould found?	Comments from Round 115 Inspection
Viola Desmond P.S.	HBL287		2021-06-10	Serena Romito	Sep-21	N	NSMOMO
W.H. Morden P.S.	HB199	7	2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
W.H. Morden P.S.	HB200		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
W.H. Morden P.S.	HBL201		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
W.H. Morden P.S.	HBL250		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
W.H. Morden P.S.	HBL249		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
W.H. Morden P.S.	HB055		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
W.H. Morden P.S.	HB138		2021-06-10	Erin Kulikowski	Sep-21	Y	Level 2- wet drywall wall to the left and right of the HVAC unit. Mould present at baseboards
W.I. Dick P.S.	HB183	3	2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
W.I. Dick P.S.	HB002		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
W.I. Dick P.S.	HB007		2021-06-23	Erin Kulikowski	Sep-21	N	NSMOMO
West Oak P.S.	RM1	6	2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
West Oak P.S.	RM2		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
West Oak P.S.	RM3		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
West Oak P.S.	RM4		2021-06-11	Erin Kulikowski	Sep-21	N	Occupied for online teaching
West Oak P.S.	RM5		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
West Oak P.S.	RM6		2021-06-11	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. North	HBL092	5	2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. North	HBL093		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. North	HBL094		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. North	HBL095		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. North	HB060		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HBL018	16	2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HBL017		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HBL016		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HB054		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HBL096		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HBL097		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HB042		2021-06-10	Erin Kulikowski	Sep-21	Y	Level 1 - Wet drywall wall to left of door
White Oaks S.S. South	HB023		2021-06-10	Erin Kulikowski	Sep-21	Y	Level 1 - Wet floor tiles at entrance
White Oaks S.S. South	HB205		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HB078		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HBL085		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HBL261		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HB130		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HB201		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HB112		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO
White Oaks S.S. South	HB153		2021-06-10	Erin Kulikowski	Sep-21	N	NSMOMO