

## Portable Classroom - Preventative Inspection Round 116

School	Portable Number	Portables on Site	Round 116 Inspection Date	Pinchin Inspector	Proposed Round 117 Inspection Date	Moisture/ Mould found?	Comments from Round 116 Inspection
Abbey Park H.S.	HB164	12	30-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Abbey Park H.S.	HB163		30-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Abbey Park H.S.	HB108		30-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Abbey Park H.S.	HB177		30-Sep-21	Serena Romito	Dec-21	N	Rear down spout damaged
Abbey Park H.S.	HBL213		30-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around windows
Abbey Park H.S.	HBL227		30-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Abbey Park H.S.	HB043		30-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Abbey Park H.S.	HB131		30-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Abbey Park H.S.	HB072		30-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around HVAC louvre
Abbey Park H.S.	HB053		30-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around window, door and HVAC louvre
Abbey Park H.S.	HB206		30-Sep-21	Serena Romito	Dec-21	Y	Level 1 - wet drywall near door due to degraded caulking around door
Abbey Park H.S.	HBL224		30-Sep-21	Serena Romito	Dec-21	Y	Level 1 - wet flooring around HVAC unit. Inspect for leaks within HVAC unit
Alton Village P.S.	HB169	10	18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HBL225		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HB068		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HB037		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HBL237		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HBL238		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HBL239		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HBL234		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Alton Village P.S.	HBL235		18-Oct-21	Evan Faubert	Dec-21	N	Rusting cladding beneath door.
Alton Village P.S.	HBL236		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL215	15	23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL214		23-Sep-21	Evan Faubert	Dec-21	N	Degraded caulking at windows.
Anne J. MacArthur P.S.	HB174		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL219		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL216		23-Sep-21	Evan Faubert	Dec-21	N	Cracked caulking at window corners.
Anne J. MacArthur P.S.	HBL221		23-Sep-21	Evan Faubert	Dec-21	Y	Interior Ceiling: Level 1 : 1 Water stained ceiling tile at south east corner.
Anne J. MacArthur P.S.	HB111		23-Sep-21	Evan Faubert	Dec-21	N	Screw holes in cladding to right and left of door.
Anne J. MacArthur P.S.	HB061		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HB165		23-Sep-21	Evan Faubert	Dec-21	N	Interior Floor: Damaged floor tiles along centre of the room.
Anne J. MacArthur P.S.	HBL202		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL203		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL204		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL205		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL232		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Anne J. MacArthur P.S.	HBL233		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL106	18	23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HB208		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HB033		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL110		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL241		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HB028		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL226		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL257		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HB179		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL251		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL253		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HB152		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HB015		23-Sep-21	Evan Faubert	Dec-21	N	Exterior: Missing caulking at new HVAC louvre.
Boyne P.S.	HBL254		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL252		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL291		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL292		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Boyne P.S.	HBL293		23-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HBL206	16	16-Sep-21	Evan Faubert	Dec-21	Y	Level 1: 2 Square feet of wet drywall below west window/ nearest to door.
Bruce Trail P.S.	HBL262		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HBL107		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HB075		16-Sep-21	Evan Faubert	Dec-21	N	Screw holes in cladding at W corner
Bruce Trail P.S.	HB181		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HB103		16-Sep-21	Evan Faubert	Dec-21	Y	Level 4: Wet and Mould impacted drywall near door, HVAC and east window. Up to 5 feet.
Bruce Trail P.S.	HB110		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HB046		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HB114		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HB062		16-Sep-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC condensate hose
Bruce Trail P.S.	HBL105		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HB115		16-Sep-21	Evan Faubert	Dec-21	N	Damaged caulking at conduit
Bruce Trail P.S.	HBL231		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HBL230		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HBL228		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Bruce Trail P.S.	HBL229		16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Captain R. Wilson P.S.	HB047	6	6-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around door. HVAC louvre covered. Missing railing.
Captain R. Wilson P.S.	HB106		6-Sep-21	Serena Romito	Dec-21	N	HVAC louvre covered. Missing railing.
Captain R. Wilson P.S.	HB065		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Captain R. Wilson P.S.	HB014		6-Sep-21	Serena Romito	Dec-21	N	Rear down spout misaligned
Captain R. Wilson P.S.	HBL217		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Captain R. Wilson P.S.	HB087		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HBL266	20	15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HB051		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO

## Portable Classroom - Preventative Inspection Round 116

School	Portable Number	Portables on Site	Round 116 Inspection Date	Pinchin Inspector	Proposed Round 117 Inspection Date	Moisture/ Mould found?	Comments from Round 116 Inspection
Chris Hadfield P.S.	HB034		15-Sep-21	Evan Faubert	Dec-21	N	Holes in both south corners of cladding. Degraded Caulking at HVAC
Chris Hadfield P.S.	HB168		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HB035		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HBL259		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HBL265		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A10		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A09		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A08		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A07		15-Sep-21	Evan Faubert	Dec-21	N	Degraded caulking at exterior windows
Chris Hadfield P.S.	RM A06		15-Sep-21	Evan Faubert	Dec-21	N	Degraded caulking at exterior windows
Chris Hadfield P.S.	RM A05		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A04		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A03		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A02		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	RM A01		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HB036		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HBL288		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Chris Hadfield P.S.	HBL289		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HB128	24	15-Oct-21	Evan Faubert	Dec-21	N	Degraded Caulking at HVAC, No caulking at HVAC condensate hose
Craig Kielburger S.S.	HB113		15-Oct-21	Evan Faubert	Dec-21	N	Missing Caulking at HVAC louvre and windows
Craig Kielburger S.S.	HB147		15-Oct-21	Evan Faubert	Dec-21	N	Missing Caulking at HVAC louvre and windows
Craig Kielburger S.S.	HB132		15-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at windows and HVAC louvre and conduit
Craig Kielburger S.S.	HB073		15-Oct-21	Evan Faubert	Dec-21	Y	Level 1: 1 Water stained ceiling tile near south side of portable. Missing caulking at sides of windows and conduits. Damaged skirting at west end.
Craig Kielburger S.S.	HB143		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HB133		15-Oct-21	Evan Faubert	Dec-21	N	Large hole in North exterior cladding
Craig Kielburger S.S.	HB203		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HB134		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HB057		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HB159		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HBL014		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HBL015		15-Oct-21	Evan Faubert	Dec-21	N	Caulking separating at windows.
Craig Kielburger S.S.	HB125		15-Oct-21	Evan Faubert	Dec-21	N	Screwholes in cladding left of door
Craig Kielburger S.S.	HBL084		15-Oct-21	Evan Faubert	Dec-21	N	Screwholes in door
Craig Kielburger S.S.	HB029		15-Oct-21	Evan Faubert	Dec-21	Y	Level 1 : Five water stained ceiling tiles below center beam
Craig Kielburger S.S.	HB140		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HB136		15-Oct-21	Evan Faubert	Dec-21	N	Screwholes left of door
Craig Kielburger S.S.	HBL098		15-Oct-21	Evan Faubert	Dec-21	N	Caulking separating at windows.
Craig Kielburger S.S.	HBL288		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HBL289		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HBL290		15-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Craig Kielburger S.S.	HBL312						Not installed yet
Craig Kielburger S.S.	HBL313						Not installed yet
Dr. David R. Williams P.S.	HBL300	12	9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL301		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL302		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL303		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL304		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL305		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL306		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL307		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL308		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL309		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL310		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. David R. Williams P.S.	HBL311		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Dr. Frank Hayden S.S.	HB059	9	18-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB120		18-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at exterior windows
Dr. Frank Hayden S.S.	HB172		18-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB092		18-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB010		18-Oct-21	Evan Faubert	Dec-21	Y	Level 2- Taped over mould present on drywall wall at left corner of door (2ft). Separating caulking at windows.
Dr. Frank Hayden S.S.	HBL256		18-Oct-21	Evan Faubert	Dec-21	N	Separating caulking at windows.
Dr. Frank Hayden S.S.	HB137		18-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB207		18-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB151		18-Oct-21	Evan Faubert	Dec-21	Y	Level 2- Wet drywall and mould growth on bottom foot of drywall wall on both sides of HVAC unit (3ft)
E.J. James P.S.	HB121	1	15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
E.W. Foster's P.S.	HB189	1	16-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Emily Carr P.S.	HB084	4	6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Emily Carr P.S.	HB040		6-Sep-21	Serena Romito	Dec-21	N	HVAC is being removed. No louvre flashing. Rear downspout misaligned
Emily Carr P.S.	HB008		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Emily Carr P.S.	HBL008		6-Sep-21	Serena Romito	Dec-21	N	Window screen damaged
Escarment View P.S.	HBL090	12	21-Sep-21	Evan Faubert	Dec-21	N	Degraded caulking at exterior windows
Escarment View P.S.	HBL103		21-Sep-21	Evan Faubert	Dec-21	N	Degraded caulking at exterior windows
Escarment View P.S.	HBL104		21-Sep-21	Evan Faubert	Dec-21	N	Missing caulking at NE air exchanger.
Escarment View P.S.	HB144		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Escarment View P.S.	HB005		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Escarment View P.S.	HB089		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Escarment View P.S.	HBL082		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Escarment View P.S.	HBL081		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO

## Portable Classroom - Preventative Inspection Round 116

School	Portable Number	Portables on Site	Round 116 Inspection Date	Pinchin Inspector	Proposed Round 117 Inspection Date	Moisture/ Mould found?	Comments from Round 116 Inspection
Escarpment View P.S.	HB056		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Escarpment View P.S.	HBL088		21-Sep-21	Evan Faubert	Dec-21	N	Degraded caulking at exterior windows
Escarpment View P.S.	HBL089		21-Sep-21	Evan Faubert	Dec-21	N	Damaged downspout
Escarpment View P.S.	HBL083		21-Sep-21	Evan Faubert	Dec-21	N	Degraded caulking at exterior HVAC
Ethel Gardner P.S.	HB049	5	14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Ethel Gardner P.S.	HBL212		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Ethel Gardner P.S.	HBL207		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Ethel Gardner P.S.	HBL263		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Ethel Gardner P.S.	HBL101		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Falgarwood P.S.	HB167	1	3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Florence Meares P.S.	HB069	3	18-Oct-21	Evan Faubert	Dec-21	N	Caulking degrading around windows
Florence Meares P.S.	HBL100		18-Oct-21	Evan Faubert	Dec-21	N	Under Construction
Florence Meares P.S.	HB139		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Garth Webb S.S.	HBL080	12	6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Garth Webb S.S.	HBL258		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Garth Webb S.S.	HB038		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Garth Webb S.S.	HB045		6-Sep-21	Serena Romito	Dec-21	Y	Level 1 - Wet drywall around HVAC unit. Inspect within HVAC unit for leaks.
Garth Webb S.S.	HBL009		6-Sep-21	Serena Romito	Dec-21	N	Portable relocated
Garth Webb S.S.	HBL005		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Garth Webb S.S.	HB090		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Garth Webb S.S.	HB052		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Garth Webb S.S.	HB076		6-Sep-21	Serena Romito	Dec-21	N	Rear down spout and eavestrough damaged
Garth Webb S.S.	HB100		6-Sep-21	Serena Romito	Dec-21	Y	Level 1 - water stained ceiling tile.
Garth Webb S.S.	HB135		6-Sep-21	Serena Romito	Dec-21	N	Missing flashing at top of walls front elevation
Garth Webb S.S.	HB091		6-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Glen Williams P.S.	HB184	2	14-Sep-21	Evan Faubert	Dec-21	Y	LEVEL 1 : Water stained ceiling tile and vapour barrier above north window
Glen Williams P.S.	HB178		14-Sep-21	Evan Faubert	Dec-21	N	Cracked caulking at east window. Missing caulking at HVAC condensate penetration
Glenview P.S.	HB166	3	20-Oct-21		Dec-21	N	Screwholes at NE corner cladding
Glenview P.S.	HB122		20-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Glenview P.S.	HB148		20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC condensate hose and cladding
Hawthorne Village P.S.	RM318	12	13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM302		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM303		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM304		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM305		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM306		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM307		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM308		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM309		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	RM310		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	HB162		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Hawthorne Village P.S.	HB013		13-Oct-21	Evan Faubert	Dec-21	N	louvre.
Irma Coulson P.S.	HBL246	15	8-Oct-21	Evan Faubert	Dec-21	N	Degraded calking around windows and HVAC louvre, missing conduit cover with exposed wiring.
Irma Coulson P.S.	HBL245		8-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Irma Coulson P.S.	HBL244		8-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Irma Coulson P.S.	HB142		8-Oct-21	Evan Faubert	Dec-21	N	Renovating
Irma Coulson P.S.	HBL243		8-Oct-21	Evan Faubert	Dec-21	N	Degraded caulking at windows and doors.
Irma Coulson P.S.	HBL242		8-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Irma Coulson P.S.	HB195		8-Oct-21	Evan Faubert	Dec-21	N	Holes in door
Irma Coulson P.S.	HB149		8-Oct-21	Evan Faubert	Dec-21	N	Holes in cladding near HVAC louvre
Irma Coulson P.S.	HB196		8-Oct-21	Evan Faubert	Dec-21	N	Screwholes in cladding near windows
Irma Coulson P.S.	HB081		8-Oct-21	Evan Faubert	Dec-21	N	Renovating
Irma Coulson P.S.	HB150		8-Oct-21	Evan Faubert	Dec-21	N	Degraded caulking at door. Screw holes in cladding left of door.
Irma Coulson P.S.	HB204		8-Oct-21	Evan Faubert	Dec-21	N	Degraded window caulking.
Irma Coulson P.S.	HBL111		8-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Irma Coulson P.S.	HB146		8-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Irma Coulson P.S.	HB009		8-Oct-21	Evan Faubert	Dec-21	N	Missing cover cladding at West end roof gable. Missing caulking at west HVAC conduit. Screw holes to the right of door.
Iroquois Ridge H.S.	HB145	6	14-Sep-21	Serena Romito	Dec-21	N	Missing railing
Iroquois Ridge H.S.	HB088		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Iroquois Ridge H.S.	HB202		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Iroquois Ridge H.S.	HB070		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Iroquois Ridge H.S.	HB209		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Iroquois Ridge H.S.	HBL264		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
J.W. Singleton Ed. Ctr.	HB119	4	22-Oct-21	Evan Faubert	Dec-21	Y	Level 1 - Water Stained Ceiling Tile, vapour barrier and insulation from a roof leak in the south east office
J.W. Singleton Ed. Ctr.	HB118		22-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
J.W. Singleton Ed. Ctr.	HB117		22-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
J.W. Singleton Ed. Ctr.	HB003		22-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
James W. Hill P.S.	HB050	6	14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
James W. Hill P.S.	HB086		14-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around door
James W. Hill P.S.	HB080		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
James W. Hill P.S.	HB099		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
James W. Hill P.S.	HB176		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
James W. Hill P.S.	HB107		14-Sep-21	Serena Romito	Dec-21	Y	Level 1 - water stained ceiling tile
John T. Tuck P.S.	HBL220	5	20-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at exterior windows, HVAC and condensate hose
John T. Tuck P.S.	HB173		20-Oct-21	Evan Faubert	Dec-21	N	Rusting cladding under door.
John T. Tuck P.S.	HB157		20-Oct-21	Evan Faubert	Dec-21	N	Large hole in west cladding from removed conduit

## Portable Classroom - Preventative Inspection Round 116

School	Portable Number	Portables on Site	Round 116 Inspection Date	Pinchin Inspector	Proposed Round 117 Inspection Date	Moisture/ Mould found?	Comments from Round 116 Inspection
John T. Tuck P.S.	HB156		20-Oct-21	Evan Faubert	Dec-21	N	Rusting cladding under door.
John T. Tuck P.S.	HB064		20-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Joshua Creek P.S.	HB085	5	14-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around door
Joshua Creek P.S.	HB011		14-Sep-21	Serena Romito	Dec-21	N	Front downspout is missing
Joshua Creek P.S.	HB077		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Joshua Creek P.S.	HB155		14-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Joshua Creek P.S.	HB161		14-Sep-21	Serena Romito	Dec-21	Y	Level 1 - Water stained ceiling tile. Erosion around rear footing.
Kilbride P.S.	HB074	1	18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Milton District H.S.	HB154	5	14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Milton District H.S.	HB093		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Milton District H.S.	HB041		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Milton District H.S.	HBL223		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Milton District H.S.	HB001		14-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Montclair P.S.	HBL210	1	21-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Munn's P.S.	HBL001	2	21-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around door
Munn's P.S.	HBL002		21-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around window
New Central P.S.	HB079	2	15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
New Central P.S.	HB104		15-Sep-21	Serena Romito	Dec-21	Y	Level 4 - Leaking around door, condensation from AC line, and potential leaks through HVAC and wall flashing resulting in impacted ceiling tile, 7 water stained ceiling tiles, impacted drywall, and impacted flooring. Repair degraded caulking around door.
Oakville Trafalgar H.S.	RM190	11	15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM191		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM192		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM193		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM194		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM189A		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM189B		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM195		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM196		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM197		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oakville Trafalgar H.S.	RM198		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HB058	11	9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HB101		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HBL260		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HBL248		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HB171		9-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around door
Oodenawi P.S.	HB175		9-Sep-21	Serena Romito	Dec-21	Y	Level 1 - 6 water stained ceiling tiles due to roof leak
Oodenawi P.S.	HBL086		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HB067		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HB044		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HB094		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
Oodenawi P.S.	HB096		9-Sep-21	Serena Romito	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HB004	9	21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HB027		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HB021		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HB030		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HB016		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HB022		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HB039		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HBL091		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
P.L. Robertson P.S.	HBL228		21-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Paul A. Fisher	HBL247	1	22-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Pauline Johnson P.S.	HB024	3	20-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at HVAC condensate hose
Pauline Johnson P.S.	HBL222		20-Oct-21	Evan Faubert	Dec-21	N	Inadequate caulking at HVAC condensate hose
Pauline Johnson P.S.	HB102		20-Oct-21	Evan Faubert	Dec-21	N	Separating caulking at windows.
Pilgrim Wood P.S.	HB006	3	21-Sep-21	Serena Romito	Dec-21	N	eavestrough
Pilgrim Wood P.S.	HBL267		21-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around windows
Pilgrim Wood P.S.	HBL087		21-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around windows
Post's Corners P.S.	HBL102	12	3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HB180		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HB129		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HBL006		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HBL218		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HBL255		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HBL211		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HBL007		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HB123		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HB158		3-Oct-21	Serena Romito	Dec-21	Y	Level 1 - water stained ceiling tile
Post's Corners P.S.	HBL269		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Post's Corners P.S.	HBL268		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
River Oaks P.S.	HBL294	2	3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
River Oaks P.S.	HBL295		3-Oct-21	Serena Romito	Dec-21	N	NSMOMO
Sam Sherrat P.S.	HB082	8	18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Sam Sherrat P.S.	HB083		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Sam Sherrat P.S.	HB066		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Sam Sherrat P.S.	HB127		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Sam Sherrat P.S.	HBL099		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Sam Sherrat P.S.	HB032		18-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Sam Sherrat P.S.	UNKN		18-Oct-21	Evan Faubert	Dec-21	N	UNTAGGED

## Portable Classroom - Preventative Inspection Round 116

School	Portable Number	Portables on Site	Round 116 Inspection Date	Pinchin Inspector	Proposed Round 117 Inspection Date	Moisture/ Mould found?	Comments from Round 116 Inspection
Sam Sherratt P.S.	UNKN		18-Oct-21	Evan Faubert	Dec-21	N	UNTAGGED
Tiger Jeet Singh P.S.	HBL079	9	13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Tiger Jeet Singh P.S.	HBL108		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Tiger Jeet Singh P.S.	HBL013		13-Oct-21	Evan Faubert	Dec-21	N	Separating caulking at windows and HVAC Louve
Tiger Jeet Singh P.S.	HB095		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB187		13-Oct-21	Evan Faubert	Dec-21	N	Separating caulking at windows
Tiger Jeet Singh P.S.	HB116		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB109		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB063		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Tiger Jeet Singh P.S.	HB126		13-Oct-21	Evan Faubert	Dec-21	N	NSMOMO
Tom Thomson P.S.	HB124	7	20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB031		20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB105		20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB098		20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HBL109		20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB141		20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB012		20-Oct-21	Evan Faubert	Dec-21	N	Missing caulking at HVAC and condensate hose at cladding
Viola Desmond P.S.	HBL270	18	22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL271		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL272		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL273		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL274		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL275		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL276		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL277		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL278		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL279		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL280		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL281		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL282		22-Sep-21	Evan Faubert	Dec-21	N	Damaged downspout at front elevation
Viola Desmond P.S.	HBL283		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL284		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL285		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL286		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
Viola Desmond P.S.	HBL287		22-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
W.H. Morden P.S.	HB199	7	15-Sep-21	Serena Romito	Dec-21	N	Damaged downspout
W.H. Morden P.S.	HB200		15-Sep-21	Serena Romito	Dec-21	Y	Level 1 - wet drywall near door. Inspect for leaks around door flashing once drywall removed.
W.H. Morden P.S.	HBL201		15-Sep-21	Serena Romito	Dec-21	N	Door not working
W.H. Morden P.S.	HBL250		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
W.H. Morden P.S.	HBL249		15-Sep-21	Serena Romito	Dec-21	N	NSMOMO
W.H. Morden P.S.	HB055		15-Sep-21	Serena Romito	Dec-21	N	Missing downspout
W.H. Morden P.S.	HB138		15-Sep-21	Serena Romito	Dec-21	Y	Level 4 - wet drywall and impacted flooring around HVAC unit. Inspect for leaks within HVAC unit.
W.I. Dick P.S.	HB183	3	15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
W.I. Dick P.S.	HB002		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
W.I. Dick P.S.	HB007		15-Sep-21	Evan Faubert	Dec-21	N	NSMOMO
West Oak P.S.	RM1	6	21-Sep-21	Serena Romito	Dec-21	N	NSMOMO
West Oak P.S.	RM2		21-Sep-21	Serena Romito	Dec-21	N	NSMOMO
West Oak P.S.	RM3		21-Sep-21	Serena Romito	Dec-21	N	NSMOMO
West Oak P.S.	RM4		21-Sep-21	Serena Romito	Dec-21	N	NSMOMO
West Oak P.S.	RM5		21-Sep-21	Serena Romito	Dec-21	N	NSMOMO
West Oak P.S.	RM6		21-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. North	HBL092	5	20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. North	HBL093		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. North	HBL094		20-Sep-21	Serena Romito	Dec-21	Y	Level 1 - water stained ceiling tile
White Oaks S.S. North	HBL095		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. North	HB060		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HBL018	16	20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HBL017		20-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around windows
White Oaks S.S. South	HBL016		20-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around windows
White Oaks S.S. South	HB054		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HBL096		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HBL097		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HB042		20-Sep-21	Serena Romito	Dec-21	N	Rear downspout misaligned
White Oaks S.S. South	HB023		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HB205		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HB078		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HBL085		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HBL261		20-Sep-21	Serena Romito	Dec-21	N	Degraded caulking around windows
White Oaks S.S. South	HB130		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HB201		20-Sep-21	Serena Romito	Dec-21	N	Damaged wall sheathing around conduits
White Oaks S.S. South	HB112		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO
White Oaks S.S. South	HB153		20-Sep-21	Serena Romito	Dec-21	N	NSMOMO