

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Abbey Park H.S.	HB164	12	7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HB163		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HB108		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HB177		7-Dec-21	Serena Romito	Mar-22	Damaged downspout rear elevation. Degraded caulking around door.
Abbey Park H.S.	HBL213		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HBL227		7-Dec-21	Serena Romito	Mar-22	Damaged rear eavestrough
Abbey Park H.S.	HB043		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HB131		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HB072		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HB053		7-Dec-21	Serena Romito	Mar-22	Degraded caulking around windows, door and HVAC louvre
Abbey Park H.S.	HB206		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Abbey Park H.S.	HBL224		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Captain R. Wilson P.S.	HB047	6	2-Dec-21	Serena Romito	Mar-22	Degraded caulking around door. Damaged spoutdown rear elevation
Captain R. Wilson P.S.	HB106		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Captain R. Wilson P.S.	HB065		2-Dec-21	Serena Romito	Mar-22	Level 1 - water stained ceiling tile
Captain R. Wilson P.S.	HB014		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Captain R. Wilson P.S.	HBL217		2-Dec-21	Serena Romito	Mar-22	Degraded caulking around windows.
Captain R. Wilson P.S.	HB087		2-Dec-21	Serena Romito	Mar-22	Level 1 - water stained ceiling tile
David R. Williams P.S.	HBL300	12	6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL301		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL302		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL303		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL304		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL305		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL306		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL307		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL308		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL309		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL310		6-Dec-21	Serena Romito	Mar-22	NSMOMO
David R. Williams P.S.	HBL311		6-Dec-21	Serena Romito	Mar-22	NSMOMO
E.J. James P.S.	HB121	1	13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Emily Carr P.S.	HB084	4	2-Dec-21	Serena Romito	Mar-22	Lifting vinyl floor tiles throughout
Emily Carr P.S.	HB040		2-Dec-21	Serena Romito	Mar-22	Damaged downspout rear elevation.
Emily Carr P.S.	HB008		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Emily Carr P.S.	HBL008		2-Dec-21	Serena Romito	Mar-22	Window screen damaged
Falgarwood P.S.	HB167	1	12-Jan-22	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HBL080	12	2-Dec-21	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HBL258		2-Dec-21	Serena Romito	Mar-22	NSMOMO

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Garth Webb S.S.	HB038		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HB045		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HBL005		2-Dec-21	Serena Romito	Mar-22	One damaged ceiling tile near door
Garth Webb S.S.	HB090		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HB052		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HB076		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HB100		2-Dec-21	Serena Romito	Mar-22	Level 1 - water damaged ceiling tile
Garth Webb S.S.	HB135		2-Dec-21	Serena Romito	Mar-22	Approximately 50 damaged vinyl floor tiles
Garth Webb S.S.	HB091		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Garth Webb S.S.	HBL085		2-Dec-21	Serena Romito	Mar-22	NSMOMO
Iroquois Ridge H.S.	HB145	6	11-Jan-22	Matt Pitman	Mar-22	Missing railing
Iroquois Ridge H.S.	HB088		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
Iroquois Ridge H.S.	HB202		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
Iroquois Ridge H.S.	HB070		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
Iroquois Ridge H.S.	HB209		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
Iroquois Ridge H.S.	HBL264		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
James W. Hill P.S.	HB050	6	11-Jan-22	Matt Pitman	Mar-22	NSMOMO
James W. Hill P.S.	HB086		11-Jan-22	Matt Pitman	Mar-22	Degraded caulking around door
James W. Hill P.S.	HB080		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
James W. Hill P.S.	HB099		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
James W. Hill P.S.	HB176		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
James W. Hill P.S.	HB107		11-Jan-22	Matt Pitman	Mar-22	NSMOMO
Joshua Creek P.S.	HB085	5	12-Jan-22	Matt Pitman	Mar-22	Degraded caulking around door
Joshua Creek P.S.	HB011		12-Jan-22	Matt Pitman	Mar-22	Front downspout is missing
Joshua Creek P.S.	HB077		12-Jan-22	Matt Pitman	Mar-22	NSMOMO
Joshua Creek P.S.	HB155		12-Jan-22	Matt Pitman	Mar-22	NSMOMO
Joshua Creek P.S.	HB161		12-Jan-22	Matt Pitman	Mar-22	NSMOMO
Montclair P.S.	HBL210	1	14-Jan-22	Matt Pitman	Mar-22	NSMOMO
Munn's P.S.	HBL001	2	14-Jan-22	Matt Pitman	Mar-22	Degraded caulking around door
Munn's P.S.	HBL002		14-Jan-22	Matt Pitman	Mar-22	Degraded caulking around window
New Central P.S.	HB079	2	14-Jan-22	Matt Pitman	Mar-22	NSMOMO
New Central P.S.	HB104		14-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM190	11	13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM191		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM192		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM193		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM194		13-Jan-22	Matt Pitman	Mar-22	NSMOMO

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Oakville Trafalgar H.S.	RM189A		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM189B		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM195		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM196		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM197		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oakville Trafalgar H.S.	RM198		13-Jan-22	Matt Pitman	Mar-22	NSMOMO
Oodenawi P.S.	HB058	11	6-Dec-21	Serena Romito	Mar-22	NSMOMO
Oodenawi P.S.	HB101		6-Dec-21	Serena Romito	Mar-22	Level 1 - wet drwall on near windows and HVAC due to leaking eavestrough
Oodenawi P.S.	HBL260		6-Dec-21	Serena Romito	Mar-22	NSMOMO
Oodenawi P.S.	HBL248		6-Dec-21	Serena Romito	Mar-22	NSMOMO
Oodenawi P.S.	HB171		6-Dec-21	Serena Romito	Mar-22	Level 2 - impacted drywall under window. Degraded caulking around door.
Oodenawi P.S.	HB175		6-Dec-21	Serena Romito	Mar-22	Level 1 - 6 water stained ceiling tiles
Oodenawi P.S.	HBL086		6-Dec-21	Serena Romito	Mar-22	NSMOMO
Oodenawi P.S.	HB067		6-Dec-21	Serena Romito	Mar-22	NSMOMO
Oodenawi P.S.	HB044		6-Dec-21	Serena Romito	Mar-22	NSMOMO
Oodenawi P.S.	HB094		6-Dec-21	Serena Romito	Mar-22	NSMOMO
Oodenawi P.S.	HB096		6-Dec-21	Serena Romito	Mar-22	NSMOMO
Pilgrim Wood P.S.	HB006	3	7-Dec-21	Serena Romito	Mar-22	Degraded caulking around windows. Damaged downspout and eavestrough front and rear elevation.
Pilgrim Wood P.S.	HBL267		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Pilgrim Wood P.S.	HBL087		7-Dec-21	Serena Romito	Mar-22	NSMOMO
Post's Corners P.S.	HBL102	12	14-Dec-21	Serena Romito	Mar-22	Vinyl floor tiles lifting throughout. Approximately 100 damaged, and 4 missing.
Post's Corners P.S.	HB180		14-Dec-21	Serena Romito	Mar-22	NSMOMO
Post's Corners P.S.	HB129		14-Dec-21	Serena Romito	Mar-22	NSMOMO
Post's Corners P.S.	HBL006		14-Dec-21	Serena Romito	Mar-22	NSMOMO
Post's Corners P.S.	HBL218		14-Dec-21	Serena Romito	Mar-22	Missing number plate
Post's Corners P.S.	HBL255		14-Dec-21	Serena Romito	Mar-22	NSMOMO
Post's Corners P.S.	HBL211		14-Dec-21	Serena Romito	Mar-22	NSMOMO
Post's Corners P.S.	HBL007		14-Dec-21	Serena Romito	Mar-22	Missing downspout rear elevation
Post's Corners P.S.	HB123		14-Dec-21	Serena Romito	Mar-22	Missing inspection port cover
Post's Corners P.S.	HB158		14-Dec-21	Serena Romito	Mar-22	Level 1 - water stained ceiling tile
Post's Corners P.S.	HBL269		14-Dec-21	Serena Romito	Mar-22	NSMOMO
Post's Corners P.S.	HBL268		14-Dec-21	Serena Romito	Mar-22	NSMOMO
River Oaks P.S.	HBL294	2	14-Jan-22	Matt Pitman	Mar-22	NSMOMO
River Oaks P.S.	HBL295		14-Jan-22	Matt Pitman	Mar-22	NSMOMO
W.H. Morden P.S.	HB199	7	7-Dec-21	Serena Romito	Mar-22	4 damaged vinyl floor tiles
W.H. Morden P.S.	HB200		7-Dec-21	Serena Romito	Mar-22	NSMOMO

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
W.H. Morden P.S.	HBL201		7-Dec-21	Serena Romito	Mar-22	Door wont open. Damaged downspout rear elevation.
W.H. Morden P.S.	HBL250		7-Dec-21	Serena Romito	Mar-22	NSMOMO
W.H. Morden P.S.	HBL249		7-Dec-21	Serena Romito	Mar-22	Degraded window caulking.
W.H. Morden P.S.	HB055		7-Dec-21	Serena Romito	Mar-22	NSMOMO
W.H. Morden P.S.	HB138		7-Dec-21	Serena Romito	Mar-22	NSMOMO
West Oak P.S.	RM1	6	14-Jan-22	Matt Pitman	Mar-22	NSMOMO
West Oak P.S.	RM2		14-Jan-22	Matt Pitman	Mar-22	NSMOMO
West Oak P.S.	RM3		14-Jan-22	Matt Pitman	Mar-22	NSMOMO
West Oak P.S.	RM4		14-Jan-22	Matt Pitman	Mar-22	NSMOMO
West Oak P.S.	RM5		14-Jan-22	Matt Pitman	Mar-22	NSMOMO
West Oak P.S.	RM6		14-Jan-22	Matt Pitman	Mar-22	NSMOMO
White Oaks North H.S.	HBL092	5	12-Jan-22	Matt Pitman	Mar-22	NSMOMO
White Oaks North H.S.	HBL093		12-Jan-22	Matt Pitman	Mar-22	NSMOMO
White Oaks North H.S.	HBL094		12-Jan-22	Matt Pitman	Mar-22	NSMOMO
White Oaks North H.S.	HBL095		12-Jan-22	Matt Pitman	Mar-22	NSMOMO
White Oaks North H.S.	HB060		12-Jan-22	Matt Pitman	Mar-22	NSMOMO
White Oaks South H.S.	HBL018	16	9-Dec-21	Serena Romito	Mar-22	NSMOMO
White Oaks South H.S.	HBL017		9-Dec-21	Serena Romito	Mar-22	Degraded window caulking.
White Oaks South H.S.	HBL016		9-Dec-21	Serena Romito	Mar-22	Damaged deck boards
White Oaks South H.S.	HB054		9-Dec-21	Serena Romito	Mar-22	Missing inspection port cover
White Oaks South H.S.	HBL096		9-Dec-21	Serena Romito	Mar-22	NSMOMO
White Oaks South H.S.	HBL097		9-Dec-21	Serena Romito	Mar-22	NSMOMO
White Oaks South H.S.	HB042		9-Dec-21	Serena Romito	Mar-22	Damaged downspout rear elevation
White Oaks South H.S.	HB023		9-Dec-21	Serena Romito	Mar-22	Degraded window caulking. Damaged t-bar grid
White Oaks South H.S.	HB205		9-Dec-21	Serena Romito	Mar-22	1 missing ceiling tile
White Oaks South H.S.	HB078		9-Dec-21	Serena Romito	Mar-22	NSMOMO
White Oaks South H.S.	HBL261		9-Dec-21	Serena Romito	Mar-22	NSMOMO
White Oaks South H.S.	HB130		9-Dec-21	Serena Romito	Mar-22	Approximately 20 damaged vinyl floor tile
White Oaks South H.S.	HB201		9-Dec-21	Serena Romito	Mar-22	Damaged wall sheathing around conduits
White Oaks South H.S.	HB112		9-Dec-21	Serena Romito	Mar-22	NSMOMO
White Oaks South H.S.	HB153		9-Dec-21	Serena Romito	Mar-22	NSMOMO
White Oaks South H.S.	HBL009		9-Dec-21	Serena Romito	Mar-22	Level 1 - 2 water stained ceiling tiles due to uncapped conduits
Alton Village P.S.	HB169	10	30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Alton Village P.S.	HBL225		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Alton Village P.S.	HB068		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Alton Village P.S.	HB037		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Alton Village P.S.	HBL237		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Alton Village P.S.	HBL238		30-Dec-21	Matt Pitman	Mar-22	NSMOMO

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Alton Village P.S.	HBL239		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Alton Village P.S.	HBL234		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Alton Village P.S.	HBL235		30-Dec-21	Matt Pitman	Mar-22	Rusting cladding beneath door.
Alton Village P.S.	HBL236		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Dr. Frank Hayden S.S.	HB059	9	30-Dec-21	Matt Pitman	Mar-22	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB120		30-Dec-21	Matt Pitman	Mar-22	Inadequate caulking at exterior windows
Dr. Frank Hayden S.S.	HB172		30-Dec-21	Matt Pitman	Mar-22	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB092		30-Dec-21	Matt Pitman	Mar-22	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB010		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Dr. Frank Hayden S.S.	HBL256		30-Dec-21	Matt Pitman	Mar-22	Seperating caulking at windows.
Dr. Frank Hayden S.S.	HB137		30-Dec-21	Matt Pitman	Mar-22	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB207		30-Dec-21	Matt Pitman	Mar-22	Inadequate caulking at exterior windows and HVAC condensate hose
Dr. Frank Hayden S.S.	HB151		30-Dec-21	Matt Pitman	Mar-22	NSMOMO
Florence Meares P.S.	HB069	3	3-Jan-22	Matt Pitman	Mar-22	Caulking degrading around windows
Florence Meares P.S.	HBL100		3-Jan-22	Matt Pitman	Mar-22	Under Construction
Florence Meares P.S.	HB139		3-Jan-22	Matt Pitman	Mar-22	NSMOMO
Glenview P.S.	HB166	3	29-Dec-21	Matt Pitman	Mar-22	Screwholes at NE corner cladding
Glenview P.S.	HB122		29-Dec-21	Matt Pitman	Mar-22	NSMOMO
Glenview P.S.	HB148		29-Dec-21	Matt Pitman	Mar-22	Missing caulking at HVAC condensate hose and cladding
J.W. Singleton Ed. Ctr.	HB119	4	29-Dec-21	Matt Pitman	Mar-22	NSMOMO
J.W. Singleton Ed. Ctr.	HB118		29-Dec-21	Matt Pitman	Mar-22	NSMOMO
J.W. Singleton Ed. Ctr.	HB117		29-Dec-21	Matt Pitman	Mar-22	Damaged Caulking on exterior HVAC hose
J.W. Singleton Ed. Ctr.	HB003		29-Dec-21	Matt Pitman	Mar-22	NSMOMO
John T. Tuck P.S.	HBL220	5	6-Jan-22	Matt Pitman	Mar-22	Inadequate caulking at exterior windows, HVAC and condensate hose
John T. Tuck P.S.	HB173		6-Jan-22	Matt Pitman	Mar-22	Rusting cladding under door.
John T. Tuck P.S.	HB157		6-Jan-22	Matt Pitman	Mar-22	Large hole in west cladding from removed conduit
John T. Tuck P.S.	HB156		6-Jan-22	Matt Pitman	Mar-22	Rusting cladding under door.
John T. Tuck P.S.	HB064		6-Jan-22	Matt Pitman	Mar-22	NSMOMO
Kilbride P.S.	HB074	1	3-Jan-22	Matt Pitman	Mar-22	NSMOMO
Paul A. Fisher	HBL247	1	3-Jan-22	Matt Pitman	Mar-22	NSMOMO
Pauline Johnson P.S.	HB024	3	4-Jan-22	Matt Pitman	Mar-22	Inadequate caulking at HVAC condensate hose
Pauline Johnson P.S.	HBL222		4-Jan-22	Matt Pitman	Mar-22	Inadequate caulking at HVAC condensate hose
Pauline Johnson P.S.	HB102		4-Jan-22	Matt Pitman	Mar-22	Seperating caulking at windows.
Tom Thomson P.S.	HB124	7	4-Jan-22	Matt Pitman	Mar-22	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB031		4-Jan-22	Matt Pitman	Mar-22	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB105		4-Jan-22	Matt Pitman	Mar-22	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB098		4-Jan-22	Matt Pitman	Mar-22	Missing caulking at HVAC and condensate hose at cladding

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Tom Thomson P.S.	HBL109		4-Jan-22	Matt Pitman	Mar-22	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB141		4-Jan-22	Matt Pitman	Mar-22	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HB012		4-Jan-22	Matt Pitman	Mar-22	Missing caulking at HVAC and condensate hose at cladding
Anne J.Macarthur P.S.	HBL215	15	14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HBL214		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HB174		14-Dec-21	Evan Faubert	Mar-22	Missing caulking at SW conduit
Anne J.Macarthur P.S.	HBL219		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HBL216		14-Dec-21	Evan Faubert	Mar-22	Cracked caulking at window corners. HVAC condensate hose not visible
Anne J.Macarthur P.S.	HBL221		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HB111		14-Dec-21	Evan Faubert	Mar-22	Screw holes in cladding to right and left of door.
Anne J.Macarthur P.S.	HB061		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HB165		14-Dec-21	Evan Faubert	Mar-22	Interior Floor: Damaged floor tiles along centre of the room. Cracked caulking at windows
Anne J.Macarthur P.S.	HBL202		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HBL203		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HBL204		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HBL205		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HBL232		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Anne J.Macarthur P.S.	HBL233		14-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL106	18	13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HB208		13-Dec-21	Evan Faubert	Mar-22	Screwholes left of door
Boyne P.S.	HB033		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL110		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL241		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HB028		13-Dec-21	Evan Faubert	Mar-22	Missing HVAC hose and caulking
Boyne P.S.	HBL226		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL257		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HB179		13-Dec-21	Evan Faubert	Mar-22	Missing HVAC hose and caulking at conduits
Boyne P.S.	HBL251		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL253		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HB152		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HB015		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL254		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL252		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL291		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL292		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Boyne P.S.	HBL293		13-Dec-21	Evan Faubert	Mar-22	NSMOMO
Bruce Trail P.S.	HBL206	16	7-Jan-21	Matt Pitman	Mar-22	NSMOMO

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Bruce Trail P.S.	HBL262		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HBL107		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HB075		7-Jan-21	Matt Pitman	Mar-22	Screw holes in cladding at W corner
Bruce Trail P.S.	HB181		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HB103		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HB110		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HB046		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HB114		7-Jan-21	Matt Pitman	Mar-22	Degraded caulking at exterior windows
Bruce Trail P.S.	HB062		7-Jan-21	Matt Pitman	Mar-22	Missing caulking at HVAC condensate hose
Bruce Trail P.S.	HBL105		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HB115		7-Jan-21	Matt Pitman	Mar-22	Damaged caulking at conduit
Bruce Trail P.S.	HBL231		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HBL230		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HBL228		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Bruce Trail P.S.	HBL229		7-Jan-21	Matt Pitman	Mar-22	NSMOMO
Chris Hadfield P.S.	HBL266	20	5-Jan-22	Evan Faubert	Mar-22	Screwholes in NE corner cladding
Chris Hadfield P.S.	HB051		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	HB034		5-Jan-22	Evan Faubert	Mar-22	Holes in both south corners of cladding.
Chris Hadfield P.S.	HB168		5-Jan-22	Evan Faubert	Mar-22	Hole in cladding below window
Chris Hadfield P.S.	HB035		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	HBL259		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	HBL265		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A10		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A09		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A08		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A07		5-Jan-22	Evan Faubert	Mar-22	Degraded caulking at exterior windows
Chris Hadfield P.S.	RM A06		5-Jan-22	Evan Faubert	Mar-22	Degraded caulking at exterior windows
Chris Hadfield P.S.	RM A05		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A04		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A03		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A02		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	RM A01		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	HB036		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	HBL288		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Chris Hadfield P.S.	HBL289		5-Jan-22	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB128	24	7-Dec-21	Evan Faubert	Mar-22	Degraded Caulking at HVAC, No caulking at HVAC condensate hose
Craig Kielburger S.S.	HB113		7-Dec-21	Evan Faubert	Mar-22	Missing Caulking at HVAC louvre and windows
Craig Kielburger S.S.	HB147		7-Dec-21	Evan Faubert	Mar-22	Missing Caulking at HVAC louvre and windows

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Craig Kielburger S.S.	HB132		7-Dec-21	Evan Faubert	Mar-22	Missing caulking at windows and HVAC louvre and conduit
Craig Kielburger S.S.	HB073		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB143		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB133		7-Dec-21	Evan Faubert	Mar-22	Large hole in North exterior cladding
Craig Kielburger S.S.	HB203		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB134		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB057		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB159		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HBL014		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HBL015		7-Dec-21	Evan Faubert	Mar-22	Caulking separating at windows.
Craig Kielburger S.S.	HB125		7-Dec-21	Evan Faubert	Mar-22	Screwholes in cladding left of door
Craig Kielburger S.S.	HBL084		7-Dec-21	Evan Faubert	Mar-22	Screwholes in door
Craig Kielburger S.S.	HB029		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB140		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HB136		7-Dec-21	Evan Faubert	Mar-22	Screwholes left of door
Craig Kielburger S.S.	HBL098		7-Dec-21	Evan Faubert	Mar-22	Caulking separating at windows.
Craig Kielburger S.S.	HBL288		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HBL289		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HBL290		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HBL312		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
Craig Kielburger S.S.	HBL313		7-Dec-21	Evan Faubert	Mar-22	NSMOMO
E.W. Foster's P.S.	HB189	1	17-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HBL090	12	21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HBL103		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HBL104		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HB144		21-Dec-21	Evan Faubert	Mar-22	Missing caulking at NE air exchanger and condensate hose
Escarpment View P.S.	HB005		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HB089		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HBL082		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HBL081		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HB056		21-Dec-21	Evan Faubert	Mar-22	Under construction
Escarpment View P.S.	HBL088		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HBL089		21-Dec-21	Evan Faubert	Mar-22	NSMOMO
Escarpment View P.S.	HBL083		21-Dec-21	Evan Faubert	Mar-22	Degraded caulking at exterior HVAC
Ethel Gardner P.S.	HB049	5	17-Dec-21	Evan Faubert	Mar-22	Missing caulking at N side conduits and HVAC. Screwholes in cladding let of HVAC louvre
Ethel Gardner P.S.	HBL212		17-Dec-21	Evan Faubert	Mar-22	Denatured caulking at windows
Ethel Gardner P.S.	HBL207		17-Dec-21	Evan Faubert	Mar-22	NSMOMO



Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Ethel Gardner P.S.	HBL263		17-Dec-21	Evan Faubert	Mar-22	NSMOMO
Ethel Gardner P.S.	HBL101		17-Dec-21	Evan Faubert	Mar-22	Screwholes in cladding. NE corner
Glen Williams P.S.	HB184	2	17-Dec-21	Evan Faubert	Mar-22	LEVEL 2 : Stained vapour barrier and mould impacted fibreglass insulation above HVAC
Glen Williams P.S.	HB178		17-Dec-21	Evan Faubert	Mar-22	Under construction
Hawthorne Village P.S.	RM301	12	6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM302		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM303		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM304		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM305		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM306		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM307		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM308		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM309		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	RM310		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	HB162		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Hawthorne Village P.S.	HB013		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Irma Coulson P.S.	HBL246	15	6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Irma Coulson P.S.	HBL245		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Irma Coulson P.S.	HBL244		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Irma Coulson P.S.	HB142		6-Jan-22	Evan Faubert	Mar-22	Renovating
Irma Coulson P.S.	HBL243		6-Jan-22	Evan Faubert	Mar-22	Degraded caulking at windows and doors.
Irma Coulson P.S.	HBL242		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Irma Coulson P.S.	HB195		6-Jan-22	Evan Faubert	Mar-22	Level 2: Mould on NW corner drywall at baseboard level. Missing caulking at HVAC conduit on south side of portable.
Irma Coulson P.S.	HB149		6-Jan-22	Evan Faubert	Mar-22	Missing caulking at windows.
Irma Coulson P.S.	HB196		6-Jan-22	Evan Faubert	Mar-22	Screwholes in cladding near windows
Irma Coulson P.S.	HB081		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Irma Coulson P.S.	HB150		6-Jan-22	Evan Faubert	Mar-22	Degraded caulking at door. Screw holes in cladding left of door.
Irma Coulson P.S.	HB204		6-Jan-22	Evan Faubert	Mar-22	Missing caulking at windows and HVAC conduits.
Irma Coulson P.S.	HBL111		6-Jan-22	Evan Faubert	Mar-22	NSMOMO
Irma Coulson P.S.	HB146		6-Jan-22	Evan Faubert	Mar-22	Level 2: Water stained ceiling tile at SE corner of portble. Mould growth on vapour barrier above ceiling tile.
Irma Coulson P.S.	HB009		6-Jan-22	Evan Faubert	Mar-22	Missing caulking at west HVAC conduit. Screw holes to the right of door.
Milton District H.S.	HB154	5	7-Jan-22	Matt Pitman	Mar-22	NSMOMO
Milton District H.S.	HB093		7-Jan-22	Matt Pitman	Mar-22	NSMOMO
Milton District H.S.	HB041		7-Jan-22	Matt Pitman	Mar-22	NSMOMO
Milton District H.S.	HBL223		7-Jan-22	Matt Pitman	Mar-22	NSMOMO

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Milton District H.S.	HB001		7-Jan-22	Matt Pitman	Mar-22	NSMOMO
P.L. Robertson P.S.	HB004	9	22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HB027		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HB021		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HB030		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HB016		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HB022		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HB039		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HBL091		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
P.L. Robertson P.S.	HBL228		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Sam Sherrat P.S.	HB082	8	10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Sam Sherrat P.S.	HB083		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Sam Sherrat P.S.	HB066		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Sam Sherrat P.S.	HB127		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Sam Sherrat P.S.	HBL099		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Sam Sherrat P.S.	HB032		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Sam Sherrat P.S.	UNKN		10-Jan-22	Matt Pitman	Mar-22	UNTAGGED
Sam Sherrat P.S.	UNKN		10-Jan-22	Matt Pitman	Mar-22	UNTAGGED
Tiger Jeet Singh P.S.	HBL079	9	10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Tiger Jeet Singh P.S.	HBL108		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Tiger Jeet Singh P.S.	HBL013		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Tiger Jeet Singh P.S.	HB095		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Tiger Jeet Singh P.S.	HB187		10-Jan-22	Matt Pitman	Mar-22	Seperating caulking at windows
Tiger Jeet Singh P.S.	HB116		10-Jan-22	Matt Pitman	Mar-22	Seperating caulking at windows
Tiger Jeet Singh P.S.	HB109		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Tiger Jeet Singh P.S.	HB063		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Tiger Jeet Singh P.S.	HB126		10-Jan-22	Matt Pitman	Mar-22	NSMOMO
Viola Desmond P.S.	HBL270	18	22-Dec-21	Evan Faubert	Mar-22	Seperating caulking at windows
Viola Desmond P.S.	HBL271		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL272		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL273		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL274		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL275		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL276		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL277		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL278		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL279		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL280		22-Dec-21	Evan Faubert	Mar-22	NSMOMO

Portable Classroom - Preventative Inspection Round 117

School	Portable Number	Portables on Site	Round 117 Inspection Date	Pinchin Inspector	Proposed Round 118 Inspection Date	Comments from Round 118 Inspection
Viola Desmond P.S.	HBL281		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL282		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL283		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL284		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL285		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL286		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
Viola Desmond P.S.	HBL287		22-Dec-21	Evan Faubert	Mar-22	NSMOMO
W.I. Dick P.S.	HB183	3	17-Dec-21	Evan Faubert	Mar-22	Missing caulking at air exchanger conduits and at HVAC condensate hose penetration
W.I. Dick P.S.	HB002		17-Dec-21	Evan Faubert	Mar-22	Missing caulking at air exchanger conduits and at HVAC condensate hose penetration
W.I. Dick P.S.	HB007		17-Dec-21	Evan Faubert	Mar-22	Missing caulking at air exchanger conduits and at HVAC condensate hose penetration