

Portable Classroom Preventative Inspections

Round 119

School	Portable Number	Portables on Site	Round 119 Inspection Date	Pinchin Inspector	Proposed Round 120 Inspection Date	Comments from Round 119 Inspection
Abbey Park H.S.	HB043	12	6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB053		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB072		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB108		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB131		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB163		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB164		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB177		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HB206		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HBL213		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HBL224		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Abbey Park H.S.	HBL227		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Alton Village P.S.	HB037	10	6/14/2022	Evan Faubert	Sep-22	NSMOMO
Alton Village P.S.	HB068		6/14/2022	Evan Faubert	Sep-22	Level 2 - Water stained ceiling, fibreglass insulation and vapour barrier
Alton Village P.S.	HB169		6/14/2022	Evan Faubert	Sep-22	Missing Downspout
Alton Village P.S.	HBL225		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Alton Village P.S.	HBL234		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Alton Village P.S.	HBL235		6/14/2022	Evan Faubert	Sep-22	Level 2 - Impacted ceiling tile, fibreglass insulation and vapour barrier
Alton Village P.S.	HBL236		6/14/2022	Evan Faubert	Sep-22	Level 2 - Impacted ceiling tile, fibreglass insulation and vapour barrier
Alton Village P.S.	HBL237		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Alton Village P.S.	HBL238		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Alton Village P.S.	HBL239		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HB061	15	6/27/2022	Serena Romito	Sep-22	Gaps in sheathing around windows.
Anne J. Macarthur P.S.	HB111		6/27/2022	Serena Romito	Sep-22	No interior caulking around HVAC unit.
Anne J. Macarthur P.S.	HB165		6/27/2022	Serena Romito	Sep-22	Level 1 - 1 water stained ceiling tile due to roof leak. No interior caulking around HVAC unit.
Anne J. Macarthur P.S.	HB174		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL202		6/27/2022	Serena Romito	Sep-22	Damaged caulking around HVAC louvre
Anne J. Macarthur P.S.	HBL203		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL204		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL205		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL214		6/27/2022	Serena Romito	Sep-22	Uncapped conduit on North side.
Anne J. Macarthur P.S.	HBL215		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL216		6/27/2022	Serena Romito	Sep-22	Level 1 - water stained ceiling tile
Anne J. Macarthur P.S.	HBL219		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL221		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL232		6/27/2022	Serena Romito	Sep-22	NSMOMO
Anne J. Macarthur P.S.	HBL233		6/27/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HB015	18	6/28/2022	Serena Romito	Sep-22	No window trim interior.
Boyne P.S.	HB028		6/28/2022	Serena Romito	Sep-22	Damaged flashing around interior HVAC.
Boyne P.S.	HB033		6/28/2022	Serena Romito	Sep-22	Holes/gaps in flashing around interior HVAC. No window trim inside.
Boyne P.S.	HB152		6/28/2022	Serena Romito	Sep-22	No flashing around interior HVAC.
Boyne P.S.	HB179		6/28/2022	Serena Romito	Sep-22	No window trim inside. Damaged flashing under door. Damaged flashing around interior HVAC flashing.
Boyne P.S.	HB208		6/28/2022	Serena Romito	Sep-22	Damaged flashing under door.
Boyne P.S.	HBL106		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL110		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL226		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL241		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL251		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL252		6/28/2022	Serena Romito	Sep-22	Door knob jammed.
Boyne P.S.	HBL253		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL254		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL257		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL291		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL292		6/28/2022	Serena Romito	Sep-22	NSMOMO
Boyne P.S.	HBL293		6/28/2022	Serena Romito	Sep-22	NSMOMO
Bruce Trail P.S.	HB046	15	6/29/2022	Serena Romito	Sep-22	Degraded caulking around door. No interior flashing around HVAC.
Bruce Trail P.S.	HB062		6/29/2022	Serena Romito	Sep-22	NSMOMO
Bruce Trail P.S.	HB075		6/29/2022	Serena Romito	Sep-22	No caulking around condensate hose. Degraded caulking around windows. Damaged drywall near door.
Bruce Trail P.S.	HB103		6/29/2022	Serena Romito	Sep-22	No caulking around condensate hose. Screw holes near door.
Bruce Trail P.S.	HB110		6/29/2022	Serena Romito	Sep-22	Degraded caulking around windows and door. Rear downspout detached.
Bruce Trail P.S.	HB114		6/29/2022	Serena Romito	Sep-22	Damaged rear downspout.
Bruce Trail P.S.	HB115		6/29/2022	Serena Romito	Sep-22	Degraded caulking around condensate hose.
Bruce Trail P.S.	HB181		6/29/2022	Serena Romito	Sep-22	No caulking around condensate hose.
Bruce Trail P.S.	HBL105		6/29/2022	Serena Romito	Sep-22	NSMOMO
Bruce Trail P.S.	HBL107		6/29/2022	Serena Romito	Sep-22	NSMOMO
Bruce Trail P.S.	HBL206		6/29/2022	Serena Romito	Sep-22	Damaged window caulking
Bruce Trail P.S.	HBL229		6/29/2022	Serena Romito	Sep-22	NSMOMO
Bruce Trail P.S.	HBL230		6/29/2022	Serena Romito	Sep-22	NSMOMO
Bruce Trail P.S.	HBL231		6/29/2022	Serena Romito	Sep-22	NSMOMO
Bruce Trail P.S.	HBL262		6/29/2022	Serena Romito	Sep-22	NSMOMO
Captain R. Wilson P.S.	HB014	6	6/17/2022	Evan Faubert	Sep-22	NSMOMO
Captain R. Wilson P.S.	HB047		6/17/2022	Evan Faubert	Sep-22	Level 3 - Impacted drywall below NW window
Captain R. Wilson P.S.	HB065		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Captain R. Wilson P.S.	HB087		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Captain R. Wilson P.S.	HB106		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Captain R. Wilson P.S.	HBL217		6/17/2022	Evan Faubert	Sep-22	NSMOMO

Portable Classroom Preventative Inspections

Round 119

School	Portable Number	Portables on Site	Round 119 Inspection Date	Pinchin Inspector	Proposed Round 120 Inspection Date	Comments from Round 119 Inspection
Chris Hadfield P.S.	HB034	20	7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	HB035		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	HB036		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	HB051		7/14/2022	Serena Romito	Sep-22	Level 1 - 1 water stained ceiling tile due to condensation
Chris Hadfield P.S.	HB168		7/14/2022	Serena Romito	Sep-22	Under construction.
Chris Hadfield P.S.	HBL259		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	HBL265		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	HBL266		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	HBL298		7/14/2022	Serena Romito	Sep-22	Under construction.
Chris Hadfield P.S.	HBL299		7/14/2022	Serena Romito	Sep-22	Under construction.
Chris Hadfield P.S.	RM A01		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A02		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A03		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A04		7/14/2022	Serena Romito	Sep-22	Level 2 - Impacted drywall window sills due to spillage from cups.
Chris Hadfield P.S.	RM A05		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A06		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A07		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A08		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A09		7/14/2022	Serena Romito	Sep-22	NSMOMO
Chris Hadfield P.S.	RM A10		7/14/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB029	24	6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB057		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB073		6/6/2022	Serena Romito	Sep-22	Damaged front downspout. Damaged caulking around electrical cables through exterior sheathing. Hole in drywall.
Craig Kielburger S.S.	HB113		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB125		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB128		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB132		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB133		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB134		6/6/2022	Serena Romito	Sep-22	3 Missing ceiling tiles. ~10 lifting floor tiles under windows.
Craig Kielburger S.S.	HB136		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB140		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB143		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB147		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HB159		6/6/2022	Serena Romito	Sep-22	No window trim interior. Missing centre wall cap.
Craig Kielburger S.S.	HB203		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HBL014		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HBL015		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HBL084		6/6/2022	Serena Romito	Sep-22	Level 1 - 1 water stained ceiling tile due to roof leak
Craig Kielburger S.S.	HBL098		6/6/2022	Serena Romito	Sep-22	Level 1 - 1 water stained ceiling tile due to roof leak.
Craig Kielburger S.S.	HBL288		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HBL289		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HBL290		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HBL312		6/6/2022	Serena Romito	Sep-22	NSMOMO
Craig Kielburger S.S.	HBL313		6/6/2022	Serena Romito	Sep-22	NSMOMO
David R. Williams P.S.	HBL300	12	6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL301		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL302		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL303		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL304		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL305		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL306		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL307		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL308		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL309		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL310		6/21/2022	Evan Faubert	Sep-22	NSMOMO
David R. Williams P.S.	HBL311		6/21/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB010	9	6/14/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB059		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB092		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB120		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB137		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB151		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB172		6/14/2022	Evan Faubert	Sep-22	NSMOMO
Dr. Frank Hayden S.S.	HB207		6/14/2022	Evan Faubert	Sep-22	Split caulking at exterior windows
Dr. Frank Hayden S.S.	HBL256		6/14/2022	Evan Faubert	Sep-22	NSMOMO
E.J. James P.S.	HB121	1	6/17/2022	Evan Faubert	Sep-22	NSMOMO
E.W. Foster's P.S.	HB189	1	7/18/2022	Serena Romito	Sep-22	Damaged caulking around condensate line.
Emily Carr P.S.	HB008	4	6/17/2022	Evan Faubert	Sep-22	Level 4 -Water damaged and impacted subfloor, doorsill plate and lifting floor tiles (8X12) near entrance.
Emily Carr P.S.	HB040		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Emily Carr P.S.	HB084		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Emily Carr P.S.	HBL008		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Escarpment View P.S.	HB005	12	6/1/2022	Serena Romito	Sep-22	No caulking around condensate hose. Degraded window caulking. No interior window trim.
Escarpment View P.S.	HB056		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HB089		6/1/2022	Serena Romito	Sep-22	NSMOMO

Portable Classroom Preventative Inspections

Round 119

School	Portable Number	Portables on Site	Round 119 Inspection Date	Pinchin Inspector	Proposed Round 120 Inspection Date	Comments from Round 119 Inspection
Escarpment View P.S.	HB144		6/1/2022	Serena Romito	Sep-22	Level 2- 1 water stained ceiling tiles and impacted drywall beneath window and near HVAC unit. Missing caulking at NE air exchanger and condensate hose. Degraded window caulking. No window trim.
Escarpment View P.S.	HBL081		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HBL082		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HBL083		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HBL088		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HBL089		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HBL090		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HBL103		6/1/2022	Serena Romito	Sep-22	NSMOMO
Escarpment View P.S.	HBL104		6/1/2022	Serena Romito	Sep-22	Most floor tiles cracked at edges.
Ethel Gardner P.S.	HB049	5	7/17/2022	Serena Romito	Sep-22	Under construction.
Ethel Gardner P.S.	HBL101		7/17/2022	Serena Romito	Sep-22	NSMOMO
Ethel Gardner P.S.	HBL207		7/17/2022	Serena Romito	Sep-22	Key doesn't work. No number plate.
Ethel Gardner P.S.	HBL212		7/17/2022	Serena Romito	Sep-22	Key doesn't work. NSMOMO outside.
Ethel Gardner P.S.	HBL263		7/17/2022	Serena Romito	Sep-22	NSMOMO
Falgarwood P.S.	HB167	1	6/29/2022	Evan Faubert	Sep-22	NSMOMO
Florence Meares P.S.	HB139	1	6/15/2022	Evan Faubert	Sep-22	Missing caulking at air exchange conduit
Garth Webb S.S.	HB038	12	6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HB045		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HB052		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HB076		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HB090		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HB091		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HB100		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HB135		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HBL005		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HBL080		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HBL085		6/21/2022	Evan Faubert	Sep-22	NSMOMO
Garth Webb S.S.	HBL258		6/29/2022	Evan Faubert	Sep-22	NSMOMO
Glen Williams P.S.	HB178	2	7/17/2022	Serena Romito	Sep-22	2 missing ceiling tiles.
Glen Williams P.S.	HB184		7/17/2022	Serena Romito	Sep-22	NSMOMO
Glenview P.S.	HB122	3	6/15/2022	Evan Faubert	Sep-22	NSMOMO
Glenview P.S.	HB148		6/15/2022	Evan Faubert	Sep-22	NSMOMO
Glenview P.S.	HB166		6/15/2022	Evan Faubert	Sep-22	Screwholes at NE corner cladding
Hawthorne Village P.S.	HB013	12	7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	HB162		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM301		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM302		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM303		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM304		7/18/2022	Serena Romito	Sep-22	1 broken window.
Hawthorne Village P.S.	RM305		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM306		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM307		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM308		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM309		7/18/2022	Serena Romito	Sep-22	NSMOMO
Hawthorne Village P.S.	RM310		7/18/2022	Serena Romito	Sep-22	NSMOMO
Irma Coulson P.S.	HB009	15	7/12/2022	Serena Romito	Sep-22	No window trim interior. Damaged window screens.
Irma Coulson P.S.	HB081		7/12/2022	Serena Romito	Sep-22	No window trim interior. No caulking around condensate hose.
Irma Coulson P.S.	HB142		7/12/2022	Serena Romito	Sep-22	No window trim interior.
Irma Coulson P.S.	HB146		7/12/2022	Serena Romito	Sep-22	NSMOMO
Irma Coulson P.S.	HB149		7/12/2022	Serena Romito	Sep-22	No caulking around condensate line. No window caulking. No flashing around interior HVAC.
Irma Coulson P.S.	HB150		7/12/2022	Serena Romito	Sep-22	No window trim interior.
Irma Coulson P.S.	HB195		7/12/2022	Serena Romito	Sep-22	No window trim interior.
Irma Coulson P.S.	HB196		7/12/2022	Serena Romito	Sep-22	NSMOMO
Irma Coulson P.S.	HB204		7/12/2022	Serena Romito	Sep-22	Degraded caulking around windows. No caulking around condensate line. Door stuck.
Irma Coulson P.S.	HBL111		7/12/2022	Serena Romito	Sep-22	Damaged window screens.
Irma Coulson P.S.	HBL242		7/12/2022	Serena Romito	Sep-22	NSMOMO
Irma Coulson P.S.	HBL243		7/12/2022	Serena Romito	Sep-22	Under construction.
Irma Coulson P.S.	HBL244		7/12/2022	Serena Romito	Sep-22	NSMOMO
Irma Coulson P.S.	HBL245		7/12/2022	Serena Romito	Sep-22	Key doesn't work. NSMOMO outside.
Irma Coulson P.S.	HBL246		7/12/2022	Serena Romito	Sep-22	NSMOMO
Iroquois Ridge H.S.	HB070	6	6/23/2022	Evan Faubert	Sep-22	Missing caulking at NE exterior air exchange unit
Iroquois Ridge H.S.	HB088		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Iroquois Ridge H.S.	HB145		6/23/2022	Evan Faubert	Sep-22	Missing SW corner cladding
Iroquois Ridge H.S.	HB202		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Iroquois Ridge H.S.	HB209		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Iroquois Ridge H.S.	HBL264		6/23/2022	Evan Faubert	Sep-22	NSMOMO
J.W. Singleton Ed. Ctr.	HB003	4	6/15/2022	Evan Faubert	Sep-22	NSMOMO
J.W. Singleton Ed. Ctr.	HB117		6/15/2022	Evan Faubert	Sep-22	NSMOMO
J.W. Singleton Ed. Ctr.	HB118		6/15/2022	Evan Faubert	Sep-22	NSMOMO
J.W. Singleton Ed. Ctr.	HB119		6/15/2022	Evan Faubert	Sep-22	Level 2- Impacted fibreglass and vapour barrier
James W. Hill P.S.	HB050	6	6/29/2022	Evan Faubert	Sep-22	NSMOMO
James W. Hill P.S.	HB080		6/29/2022	Evan Faubert	Sep-22	NSMOMO
James W. Hill P.S.	HB086		6/29/2022	Evan Faubert	Sep-22	NSMOMO
James W. Hill P.S.	HB099		6/29/2022	Evan Faubert	Sep-22	NSMOMO
James W. Hill P.S.	HB107		6/29/2022	Evan Faubert	Sep-22	NSMOMO

Portable Classroom Preventative Inspections

Round 119

School	Portable Number	Portables on Site	Round 119 Inspection Date	Pinchin Inspector	Proposed Round 120 Inspection Date	Comments from Round 119 Inspection
James W. Hill P.S.	HB176		6/29/2022	Evan Faubert	Sep-22	Damaged caulking at HVAC condensate hose
John T. Tuck P.S.	HB064	5	6/15/2022	Evan Faubert	Sep-22	NSMOMO
John T. Tuck P.S.	HB156		6/15/2022	Evan Faubert	Sep-22	NSMOMO
John T. Tuck P.S.	HB157		6/15/2022	Evan Faubert	Sep-22	NSMOMO
John T. Tuck P.S.	HB173		6/15/2022	Evan Faubert	Sep-22	Rusting cladding under door.
John T. Tuck P.S.	HBL220		6/15/2022	Evan Faubert	Sep-22	NSMOMO
Joshua Creek P.S.	HB011	5	6/17/2022	Evan Faubert	Sep-22	NSMOMO
Joshua Creek P.S.	HB077		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Joshua Creek P.S.	HB085		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Joshua Creek P.S.	HB155		6/17/2022	Evan Faubert	Sep-22	Denatured caulking at door
Joshua Creek P.S.	HB161		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Kilbride P.S.	HB074	1	6/13/2022	Evan Faubert	Sep-22	NSMOMO
Milton District H.S.	HB001	9	7/4/2022	Serena Romito	Sep-22	No number plate. No gable screen near AC line.
Milton District H.S.	HB041		7/4/2022	Serena Romito	Sep-22	~20 damaged vinyl floor tile.
Milton District H.S.	HB069		7/4/2022	Serena Romito	Sep-22	Degraded window caulking.
Milton District H.S.	HB093		7/4/2022	Serena Romito	Sep-22	No caulking/spray foam around AC line through exterior sheathing.
Milton District H.S.	HB154		7/4/2022	Serena Romito	Sep-22	damaged gable screen around AC line.
Milton District H.S.	HBL001		7/4/2022	Serena Romito	Sep-22	NSMOMO
Milton District H.S.	HBL002		7/4/2022	Serena Romito	Sep-22	NSMOMO
Milton District H.S.	HBL100		7/4/2022	Serena Romito	Sep-22	NSMOMO
Milton District H.S.	HBL223		7/4/2022	Serena Romito	Sep-22	NSMOMO
Montclair P.S.	HBL210	1	6/23/2022	Evan Faubert	Sep-22	NSMOMO
New Central P.S.	HB079	2	6/23/2022	Evan Faubert	Sep-22	NSMOMO
New Central P.S.	HB104		6/23/2022	Evan Faubert	Sep-22	Hole in west cladding near air exchange.
Oakville Trafalgar H.S.	RM189A	11	6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM189B		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM190		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM191		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM192		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM193		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM194		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM195		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM196		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM197		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oakville Trafalgar H.S.	RM198		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HB044	11	6/17/2022	Evan Faubert	Sep-22	Separated conduits from SE side cladding
Oodenawi P.S.	HB058		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HB067		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HB094		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HB096		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HB101		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HB171		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HB175		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HBL086		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HBL248		6/17/2022	Evan Faubert	Sep-22	NSMOMO
Oodenawi P.S.	HBL260		6/17/2022	Evan Faubert	Sep-22	NSMOMO
P.L. Robertson P.S.	HB004	9	6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HB016		6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HB021		6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HB022		6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HB027		6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HB030		6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HB039		6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HBL091		6/1/2022	Serena Romito	Sep-22	NSMOMO
P.L. Robertson P.S.	HBL228		6/1/2022	Serena Romito	Sep-22	NSMOMO
Paul A. Fisher	HBL247	1	6/13/2022	Evan Faubert	Sep-22	Screwholes at NW corner cladding
Pauline Johnson P.S.	HB024	4	6/15/2022	Evan Faubert	Sep-22	Inadequate caulking at HVAC condensate hose
Pauline Johnson P.S.	HB102		6/15/2022	Evan Faubert	Sep-22	NSMOMO
Pauline Johnson P.S.	HBL222		6/15/2022	Evan Faubert	Sep-22	NSMOMO
Pauline Johnson P.S.	HBL316		6/15/2022	Evan Faubert	Sep-22	NSMOMO
Pilgrim Wood P.S.	HB006	3	6/23/2022	Evan Faubert	Sep-22	Damaged floor tiles at entrance.
Pilgrim Wood P.S.	HBL087		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Pilgrim Wood P.S.	HBL267		6/23/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HB123	12	6/28/2022	Evan Faubert	Sep-22	Missing inspection port cover.
Post's Corners P.S.	HB129		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HB158		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HB180		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HBL006		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HBL007		6/28/2022	Evan Faubert	Sep-22	Large conduit hole in cladding, east side.
Post's Corners P.S.	HBL102		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HBL211		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HBL218		6/28/2022	Evan Faubert	Sep-22	Missing number plate
Post's Corners P.S.	HBL255		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HBL268		6/28/2022	Evan Faubert	Sep-22	NSMOMO
Post's Corners P.S.	HBL269		6/28/2022	Evan Faubert	Sep-22	NSMOMO
River Oaks P.S.	HBL294	4	6/17/2022	Evan Faubert	Sep-22	NSMOMO
River Oaks P.S.	HBL295		6/17/2022	Evan Faubert	Sep-22	NSMOMO
River Oaks P.S.	HBL314		6/17/2022	Evan Faubert	Sep-22	NSMOMO
River Oaks P.S.	HBL315		6/17/2022	Evan Faubert	Sep-22	NSMOMO

Portable Classroom Preventative Inspections

Round 119

School	Portable Number	Portables on Site	Round 119 Inspection Date	Pinchin Inspector	Proposed Round 120 Inspection Date	Comments from Round 119 Inspection
Sam Sherrat P.S.	HB032	10	7/4/2022	Serena Romito	Sep-22	Screw holes near door.
Sam Sherrat P.S.	HB066		7/4/2022	Serena Romito	Sep-22	Damaged door caulking. ~10 damaged vinyl floor tiles.
Sam Sherrat P.S.	HB082		7/4/2022	Serena Romito	Sep-22	Level 1 - 1 water stained ceiling tile. No caulking/spray foam around AC line through exterior sheathing. Screw holes near AC unit and conduits. Damaged caulking around conduit.
Sam Sherrat P.S.	HB083		7/4/2022	Serena Romito	Sep-22	No caulking/spray foam around AC line through exterior sheathing.
Sam Sherrat P.S.	HB127		7/4/2022	Serena Romito	Sep-22	Screw holes around HVAC louvre. Damaged front downspout.
Sam Sherrat P.S.	HBL099		7/4/2022	Serena Romito	Sep-22	NSMOMO
Sam Sherrat P.S.	HBL296		7/4/2022	Serena Romito	Sep-22	NSMOMO
Sam Sherrat P.S.	HBL297		7/4/2022	Serena Romito	Sep-22	~10 square feet of damaged flooring.
Sam Sherrat P.S.	HBL317		7/4/2022	Serena Romito	Sep-22	NSMOMO
Sam Sherrat P.S.	HBL318		7/4/2022	Serena Romito	Sep-22	NSMOMO
Tiger Jeet Singh P.S.	HB063	9	7/4/2022	Serena Romito	Sep-22	Damaged caulking around condensate line. 1 missing ceiling tile.
Tiger Jeet Singh P.S.	HB095		7/4/2022	Serena Romito	Sep-22	Damaged caulking around door. 1 missing ceiling tile.
Tiger Jeet Singh P.S.	HB109		7/4/2022	Serena Romito	Sep-22	Level 1 - 1 water stained ceiling tile
Tiger Jeet Singh P.S.	HB116		7/4/2022	Serena Romito	Sep-22	NSMOMO
Tiger Jeet Singh P.S.	HB126		7/4/2022	Serena Romito	Sep-22	Damaged caulking around condensate line.
Tiger Jeet Singh P.S.	HB187		7/4/2022	Serena Romito	Sep-22	Level 1 - wet drywall due to water being directed towards wall due to drip edge sloping towards wall. Repair drip edge under front elevation to prevent water from running under flooring.
Tiger Jeet Singh P.S.	HBL013		7/4/2022	Serena Romito	Sep-22	NSMOMO
Tiger Jeet Singh P.S.	HBL079		7/4/2022	Serena Romito	Sep-22	NSMOMO
Tiger Jeet Singh P.S.	HBL108		7/4/2022	Serena Romito	Sep-22	Holes in sheathing north side.
Tom Thomson P.S.	HB012	7	6/13/2022	Evan Faubert	Sep-22	NSMOMO
Tom Thomson P.S.	HB031		6/13/2022	Evan Faubert	Sep-22	NSMOMO
Tom Thomson P.S.	HB098		6/13/2022	Evan Faubert	Sep-22	NSMOMO
Tom Thomson P.S.	HB105		6/13/2022	Evan Faubert	Sep-22	NSMOMO
Tom Thomson P.S.	HB124		6/13/2022	Evan Faubert	Sep-22	NSMOMO
Tom Thomson P.S.	HB141		6/13/2022	Evan Faubert	Sep-22	Missing caulking at HVAC and condensate hose at cladding
Tom Thomson P.S.	HBL109		6/13/2022	Evan Faubert	Sep-22	Level 1- 1 water stained ceiling tile
Viola Desmond P.S.	HBL270	18	6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL271		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL272		6/13/2022	Serena Romito	Sep-22	Damaged panel cap and screw holes south side.
Viola Desmond P.S.	HBL273		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL274		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL275		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL276		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL277		6/13/2022	Serena Romito	Sep-22	Flex duct detaching from diffuser near door.
Viola Desmond P.S.	HBL278		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL279		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL280		6/13/2022	Serena Romito	Sep-22	Flex duct detaching from diffuser near door.
Viola Desmond P.S.	HBL281		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL282		6/13/2022	Serena Romito	Sep-22	Damaged front downspout
Viola Desmond P.S.	HBL283		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL284		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL285		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL286		6/13/2022	Serena Romito	Sep-22	NSMOMO
Viola Desmond P.S.	HBL287		6/13/2022	Serena Romito	Sep-22	NSMOMO
W.H. Morden P.S.	HB055	7	6/28/2022	Evan Faubert	Sep-22	NSMOMO
W.H. Morden P.S.	HB138		6/28/2022	Evan Faubert	Sep-22	NSMOMO
W.H. Morden P.S.	HB199		6/28/2022	Evan Faubert	Sep-22	NSMOMO
W.H. Morden P.S.	HB200		6/28/2022	Evan Faubert	Sep-22	NSMOMO
W.H. Morden P.S.	HBL201		6/28/2022	Evan Faubert	Sep-22	NSMOMO
W.H. Morden P.S.	HBL249		6/28/2022	Evan Faubert	Sep-22	NSMOMO
W.H. Morden P.S.	HBL250		6/28/2022	Evan Faubert	Sep-22	NSMOMO
W.I. Dick P.S.	HB002	3	7/18/2022	Serena Romito	Sep-22	Key does not work.
W.I. Dick P.S.	HB007		7/18/2022	Serena Romito	Sep-22	Key does not work.
W.I. Dick P.S.	HB183		7/18/2022	Serena Romito	Sep-22	Damaged skirting.
West Oak P.S.	RM1	6	6/28/2022	Evan Faubert	Sep-22	NSMOMO
West Oak P.S.	RM2		6/28/2022	Evan Faubert	Sep-22	NSMOMO
West Oak P.S.	RM3		6/28/2022	Evan Faubert	Sep-22	NSMOMO
West Oak P.S.	RM4		6/28/2022	Evan Faubert	Sep-22	NSMOMO
West Oak P.S.	RM5		6/28/2022	Evan Faubert	Sep-22	NSMOMO
West Oak P.S.	RM6		6/28/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks North H.S.	HB060	5	6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks North H.S.	HBL092		6/24/2022	Evan Faubert	Sep-22	Damaged skirting at SE corner
White Oaks North H.S.	HBL093		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks North H.S.	HBL094		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks North H.S.	HBL095		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB023	16	6/24/2022	Evan Faubert	Sep-22	Uncaulked gap in cladding and HVAC unit
White Oaks South H.S.	HB042		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB054		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB078		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB112		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB130		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB153		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB201		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HB205		6/24/2022	Evan Faubert	Sep-22	NSMOMO

Portable Classroom Preventative Inspections

Round 119

School	Portable Number	Portables on Site	Round 119 Inspection Date	Pinchin Inspector	Proposed Round 120 Inspection Date	Comments from Round 119 Inspection
White Oaks South H.S.	HBL009		6/24/2022	Evan Faubert	Sep-22	Level 1 - 1 water stained ceiling tile, insulation, vapour barrier due to uncapped conduits.
White Oaks South H.S.	HBL016		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HBL017		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HBL018		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HBL096		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HBL097		6/24/2022	Evan Faubert	Sep-22	NSMOMO
White Oaks South H.S.	HBL261		6/24/2022	Evan Faubert	Sep-22	NSMOMO