

## Portable Audit for HDSB Round 126



School	Portable Number	Region	Round 126 Inspection Date	Pinchin Inspector	Proposed Round 127 Inspection Date	Moisture/ Mould found?	Other Deficiency	Location of Condition	Comments from Round 126 Inspection
Anne J. Macarthur P.S.	HBL216	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Anne J. Macarthur P.S.	HBL221	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Anne J. Macarthur P.S.	HB111	NORTH	2024-04-17	Serena Romito	June 2024	No	Yes		Degraded window caulking
Anne J. Macarthur P.S.	HB061	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Anne J. Macarthur P.S.	HBL202	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Anne J. Macarthur P.S.	HBL203	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Anne J. Macarthur P.S.	HBL204	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Anne J. Macarthur P.S.	HBL205	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Anne J. Macarthur P.S.	HBL232	NORTH	2024-04-17	Serena Romito	June 2024	No	Yes		Damaged landing railing
Anne J. Macarthur P.S.	HBL233	NORTH	2024-04-17	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL106	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HB208	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HB033	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL241	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HB028	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL226	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL251	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL253	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HB152	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HB015	NORTH	2024-04-19	Serena Romito	June 2024	No	Yes		Damaged landing. Approximately 20 damaged vinyl floor tiles
Boyne P.S.	HBL254	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL252	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL291	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL292	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL293	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HB165	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Boyne P.S.	HBL259	NORTH	2024-04-19	Serena Romito	June 2024	No	Yes		Damaged front siding, interior wall bowed in significantly.
Boyne P.S.	HB050	NORTH	2024-04-19	Serena Romito	June 2024	No	No		NSMOMO
Bruce Trail P.S.	HBL206	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Damaged downspout
Bruce Trail P.S.	HBL262	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Bruce Trail P.S.	HB075	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Damaged downspout. Door not sealed properly
Bruce Trail P.S.	HB181	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Damaged downspout
Bruce Trail P.S.	HB103	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Bruce Trail P.S.	HB110	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Bruce Trail P.S.	HB046	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Bruce Trail P.S.	HB114	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Screw holes in cladding at bottom left of door. Approximately 6 broken floor tiles
Bruce Trail P.S.	HB062	NORTH	2024-03-14	Erin Zylstra	June 2024	No	N/A		Inaccessible due to recent fire. Under construction.
Bruce Trail P.S.	HBL105	NORTH	2024-03-14	Erin Zylstra	June 2024	No	N/A		Inaccessible due to recent fire. Under construction.
Bruce Trail P.S.	HB115	NORTH	2024-03-14	Erin Zylstra	June 2024	No	N/A		Inaccessible due to recent fire. Under construction.
Bruce Trail P.S.	HBL229	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Cracked caulking around windows
Bruce Trail P.S.	HBL107	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Chris Hadfield P.S.	HBL266	NORTH	2024-03-12	Harman Singh	June 2024	No	No		NSMOMO
Chris Hadfield P.S.	HBL265	NORTH	2024-03-12	Harman Singh	June 2024	No	No		NSMOMO
Chris Hadfield P.S.	RM A10	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre

Chris Hadfield P.S.	RM A09	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A08	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A07	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre
Chris Hadfield P.S.	RM A06	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre
Chris Hadfield P.S.	RM A05	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A04	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A03	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A02	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A01	NORTH	2024-03-12	Harman Singh	June 2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Craig Kielburger S.S.	HB128	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB113	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB147	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB132	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB073	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Screw holes in cladding on right wall
Craig Kielburger S.S.	HB143	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB133	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Screw holes in cladding at rear of portable
Craig Kielburger S.S.	HB203	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Approximately 5 damaged floor tiles
Craig Kielburger S.S.	HB134	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB057	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB159	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL014	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL015	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB125	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL084	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Screw holes in cladding on right wall
Craig Kielburger S.S.	HB029	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB140	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HB136	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Screw holes in cladding on front left corner of portable
Craig Kielburger S.S.	HBL098	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL288	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL289	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL290	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL312	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL313	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
E.W. Foster's P.S.	HB189	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Escarpment View P.S.	HBL090	NORTH	2024-04-24	Serena Romito	June 2024	No	No		NSMOMO
Escarpment View P.S.	HBL103	NORTH	2024-04-24	Serena Romito	June 2024	No	No		NSMOMO
Escarpment View P.S.	HBL104	NORTH	2024-04-24	Serena Romito	June 2024	No	No		NSMOMO
Escarpment View P.S.	HB144	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Escarpment View P.S.	HB005	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Degraded caulking around windows
Escarpment View P.S.	HB089	NORTH	2024-04-24	Serena Romito	June 2024	No	Yes		Degraded caulking around condensate hose. 2 damaged vinyl floor tiles
Escarpment View P.S.	HBL082	NORTH	2024-04-24	Serena Romito	June 2024	No	No		NSMOMO
Escarpment View P.S.	HBL088	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Damaged downspout
Escarpment View P.S.	HBL089	NORTH	2024-04-24	Serena Romito	June 2024	No	No		NSMOMO
Escarpment View P.S.	HBL083	NORTH	2024-04-24	Serena Romito	June 2024	No	Yes		Approximately 15 damaged vinyl floor tiles.
Escarpment View P.S.	HB056	NORTH	2024-04-24	Serena Romito	June 2024	No	Yes		No caulking around refrigerant line left exterior wall.
Ethel Gardner P.S.	HB049	NORTH	2024-04-26	Serena Romito	June 2024	Yes	No	Roof (ceiling space)	Level 1 - 2 water stained ceiling tiles
Ethel Gardner P.S.	HBL212	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Ethel Gardner P.S.	HBL207	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Ethel Gardner P.S.	HBL263	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Ethel Gardner P.S.	HBL101	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Ethel Gardner P.S.	HBL240	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Ethel Gardner P.S.	HBL335	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Glen Williams P.S.	HB184	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Glen Williams P.S.	HB178	NORTH	2024-04-26	Serena Romito	June 2024	No	Yes		Degraded window caulking
Hawthorne Village P.S.	RM301	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO

Hawthorne Village P.S.	RM302	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM303	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM304	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM305	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM306	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM307	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM308	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM309	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Hawthorne Village P.S.	RM310	NORTH	2024-04-26	Serena Romito	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HBL246	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Caulking cracking around window corners
Irma Coulson P.S.	HBL245	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HBL244	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HB142	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HBL242	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HB081	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HB150	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Baseboards peeling off wall throughout
Irma Coulson P.S.	HB204	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HBL111	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Four damaged floor tiles. Crack caulking around window corners
Irma Coulson P.S.	HB146	NORTH	2024-03-14	Erin Zylstra	June 2024	No	No		NSMOMO
Irma Coulson P.S.	HB009	NORTH	2024-03-14	Erin Zylstra	June 2024	No	Yes		Approximately 10 cracked floor tiles.
J.M. Denyes P.S.	HBL317	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
J.M. Denyes P.S.	HBL318	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HB154	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HB093	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HB041	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HBL223	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HB069	NORTH	2024-03-18	Harman Singh	June 2024	No	Yes		Screw holes in cladding to right of door
Milton District H.S.	HBL001	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HBL002	NORTH	2024-03-18	Harman Singh	June 2024	No	Yes		Screw holes in cladding at corner near downspout
Milton District H.S.	HBL100	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HB168	NORTH	2024-03-18	Harman Singh	June 2024	No	Yes		Degraded caulking around door. Damaged downspout
Milton District H.S.	HB035	NORTH	2024-03-18	Harman Singh	June 2024	No	Yes		Missing baseboard on east wall
Milton District H.S.	HB036	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
Milton District H.S.	HB034	NORTH	2024-03-18	Harman Singh	June 2024	No	No		NSMOMO
P.L. Robertson P.S.	HB004	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
P.L. Robertson P.S.	HB027	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Degraded caulking around condensate line.
P.L. Robertson P.S.	HB021	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Damaged sheathing around HVAC louvre
P.L. Robertson P.S.	HB030	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
P.L. Robertson P.S.	HB016	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Degraded caulking around condensate line.
P.L. Robertson P.S.	HB022	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Condensate line not draining properly. Approximately 10 damaged vinyl floor tiles.
P.L. Robertson P.S.	HB039	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Damaged flashing around HVAC louvre. Approximately 20 damaged vinyl floor tiles.
P.L. Robertson P.S.	HBL091	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
P.L. Robertson P.S.	HBL228	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Vinyl floor tiles lifting/curling in approximately half of portable
P.L. Robertson P.S.	HBL257	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
P.L. Robertson P.S.	HB179	NORTH	2024-04-22	Serena Romito	June 2024	Yes	Yes	Roof (ceiling space)	Level 1 - 3 water stained ceiling tiles. Hole in sheathing right side. No caulking around condensate line.
P.L. Robertson P.S.	HBL110	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
Rattlesnake Point P.S.	HBL219	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Missing downspout at rear or portable
Rattlesnake Point P.S.	HBL339	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Rattlesnake Point P.S.	HBL338	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Sam Sherrat P.S.	HB082	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Screw holes in cladding on left wall
Sam Sherrat P.S.	HB083	NORTH	2024-03-26	Harman Singh	June 2024	No	Yes		Screw holes in cladding on south wall
Sam Sherrat P.S.	HBL099	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Sam Sherrat P.S.	HB032	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Sam Sherrat P.S.	HBL297	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO
Sam Sherrat P.S.	HBL296	NORTH	2024-03-26	Harman Singh	June 2024	No	No		NSMOMO

Silver Creek P.S.	HBL336	NORTH	2024-04-22	Serena Romito	June 2024	Yes	No	Roof (ceiling space)	Level 1 - 1 water stained ceiling tile
Tiger Jeet Singh P.S.	HBL079	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
Tiger Jeet Singh P.S.	HBL013	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Damaged rear downspout
Tiger Jeet Singh P.S.	HB095	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
Tiger Jeet Singh P.S.	HB187	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
Tiger Jeet Singh P.S.	HB116	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Degraded window caulking
Tiger Jeet Singh P.S.	HB109	NORTH	2024-04-22	Serena Romito	June 2024	No	Yes		Damaged window screen
Tiger Jeet Singh P.S.	HB063	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
Tiger Jeet Singh P.S.	HB126	NORTH	2024-04-22	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL270	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL271	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL272	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL273	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL274	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL275	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL276	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL277	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL278	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL279	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL280	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL281	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL282	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL283	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL284	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL285	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL286	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
Viola Desmond P.S.	HBL287	NORTH	2024-04-15	Serena Romito	June 2024	No	No		NSMOMO
W.I. Dick P.S.	HB183	NORTH	2024-04-26	Serena Romito	June 2024	No	Yes		NSMOMO. Limited access due to temporary contents.
W.I. Dick P.S.	HB002	NORTH	2024-04-26	Serena Romito	June 2024	No	Yes		Damaged window screen
W.I. Dick P.S.	HB007	NORTH	2024-04-26	Serena Romito	June 2024	No	Yes		Degraded wdoor caulking. Hole in front sheathing.
Abbey Park H.S.	HB164	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB163	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB108	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB177	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HBL213	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HBL227	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB043	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB131	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB072	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB053	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HB206	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Abbey Park H.S.	HBL224	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB047	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB106	EAST	2024-04-03	Evan Faubert	June 2024	No	Yes		Degraded caulking at windows.
Captain R. Wilson P.S.	HB065	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB014	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Captain R. Wilson P.S.	HBL217	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB174	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB087	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB162	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL300	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL301	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL302	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL303	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL304	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO

David R. Williams P.S.	HBL305	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL306	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Missing caulking at conduits.
David R. Williams P.S.	HBL307	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL308	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL309	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL310	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL311	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL320	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL321	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL322	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL323	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL324	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL325	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Two lifting and damaged floor planks. Degraded caulking at windows.
David R. Williams P.S.	HBL326	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Three missing acoustic ceiling tiles.Screw holes in window frame.
David R. Williams P.S.	HBL327	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL328	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Screwholes in cladding, NE side. Degraded caulking at conduits.
David R. Williams P.S.	HBL329	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL330	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
David R. Williams P.S.	HBL331	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Screw holes at SW corner.
David R. Williams P.S.	HB013	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Screw holes at window frame. Degraded and missing caulking at door frame. Missing caulking at conduit.
Emily Carr P.S.	HB084	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Emily Carr P.S.	HBL008	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Falgarwood P.S.	HB167	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Falgarwood P.S.	HB121	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HBL080	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HBL258	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HB038	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HB045	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HBL005	EAST	2024-04-03	Evan Faubert	June 2024	No	Yes		Screwholes in in cladding on north side
Garth Webb S.S.	HB090	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HB052	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HB076	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HB100	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HB135	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HB091	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Garth Webb S.S.	HBL085	EAST	2024-04-03	Evan Faubert	June 2024	No	No		NSMOMO
Heritage Glen	HBL208	EAST	2024-04-19	Evan Faubert	June 2024	No	No		NSMOMO
Heritage Glen	HBL268	EAST	2024-04-19	Evan Faubert	June 2024	No	Yes		Degraded caulking at door.
Iroquois Ridge H.S.	HB145	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB088	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB202	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB070	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB209	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HBL264	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB036	EAST	2024-04-25	Evan Faubert	June 2024	No	Yes		Holes in cladding at NW corner.
Iroquois Ridge H.S.	HB034	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB010	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Iroquois Ridge H.S.	HBL256	EAST	2024-04-25	Evan Faubert	June 2024	No	Yes	Ceiling Space (Roof)	Level 1: Water stained vapour barrier and fibreglass insulation above ceiling grid. Two missing ceiling tiles.
James W. Hill P.S.	HB086	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
James W. Hill P.S.	HB080	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
James W. Hill P.S.	HB099	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
James W. Hill P.S.	HB176	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
James W. Hill P.S.	HB107	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO

Joshua Creek P.S.	HB085	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Joshua Creek P.S.	HB011	EAST	2024-04-15	Evan Faubert	June 2024	No	Yes		Screw holes in cladding at door.
Joshua Creek P.S.	HB077	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Joshua Creek P.S.	HB155	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Joshua Creek P.S.	HB161	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Montclair P.S.	HBL299	EAST	2024-04-26	Evan Faubert	June 2024	No	Yes		Degraded caulking at windows. Screw holes at corner cladding.
Montclair P.S.	HBL298	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
Montclair P.S.	HBL210	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
New Central P.S.	HB079	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
New Central P.S.	HB104	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM190	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM191	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM192	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM193	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM194	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM189A	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM189B	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM195	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM196	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM197	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM198	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB058	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB101	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Screwholes in NE cladding.
Odenawi P.S.	HBL260	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HBL248	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB171	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB175	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HBL086	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB067	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB044	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB094	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HBL214	EAST	2024-04-18	Evan Faubert	June 2024	No	No		NSMOMO
Odenawi P.S.	HB096	EAST	2024-04-18	Evan Faubert	June 2024	No	Yes		Screwholes at door.
Pilgrim Wood P.S.	HBL243	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL200	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Pilgrim Wood P.S.	HB006	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL267	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL087	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL337	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Pilgrim Wood P.S.	HB040	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Pilgrim Wood P.S.	HB008	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL102	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HB180	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HB129	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL006	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL218	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL255	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL211	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL007	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HB123	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HB158	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL269	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
Post's Corners P.S.	HBL268	EAST	2024-04-15	Evan Faubert	June 2024	No	No		NSMOMO
River Oaks P.S.	HBL294	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
River Oaks P.S.	HBL295	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO

River Oaks P.S.	HBL314	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
River Oaks P.S.	HBL215	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
River Oaks P.S.	HBL081	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
River Oaks P.S.	HBL315	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
Sheridan	HBL108	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HBL209	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HB199	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HB200	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HBL201	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HBL250	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HBL249	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HB055	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
W.H. Morden P.S.	HB138	EAST	2024-04-02	Evan Faubert	June 2024	No	No		NSMOMO
West Oak P.S.	RM1	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
West Oak P.S.	RM2	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
West Oak P.S.	RM3	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
West Oak P.S.	RM4	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
West Oak P.S.	RM5	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
West Oak P.S.	RM6	EAST	2024-04-25	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks North H.S.	HB149	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks North H.S.	HBL334	EAST	2024-04-26	Evan Faubert	June 2024	No	Yes		Screwholes at door.
White Oaks North H.S.	HBL333	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks North H.S.	HBL092	EAST	2024-04-26	Evan Faubert	June 2024	No	Yes		Degraded caulking at windows.
White Oaks North H.S.	HBL093	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks North H.S.	HBL094	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks North H.S.	HBL095	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks North H.S.	HB060	EAST	2024-04-26	Evan Faubert	June 2024	No	Yes		No access.
White Oaks South H.S.	HBL018	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HBL017	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HBL016	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB054	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HBL096	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HBL097	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB042	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB023	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB205	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB078	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HBL261	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB130	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB201	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB112	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HB153	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
White Oaks South H.S.	HBL009	EAST	2024-04-26	Evan Faubert	June 2024	No	No		NSMOMO
Alton Village P.S.	HBL225	WEST	2024-03-13	Erin Zylstra	June 2024	No	Yes		Screw holes in cladding at east corner
Alton Village P.S.	HBL237	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Alton Village P.S.	HBL238	WEST	2024-03-13	Erin Zylstra	June 2024	No	Yes		Approximately 10 damaged floor tiles
Alton Village P.S.	HBL239	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Alton Village P.S.	HBL234	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Alton Village P.S.	HBL235	WEST	2024-03-13	Erin Zylstra	June 2024	Yes	Yes	Flooring/HVAC	Level 1 - Approximately 6 sf of wet floor tile around HVAC unit remain from previous round. Inspect interior of HVAC for proper draining.
Alton Village P.S.	HBL236	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Brant Hills P.S.	HB169	WEST	2024-03-13	Erin Zylstra	June 2024	Yes	Yes	Flooring/HVAC	Level 1 - Wet floor tile around HVAC unit. Inspect interior of HVAC for proper draining.
Bruce T. Lindley	HBL332	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Central P.S.	HBL230	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Central P.S.	HBL231	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO

Dr. Charles Best P.S.	HB139	WEST	2024-03-13	Erin Zylstra	June 2024	No	Yes		Detached downspout. Missing caulking at conduits. No sealant present between HVAC unit and exterior wall.
Dr. Frank Hayden S.S.	HB059	WEST	2024-03-13	Erin Zylstra	June 2024	No	Yes		Degraded caulking around conduits
Dr. Frank Hayden S.S.	HB120	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB172	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB092	WEST	2024-03-13	Erin Zylstra	June 2024	Yes	Yes	Ceiling Space	Level 1 - Four water stained ceiling tiles. Top corners of front door not sealed properly.
Dr. Frank Hayden S.S.	HB137	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB207	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB151	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Glenview P.S.	HB024	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Glenview P.S.	HB0316	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Glenview P.S.	HB166	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Glenview P.S.	HB122	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Glenview P.S.	HB148	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
J.W. Singleton Ed. Ctr.	HB119	WEST	2024-03-13	Erin Zylstra	June 2024	Yes	No	Ceiling Space	Level 1 - Two water stained ceiling tiles
J.W. Singleton Ed. Ctr.	HB118	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
J.W. Singleton Ed. Ctr.	HB117	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
J.W. Singleton Ed. Ctr.	HB003	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
John T. Tuck P.S.	HBL220	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
John T. Tuck P.S.	HB173	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
John T. Tuck P.S.	HB157	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
John T. Tuck P.S.	HB156	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
John T. Tuck P.S.	HB064	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Screw holes in cladding below window
Kilbride P.S.	HB074	WEST		Erin Zylstra	June 2024	No	No		NSMOMO
King's Road P.S.	HB195	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
King's Road P.S.	HB196	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Damaged downspouts
King's Road P.S.	HB127	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Orchard Park P.S.	HB066	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Paul A. Fisher	HB037	WEST	2024-03-13	Erin Zylstra	June 2024	Yes	No	Flooring/Door	Level 1 - Wet floor tile at entrance to portable
Paul A. Fisher	HBL247	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Paul A. Fisher	HB013	WEST	2024-03-13	Erin Zylstra	June 2024	No	No		NSMOMO
Pauline Johnson P.S.	HBL222	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Pauline Johnson P.S.	HB102	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Degraded caulking around conduits
Tom Thomson P.S.	HB124	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Degraded caulking around HVAC condensate hose. Screw holes in cladding
Tom Thomson P.S.	HB031	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Damaged soffit at east corner. Screw holes in cladding around HVAC louver
Tom Thomson P.S.	HB105	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Tom Thomson P.S.	HB098	WEST	2024-03-12	Erin Zylstra	June 2024	No	No		NSMOMO
Tom Thomson P.S.	HBL109	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Screw holes in cladding at northwest corner
Tom Thomson P.S.	HB141	WEST	2024-03-12	Erin Zylstra	June 2024	Yes	No	Ceiling Space	Level 1 - Two water stained ceiling tiles
Tom Thomson P.S.	HB012	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Approximately 10 damaged floor tiles
Tom Thomson P.S.	HB051	WEST	2024-03-12	Erin Zylstra	June 2024	No	Yes		Missing eaves trough at rear of portable. Screw holes in cladding around back door. Missing fascia at center beam on north wall.