

David R. Williams P.S.	TBD					Dec-22		
David R. Williams P.S.	TBD					Dec-22		
David R. Williams P.S.	TBD					Dec-22		
David R. Williams P.S.	TBD					Dec-22		
David R. Williams P.S.	TBD					Dec-22		
David R. Williams P.S.	HBL311	EAST		10/22/22	Evan Faubert	Dec-22	No	NSMOMO
E.J. James P.S.	HB121	EAST	1	10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Emily Carr P.S.	HB084	EAST	4	9/23/22	Evan Faubert	Dec-22	No	Loose Planks at stairs landing
Emily Carr P.S.	HB040	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Emily Carr P.S.	HB008	EAST		9/23/22	Evan Faubert	Dec-22	No	Missing conduit holes in cladding North and West Sides
Emily Carr P.S.	HBL008	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Falgarwood P.S.	HB167	EAST	1	9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HBL080	EAST	12	9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HBL258	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HB038	EAST		9/23/22	Evan Faubert	Dec-22	No	Broken a lifting floor tiles in center of room 3x10
Garth Webb S.S.	HB045	EAST		9/23/22	Evan Faubert	Dec-22	No	Holes in cladding near HVAC
Garth Webb S.S.	HBL005	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HB090	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HB052	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HB076	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HB100	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HB135	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HB091	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Garth Webb S.S.	HBL085	EAST		9/23/22	Evan Faubert	Dec-22	No	NSMOMO
Heritage Glen	TBD		1			Dec-22		
Iroquois Ridge H.S.	HB145	EAST	6	9/27/2022	Evan Faubert	Dec-22	No	Missing SW corner cladding
Iroquois Ridge H.S.	HB088	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
Iroquois Ridge H.S.	HB202	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
Iroquois Ridge H.S.	HB070	EAST		9/27/2022	Evan Faubert	Dec-22	No	Missing caulking at NE exterior air exchange unit
Iroquois Ridge H.S.	HB209	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
Iroquois Ridge H.S.	HBL264	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
James W. Hill P.S.	HB050	EAST	6	9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
James W. Hill P.S.	HB086	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
James W. Hill P.S.	HB080	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
James W. Hill P.S.	HB099	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
James W. Hill P.S.	HB176	EAST		9/27/2022	Evan Faubert	Dec-22	No	Damaged caulking at HVAC condensate hose
James W. Hill P.S.	HB107	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
Joshua Creek P.S.	HB085	EAST	5	9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
Joshua Creek P.S.	HB011	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
Joshua Creek P.S.	HB077	EAST		9/27/2022	Evan Faubert	Dec-22	No	NSMOMO
Joshua Creek P.S.	HB155	EAST		9/27/2022	Evan Faubert	Dec-22	No	Denatured caulking at door
Joshua Creek P.S.	HB161	EAST		9/27/2022	Evan Faubert	Dec-22	No	Ground eroding below SE corner support pad
Montclair P.S.	HBL299		3	10/14/22	Evan Faubert	Dec-22	No	NSMOMO
Montclair P.S.	HBL298			10/14/22	Evan Faubert	Dec-22	No	NSMOMO
Montclair P.S.	HBL210	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO

New Central P.S.	HB079	EAST	2	10/26/22	Evan Faubert	Dec-22	No	NSMOMO
New Central P.S.	HB104	EAST		10/26/22	Evan Faubert	Dec-22	No	Hole in west cladding near air exchange.
Oakville Trafalgar H.S.	RM190	EAST	11	10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM191	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM192	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM193	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM194	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM189A	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM189B	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM195	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM196	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM197	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oakville Trafalgar H.S.	RM198	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HB058	EAST	12	9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HB101	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HBL260	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HBL248	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HB171	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HB175	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HBL086	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HB067	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HB044	EAST		9/30/22	Evan Faubert	Dec-22	No	Missing caulking at SE side cladding
Oodenawi P.S.	HB094	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Oodenawi P.S.	HBL214			9/30/22	Evan Faubert	Dec-22	No	Missing caulking a corners of door
Oodenawi P.S.	HB096	EAST		9/30/22	Evan Faubert	Dec-22	No	NSMOMO
Pilgrim Wood P.S.	HBL243		5	10/21/22	Evan Faubert	Dec-22	No	NSMOMO
Pilgrim Wood P.S.	TBD			10/21/22	Evan Faubert	Dec-22		
Pilgrim Wood P.S.	HB006	EAST		10/21/22	Evan Faubert	Dec-22	No	Damaged floor tiles at entrance.
Pilgrim Wood P.S.	HBL267	EAST		10/21/22	Evan Faubert	Dec-22	No	NSMOMO
Pilgrim Wood P.S.	HBL087	EAST		10/21/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HBL102	EAST	12	9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HB180	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HB129	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HBL006	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HBL218	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HBL255	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HBL211	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HBL007	EAST		9/28/22	Evan Faubert	Dec-22	No	Large conduit hole in cladding, east side.
Post's Corners P.S.	HB123	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HB158	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
Post's Corners P.S.	HBL269	EAST		9/28/22	Evan Faubert	Dec-22	No	Missing caulking at air exchange unit conduits.
Post's Corners P.S.	HBL268	EAST		9/28/22	Evan Faubert	Dec-22	No	NSMOMO
River Oaks P.S.	HBL294	EAST	6	10/16/22	Evan Faubert	Dec-22	No	NSMOMO
River Oaks P.S.	HBL295	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
River Oaks P.S.	HBL314	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
River Oaks P.S.	HBL215			10/16/22	Evan Faubert	Dec-22	No	NSMOMO

River Oaks P.S.	HBL081			10/16/22	Evan Faubert	Dec-22	No	NSMOMO
River Oaks P.S.	HBL315	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
Sheridan	HBL108		1	10/16/22	Evan Faubert	Dec-22	No	NSMOMO
W.H. Morden P.S.	HB199	EAST	7	10/26/22	Evan Faubert	Dec-22	No	NSMOMO
W.H. Morden P.S.	HB200	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
W.H. Morden P.S.	HBL201	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
W.H. Morden P.S.	HBL250	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
W.H. Morden P.S.	HBL249	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
W.H. Morden P.S.	HB055	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
W.H. Morden P.S.	HB138	EAST		10/26/22	Evan Faubert	Dec-22	No	NSMOMO
West Oak P.S.	RM1	EAST	6	10/16/22	Evan Faubert	Dec-22	No	NSMOMO
West Oak P.S.	RM2	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
West Oak P.S.	RM3	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
West Oak P.S.	RM4	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
West Oak P.S.	RM5	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
West Oak P.S.	RM6	EAST		10/16/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks North H.S.	HB196		8	10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks North H.S.	TBD					Dec-22		
White Oaks North H.S.	TBD					Dec-22		
White Oaks North H.S.	HBL092	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks North H.S.	HBL093	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks North H.S.	HBL094	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks North H.S.	HBL095	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks North H.S.	HB060	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HBL018	EAST	16	10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HBL017	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HBL016	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB054	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HBL096	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HBL097	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB042	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB023	EAST		10/14/22	Evan Faubert	Dec-22	No	Uncalked gap in cladding and HVAC unit
White Oaks South H.S.	HB205	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB078	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HBL261	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB130	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB201	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB112	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HB153	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
White Oaks South H.S.	HBL009	EAST		10/14/22	Evan Faubert	Dec-22	No	NSMOMO
Alton Village P.S.	HB169	WEST	8	9/22/22	Evan Faubert	Dec-22	No	Missing Downspout, holes in cladding at SW corner, damaged caulking at HVAC
Alton Village P.S.	HBL225	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Alton Village P.S.	HBL237	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Alton Village P.S.	HBL238	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Alton Village P.S.	HBL239	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO

Alton Village P.S.	HBL234	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Alton Village P.S.	HBL235	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Alton Village P.S.	HBL236	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Bruce T. Lindley			1	10/28/22	Evan Faubert	Dec-22	No	NSMOMO
Dr. Frank Hayden S.S.	HB059	WEST	9	9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Dr. Frank Hayden S.S.	HB120	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Dr. Frank Hayden S.S.	HB172	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Dr. Frank Hayden S.S.	HB092	WEST		9/22/22	Evan Faubert	Dec-22	No	Split caulking at exterior windows
Dr. Frank Hayden S.S.	HB010	WEST		9/22/22	Evan Faubert	Dec-22	No	Missing caulking at door
Dr. Frank Hayden S.S.	HBL256	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Dr. Frank Hayden S.S.	HB137	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Dr. Frank Hayden S.S.	HB207	WEST		9/22/22	Evan Faubert	Dec-22	No	Split caulking at exterior windows
Dr. Frank Hayden S.S.	HB151	WEST		9/22/22	Evan Faubert	Dec-22	No	NSMOMO
Florence Meares P.S.	HB139	WEST	1	10/28/22	Evan Faubert	Dec-22	No	NSMOMO
Glenview P.S.	HB024		6	10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Glenview P.S.	HB0316			10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Glenview P.S.	HB068			10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Glenview P.S.	HB166	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Glenview P.S.	HB122	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Glenview P.S.	HB148	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
J.W. Singleton Ed. Ctr.	HB119	WEST	4	10/28/22	Evan Faubert	Dec-22	Yes	Level 2- Impacted fibreglass and vapour barrier
J.W. Singleton Ed. Ctr.	HB118	WEST		10/28/22	Evan Faubert	Dec-22	No	NSMOMO
J.W. Singleton Ed. Ctr.	HB117	WEST		10/28/22	Evan Faubert	Dec-22	No	NSMOMO
J.W. Singleton Ed. Ctr.	HB003	WEST		10/28/22	Evan Faubert	Dec-22	No	NSMOMO
John T. Tuck P.S.	HBL220	WEST	5	10/31/22	Evan Faubert	Dec-22	No	NSMOMO
John T. Tuck P.S.	HB173	WEST		10/31/22	Evan Faubert	Dec-22	No	Rusting cladding under door.
John T. Tuck P.S.	HB157	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
John T. Tuck P.S.	HB156	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
John T. Tuck P.S.	HB064	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Kilbride P.S.	HB074	WEST	1	10/28/22	Evan Faubert	Dec-22	No	NSMOMO
King's Road	HB149		2	10/28/22	Evan Faubert	Dec-22	No	NSMOMO
King's Road	HB195			10/28/22	Evan Faubert	Dec-22	No	NSMOMO
Paul A. Fisher	HB037		2	10/28/22	Evan Faubert	Dec-22	No	NSMOMO
Paul A. Fisher	HBL247	WEST		10/28/22	Evan Faubert	Dec-22	No	NSMOMO
Pauline Johnson P.S.	HBL222	WEST		10/28/22	Evan Faubert	Dec-22	No	NSMOMO
Pauline Johnson P.S.	HB102	WEST		10/28/22	Evan Faubert	Dec-22	Yes	Level 2 - Impacted drywall left of HVAC Unit
Tom Thomson P.S.	HB124	WEST	7	10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Tom Thomson P.S.	HB031	WEST		10/31/22	Evan Faubert	Dec-22	No	Open screw holes in cladding above HVAC
Tom Thomson P.S.	HB105	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Tom Thomson P.S.	HB098	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Tom Thomson P.S.	HBL109	WEST		10/31/22	Evan Faubert	Dec-22	Yes	Level 1- 1 water stained ceiling tile
Tom Thomson P.S.	HB141	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Tom Thomson P.S.	HB012	WEST		10/31/22	Evan Faubert	Dec-22	No	NSMOMO
Anne J. Macarthur P.S.	HBL219	NORTH	12	9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Anne J. Macarthur P.S.	HBL216	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Anne J. Macarthur P.S.	HBL221	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO

Anne J. Macarthur P.S.	HB111	NORTH		9/1/2022	Serena Romito	Dec-22	No	No interior caulking around HVAC unit.
Anne J. Macarthur P.S.	HB061	NORTH		9/1/2022	Serena Romito	Dec-22	No	Gaps in sheathing around windows.
Anne J. Macarthur P.S.	HB165	NORTH		9/1/2022	Serena Romito	Dec-22	No	No interior caulking around HVAC unit.
Anne J. Macarthur P.S.	HBL202	NORTH		9/1/2022	Serena Romito	Dec-22	Yes	Level 1 - 2 water stained ceiling tiles due to roof leak. Damaged caulking around HVAC louvre
Anne J. Macarthur P.S.	HBL203	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Anne J. Macarthur P.S.	HBL204	NORTH		9/1/2022	Serena Romito	Dec-22	No	1 damaged vinyl floor tile
Anne J. Macarthur P.S.	HBL205	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Anne J. Macarthur P.S.	HBL232	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Anne J. Macarthur P.S.	HBL233	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HBL106	NORTH	15	10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HB208	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HB033	NORTH		10/11/2022	Serena Romito	Dec-22	No	Holes/gaps in flashing around interior HVAC. No window trim inside. Damaged gable siding east side.
Boyne P.S.	HBL241	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HB028	NORTH		10/11/2022	Serena Romito	Dec-22	No	Damaged flashing around interior HVAC.
Boyne P.S.	HBL226	NORTH		10/11/2022	Serena Romito	Dec-22	No	Damaged HVAC grill inside.
Boyne P.S.	HBL251	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HBL253	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HB152	NORTH		10/11/2022	Serena Romito	Dec-22	No	No flashing around interior HVAC.
Boyne P.S.	HB015	NORTH		10/11/2022	Serena Romito	Dec-22	No	No window trim interior.
Boyne P.S.	HBL254	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HBL252	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HBL291	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HBL292	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Boyne P.S.	HBL293	NORTH		10/11/2022	Serena Romito	Dec-22	No	NSMOMO
Bruce Trail P.S.	HBL206	NORTH	15	10/13/2022	Serena Romito	Dec-22	No	Damaged window caulking
Bruce Trail P.S.	HBL262	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Bruce Trail P.S.	HBL107	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Bruce Trail P.S.	HB075	NORTH		10/13/2022	Serena Romito	Dec-22	No	No caulking around condensate hose. Degraded caulking around windows. Damaged drywall near door. Rotting wooden window frames on exterior.
Bruce Trail P.S.	HB181	NORTH		10/13/2022	Serena Romito	Dec-22	No	No caulking around condensate hose.
Bruce Trail P.S.	HB103	NORTH		10/13/2022	Serena Romito	Dec-22	No	No caulking around condensate hose. Screw holes near door.
Bruce Trail P.S.	HB110	NORTH		10/13/2022	Serena Romito	Dec-22	No	Degraded caulking around windows and door. Rear eaves detached. Degraded caulking around condensate hose.
Bruce Trail P.S.	HB046	NORTH		10/13/2022	Serena Romito	Dec-22	No	Degraded caulking around door. No interior flashing around HVAC.
Bruce Trail P.S.	HB114	NORTH		10/13/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
Bruce Trail P.S.	HB062	NORTH		10/13/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
Bruce Trail P.S.	HBL105	NORTH		10/13/2022	Serena Romito	Dec-22	No	Door does not latch consistently.
Bruce Trail P.S.	HB115	NORTH		10/13/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.

Bruce Trail P.S.	HBL231	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Bruce Trail P.S.	HBL230	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Bruce Trail P.S.	HBL229	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	HBL266	NORTH	17	10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	HB051	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	HB034	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	HB035	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	HBL259	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	HBL265	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A10	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A09	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A08	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A07	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A06	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A05	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A04	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A03	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A02	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	RM A01	NORTH		10/26/2022	Serena Romito	Dec-22	No	NSMOMO
Chris Hadfield P.S.	HB036	NORTH		10/26/2022	Serena Romito	Dec-22	No	Damaged skirting.
Craig Kielburger S.S.	HB128	NORTH	24	10/20/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
Craig Kielburger S.S.	HB113	NORTH		10/20/2022	Serena Romito	Dec-22	No	Degraded window caulking.
Craig Kielburger S.S.	HB147	NORTH		10/20/2022	Serena Romito	Dec-22	No	Degraded window caulking.
Craig Kielburger S.S.	HB132	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HB073	NORTH		10/20/2022	Serena Romito	Dec-22	No	Damaged front downspout. Hole in drywall.
Craig Kielburger S.S.	HB143	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HB133	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HB203	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HB134	NORTH		10/20/2022	Serena Romito	Dec-22	No	~10 lifting floor tiles under windows.
Craig Kielburger S.S.	HB057	NORTH		10/20/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
Craig Kielburger S.S.	HB159	NORTH		10/20/2022	Serena Romito	Dec-22	No	Damaged window screen. Missing centre wall cap.
Craig Kielburger S.S.	HBL014	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HBL015	NORTH		10/20/2022	Serena Romito	Dec-22	No	Damaged front eaves.
Craig Kielburger S.S.	HB125	NORTH		10/20/2022	Serena Romito	Dec-22	No	Degraded caulking at condensate hose and windows.
Craig Kielburger S.S.	HBL084	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HB029	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HB140	NORTH		10/20/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
Craig Kielburger S.S.	HB136	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HBL098	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HBL288	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HBL289	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HBL290	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HBL312	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO
Craig Kielburger S.S.	HBL313	NORTH		10/20/2022	Serena Romito	Dec-22	No	NSMOMO

E.W. Foster's P.S.	HB189	NORTH	1	10/22/2022	Serena Romito	Dec-22	No	Damaged caulking around condensate line.
Escarpment View P.S.	HBL090	NORTH	11	10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Escarpment View P.S.	HBL103	NORTH		10/31/2022	Serena Romito	Dec-22	Yes	Level 1 - 4 water stained ceiling tiles due to roof leak.
Escarpment View P.S.	HBL104	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Escarpment View P.S.	HB144	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Escarpment View P.S.	HB005	NORTH		10/31/2022	Serena Romito	Dec-22	Yes	Level 1 - 1 water stained ceiling tile. Large hive with dead bees on top of water stained ceiling tile. No caulking around condensate hose.
Escarpment View P.S.	HB089	NORTH		10/31/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
Escarpment View P.S.	HBL082	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Escarpment View P.S.	HB056	NORTH		10/31/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
Escarpment View P.S.	HBL088	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Escarpment View P.S.	HBL089	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Escarpment View P.S.	HBL083	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Ethel Gardner P.S.	HB049	NORTH	8	10/27/2022	Serena Romito	Dec-22	No	Screw holes around HVAC louvre. 2 missing ceiling tiles.
Ethel Gardner P.S.	HBL212	NORTH		10/27/2022	Serena Romito	Dec-22	No	NSMOMO
Ethel Gardner P.S.	HBL207	NORTH		10/27/2022	Serena Romito	Dec-22	No	No number plate.
Ethel Gardner P.S.	HBL263	NORTH		10/27/2022	Serena Romito	Dec-22	No	NSMOMO
Ethel Gardner P.S.	HBL101	NORTH		10/27/2022	Serena Romito	Dec-22	No	NSMOMO
Ethel Gardner P.S.	HBL240	NORTH		10/27/2022	Serena Romito	Dec-22	No	NSMOMO
Ethel Gardner P.S.	HBL336	NORTH		10/27/2022	Serena Romito	Dec-22	Yes	Level 1 - Wet drywall walls sporadically to full height throughout.
Ethel Gardner P.S.	HBL335	NORTH		10/27/2022	Serena Romito	Dec-22	Yes	Level 1 - Wet drywall walls sporadically to full height throughout.
Glen Williams P.S.	HB184	NORTH	2	10/27/2022	Serena Romito	Dec-22	No	NSMOMO
Glen Williams P.S.	HB178	NORTH		10/27/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM301	NORTH	12	10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM302	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM303	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM304	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM305	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM306	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM307	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM308	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM309	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	RM310	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	HB162	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Hawthorne Village P.S.	HB013	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Irma Coulson P.S.	HBL246	NORTH	11	10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Irma Coulson P.S.	HBL245	NORTH		10/12/2022	Serena Romito	Dec-22	No	Key doesn't work. NSMOMO outside.
Irma Coulson P.S.	HBL244	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Irma Coulson P.S.	HB142	NORTH		10/12/2022	Serena Romito	Dec-22	No	No window trim interior.
Irma Coulson P.S.	HBL242	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO

Irma Coulson P.S.	HB081	NORTH		10/12/2022	Serena Romito	Dec-22	No	No window trim interior. No caulking around condensate hose.
Irma Coulson P.S.	HB150	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Irma Coulson P.S.	HB204	NORTH		10/12/2022	Serena Romito	Dec-22	Yes	Level 3 - Impacted drywall along exterior wall and wet drywall under windows near teacher desk. Degraded/missing caulking around windows. No caulking around condensate line.
Irma Coulson P.S.	HBL111	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Irma Coulson P.S.	HB146	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
Irma Coulson P.S.	HB009	NORTH		10/12/2022	Serena Romito	Dec-22	No	NSMOMO
J.M. Denyes P.S.	HBL317	NORTH	2	10/27/2022	Serena Romito	Dec-22	No	NSMOMO
J.M. Denyes P.S.	HBL318	NORTH		10/27/2022	Serena Romito	Dec-22	No	NSMOMO
Milton District H.S.	HB154	NORTH	10	9/1/2022	Serena Romito	Dec-22	No	~20 damaged vinyl floor tile.
Milton District H.S.	HB093	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Milton District H.S.	HB041	NORTH		9/1/2022	Serena Romito	Dec-22	No	~5 damaged vinyl floor tile.
Milton District H.S.	HBL223	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Milton District H.S.	HB001	NORTH		9/1/2022	Serena Romito	Dec-22	No	No number plate.
Milton District H.S.	HB069	NORTH		9/1/2022	Serena Romito	Dec-22	No	Degraded window caulking.
Milton District H.S.	HBL001	NORTH		9/1/2022	Serena Romito	Dec-22	No	Degraded door caulking.
Milton District H.S.	HBL002	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Milton District H.S.	HBL100	NORTH		9/1/2022	Serena Romito	Dec-22	No	NSMOMO
Milton District H.S.	HB168	NORTH		9/1/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose. Damaged siding south side. Damaged rear downspout.
P.L. Robertson P.S.	HB004	NORTH	11	10/31/2022	Serena Romito	Dec-22	No	NSMOMO
P.L. Robertson P.S.	HB027	NORTH		10/31/2022	Serena Romito	Dec-22	Yes	Level 1 - 1 water stained ceiling tile due to roof leak.
P.L. Robertson P.S.	HB021	NORTH		10/31/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
P.L. Robertson P.S.	HB030	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
P.L. Robertson P.S.	HB016	NORTH		10/31/2022	Serena Romito	Dec-22	No	Degraded caulking around condensate hose.
P.L. Robertson P.S.	HB022	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
P.L. Robertson P.S.	HB039	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
P.L. Robertson P.S.	HBL091	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
P.L. Robertson P.S.	HBL228	NORTH		10/31/2022	Serena Romito	Dec-22	No	6 missing ceiling tiles.
P.L. Robertson P.S.	HBL257	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
P.L. Robertson P.S.	HB179	NORTH		10/31/2022	Serena Romito	Dec-22	No	No door sweep. No interior window trim.
P.L. Robertson P.S.	HBL110	NORTH		10/31/2022	Serena Romito	Dec-22	No	NSMOMO
Sam Sherrat P.S.	HB082	NORTH	8	10/19/2022	Serena Romito	Dec-22	No	Screw holes near AC unit and conduits. Damaged caulking around conduit.
Sam Sherrat P.S.	HB083	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Sam Sherrat P.S.	HB066	NORTH		10/19/2022	Serena Romito	Dec-22	No	Damaged door caulking. ~10 damaged vinyl floor tiles.
Sam Sherrat P.S.	HB127	NORTH		10/19/2022	Serena Romito	Dec-22	No	Screw holes around HVAC louvre. Damaged front downspout.
Sam Sherrat P.S.	HBL099	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Sam Sherrat P.S.	HB032	NORTH		10/19/2022	Serena Romito	Dec-22	No	Damaged rear eaves.

Sam Sherrat P.S.	HBL297	NORTH		10/19/2022	Serena Romito	Dec-22	No	~10 square feet of damaged flooring.
Sam Sherrat P.S.	HBL296	NORTH		10/19/2022	Serena Romito	Dec-22	No	~5 square feet damaged flooring.
Tiger Jeet Singh P.S.	HBL079	NORTH	9	10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Tiger Jeet Singh P.S.	HBL013	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Tiger Jeet Singh P.S.	HB095	NORTH		10/13/2022	Serena Romito	Dec-22	No	Damaged caulking around door. 1 missing ceiling tile.
Tiger Jeet Singh P.S.	HB187	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Tiger Jeet Singh P.S.	HB116	NORTH		10/13/2022	Serena Romito	Dec-22	No	NSMOMO
Tiger Jeet Singh P.S.	HB109	NORTH		10/13/2022	Serena Romito	Dec-22	No	Damaged front eaves. Damaged door weather stripping.
Tiger Jeet Singh P.S.	HB063	NORTH		10/13/2022	Serena Romito	Dec-22	No	Damaged caulking around condensate line.
Tiger Jeet Singh P.S.	HB126	NORTH		10/13/2022	Serena Romito	Dec-22	No	Damaged caulking around condensate line.
Viola Desmond P.S.	HBL270	NORTH	18	10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL271	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL272	NORTH		10/19/2022	Serena Romito	Dec-22	No	Damaged wall seam panel cap and screw holes south side.
Viola Desmond P.S.	HBL273	NORTH		10/19/2022	Serena Romito	Dec-22	No	1 broken ceiling tile near door.
Viola Desmond P.S.	HBL274	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL275	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL276	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL277	NORTH		10/19/2022	Serena Romito	Dec-22	No	Flex duct detaching from diffuser near door.
Viola Desmond P.S.	HBL278	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL279	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL280	NORTH		10/19/2022	Serena Romito	Dec-22	No	Flex duct detaching from diffuser near door.
Viola Desmond P.S.	HBL281	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL282	NORTH		10/19/2022	Serena Romito	Dec-22	No	Damaged front downspout
Viola Desmond P.S.	HBL283	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL284	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL285	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL286	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
Viola Desmond P.S.	HBL287	NORTH		10/19/2022	Serena Romito	Dec-22	No	NSMOMO
W.I. Dick P.S.	HB183	NORTH	3	10/31/2022	Serena Romito	Dec-22	No	Damaged skirting.
W.I. Dick P.S.	HB002	NORTH		10/31/2022	Serena Romito	Dec-22	No	Key does not work. Degraded window caulking.
W.I. Dick P.S.	HB007	NORTH		10/31/2022	Serena Romito	Dec-22	No	Key does not work. Degraded window caulking.