

## Portable Audit for HDSB

### Round 121



School	Portable Number	Region	Portables on Site	Round 121 Inspection Date	Pinchin Inspector	Proposed Round 122 Inspection Date	Moisture/Mould found?	Comments from Round 121 Inspection
Abbey Park H.S.	HB164	EAST	12	12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB163	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB108	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB177	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HBL213	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HBL227	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB043	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB131	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB072	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB053	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HB206	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Abbey Park H.S.	HBL224	EAST		12/5/2023	Evan Faubert	Mar-23	No	NSMOMO
Captain R. Wilson P.S.	HB047	EAST	7	1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Captain R. Wilson P.S.	HB106	EAST		1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1: Two waterstained ceiling tiles due to condensation on I beam.
Captain R. Wilson P.S.	HB065	EAST		1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1: One waterstained ceiling tile due to possible roof leak.
Captain R. Wilson P.S.	HB014	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Captain R. Wilson P.S.	HBL217	EAST		1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1: One waterstained ceiling tile due to possible roof leak. Damaged downspout at front of portable.
Captain R. Wilson P.S.	HB174	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Captain R. Wilson P.S.	HB087	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL300	EAST	24	01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL301	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL302	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL303	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL304	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL305	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL306	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL307	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL308	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO

David R. Williams P.S.	HBL309	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL310	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL311	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL320	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL321	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL322	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL323	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL324	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL325	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL326	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL327	EAST		01/13/2023	Evan Faubert	Mar-23	No	Denatured caulking at windows Screwholes in cladding left of door
David R. Williams P.S.	HBL328	EAST		01/13/2023	Evan Faubert	Mar-23	No	Denatured caulking at windows
David R. Williams P.S.	HBL329	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL330	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
David R. Williams P.S.	HBL331	EAST		01/13/2023	Evan Faubert	Mar-23	No	NSMOMO
E.J. James P.S.	HB121	EAST	1	1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Emily Carr P.S.	HB084	EAST	4	1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Emily Carr P.S.	HB040	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Emily Carr P.S.	HB008	EAST		1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1: Wet floor tile at entrance to portable. Missing conduit holes in cladding North and West Sides.
Emily Carr P.S.	HBL008	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Falgarwood P.S.	HB167	EAST	1	1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1 - 1 water stained ceiling tile
Garth Webb S.S.	HBL080	EAST	12	1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Garth Webb S.S.	HBL258	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Garth Webb S.S.	HB038	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Garth Webb S.S.	HB045	EAST		1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1: Wet floor tile and subfloor by entrance. Screw holes in cladding on NW wall by conduits.
Garth Webb S.S.	HBL005	EAST		1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1: Wet floor tile and subfloor by entrance. Screw holes in cladding on NW wall by conduits.
Garth Webb S.S.	HB090	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Garth Webb S.S.	HB052	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Garth Webb S.S.	HB076	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Garth Webb S.S.	HB100	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	Missing metal fascia trim on SW and NW walls. Wooden fascia starting to rot on both sides as well. Missing the steel plate at the entrance door to portable. Big air gap between floor and front door.

Garth Webb S.S.	HB135	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Garth Webb S.S.	HB091	EAST		1/6/2023	Erin Kulikowski	Mar-23	Yes	Level 1: One water stained ceiling tile to due condensation on the HVAC condensate line. Miissing metal fasica trim on SW and NW walls. Wooden fascia starting to rot on both sides as well.
Garth Webb S.S.	HBL085	EAST		1/6/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Heritage Glen	TBD	EAST	2	12/5/2023	Evan Faubert	Mar-23		
Heritage Glen	HBL008	EAST		12/5/2023	Evan Faubert	Mar-23	No	Denatured caulking at door.
Iroquois Ridge H.S.	HB145	EAST	6	12/8/2023	Evan Faubert	Mar-23	No	Denatured caulking at door. Screwholes at all corners of cladding.
Iroquois Ridge H.S.	HB088	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Iroquois Ridge H.S.	HB202	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Iroquois Ridge H.S.	HB070	EAST		12/8/2023	Evan Faubert	Mar-23	No	Missing caulking at NE exterior air exchange unit
Iroquois Ridge H.S.	HB209	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Iroquois Ridge H.S.	HBL264	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
James W. Hill P.S.	HB050	EAST	6	1/5/2023	Erin Kulikowski	Mar-23	No	Missing downspout at front of portable
James W. Hill P.S.	HB086	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
James W. Hill P.S.	HB080	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Multiple damaged floor tiles
James W. Hill P.S.	HB099	EAST		1/5/2023	Erin Kulikowski	Mar-23	Yes	Level 1: Three waterstained ceiling tiles due to roof leak
James W. Hill P.S.	HB176	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Damaged caulking at HVAC condensate hose
James W. Hill P.S.	HB107	EAST		1/5/2023	Erin Kulikowski	Mar-23	Yes	Level 1: One waterstained ceiling tile due to condensation on I beam. Cracking caulking around HVAC condensate hose
Joshua Creek P.S.	HB085	EAST	5	12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Joshua Creek P.S.	HB011	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Joshua Creek P.S.	HB077	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Joshua Creek P.S.	HB155	EAST		12/8/2023	Evan Faubert	Mar-23	No	Denatured caulking at door
Joshua Creek P.S.	HB161	EAST		12/8/2023	Evan Faubert	Mar-23	No	Ground eroding below SE corner support pad
Montclair P.S.	HBL299	EAST	3	12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Montclair P.S.	HBL298	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Montclair P.S.	HBL210	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
New Central P.S.	HB079	EAST	2	1/5/2023	Erin Kulikowski	Mar-23	No	Damaged downspout
New Central P.S.	HB104	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM190	EAST	11	1/5/2023	Erin Kulikowski	Mar-23	No	Damaged drywall on exterior wall
Oakville Trafalgar H.S.	RM191	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM192	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM193	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Three missing floor tiles
Oakville Trafalgar H.S.	RM194	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO

Oakville Trafalgar H.S.	RM189A	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM189B	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM195	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM196	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM197	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
Oakville Trafalgar H.S.	RM198	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Missing caulking around middle window
Oodenawi P.S.	HB058	EAST	12	12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HB101	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HBL260	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HBL248	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HB171	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HB175	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HBL086	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HB067	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HB044	EAST		12/8/2023	Evan Faubert	Mar-23	No	Missing caulking at SE side cladding
Oodenawi P.S.	HB094	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Oodenawi P.S.	HBL214	EAST		12/8/2023	Evan Faubert	Mar-23	No	Missing caulking a corners of door
Oodenawi P.S.	HB096	EAST		12/8/2023	Evan Faubert	Mar-23	No	NSMOMO
Pilgrim Wood P.S.	HBL243	EAST	5	12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Pilgrim Wood P.S.	TBD	EAST		12/9/2023	Evan Faubert	Mar-23		
Pilgrim Wood P.S.	HB006	EAST		12/9/2023	Evan Faubert	Mar-23	No	Damaged floor tiles at entrance.
Pilgrim Wood P.S.	HBL267	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Pilgrim Wood P.S.	HBL087	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HBL102	EAST	12	12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HB180	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HB129	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HBL006	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HBL218	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HBL255	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HBL211	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HBL007	EAST		12/9/2023	Evan Faubert	Mar-23	No	Large conduit hole in cladding, east side.
Post's Corners P.S.	HB123	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HB158	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
Post's Corners P.S.	HBL269	EAST		12/9/2023	Evan Faubert	Mar-23	No	Missing caulking at air exchange unit conduits.
Post's Corners P.S.	HBL268	EAST		12/9/2023	Evan Faubert	Mar-23	No	NSMOMO
River Oaks P.S.	HBL294	EAST	6	12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
River Oaks P.S.	HBL295	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
River Oaks P.S.	HBL314	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
River Oaks P.S.	HBL215	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
River Oaks P.S.	HBL081	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
River Oaks P.S.	HBL315	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO

Sheridan	HBL108	EAST	1	12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
W.H. Morden P.S.	HB199	EAST	7	1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
W.H. Morden P.S.	HB200	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
W.H. Morden P.S.	HBL201	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
W.H. Morden P.S.	HBL250	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Thick dirt present at bottom of windows inside portable
W.H. Morden P.S.	HBL249	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Thick dirt present at bottom of windows inside portable
W.H. Morden P.S.	HB055	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Some dirt present at bottom of windows inside portable
W.H. Morden P.S.	HB138	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	Some dirt present at bottom of windows inside portable. Damaged downspout. Screw holes in cladding at front of portable
West Oak P.S.	RM1	EAST	6	1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
West Oak P.S.	RM2	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
West Oak P.S.	RM3	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
West Oak P.S.	RM4	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
West Oak P.S.	RM5	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
West Oak P.S.	RM6	EAST		1/5/2023	Erin Kulikowski	Mar-23	No	NSMOMO
White Oaks North H.S.	HB149	EAST	8	12/12/2023	Evan Faubert	Mar-23	No	Missing caulking at windows. Screwholes next to door. Hole in caldding North saide.
White Oaks North H.S.	HBL334	EAST		12/12/2023	Evan Faubert	Mar-23	No	Missing ceiling tile
White Oaks North H.S.	HBL333	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks North H.S.	HBL092	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks North H.S.	HBL093	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks North H.S.	HBL094	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks North H.S.	HBL095	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks North H.S.	HB060	EAST		12/12/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HBL018	EAST	16	12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HBL017	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HBL016	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HB054	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HBL096	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HBL097	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HB042	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HB023	EAST		12/13/2023	Evan Faubert	Mar-23	No	Uncalked gap in cladding and HVAC unit
White Oaks South H.S.	HB205	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HB078	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HBL261	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HB130	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HB201	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO

White Oaks South H.S.	HB112	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HB153	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
White Oaks South H.S.	HBL009	EAST		12/13/2023	Evan Faubert	Mar-23	No	NSMOMO
Alton Village P.S.	HB169	WEST	8	12/19/2022	Evan Faubert	Mar-23	No	Missing Downspout, holes in cladding at SW corner, damaged caulking at HVAC
Alton Village P.S.	HBL225	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Alton Village P.S.	HBL237	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Alton Village P.S.	HBL238	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Alton Village P.S.	HBL239	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Alton Village P.S.	HBL234	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Alton Village P.S.	HBL235	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Alton Village P.S.	HBL236	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Bruce T. Lindley	HBL332	WEST	1	12/19/2022	Evan Faubert	Mar-23	No	Holes in cladding on all corners. Missing caulking at door frame. Denatured caulking at conduits.
Dr. Frank Hayden S.S.	HB059	WEST	9	12/19/2022	Evan Faubert	Mar-23	No	Denatured caulking at windows.
Dr. Frank Hayden S.S.	HB120	WEST		12/19/2022	Evan Faubert	Mar-23	No	Denatured caulking at windows.
Dr. Frank Hayden S.S.	HB172	WEST		12/19/2022	Evan Faubert	Mar-23	No	Denatured caulking at windows.
Dr. Frank Hayden S.S.	HB092	WEST		12/19/2022	Evan Faubert	Mar-23	No	Split caulking at exterior windows and door frame.
Dr. Frank Hayden S.S.	HB010	WEST		12/19/2022	Evan Faubert	Mar-23	No	Missing caulking at door
Dr. Frank Hayden S.S.	HBL256	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Dr. Frank Hayden S.S.	HB137	WEST		12/19/2022	Evan Faubert	Mar-23	No	NSMOMO
Dr. Frank Hayden S.S.	HB207	WEST		12/19/2022	Evan Faubert	Mar-23	No	Split caulking at exterior windows
Dr. Frank Hayden S.S.	HB151	WEST		12/19/2022	Evan Faubert	Mar-23	Yes	Level 2 Remediation - Impacted drywall at baseboard level on both sides of HVAC. Split caulking at windows.
Florence Meares P.S.	HB139	WEST	1	12/19/2022	Evan Faubert	Mar-23	Yes	Level 1 Remediation - Wet drywall at baseboard level on north side of HVAC unit. Denature caulking at HVAC. Screwholes in SW NW and SW corner cladding.
Glenview P.S.	HB024	WEST	6	1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Glenview P.S.	HB0316	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Glenview P.S.	HB068	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Glenview P.S.	HB166	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Glenview P.S.	HB122	WEST		1/10/2023	Evan Faubert	Mar-23	No	Denatured caulking at conduits.
Glenview P.S.	HB148	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
J.W. Singleton Ed. Ctr.	HB119	WEST	4	1/11/2023	Evan Faubert	Mar-23	Yes	Level 2- Impacted fibreglass and vapour barrier in SE office and Storage room. Two water stained ceiling tiles in Storage room
J.W. Singleton Ed. Ctr.	HB118	WEST		1/11/2023	Evan Faubert	Mar-23	No	NSMOMO

J.W. Singleton Ed. Ctr.	HB117	WEST		1/11/2023	Evan Faubert	Mar-23	No	NSMOMO
J.W. Singleton Ed. Ctr.	HB003	WEST		1/11/2023	Evan Faubert	Mar-23	No	NSMOMO
John T. Tuck P.S.	HBL220	WEST	5	1/11/2023	Evan Faubert	Mar-23	No	Denatured caulking at windows.
John T. Tuck P.S.	HB173	WEST		1/11/2023	Evan Faubert	Mar-23	No	Denatured caulking at windows and HVAC louvre
John T. Tuck P.S.	HB157	WEST		1/11/2023	Evan Faubert	Mar-23	No	Denatured caulking at HVAC louvre.
John T. Tuck P.S.	HB156	WEST		1/11/2023	Evan Faubert	Mar-23	No	NSMOMO
John T. Tuck P.S.	HB064	WEST		1/11/2023	Evan Faubert	Mar-23	No	NSMOMO
Kilbride P.S.	HB074	WEST	1	1/11/2023	Evan Faubert	Mar-23	No	Denature caulking at windows and door
King's Road	HB149	WEST	2	1/10/2023	Evan Faubert	Mar-23	No	Missing cladding for south portable seam.
King's Road	HB196	WEST		1/10/2023	Evan Faubert	Mar-23	No	Denature caulking at windows and door. Breaking and lifting vinyl floor tiles throughout
Paul A. Fisher	HB037	WEST	2	1/11/2023	Evan Faubert	Mar-23	No	NSMOMO
Paul A. Fisher	HBL247	WEST		1/11/2023	Evan Faubert	Mar-23	No	NSMOMO
Pauline Johnson P.S.	HBL222	WEST	2	1/10/2023	Evan Faubert	Mar-23	Yes	Level 3 Remediation - Water damage and impacted vapour barrier and fiberglass batt insulation above acoustic ceiling tiles. Approximately 30 square feet. Impacted book wood book shelf and approximately 4 acoustic ceiling tiles. Remove and replace fiberglass
Pauline Johnson P.S.	HB102	WEST		1/10/2023	Evan Faubert	Mar-23	Yes	Level 2 - Impacted drywall left of HVAC Unit
Tom Thomson P.S.	HB124	WEST	7	1/10/2023	Evan Faubert	Mar-23	No	Denature caulking at HVAC
Tom Thomson P.S.	HB031	WEST		1/10/2023	Evan Faubert	Mar-23	No	Open screw holes in cladding above HVAC
Tom Thomson P.S.	HB105	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Tom Thomson P.S.	HB098	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Tom Thomson P.S.	HBL109	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Tom Thomson P.S.	HB141	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Tom Thomson P.S.	HB012	WEST		1/10/2023	Evan Faubert	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HBL219	NORTH	12	1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HBL216	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HBL221	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HB111	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HB061	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HB165	NORTH		1/12/2023	Serena Romito	Mar-23	No	No caulking around condensate line.
Anne J. Macarthur P.S.	HBL202	NORTH		1/12/2023	Serena Romito	Mar-23	Yes	Level 1 - 2 Water stained ceiling tiles. Damaged caulking around HVAC louvre.
Anne J. Macarthur P.S.	HBL203	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HBL204	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HBL205	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HBL232	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Anne J. Macarthur P.S.	HBL233	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO

Boyne P.S.	HBL106	NORTH	15	1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HB208	NORTH		1/12/2023	Serena Romito	Mar-23	Yes	Level 1 - 1 water stained ceiling tile
Boyne P.S.	HB033	NORTH		1/12/2023	Serena Romito	Mar-23	No	Approximately 10 damaged vinyl floor tiles.
Boyne P.S.	HBL241	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HB028	NORTH		1/12/2023	Serena Romito	Mar-23	No	Approximately 20 damaged vinyl floor tiles.
Boyne P.S.	HBL226	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HBL251	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HBL253	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HB152	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HB015	NORTH		1/12/2023	Serena Romito	Mar-23	No	Approximately 10 damaged vinyl floor tiles.
Boyne P.S.	HBL254	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HBL252	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HBL291	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HBL292	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Boyne P.S.	HBL293	NORTH		1/12/2023	Serena Romito	Mar-23	No	NSMOMO
Bruce Trail P.S.	HBL206	NORTH	15	1/27/2023	Serena Romito	Mar-23	No	Damaged window caulking
Bruce Trail P.S.	HBL262	NORTH		1/27/2023	Serena Romito	Mar-23	No	NSMOMO
Bruce Trail P.S.	HBL107	NORTH		1/27/2023	Serena Romito	Mar-23	No	Front steps under construction
Bruce Trail P.S.	HB075	NORTH		1/27/2023	Serena Romito	Mar-23	No	No caulking around condensate hose. Screw holes in window frames. Damaged front downspout.
Bruce Trail P.S.	HB181	NORTH		1/27/2023	Serena Romito	Mar-23	No	No caulking around condensate hose. Screw holes near door.
Bruce Trail P.S.	HB103	NORTH		1/27/2023	Serena Romito	Mar-23	No	No caulking around condensate hose. Damaged front eaves.
Bruce Trail P.S.	HB110	NORTH		1/27/2023	Serena Romito	Mar-23	No	Screw holes around windows. Degraded caulking around condensate hose.
Bruce Trail P.S.	HB046	NORTH		1/27/2023	Serena Romito	Mar-23	No	No interior flashing around HVAC.
Bruce Trail P.S.	HB114	NORTH		1/27/2023	Serena Romito	Mar-23	No	Degraded caulking around condensate hose.
Bruce Trail P.S.	HB062	NORTH		1/27/2023	Serena Romito	Mar-23	No	NSMOMO
Bruce Trail P.S.	HBL105	NORTH		1/27/2023	Serena Romito	Mar-23	No	Degraded door caulking.
Bruce Trail P.S.	HB115	NORTH		1/27/2023	Serena Romito	Mar-23	No	NSMOMO
Bruce Trail P.S.	HBL231	NORTH		1/27/2023	Serena Romito	Mar-23	No	NSMOMO
Bruce Trail P.S.	HBL230	NORTH		1/27/2023	Serena Romito	Mar-23	No	NSMOMO
Bruce Trail P.S.	HBL229	NORTH		1/27/2023	Serena Romito	Mar-23	No	NSMOMO
Chris Hadfield P.S.	HBL266	NORTH	17	12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	HB051	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	HB034	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	HB035	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	HBL259	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	HBL265	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO



Chris Hadfield P.S.	RM A10	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A09	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A08	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A07	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A06	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A05	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A04	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A03	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A02	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	RM A01	NORTH		12/27/2022	Evan Faubert	Mar-23	No	NSMOMO
Chris Hadfield P.S.	HB036	NORTH		12/27/2022	Evan Faubert	Mar-23	No	Damaged skirting.
Craig Kielburger S.S.	HB128	NORTH	24	1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB113	NORTH		1/19/2023	Serena Romito	Mar-23	No	Degraded caulking around condensate hose.
Craig Kielburger S.S.	HB147	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB132	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB073	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB143	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB133	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB203	NORTH		1/19/2023	Serena Romito	Mar-23	Yes	Level 1 - 2 water stained ceiling tiles.
Craig Kielburger S.S.	HB134	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB057	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB159	NORTH		1/19/2023	Serena Romito	Mar-23	No	Damaged window screen. Missing centre wall cap.
Craig Kielburger S.S.	HBL014	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL015	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB125	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL084	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB029	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB140	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HB136	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL098	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL288	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL289	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL290	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL312	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
Craig Kielburger S.S.	HBL313	NORTH		1/19/2023	Serena Romito	Mar-23	No	NSMOMO
E.W. Foster's P.S.	HB189	NORTH	1	1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Escarpment View P.S.	HBL090	NORTH	11	1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Escarpment View P.S.	HBL103	NORTH		1/6/2023	Serena Romito	Mar-23	Yes	Level 1 - 3 water stained ceiling tiles due to roof leak. Approximately 5 damaged vinyl floor tiles. Degraded caulking around windows.

Escarpment View P.S.	HBL104	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Escarpment View P.S.	HB144	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Escarpment View P.S.	HB005	NORTH		1/6/2023	Serena Romito	Mar-23	No	No caulking around condensate hose. Hole in exterior moisture barrier in inspection ports under windows.
Escarpment View P.S.	HB089	NORTH		1/6/2023	Serena Romito	Mar-23	No	Degraded caulking around condensate hose.
Escarpment View P.S.	HBL082	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Escarpment View P.S.	HB056	NORTH		1/6/2023	Serena Romito	Mar-23	No	Degraded caulking around condensate hose.
Escarpment View P.S.	HBL088	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Escarpment View P.S.	HBL089	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Escarpment View P.S.	HBL083	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Ethel Gardner P.S.	HB049	NORTH	8	1/6/2023	Serena Romito	Mar-23	No	Screw holes around HVAC louvre.
Ethel Gardner P.S.	HBL212	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Ethel Gardner P.S.	HBL207	NORTH		1/6/2023	Serena Romito	Mar-23	No	No number plate.
Ethel Gardner P.S.	HBL263	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Ethel Gardner P.S.	HBL101	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Ethel Gardner P.S.	HBL240	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Ethel Gardner P.S.	HBL336	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Ethel Gardner P.S.	HBL335	NORTH		1/6/2023	Serena Romito	Mar-23	No	NSMOMO
Glen Williams P.S.	HB184	NORTH	2	1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Glen Williams P.S.	HB178	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM301	NORTH	12	1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM302	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM303	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM304	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM305	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM306	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM307	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM308	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM309	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	RM310	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	HB162	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Hawthorne Village P.S.	HB013	NORTH		1/16/2023	Serena Romito	Mar-23	No	Approximately 5 damaged vinyl floor tiles.
Irma Coulson P.S.	HBL246	NORTH	11	1/16/2023	Serena Romito	Mar-23	No	Missing baseboards south wall.
Irma Coulson P.S.	HBL245	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Irma Coulson P.S.	HBL244	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Irma Coulson P.S.	HB142	NORTH		1/16/2023	Serena Romito	Mar-23	No	No window trim interior.
Irma Coulson P.S.	HBL242	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Irma Coulson P.S.	HB081	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Irma Coulson P.S.	HB150	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO

Irma Coulson P.S.	HB204			1/16/2023	Serena Romito	Mar-23	Yes	Level 1 - Wet drywall along exterior wall and under windows likely due to improperly install plywood and moistuer barrier on exterior of portable. No caulking around condensate line.
Irma Coulson P.S.	HBL111	NORTH		1/16/2023	Serena Romito	Mar-23	No	Damaged front downspout
Irma Coulson P.S.	HB146	NORTH		1/16/2023	Serena Romito	Mar-23	Yes	Level 1 - 1 water stained ceiling tile.
Irma Coulson P.S.	HB009	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
J.M. Denyes P.S.	HBL317	NORTH	2	1/16/2023	Serena Romito	Mar-23	No	NSMOMO
J.M. Denyes P.S.	HBL318	NORTH		1/16/2023	Serena Romito	Mar-23	No	NSMOMO
Milton District H.S.	HB154	NORTH	10	1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Milton District H.S.	HB093	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Milton District H.S.	HB041	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Milton District H.S.	HBL223	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Milton District H.S.	HB001	NORTH		1/23/2023	Evan Faubert	Mar-23	No	No number plate.
Milton District H.S.	HB069	NORTH		1/23/2023	Evan Faubert	Mar-23	Yes	Level 3 Remediation - Wet drywall wall below east window approximately 30 sq/ft. Missing exterior cladding on windows.
Milton District H.S.	HBL001	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Milton District H.S.	HBL002	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Milton District H.S.	HBL100	NORTH		1/23/2023	Evan Faubert	Mar-23	Yes	Level 2 Remediation - Impacted HVAC grilles in interior.
Milton District H.S.	HB168	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HB004	NORTH	12	1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HB027	NORTH		1/13/2023	Serena Romito	Mar-23	Yes	Level 1 - 1 water stained ceiling tile due to roof leak.
P.L. Robertson P.S.	HB021	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HB030	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HB016	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HB022	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HB039	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HBL091	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HBL228	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HBL257	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HB179	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
P.L. Robertson P.S.	HBL110	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Sam Sherrat P.S.	HB082	NORTH	8	1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Sam Sherrat P.S.	HB083	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Sam Sherrat P.S.	HB066	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Sam Sherrat P.S.	HB127	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Sam Sherrat P.S.	HBL099	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Sam Sherrat P.S.	HB032	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO

Sam Sherrat P.S.	HBL297	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Sam Sherrat P.S.	HBL296	NORTH		1/24/2023	Serena Romito	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HBL079	NORTH	8	1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HBL013	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB095	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB187	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB116	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB109	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB063	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB126	NORTH		1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL270	NORTH	18	1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL271	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL272	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL273	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL274	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL275	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL276	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL277	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL278	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL279	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL280	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL281	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL282	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL283	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL284	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL285	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL286	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
Viola Desmond P.S.	HBL287	NORTH		1/13/2023	Serena Romito	Mar-23	No	NSMOMO
W.I. Dick P.S.	HB183	NORTH	3	1/23/2023	Evan Faubert	Mar-23	No	NSMOMO
W.I. Dick P.S.	HB002	NORTH		1/23/2023	Evan Faubert	Mar-23	No	Key does not work.
W.I. Dick P.S.	HB007	NORTH		1/23/2023	Evan Faubert	Mar-23	No	Key does not work.