

Portable Audit for HDSB

Round 122



School	Portable Number	Region	Portables on Site	Round 122 Inspection Date	Pinchin Inspector	Proposed Round 123 Inspection Date	Moisture/Mould found?	Comments from Round 122 Inspection
Abbey Park H.S.	HB164	EAST	12	3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HB163	EAST		3/31/2023	Evan Faubert	June 2023	No	Broken floor tiles at entrance and in SW corner.
Abbey Park H.S.	HB108	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HB177	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HBL213	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HBL227	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HB043	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HB131	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HB072	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HB053	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HB206	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Abbey Park H.S.	HBL224	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Captain R. Wilson P.S.	HB047	EAST	7	3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Captain R. Wilson P.S.	HB106	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Captain R. Wilson P.S.	HB065	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Captain R. Wilson P.S.	HB014	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Captain R. Wilson P.S.	HBL217	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Captain R. Wilson P.S.	HB174	EAST		3/20/2023	Evan Faubert	June 2023	Yes	Level 1 - Two water stained ceiling tiles. Missing vapour barrier and wasp nest above ceiling tiles.
Captain R. Wilson P.S.	HB087	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL300	EAST	24	4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL301	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL302	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL303	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL304	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL305	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL306	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL307	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL308	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL309	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL310	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL311	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL320	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL321	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL322	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL323	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL324	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL325	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL326	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL327	EAST		4/4/2023	Evan Faubert	June 2023	No	Denatured caulking at windows. Screwholes in exterior cladding left of door.
David R. Williams P.S.	HBL328	EAST		4/4/2023	Evan Faubert	June 2023	No	Denatured caulking at windows.

David R. Williams P.S.	HBL329	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL330	EAST		4/4/2023	Evan Faubert	June 2023	No	NSMOMO
David R. Williams P.S.	HBL331	EAST		4/4/2023	Evan Faubert	June 2023	No	Screwholes in SW corner cladding
E.J. James P.S.	HB121	EAST	1	4/3/2023	Evan Faubert	June 2023	No	NSMOMO
Emily Carr P.S.	HB084	EAST	4	3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Emily Carr P.S.	HB040	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Emily Carr P.S.	HB008	EAST		3/20/2023	Evan Faubert	June 2023	No	Missing caulking in conduit holes in cladding on N and W sides.
Emily Carr P.S.	HBL008	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Falgarwood P.S.	HB167	EAST	1	4/3/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HBL080	EAST	12	4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HBL258	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HB038	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HB045	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HBL005	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HB090	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HB052	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HB076	EAST		4/7/2023	Evan Faubert	June 2023	No	Screwholes present around HVAC louvre.
Garth Webb S.S.	HB100	EAST		4/7/2023	Evan Faubert	June 2023	No	Missing steel plate at entrance to portable. Large gap between floor and front door.
Garth Webb S.S.	HB135	EAST		4/7/2023	Evan Faubert	June 2023	No	Hole in cladding above HVAC louvre and screwholes.
Garth Webb S.S.	HB091	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Garth Webb S.S.	HBL085	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Heritage Glen	TBD	EAST	2	3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Heritage Glen	HBL268	EAST		3/31/2023	Evan Faubert	June 2023	No	Missing caulking at HVAC condensate line. Screwholes and missing caulking on west side. Screwholes right of door. Damaged floor tiles at front entrance.
Iroquois Ridge H.S.	HB145	EAST	6	3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Iroquois Ridge H.S.	HB088	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Iroquois Ridge H.S.	HB202	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Iroquois Ridge H.S.	HB070	EAST		3/27/2023	Evan Faubert	June 2023	No	Missing caulking at NE exterior air exchange unit.
Iroquois Ridge H.S.	HB209	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Iroquois Ridge H.S.	HBL264	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
James W. Hill P.S.	HB050	EAST	6	3/27/2023	Evan Faubert	June 2023	No	NSMOMO
James W. Hill P.S.	HB086	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
James W. Hill P.S.	HB080	EAST		3/27/2023	Evan Faubert	June 2023	No	Multiple damaged floor tiles.
James W. Hill P.S.	HB099	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
James W. Hill P.S.	HB176	EAST		3/27/2023	Evan Faubert	June 2023	No	Damaged caulking at HVAC condensate hose.
James W. Hill P.S.	HB107	EAST		3/27/2023	Evan Faubert	June 2023	No	Damaged caulking at HVAC condensate hose.
Joshua Creek P.S.	HB085	EAST	5	3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Joshua Creek P.S.	HB011	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Joshua Creek P.S.	HB077	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Joshua Creek P.S.	HB155	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Joshua Creek P.S.	HB161	EAST		3/27/2023	Evan Faubert	June 2023	No	NSMOMO
Montclair P.S.	HBL299	EAST	3	3/17/2023	Evan Faubert	June 2023	No	NSMOMO
Montclair P.S.	HBL298	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
Montclair P.S.	HBL210	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
New Central P.S.	HB079	EAST	2	4/3/2023	Evan Faubert	June 2023	No	Damaged downspout.

New Central P.S.	HB104	EAST		4/3/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM190	EAST	11	4/5/2023	Evan Faubert	June 2023	No	Damaged drywall on exterior wall.
Oakville Trafalgar H.S.	RM191	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM192	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM193	EAST		4/5/2023	Evan Faubert	June 2023	No	Three missing floor tiles. Lifting and buckling floor tiles throughout the room.
Oakville Trafalgar H.S.	RM194	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM189A	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM189B	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM195	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM196	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM197	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Oakville Trafalgar H.S.	RM198	EAST		4/5/2023	Evan Faubert	June 2023	No	Missing caulking around middle window. Multiple cracked and lifting floor tiles throughout the room.
Oodenawi P.S.	HB058	EAST	12	3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HB101	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HBL260	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HBL248	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HB171	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HB175	EAST		3/20/2023	Evan Faubert	June 2023	Yes	Level 2 - Five water stained ceiling tiles and impacted fiberglass insulation and vapour barrier above.
Oodenawi P.S.	HBL086	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HB067	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HB044	EAST		3/20/2023	Evan Faubert	June 2023	No	Screwholes at SE side cladding
Oodenawi P.S.	HB094	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Oodenawi P.S.	HBL214	EAST		3/20/2023	Evan Faubert	June 2023	No	Screwholes left side of front door.
Oodenawi P.S.	HB096	EAST		3/20/2023	Evan Faubert	June 2023	No	NSMOMO
Pilgrim Wood P.S.	HBL243	EAST	6	3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Pilgrim Wood P.S.	TBD	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Pilgrim Wood P.S.	HB006	EAST		3/31/2023	Evan Faubert	June 2023	Yes	Level 1 - Two water stained ceiling tiles from roof leak. Steel deck. No insulation.
Pilgrim Wood P.S.	HBL267	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Pilgrim Wood P.S.	HBL087	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Pilgrim Wood P.S.	HBL337	EAST		3/31/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL102	EAST	12	4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HB180	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HB129	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL006	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL218	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL255	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL211	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL007	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HB123	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HB158	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL269	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
Post's Corners P.S.	HBL268	EAST		4/5/2023	Evan Faubert	June 2023	No	NSMOMO
River Oaks P.S.	HBL294	EAST	6	4/7/2023	Evan Faubert	June 2023	No	NSMOMO
River Oaks P.S.	HBL295	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
River Oaks P.S.	HBL314	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO

River Oaks P.S.	HBL215	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
River Oaks P.S.	HBL081	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
River Oaks P.S.	HBL315	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
Sheridan	HBL108	EAST	1	4/7/2023	Evan Faubert	June 2023	No	NSMOMO
W.H. Morden P.S.	TBD	EAST	8	4/3/2023	Evan Faubert	June 2023	No	NSMOMO
W.H. Morden P.S.	HB199	EAST		4/3/2023	Evan Faubert	June 2023	No	NSMOMO
W.H. Morden P.S.	HB200	EAST		4/3/2023	Evan Faubert	June 2023	No	NSMOMO
W.H. Morden P.S.	HBL201	EAST		4/3/2023	Evan Faubert	June 2023	No	NSMOMO
W.H. Morden P.S.	HBL250	EAST		4/3/2023	Evan Faubert	June 2023	No	Damaged to exterior cladding east side.
W.H. Morden P.S.	HBL249	EAST		4/3/2023	Evan Faubert	June 2023	No	NSMOMO
W.H. Morden P.S.	HB055	EAST		4/3/2023	Evan Faubert	June 2023	No	NSMOMO
W.H. Morden P.S.	HB138	EAST		4/3/2023	Evan Faubert	June 2023	No	Screwholes in cladding at front of portable and sides of windows.
West Oak P.S.	RM1	EAST	6	4/7/2023	Evan Faubert	June 2023	No	NSMOMO
West Oak P.S.	RM2	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
West Oak P.S.	RM3	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
West Oak P.S.	RM4	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
West Oak P.S.	RM5	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
West Oak P.S.	RM6	EAST		4/7/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks North H.S.	HB149	EAST	8	3/17/2023	Evan Faubert	June 2023	No	Missing caulking at windows. Screwholes next to door. Hole in cladding north side.
White Oaks North H.S.	HBL334	EAST		3/17/2023	Evan Faubert	June 2023	No	Missing ceiling tile.
White Oaks North H.S.	HBL333	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks North H.S.	HBL092	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks North H.S.	HBL093	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks North H.S.	HBL094	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks North H.S.	HBL095	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks North H.S.	HB060	EAST		3/17/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HBL018	EAST	16	3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HBL017	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HBL016	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB054	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HBL096	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HBL097	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB042	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB023	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB205	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB078	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HBL261	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB130	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB201	EAST		3/16/2023	Evan Faubert	June 2023	Yes	Level 2 - Impacted and deteriorated drywall right side of HVAC. Approximately 3 square feet.
White Oaks South H.S.	HB112	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HB153	EAST		3/16/2023	Evan Faubert	June 2023	No	NSMOMO
White Oaks South H.S.	HBL009	EAST		3/16/2023	Evan Faubert	June 2023	No	Denatured caulking at HVAC louvre. Lifting deck boards on stair landing.
Alton Village P.S.	HB169	WEST	8	March 15 2023	Erin Kulikowski	June 2023	Yes	Level 1 - One water stained ceiling tile. Missing downspout, holes in cladding at SW corner and damaged caulking at HVAC
Alton Village P.S.	HBL225	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO

Alton Village P.S.	HBL237	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Alton Village P.S.	HBL238	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Alton Village P.S.	HBL239	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Alton Village P.S.	HBL234	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Alton Village P.S.	HBL235	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Alton Village P.S.	HBL236	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Bruce T. Lindley	HBL332	WEST	1	March 15 2023	Erin Kulikowski	June 2023	No	Holes in cladding on all corners. Missing caulking at door frame. Degrading caulking at conduits.
Dr. Frank Hayden S.S.	HB059	WEST	9	March 15 2023	Erin Kulikowski	June 2023	Yes	Level 2 - Impacted drywall wall on both sides of the HVAC unit. Approximately 2 ft2
Dr. Frank Hayden S.S.	HB120	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Dr. Frank Hayden S.S.	HB172	WEST		March 15 2023	Erin Kulikowski	June 2023	No	Dregraded caulking at windows. Gap in between wall and HVAC unit (air coming in).
Dr. Frank Hayden S.S.	HB092	WEST		March 15 2023	Erin Kulikowski	June 2023	No	Caulking splitting at windows
Dr. Frank Hayden S.S.	HB010	WEST		March 15 2023	Erin Kulikowski	June 2023	Yes	Level 3 - Impacted drywall wall. Approximately 18 ft2. Window caulking splitting.
Dr. Frank Hayden S.S.	HBL256	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Dr. Frank Hayden S.S.	HB137	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Dr. Frank Hayden S.S.	HB207	WEST		March 15 2023	Erin Kulikowski	June 2023	Yes	Level 3 - Impacted drywall wall. Approximately 23 ft2. Splitting caulking around windows.
Dr. Frank Hayden S.S.	HB151	WEST		March 15 2023	Erin Kulikowski	June 2023	Yes	Level 2 - Impacted drywall wall on both sides of HVAC. Caulking splitting at windows.
Florence Meares P.S.	HB139	WEST	1	March 15 2023	Erin Kulikowski	June 2023	No	Degraded caulking around windows. Screw holes in cladding on SW and NW corner. Missing fascia at top of portable on W and E side (exposed wood).
Glenview P.S.	HB024	WEST	6	March 14 2023	Erin Kulikowski	June 2023	No	Conduits need caulking or the covers need to be closed.
Glenview P.S.	HB0316	WEST		March 14 2023	Erin Kulikowski	June 2023	No	NSMOMO
Glenview P.S.	HB068	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Portable not there
Glenview P.S.	HB166	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Damaged downspout
Glenview P.S.	HB122	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Degraded caulking around conduits. Damaged downspout.
Glenview P.S.	HB148	WEST		March 14 2023	Erin Kulikowski	June 2023	Yes	Level 1 - 2 water stained ceiling tiles due to mouse urine and hole in vapour barrier. Replace impacted insulation. Penetration in cladding at front of portable. Missing window caulking.
J.W. Singleton Ed. Ctr.	HB119	WEST	4	April 27 2023	Serena Romito	June 2023	Yes	Level 1 - 2 water stained ceiling tiles in storage closet. Degraded caulking around door. Damaged/misaligned downspout rear elevation. Missing screws and caulking around HVAC louvre. Degraded window caulking.
J.W. Singleton Ed. Ctr.	HB118	WEST		April 27 2023	Serena Romito	June 2023	No	NSMOMO
J.W. Singleton Ed. Ctr.	HB117	WEST		April 27 2023	Serena Romito	June 2023	Yes	Level 1 - 1 water stained ceiling tile. Screw holes near door.
J.W. Singleton Ed. Ctr.	HB003	WEST		April 27 2023	Serena Romito	June 2023	Yes	Level 2 - impacted ceiling tiles stored in the HVAC closet.
John T. Tuck P.S.	HBL220	WEST	5	March 14 2023	Erin Kulikowski	June 2023	No	Degraded caulking around windows
John T. Tuck P.S.	HB173	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Degraded caulking around windows and HVAC louvre. HVAC condensate line not caulked. Door does not seal properly.

John T. Tuck P.S.	HB157	WEST		March 14 2023	Erin Kulikowski	June 2023	Yes	Level 1 - Wet floor tiles around HVAC unit. Air gaps in door. Degrading caulking around HVAC louvre. Birds nest at west end.
John T. Tuck P.S.	HB156	WEST		March 14 2023	Erin Kulikowski	June 2023	Yes	Level 1 - Wet and rotting subfloor with lifting tiles at entrance. Missing caulking around HVAC condensate line.
John T. Tuck P.S.	HB064	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Missing caulking around HVAC condensate line.
Kilbride P.S.	HB074	WEST	1	March 14 2023	Erin Kulikowski	June 2023	No	Degraded and cracking caulking around windows and doors.
King's Road	HB149	WEST	2	March 14 2023	Erin Kulikowski	June 2023	No	Missing cladding on portable seam on south side.
King's Road	HB196	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Approximately 20 broken and lifting floor tiles. Lifting subfloor by HVAC unit. Splitting caulking around conduits. Air gap in door.
Paul A. Fisher	HB037	WEST	2	March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Paul A. Fisher	HBL247	WEST		March 15 2023	Erin Kulikowski	June 2023	No	NSMOMO
Pauline Johnson P.S.	HBL222	WEST	2	March 14 2023	Erin Kulikowski	June 2023	No	NSMOMO
Pauline Johnson P.S.	HB102	WEST		March 14 2023	Erin Kulikowski	June 2023	Yes	Level 2 - Impacted drywall to left of HVAC unit.
Tom Thomson P.S.	HB124	WEST	7	March 14 2023	Erin Kulikowski	June 2023	No	Approximately 20 lifting and cracking floor tiles throughout
Tom Thomson P.S.	HB031	WEST		March 14 2023	Erin Kulikowski	June 2023	Yes	Level 1 - One water stained ceiling tile due to possible leak in roof. Screw holes in cladding above HVAC louvre.
Tom Thomson P.S.	HB105	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Screw holes in cladding by stairs.
Tom Thomson P.S.	HB098	WEST		March 14 2023	Erin Kulikowski	June 2023	No	Screw holes in cladding by stairs. Air gap in door.
Tom Thomson P.S.	HBL109	WEST		March 14 2023	Erin Kulikowski	June 2023	No	NSMOMO
Tom Thomson P.S.	HB141	WEST		March 14 2023	Erin Kulikowski	June 2023	No	NSMOMO
Tom Thomson P.S.	HB012	WEST		March 14 2023	Erin Kulikowski	June 2023	Yes	Level 1 - Wet and lifting floor tiles at entrance to portables.
Anne J.Macarthur P.S.	HBL219	NORTH	12	April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HBL216	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HBL221	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HB111	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HB061	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HB165	NORTH		April 2 2023	Serena Romito	Jun-23	No	No caulking around condensate line
Anne J.Macarthur P.S.	HBL202	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HBL203	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HBL204	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HBL205	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HBL232	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Anne J.Macarthur P.S.	HBL233	NORTH		April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HBL106	NORTH	15	April 2 2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HB208	NORTH		3/27/2023	Serena Romito	Jun-23	Yes	Level 1 - 1 Water stained ceiling tile. No caulking around condensate hose.
Boyne P.S.	HB033	NORTH		3/27/2023	Serena Romito	Jun-23	No	Approximately 10 damaged vinyl floor tiles.
Boyne P.S.	HBL241	NORTH		3/27/2023	Serena Romito	Jun-23	No	Approximately 5 damaged vinyl floor tiles.
Boyne P.S.	HB028	NORTH		3/27/2023	Serena Romito	Jun-23	No	Approximately 20 damaged vinyl floor tiles.
Boyne P.S.	HBL226	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HBL251	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HBL253	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HB152	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO

Boyne P.S.	HB015	NORTH		3/27/2023	Serena Romito	Jun-23	No	Approximately 10 damaged vinyl floor tiles
Boyne P.S.	HBL254	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HBL252	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HBL291	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HBL292	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Boyne P.S.	HBL293	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Bruce Trail P.S.	HBL206	NORTH	15	April 4 2023	Serena Romito	Jun-23	No	Damaged window caulking. Screw holes in window frames.
Bruce Trail P.S.	HBL262	NORTH		April 4 2023	Serena Romito	Jun-23	No	NSMOMO
Bruce Trail P.S.	HBL107	NORTH		April 4 2023	Serena Romito	Jun-23	No	NSMOMO
Bruce Trail P.S.	HB075	NORTH		April 4 2023	Serena Romito	Jun-23	No	No caulking around condensate hose. Screw holes in window frames. Damaged flashing at base of wall front elevation.
Bruce Trail P.S.	HB181	NORTH		April 4 2023	Serena Romito	Jun-23	No	No caulking around condensate hose. Screw holes near door. Hole in sheathing rear elevation.
Bruce Trail P.S.	HB103	NORTH		April 4 2023	Serena Romito	Jun-23	No	No caulking around condensate hose. Damaged front eaves. Screw holes around windows.
Bruce Trail P.S.	HB110	NORTH		April 4 2023	Serena Romito	Jun-23	No	Screw holes around windows. Degraded caulking around condensate hose.
Bruce Trail P.S.	HB046	NORTH		April 4 2023	Serena Romito	Jun-23	No	No interior flashing around HVAC. Screw holes around windows.
Bruce Trail P.S.	HB114	NORTH		April 4 2023	Serena Romito	Jun-23	No	Degraded caulking around condensate hose.
Bruce Trail P.S.	HB062	NORTH		April 4 2023	Serena Romito	Jun-23	No	NSMOMO
Bruce Trail P.S.	HBL105	NORTH		April 4 2023	Serena Romito	Jun-23	Yes	Level 1 - 1 water stained ceiling tile.
Bruce Trail P.S.	HB115	NORTH		April 4 2023	Serena Romito	Jun-23	No	NSMOMO
Bruce Trail P.S.	HBL231	NORTH		April 4 2023	Serena Romito	Jun-23	No	NSMOMO
Bruce Trail P.S.	HBL230	NORTH		April 4 2023	Serena Romito	Jun-23	No	NSMOMO
Bruce Trail P.S.	HBL229	NORTH		April 4 2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	HBL266	NORTH	18	April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Chris Hadfield P.S.	HB051	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Cracked flooring at entrance and exposed subfloor. Lifting and cracking floor tiles throughout.
Chris Hadfield P.S.	HB034	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Chris Hadfield P.S.	HB035	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Chris Hadfield P.S.	HB036	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Conduits to be caulked or close conduit covers
Chris Hadfield P.S.	HBL259	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Chris Hadfield P.S.	HBL265	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A10	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A09	NORTH		4/13/2023	Serena Romito	Jun-23	Yes	Level 1 - Wet drywall window sill left window
Chris Hadfield P.S.	RM A08	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A07	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A06	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A05	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A04	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A03	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A02	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	RM A01	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Chris Hadfield P.S.	HB036	NORTH		4/13/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB128	NORTH	24	3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB113	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB147	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO

Craig Kielburger S.S.	HB132	NORTH		3/28/2023	Serena Romito	Jun-23	No	Standing water under condensate line and pooling around skirting.
Craig Kielburger S.S.	HB073	NORTH		3/28/2023	Serena Romito	Jun-23	No	Damaged skirting and sheathing south side.
Craig Kielburger S.S.	HB143	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB133	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB203	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB134	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB057	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB159	NORTH		3/28/2023	Serena Romito	Jun-23	No	Damaged window screen. Missing centre wall cap.
Craig Kielburger S.S.	HBL014	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HBL015	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB125	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HBL084	NORTH		3/28/2023	Serena Romito	Jun-23	No	Missing front and back eaves trough.
Craig Kielburger S.S.	HB029	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HB140	NORTH		3/28/2023	Serena Romito	Jun-23	No	Screw holes and missing sheathing below door.
Craig Kielburger S.S.	HB136	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HBL098	NORTH		3/28/2023	Serena Romito	Jun-23	No	Screw holes near front downspout.
Craig Kielburger S.S.	HBL288	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HBL289	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HBL290	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HBL312	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
Craig Kielburger S.S.	HBL313	NORTH		3/28/2023	Serena Romito	Jun-23	No	NSMOMO
E.W. Foster's P.S.	HB189	NORTH	1	April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Escarpment View P.S.	HBL090	NORTH	11	April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Escarpment View P.S.	HBL103	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Separating caulking around windows. Approximately 10 lifting and broken floor tiles
Escarpment View P.S.	HBL104	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Separating and cracking caulking around windows
Escarpment View P.S.	HB144	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Downspout detached. Degraded caulking around conduits.
Escarpment View P.S.	HB005	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	No caulking around condensate hose. Hole in exterior moisture barrier in inspection ports under windows.
Escarpment View P.S.	HB089	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Gap in fascia where the roof and wall intersect. Structural beams exposed
Escarpment View P.S.	HBL082	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Damaged downspout and cracking caulking around windows.
Escarpment View P.S.	HB056	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Damaged downspout and missing caulking around HVAC condensate hose.
Escarpment View P.S.	HBL088	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Escarpment View P.S.	HBL089	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Damaged downspout
Escarpment View P.S.	HBL083	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Ethel Gardner P.S.	HB049	NORTH	8	3/20/2023	Serena Romito	Jun-23	No	Screw holes around HVAC louvre.
Ethel Gardner P.S.	HBL212	NORTH		3/20/2023	Serena Romito	Jun-23	No	NSMOMO
Ethel Gardner P.S.	HBL207	NORTH		3/20/2023	Serena Romito	Jun-23	No	No number plate.
Ethel Gardner P.S.	HBL263	NORTH		3/20/2023	Serena Romito	Jun-23	No	NSMOMO
Ethel Gardner P.S.	HBL101	NORTH		3/20/2023	Serena Romito	Jun-23	No	NSMOMO
Ethel Gardner P.S.	HBL240	NORTH		3/20/2023	Serena Romito	Jun-23	No	NSMOMO
Ethel Gardner P.S.	HBL336	NORTH		3/20/2023	Serena Romito	Jun-23	No	NSMOMO
Ethel Gardner P.S.	HBL335	NORTH		3/20/2023	Serena Romito	Jun-23	No	NSMOMO
Glen Williams P.S.	HB184	NORTH	2	March 20 2023	Serena Romito	Jun-23	No	NSMOMO

Glen Williams P.S.	HB178	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM301	NORTH	12	March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM302	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM303	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM304	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM305	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM306	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM307	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM308	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM309	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	RM310	NORTH		March 30 2023	Serena Romito	Jun-23	No	NSMOMO
Hawthorne Village P.S.	HB162	NORTH		March 30 2023	Serena Romito	Jun-23	No	Approximately 10 damaged vinyl floor tiles
Hawthorne Village P.S.	HB013	NORTH		March 30 2023	Serena Romito	Jun-23	No	Approximately 5 damaged vinyl floor tiles
Irma Coulson P.S.	HBL246	NORTH	11	March 20 2023	Serena Romito	Jun-23	No	Missing baseboards south wall.
Irma Coulson P.S.	HBL245	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
Irma Coulson P.S.	HBL244	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
Irma Coulson P.S.	HB142	NORTH		March 20 2023	Serena Romito	Jun-23	No	No window trim interior.
Irma Coulson P.S.	HBL242	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
Irma Coulson P.S.	HB081	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
Irma Coulson P.S.	HB150	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
Irma Coulson P.S.	HB204	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
Irma Coulson P.S.	HBL111	NORTH		March 20 2023	Serena Romito	Jun-23	No	Damaged front downspout
Irma Coulson P.S.	HB146	NORTH		March 20 2023	Serena Romito	Jun-23	Yes	Level 1 - 1 water stained ceiling tile.
Irma Coulson P.S.	HB009	NORTH		March 20 2023	Serena Romito	Jun-23	No	NSMOMO
J.M. Denyes P.S.	HBL317	NORTH	2	4/12/2023	Serena Romito	Jun-23	No	NSMOMO
J.M. Denyes P.S.	HBL318	NORTH		4/12/2023	Serena Romito	Jun-23	No	NSMOMO
Milton District H.S.	HB154	NORTH	10	4/12/2023	Serena Romito	Jun-23	Yes	Level 1 - Wet drywall under east window. Damaged window trim around both windows.
Milton District H.S.	HB093	NORTH		4/12/2023	Serena Romito	Jun-23	No	NSMOMO
Milton District H.S.	HB041	NORTH		4/12/2023	Serena Romito	Jun-23	No	Water bottle is block eaves trough. Damaged interior window trim.
Milton District H.S.	HBL223	NORTH		4/12/2023	Serena Romito	Jun-23	Yes	Level 1 - 1 water stained ceiling tile.
Milton District H.S.	HB001	NORTH		4/12/2023	Serena Romito	Jun-23	No	No number plate.
Milton District H.S.	HB069	NORTH		4/12/2023	Serena Romito	Jun-23	No	NSMOMO
Milton District H.S.	HBL001	NORTH		4/12/2023	Serena Romito	Jun-23	No	NSMOMO
Milton District H.S.	HBL002	NORTH		4/12/2023	Serena Romito	Jun-23	No	degraded caulking around windows.
Milton District H.S.	HBL100	NORTH		4/12/2023	Serena Romito	Jun-23	No	Level 2 - Impacted HVAC louvre grilles indoors.
Milton District H.S.	HB168	NORTH		4/12/2023	Serena Romito	Jun-23	No	NSMOMO
P.L. Robertson P.S.	HB004	NORTH	12	3/24/2023	Serena Romito	Jun-23	No	NSMOMO
P.L. Robertson P.S.	HB027	NORTH		3/24/2023	Serena Romito	Jun-23	No	NSMOMO
P.L. Robertson P.S.	HB021	NORTH		3/24/2023	Serena Romito	Jun-23	No	Degraded caulking around condensate hose and HVAC louvre.
P.L. Robertson P.S.	HB030	NORTH		3/24/2023	Serena Romito	Jun-23	No	Screw holes under windows.
P.L. Robertson P.S.	HB016	NORTH		3/24/2023	Serena Romito	Jun-23	No	NSMOMO
P.L. Robertson P.S.	HB022	NORTH		3/24/2023	Serena Romito	Jun-23	No	Loose boards on stairs and landing.
P.L. Robertson P.S.	HB039	NORTH		3/24/2023	Serena Romito	Jun-23	No	NSMOMO
P.L. Robertson P.S.	HBL091	NORTH		3/24/2023	Serena Romito	Jun-23	No	NSMOMO
P.L. Robertson P.S.	HBL228	NORTH		3/24/2023	Serena Romito	Jun-23	No	Damaged interior HVAC grille. 2 missing vinyl floor tile near door.
P.L. Robertson P.S.	HBL257	NORTH		3/24/2023	Serena Romito	Jun-23	No	NSMOMO

P.L. Robertson P.S.	HB179	NORTH		3/24/2023	Serena Romito	Jun-23	Yes	Level 1 - water staining on window trim both windows. Screw holes near door. Damaged door hinge.
P.L. Robertson P.S.	HBL110	NORTH		3/24/2023	Serena Romito	Jun-23	No	NSMOMO
Sam Sherrat P.S.	HB082	NORTH	8	April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Sam Sherrat P.S.	HB083	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Sam Sherrat P.S.	HB066	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Sam Sherrat P.S.	HB127	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Sam Sherrat P.S.	HBL099	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Degraded caulking around windows.
Sam Sherrat P.S.	HB032	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	Damaged downspout
Sam Sherrat P.S.	HBL297	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Sam Sherrat P.S.	HBL296	NORTH		April 10 2023	Erin Kulikowski	Jun-23	No	NSMOMO
Tiger Jeet Singh P.S.	HBL079	NORTH	8	3/14/2023	Serena Romito	Jun-23	No	NSMOMO
Tiger Jeet Singh P.S.	HBL013	NORTH		3/14/2023	Serena Romito	Jun-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB095	NORTH		3/14/2023	Serena Romito	Jun-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB187	NORTH		3/14/2023	Serena Romito	Jun-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB116	NORTH		3/14/2023	Serena Romito	Jun-23	Yes	Level 1 - 1 water stained ceiling tile due to roof leak. Degraded door and window caulking.
Tiger Jeet Singh P.S.	HB109	NORTH		3/14/2023	Serena Romito	Jun-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB063	NORTH		3/14/2023	Serena Romito	Jun-23	No	NSMOMO
Tiger Jeet Singh P.S.	HB126	NORTH		3/14/2023	Serena Romito	Jun-23	No	Degraded door caulking.
Viola Desmond P.S.	HBL270	NORTH	18	3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL271	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL272	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL273	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL274	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL275	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL276	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL277	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL278	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL279	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL280	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL281	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL282	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL283	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL284	NORTH		3/27/2023	Serena Romito	Jun-23	No	Lifting flooring near door. Approximately 2 square feet.
Viola Desmond P.S.	HBL285	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL286	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
Viola Desmond P.S.	HBL287	NORTH		3/27/2023	Serena Romito	Jun-23	No	NSMOMO
W.I. Dick P.S.	HB183	NORTH	3	4/15/2023	Serena Romito	Jun-23	No	NSMOMO
W.I. Dick P.S.	HB002	NORTH		4/15/2023	Serena Romito	Jun-23	Yes	Level 1 - 2 water stained ceiling tiles.
W.I. Dick P.S.	HB007	NORTH		4/15/2023	Serena Romito	Jun-23	No	2 missing inspection port covers.