

## HDSB Portable Audit Round 125



School	Portable Number	Region	Round 125 Inspection Date	Pinchin Inspector	Proposed Round 126 Inspection Date	Moisture/ Mould found?	Other Deficiency	Location of Condition	Comments from Round 125 Inspection
Anne J.Macarthur P.S.	HBL216	NORTH	1/3/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at right corner
Anne J.Macarthur P.S.	HBL221	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Anne J.Macarthur P.S.	HB111	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Anne J.Macarthur P.S.	HB061	NORTH	1/3/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on left wall at rear corner
Anne J.Macarthur P.S.	HBL202	NORTH	1/3/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around HVAC louvre
Anne J.Macarthur P.S.	HBL203	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Anne J.Macarthur P.S.	HBL204	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Anne J.Macarthur P.S.	HBL205	NORTH	1/3/2024	Harman Singh	04/01/2024	No	Yes		Damaged downspout
Anne J.Macarthur P.S.	HBL232	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Anne J.Macarthur P.S.	HBL233	NORTH	1/3/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on front and left wall. Damaged eavestrough
Boyne P.S.	HBL106	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HB208	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HB033	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on front wall
Boyne P.S.	HBL241	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HB028	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on front wall. Four missing floor tiles
Boyne P.S.	HBL226	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on right wall
Boyne P.S.	HBL251	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HBL253	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding to left of door
Boyne P.S.	HB152	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HB015	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on right wall
Boyne P.S.	HBL254	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on front wall
Boyne P.S.	HBL252	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HBL291	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HBL292	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HBL293	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HB165	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Damaged rear eavestrough. Degraded caulking around door
Boyne P.S.	HBL259	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Boyne P.S.	HB050	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HBL206	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HBL262	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO

Bruce Trail P.S.	HB075	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HB181	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HB103	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HB110	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HB046	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HB114	NORTH	1/3/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around windows and doors
Bruce Trail P.S.	HB062	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HBL105	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HB115	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HBL229	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce Trail P.S.	HBL107	NORTH	1/3/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Chris Hadfield P.S.	HBL266	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on front wall
Chris Hadfield P.S.	HBL265	NORTH	1/18/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Chris Hadfield P.S.	RM A10	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A09	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre and windows
Chris Hadfield P.S.	RM A08	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre and windows
Chris Hadfield P.S.	RM A07	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre
Chris Hadfield P.S.	RM A06	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre
Chris Hadfield P.S.	RM A05	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A04	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A03	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A02	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Chris Hadfield P.S.	RM A01	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes at HVAC louvre and degraded caulking around HVAC louvre
Craig Kielburger S.S.	HB128	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB113	NORTH	1/17/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding near HVAC condensate hose. Degraded caulking around door.
Craig Kielburger S.S.	HB147	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO

Craig Kielburger S.S.	HB132	NORTH	1/17/2024	Harman Singh	04/01/2024	No	Yes		Approximately 9 damaged floor tiles
Craig Kielburger S.S.	HB073	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB143	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB133	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB203	NORTH	1/17/2024	Harman Singh	04/01/2024	No	Yes		Approximately 5 damaged floor tiles
Craig Kielburger S.S.	HB134	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB057	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB159	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL014	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL015	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB125	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL084	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB029	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB140	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HB136	NORTH	1/17/2024	Harman Singh	04/01/2024	No	Yes		Damaged vapour barrier in ceiling
Craig Kielburger S.S.	HBL098	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL288	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL289	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL290	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL312	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Craig Kielburger S.S.	HBL313	NORTH	1/17/2024	Harman Singh	04/01/2024	No	No		NSMOMO
E.W. Foster's P.S.	HB189	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around windows and HVAC condensate hose
Escarpment View P.S.	HBL090	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Damaged downspout
Escarpment View P.S.	HBL103	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around door
Escarpment View P.S.	HBL104	NORTH	1/18/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Escarpment View P.S.	HB144	NORTH	1/18/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Escarpment View P.S.	HB005	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around windows
Escarpment View P.S.	HB089	NORTH	1/18/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Escarpment View P.S.	HBL082	NORTH	1/18/2024	Harman Singh	04/01/2024	Yes	No	Ceiling Space	Level 1 - One water-stained ceiling tile
Escarpment View P.S.	HBL088	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Damaged downspout
Escarpment View P.S.	HBL089	NORTH	1/18/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Escarpment View P.S.	HBL083	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Damaged downspout
Escarpment View P.S.	HB056	NORTH	1/18/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on front and back wall.
Ethel Gardner P.S.	HB049	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on left wall
Ethel Gardner P.S.	HBL212	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on right wall
Ethel Gardner P.S.	HBL207	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Ethel Gardner P.S.	HBL263	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on right wall
Ethel Gardner P.S.	HBL101	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Ethel Gardner P.S.	HBL240	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at front left corner
Ethel Gardner P.S.	HBL335	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Glen Williams P.S.	HB184	NORTH	1/4/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Glen Williams P.S.	HB178	NORTH	1/4/2024	Harman Singh	04/01/2024	No	Yes		Approximately 15 damaged floor tiles
Hawthorne Village P.S.	RM301	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO

Hawthorne Village P.S.	RM302	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM303	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM304	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM305	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM306	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM307	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM308	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM309	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Hawthorne Village P.S.	RM310	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HBL246	NORTH	1/19/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at front right corner.
Irma Coulson P.S.	HBL245	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HBL244	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HB142	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HBL242	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HB081	NORTH	1/19/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on right wall
Irma Coulson P.S.	HB150	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HB204	NORTH	1/19/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on left wall
Irma Coulson P.S.	HBL111	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HB146	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Irma Coulson P.S.	HB009	NORTH	1/19/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on left wall
J.M. Denyes P.S.	HBL317	NORTH	1/19/2024	Harman Singh	04/01/2024	No	Yes		Approximately 4 square feet of damaged vinyl plank flooring
J.M. Denyes P.S.	HBL318	NORTH	1/19/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HB154	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HB093	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HB041	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HBL223	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HB069	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HBL001	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HBL002	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HBL100	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at front of portable
Milton District H.S.	HB168	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at front left corner of portable. Approximately 4 damaged floor tiles
Milton District H.S.	HB035	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at front of portable
Milton District H.S.	HB036	NORTH	1/5/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Milton District H.S.	HB034	NORTH	1/5/2024	Harman Singh	04/01/2024	No	Yes		Screw hole in cladding at front left corner of portable.
P.L. Robertson P.S.	HB004	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding around HVAC louvre
P.L. Robertson P.S.	HB027	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at front wall

P.L. Robertson P.S.	HB021	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Degraded caulking around HVAC louvre. Screw holes in cladding at front wall right corner
P.L. Robertson P.S.	HB030	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding on right wall
P.L. Robertson P.S.	HB016	NORTH	1/15/2024	Harman Singh	04/01/2024	No	No	NSMOMO
P.L. Robertson P.S.	HB022	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding at front and left wall. Approximately 11 broken floor tiles
P.L. Robertson P.S.	HB039	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding on front and left wall. Approximately 20 broken floor tiles
P.L. Robertson P.S.	HBL091	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding on right corner
P.L. Robertson P.S.	HBL228	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding on left corner
P.L. Robertson P.S.	HBL257	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding at both corners on left wall
P.L. Robertson P.S.	HB179	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding on front wall
P.L. Robertson P.S.	HBL110	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding on right wall corner
Rattlesnake Point P.S.	HBL219	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding at NE corner
Rattlesnake Point P.S.	HBL339	NORTH	1/15/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Rattlesnake Point P.S.	HBL338	NORTH	1/15/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Sam Sherrat P.S.	HB082	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Sam Sherrat P.S.	HB083	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Sam Sherrat P.S.	HBL099	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Sam Sherrat P.S.	HB032	NORTH	1/16/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding at right side of door
Sam Sherrat P.S.	HBL297	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Sam Sherrat P.S.	HBL296	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Silver Creek P.S.	HBL336	NORTH	1/15/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding at front right corner.
Tiger Jeet Singh P.S.	HBL079	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Tiger Jeet Singh P.S.	HBL013	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Tiger Jeet Singh P.S.	HB095	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Tiger Jeet Singh P.S.	HB187	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Tiger Jeet Singh P.S.	HB116	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Tiger Jeet Singh P.S.	HB109	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Tiger Jeet Singh P.S.	HB063	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Tiger Jeet Singh P.S.	HB126	NORTH	12/17/2023	Evan Faubert	04/01/2024	No	No	NSMOMO
Viola Desmond P.S.	HBL270	NORTH	1/16/2024	Harman Singh	04/01/2024	No	Yes	Screw holes in cladding on right wall in middle
Viola Desmond P.S.	HBL271	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Viola Desmond P.S.	HBL272	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Viola Desmond P.S.	HBL273	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO
Viola Desmond P.S.	HBL274	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No	NSMOMO

Viola Desmond P.S.	HBL275	NORTH	1/16/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on left wall in middle
Viola Desmond P.S.	HBL276	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL277	NORTH	1/16/2024	Harman Singh	04/01/2024	No	Yes		Damaged vapour barrier
Viola Desmond P.S.	HBL278	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL279	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL280	NORTH	1/16/2024	Harman Singh	04/01/2024	No	Yes		Damaged skirting on right wall
Viola Desmond P.S.	HBL281	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL282	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL283	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL284	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL285	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL286	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Viola Desmond P.S.	HBL287	NORTH	1/16/2024	Harman Singh	04/01/2024	No	No		NSMOMO
W.I. Dick P.S.	HB183	NORTH	1/15/2024	Harman Singh	04/01/2024	No	No		NSMOMO
W.I. Dick P.S.	HB002	NORTH	1/15/2024	Harman Singh	04/01/2024	No	No		NSMOMO
W.I. Dick P.S.	HB007	NORTH	1/15/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Alton Village P.S.	HBL225	WEST	1/8/2024	Harman Singh	04/01/2024	Yes	Yes	Flooring	Level 1 - Approximately 9 sf of wet floor tile at entrance to portable. Screw holes in corner cladding
Alton Village P.S.	HBL237	WEST	1/8/2024	Harman Singh	04/01/2024	No	Yes		Cracked caulking around windows
Alton Village P.S.	HBL238	WEST	1/8/2024	Harman Singh	04/01/2024	No	Yes		Approximately 10 damaged floor tiles
Alton Village P.S.	HBL239	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Alton Village P.S.	HBL234	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Alton Village P.S.	HBL235	WEST	1/8/2024	Harman Singh	04/01/2024	Yes	Yes	Flooring	Level 1 - Approximately 6 sf of wet floor tile around HVAC unit. Approximately 6 damaged floor tiles
Alton Village P.S.	HBL236	WEST	1/8/2024	Harman Singh	04/01/2024	No	Yes	Ceiling Space	Level 1 - 1 water stained ceiling tile
Brant Hills P.S.	HB169	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Bruce T. Lindley	HBL332	WEST	1/8/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding at east corner of portable. Downspout pouring water on wooden support block.
Central P.S.	HBL230	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Central P.S.	HBL231	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	Yes		Cracked caulking around windows
Dr. Charles Best P.S.	HB139	WEST	1/12/2024	Harman Singh	04/01/2024	No	Yes		No power
Dr. Frank Hayden S.S.	HB059	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB120	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB172	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB092	WEST	1/12/2024	Harman Singh	04/01/2024	Yes	Yes	Flooring	Level 1 - Approximately 6 sf of wet floor tile to left of HVAC unit. Degraded caulking around conduits.
Dr. Frank Hayden S.S.	HB137	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Dr. Frank Hayden S.S.	HB207	WEST	1/12/2024	Harman Singh	04/01/2024	No	Yes		Degraded window caulking
Dr. Frank Hayden S.S.	HB151	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Glenview P.S.	HB024	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Glenview P.S.	HB0316	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO

Glenview P.S.	HB166	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Glenview P.S.	HB122	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO
Glenview P.S.	HB148	WEST	1/8/2024	Harman Singh	04/01/2024	No	No		NSMOMO
J.W. Singleton Ed. Ctr.	HB119	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
J.W. Singleton Ed. Ctr.	HB118	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
J.W. Singleton Ed. Ctr.	HB117	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
J.W. Singleton Ed. Ctr.	HB003	WEST	1/12/2024	Harman Singh	04/01/2024	No	No		NSMOMO
John T. Tuck P.S.	HBL220	WEST	1/11/2024	Erin Zylstra	04/01/2024	Yes	Yes	Flooring	Level 1 - Approximately 4 sf of wet floor tile around HVAC unit
John T. Tuck P.S.	HB173	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
John T. Tuck P.S.	HB157	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
John T. Tuck P.S.	HB156	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
John T. Tuck P.S.	HB064	WEST	1/11/2024	Erin Zylstra	04/01/2024	Yes	Yes	Ceiling Space	Level 1 - One water-stained ceiling tile
Kilbride P.S.	HB074	WEST	1/12/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around door. Screw holes in cladding on front wall
King's Road P.S.	HB195	WEST	1/8/2024	Harman Singh	04/01/2024	No	Yes		Screw holes in cladding on front wall at both corners
King's Road P.S.	HB196	WEST	1/8/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around HVAC louvre. Screw holes in cladding on back wall and front right corner
King's Road P.S.	HB127	WEST	1/12/2024	Harman Singh	04/01/2024	No	Yes		Degraded caulking around both doors. Screw holes in cladding on back wall and front right corner
Orchard Park P.S.	HB066	WEST	1/8/2024	Harman Singh	04/01/2024	No	Yes		Penetration in cladding on west wall. Damaged louvre on south wall.
Paul A. Fisher	HB037	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	Yes		Degraded caulking around HVAC condensate hose
Paul A. Fisher	HBL247	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Paul A. Fisher	HB013	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	Yes		Screw holes in cladding on east wall
Pauline Johnson P.S.	HBL222	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Pauline Johnson P.S.	HB102	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Tom Thomson P.S.	HB124	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Tom Thomson P.S.	HB031	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Tom Thomson P.S.	HB105	WEST	1/11/2024	Erin Zylstra	04/01/2024	Yes	Yes	Flooring	Level 2 - Less than 1 sf of mould growth on wood subfloor to the left of HVAC unit remains from previous round. Degraded caulking around conduits.
Tom Thomson P.S.	HB098	WEST	1/11/2024	Erin Zylstra	04/01/2024	Yes	Yes	Ceiling Space	Level 1 - One water-stained ceiling tile
Tom Thomson P.S.	HBL109	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Tom Thomson P.S.	HB141	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Tom Thomson P.S.	HB012	WEST	1/11/2024	Erin Zylstra	04/01/2024	No	No		NSMOMO
Abbey Park H.S.	HB164	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HB163	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HB108	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO

Abbey Park H.S.	HB177	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HBL213	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HBL227	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HB043	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HB131	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HB072	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HB053	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HB206	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Abbey Park H.S.	HBL224	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB047	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB106	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB065	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB014	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HBL217	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB174	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB087	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Captain R. Wilson P.S.	HB162	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL300	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL301	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL302	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL303	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL304	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL305	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL306	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL307	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL308	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL309	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL310	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL311	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL320	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL321	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL322	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL323	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL324	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL325	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL326	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL327	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL328	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL329	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL330	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
David R. Williams P.S.	HBL331	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Emily Carr P.S.	HB084	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Emily Carr P.S.	HBL008	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Falgarwood P.S.	HB167	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Falgarwood P.S.	HB121	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HBL080	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO



Garth Webb S.S.	HBL258	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HB038	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HB045	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HBL005	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HB090	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HB052	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HB076	EAST	1/9/2024	Evan Faubert	4/1/2024	No	Yes	Ceiling Space	Level 1: Water-stained ceiling tile due to condensation
Garth Webb S.S.	HB100	EAST	1/9/2024	Evan Faubert	4/1/2024	Yes	Yes	Wall	Level 2: Impacted drywall right side of HVAC unit. > 1 sf
Garth Webb S.S.	HB135	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Garth Webb S.S.	HB091	EAST	1/9/2024	Evan Faubert	4/1/2024	No	Yes		Four lifting Floor Tiles near HVAC
Garth Webb S.S.	HBL085	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Heritage Glen	HBL208	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Heritage Glen	HBL268	EAST	1/9/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB145	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB088	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB202	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB070	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB209	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HBL264	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB036	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB034	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Iroquois Ridge H.S.	HB010	EAST	1/8/2024	Evan Faubert	4/1/2024	No	Yes		Disconnected downspout. Split caulking at windows, door and interior HVAC.
Iroquois Ridge H.S.	HBL256	EAST	1/8/2024	Evan Faubert	4/1/2024	No	Yes		Holes in cladding at SW corner.
James W. Hill P.S.	HB086	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
James W. Hill P.S.	HB080	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
James W. Hill P.S.	HB099	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
James W. Hill P.S.	HB176	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
James W. Hill P.S.	HB107	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Joshua Creek P.S.	HB085	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Joshua Creek P.S.	HB011	EAST	1/8/2024	Evan Faubert	4/1/2024	No	Yes		Screwholes in cladding at door
Joshua Creek P.S.	HB077	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Joshua Creek P.S.	HB155	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Joshua Creek P.S.	HB161	EAST	1/8/2024	Evan Faubert	4/1/2024	Yes	Yes	Ceiling Space	Level 1: Two water-stained ceiling tiles due to roof leak.
Montclair P.S.	HBL299	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Montclair P.S.	HBL298	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Montclair P.S.	HBL210	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
New Central P.S.	HB079	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
New Central P.S.	HB104	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM190	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM191	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM192	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO

Oakville Trafalgar H.S.	RM193	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM194	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM189A	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM189B	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM195	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM196	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM197	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oakville Trafalgar H.S.	RM198	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB058	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB101	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HBL260	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HBL248	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB171	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB175	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HBL086	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB067	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB044	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB094	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HBL214	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Oodenawi P.S.	HB096	EAST	1/11/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL243	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL200	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HB006	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL267	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL087	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HBL337	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HB040	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Pilgrim Wood P.S.	HB008	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL102	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HB180	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HB129	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL006	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL218	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL255	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL211	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL007	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HB123	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HB158	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL269	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
Post's Corners P.S.	HBL268	EAST	1/15/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
River Oaks P.S.	HBL294	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
River Oaks P.S.	HBL295	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
River Oaks P.S.	HBL314	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
River Oaks P.S.	HBL215	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
River Oaks P.S.	HBL081	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
River Oaks P.S.	HBL315	EAST	1/16/2024	Evan Faubert	4/1/2024	No	No		NSMOMO

Sheridan	HBL108	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
W.H. Morden P.S.	HBL209	EAST	1/8/2024	Evan Faubert	4/1/2024	No	Yes		Missing caulking at SW corner conduits.
W.H. Morden P.S.	HB199	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
W.H. Morden P.S.	HB200	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
W.H. Morden P.S.	HBL201	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
W.H. Morden P.S.	HBL250	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
W.H. Morden P.S.	HBL249	EAST	1/8/2024	Evan Faubert	4/1/2024	No	Yes		Degraded caulking at door. Screw hole in NE cladding
W.H. Morden P.S.	HB055	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
W.H. Morden P.S.	HB138	EAST	1/8/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
West Oak P.S.	RM1	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
West Oak P.S.	RM2	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
West Oak P.S.	RM3	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
West Oak P.S.	RM4	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
West Oak P.S.	RM5	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
West Oak P.S.	RM6	EAST	1/10/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HB149	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HBL334	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HBL333	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HBL092	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HBL093	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HBL094	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HBL095	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks North H.S.	HB060	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HBL018	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HBL017	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HBL016	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB054	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HBL096	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HBL097	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB042	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB023	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB205	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB078	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HBL261	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB130	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB201	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB112	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HB153	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO
White Oaks South H.S.	HBL009	EAST	1/12/2024	Evan Faubert	4/1/2024	No	No		NSMOMO