

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
Anne J. MacArthur P.S.	HB 026	11	June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 071		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 174		June 15, 2018	J. Jones		<i>Downspout missing at rear elevation.</i>
	HBL 202		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 203		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 204		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 205		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 214		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 215		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 232		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 233		June 15, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Boyne P.S.	HB 008	18	June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 015		June 13, 2018	J. Jones		<i>Screw holes observed on metal cladding at right elevation.</i>
	HB 028		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 029		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 032		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 033		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 048		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 152		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 179		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 110		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 218		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 226		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 241		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 251		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 252		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 253		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 254		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
HBL 257		June 13, 2018	J. Jones		<i>N.S.M.O.M.O.</i>	
Bruce Trail P.S.	HB 046	14	May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 062		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 075		May 29, 2018	J. Jones		<i>One 0.5" tear observed in metal cladding at right elevation.</i>
	HB 103		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 110		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 114		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 115		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 105		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 206		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 228		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 229		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 230		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 231		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
HBL 262		May 29, 2018	J. Jones		<i>N.S.M.O.M.O.</i>	
Chris Hadfield P.S.	RM A1	12	May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A2		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A3		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A4		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A5		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A6		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A7		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A8		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A9		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A10		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM A11		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
HBL 106		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>	
Craig Kielburger S.S.	HB 038	18	June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
	HB 045		June 11, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 056		June 6, 2018	J. Jones		<i>Screw holes observed in metal cladding of exterior right elevation. Seal below door missing.</i>
	HB 057		June 6, 2018	J. Jones		<i>Hole (2" diameter) in metal cladding at rear elevation.</i>
	HB 073		June 11, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 090		June 11, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 091		June 11, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 100		June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 113		June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 125		June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 133		June 11, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 134		June 6, 2018	J. Jones		<i>Two vinyl floor tiles swollen in front of the air-exchanger (signs of moisture in subfloor). Caulking degraded on the second window from the door.</i>
	HB 135		June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 143		June 11, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 203		June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 005		June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 080		June 11, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 084		June 6, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Escarpment View P.S.	HB 005	11	May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 089		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 144		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 081		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 082		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 083		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 088		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 089		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 090		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 103		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 104		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
E.W. Foster P.S.	HB 129	3	May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 180		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 189		May 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Ethel Gardiner P.S.	HB 049	5	May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 208		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 207		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 212		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 263		May 24, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Glen Williams P.S.	HB 178	2	May 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 184		May 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Hawthorne Village P.S.	HB 013	24	May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 034		May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 035		May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 036		May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 041		May 31, 2018	J. Jones		<i>Six screw holes observed on metal cladding at front elevation.</i>
	HB 136		May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 155		May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 162		May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 223		May 31, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 301		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 302		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 303		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 304		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 305		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 306		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 307		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	RM 308		May 30, 2018	J. Jones		<i>N.S.M.O.M.O.</i>

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
	RM 309		May 30, 2018	J. Jones		N.S.M.O.M.O.
	RM 310		May 30, 2018	J. Jones		N.S.M.O.M.O.
	Room 101		May 30, 2018	J. Jones		N.S.M.O.M.O.
	Room 102		May 30, 2018	J. Jones		N.S.M.O.M.O.
	Room 103		May 30, 2018	J. Jones		N.S.M.O.M.O.
	Room 104		May 30, 2018	J. Jones		N.S.M.O.M.O.
	Room 105		May 30, 2018	J. Jones		N.S.M.O.M.O.
Irma Coulson P.S.	HB 009	15	June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 081		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 142		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 146		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 149		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 150		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 195		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 196		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HB 204		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HBL 111		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HBL 242		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HBL 243		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HBL 244		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HBL 245		June 1, 2018	J. Jones		N.S.M.O.M.O.
	HBL 246		June 1, 2018	J. Jones		N.S.M.O.M.O.
Milton District H.S.	HB 001	3	May 25, 2018	J. Jones		N.S.M.O.M.O.
	HB 093		May 25, 2018	J. Jones		N.S.M.O.M.O.
	HB 154		May 25, 2018	J. Jones		N.S.M.O.M.O.
P.L. Robertson P.S.	HB 004	12	June 11, 2018	J. Jones		N.S.M.O.M.O.
	HB 016		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HB 021		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HB 022		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HB 027		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HB 030		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HB 039		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HB 051		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HBL 091		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HBL 259		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HBL 265		June 11, 2018	J. Jones		N.S.M.O.M.O.
	HBL 266		June 11, 2018	J. Jones		N.S.M.O.M.O.
Robert Baldwin P.S.	HBL 079	1	May 22, 2018	J. Jones		<i>Hole (2") observed in metal cladding at left elevation.</i>
Robert Little P.S.	HBL 107	1	May 22, 2018	J. Jones		N.S.M.O.M.O.
Sam Sherratt P.S.	HB 066	6	May 25, 2018	J. Jones		N.S.M.O.M.O.
	HB 082		May 25, 2018	J. Jones		N.S.M.O.M.O.
	HB 083		May 25, 2018	J. Jones		N.S.M.O.M.O.
	HB 127		May 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 099		May 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 227		May 25, 2018	J. Jones		N.S.M.O.M.O.
Tiger Jeet Singh P.S.	HB 063	12	June 14, 2018	J. Jones		N.S.M.O.M.O.
	HB 095		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HB 109		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HB 116		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HB 126		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HB 187		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HBL 013		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HBL 014		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HBL 015		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HBL 098		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HBL 213		June 14, 2018	J. Jones		N.S.M.O.M.O.
	HBL 258		June 14, 2018	J. Jones		N.S.M.O.M.O.

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
W.I. Dick P.S.	HB 002	3	May 28, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 007		May 28, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 183		May 28, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Total Number of Portables		171				

Notes:
 Scheduled inspection date subject to change due to availability of manpower and the facility.
N.S.M.O.M.O. = No Suspect Mould Or Moisture Observed

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
Abbey Park H.S.	HB 053	7	June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 108		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 163		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 164		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 177		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 206		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 224		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
E.J. James P.S.	HB 061	5	June 19, 2018	J. Jones		<i>N.S.M.O.M.O. Exterior review only. Interior of portable not accessible.</i>
	HB 111		June 19, 2018	J. Jones		<i>N.S.M.O.M.O. Exterior review only. Interior of portable not accessible.</i>
	HB 121		June 19, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 009		June 19, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 085		June 19, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Iroquois Ridge H.S.	HB 070	5	June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 088		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 202		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 209		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 264		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
James W. Hill P.S.	HB 050	6	June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 054		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 080		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 086		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 099		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 176		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Joshua Creek P.S.	HB 011	4	June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 077		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 085		June 18, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 160		June 18, 2018	J. Jones		<i>Corner flashing damaged with screw holes and roof edge flashing deficient at right elevation.</i>
Munn's P.S.	HBL 001	2	June 19, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 002		June 19, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Oakville Trafalgar H.S.	RM 189A	9	June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 189 B		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 190		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 191		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 192		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 193		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 194		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 198		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 199		June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
Total Number of Portables		38				

Notes:
 Scheduled inspection date subject to change due to availability of manpower and the facility.
N.S.M.O.M.O. = No Suspect Mould Or Moisture Observed

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
Captain R. Wilson P.S.	HB 014	4	June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 047		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 065		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 106		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Emily Carr P.S.	HB 147	5	June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 006		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 008		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 084		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 217		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
Oodenawi P.S.	HB 044	12	June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 058		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 067		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 094		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 096		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 101		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 128		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 171		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 175		June 20, 2018	J. Jones		<i>Portable not accessible.</i>
	HBL 086		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 248		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 260		June 20, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	Palermo P.S.	HB 087	4	June 26, 2018	A. Kaul	
HB 167			June 26, 2018	A. Kaul		<i>Corner flashing damaged at the rear elevation.</i>
HB 168			June 26, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
HB 170			June 26, 2018	A. Kaul		<i>Portable not present on site at time of inspection. Portable to be inspected at new location during next round of inspections.</i>
Pine Grove P.S.	HB 043	2	June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 131		June 20, 2018	A. Kaul		<i>Caulking degraded at air-exchanger vent at right elevation. Screw holes (2) at right elevation. Exterior caulking degraded on the first window from the door.</i>
W.H. Morden P.S.	HB 055	10	June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 097		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 138		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 199		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 200		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 006		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 007		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 201		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 249		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 250		June 20, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
West Oak P.S.	RM 1	10	June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 2		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 3		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 4		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 5		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	RM 6		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	WR		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 072		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 107		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 145		June 21, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
White Oaks Centre for Science and Technology (North Campus)	HB 060	5	June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
	HBL 092		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 093		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 094		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 095		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
White Oaks School Admin. (South Campus)	HB 023	12	June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 042		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 078		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 112		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 153		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 201		June 19, 2019	A. Kaul		<i>Degraded interior caulking on the windows. Damaged vinyl floor tiles (-6) near the door.</i>
	HB 205		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 016		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 017		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 018		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 096		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
	HBL 097		June 19, 2019	A. Kaul		<i>N.S.M.O.M.O.</i>
Total Number of Portables		64				

Notes:
 Scheduled inspection date subject to change due to availability of manpower and the facility.
N.S.M.O.M.O. = No Suspect Mould Or Moisture Observed

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
Charles R. Beaudoin P.S.	HBL 100	3	June 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 101		June 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 102		June 25, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Dr. Frank Hayden S.S.	HB 010	12	June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 059		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 092		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 120		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 137		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 151		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 172		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 207		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 210		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 211		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 255 (1114)		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HBL 256 (1362)		June 22, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
J.W. Singleton Education Centre	HB 003	4	June 28, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 117		June 28, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 118		June 28, 2018	A. Kaul		<i>N.S.M.O.M.O.</i>
	HB 119		June 28, 2018	A. Kaul		<i>Stained ceiling tile observed above window at front elevation</i>
John T. Tuck P.S.	HB 064	10	June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 122		June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 156		June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 157		June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 165		June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 173		June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
	HBL 216		June 21, 2018	J. Jones		N.S.M.O.M.O.
	HBL 219		June 21, 2018	J. Jones		N.S.M.O.M.O.
	HBL 220		June 21, 2018	J. Jones		N.S.M.O.M.O.
	HBL 221		June 21, 2018	J. Jones		N.S.M.O.M.O.
John W. Boich P.S.	HB 108	3	June 26, 2018	J. Jones		N.S.M.O.M.O.
	HB 109		June 26, 2018	J. Jones		N.S.M.O.M.O.
	HBL 247		June 26, 2018	J. Jones		N.S.M.O.M.O.
L.B. Pearson H.S.	RM 179 A/B	12	June 28, 2018	A. Kaul		N.S.M.O.M.O.
	RM 180		June 28, 2018	A. Kaul		Suspect mould on front wall near chalkboards (estimated area ~8 sq. ft). Mould on teacher's desk and other tables.
	RM 181		June 28, 2018	A. Kaul		Suspect mould on front wall and left wall near the door (estimated area ~6 sq. ft). Suspect mould on the back of the door.
	RM 182		June 28, 2018	A. Kaul		Suspect mould on various locations on the floor in small sizes.
	RM 183		June 28, 2018	A. Kaul		Suspect mould on the left wall behind the door (estimated area ~8 sq. ft.) and on various locations on the floor in small sizes.
	RM 184		June 28, 2018	A. Kaul		N.S.M.O.M.O.
	RM 185		June 28, 2018	A. Kaul		N.S.M.O.M.O.
	RM 186		June 28, 2018	A. Kaul		Vinyl floor tiles (~6) missing at right elevation.
	RM 187		June 28, 2018	A. Kaul		N.S.M.O.M.O.
	RM 188		June 28, 2018	A. Kaul		Vinyl floor tiles (~6) missing at right elevation. Suspect mould on various locations on the floor in small sizes.
	RM 189		June 28, 2018	A. Kaul		N.S.M.O.M.O.
	RM 190 A/B		June 28, 2018	A. Kaul		N.S.M.O.M.O.
Pineland P.S.	HB 069	1	June 26, 2018	J. Jones		N.S.M.O.M.O.
Total Number of Portables		45				

Notes:
 Scheduled inspection date subject to change due to availability of manpower and the facility.
N.S.M.O.M.O. = No Suspect Mould Or Moisture Observed

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
Alton Village P.S.	HB 037	9	June 25, 2018	J. Jones		N.S.M.O.M.O.
	HB 068		June 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 225		June 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 234		June 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 235		June 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 236		June 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 237		June 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 238		June 25, 2018	J. Jones		N.S.M.O.M.O.
	HBL 239		June 25, 2018	J. Jones		N.S.M.O.M.O.
Florence Meares P.S.	HB 139	1	June 22, 2018	J. Jones		N.S.M.O.M.O.
Kilbride P.S.	HB 074	1	June 12, 2018	J. Jones		N.S.M.O.M.O. Exterior review only. Interior of portable not accessible.
Orchard Park P.S.	HB 040	3	June 19, 2018	J. Jones		N.S.M.O.M.O.
	HB 140		June 19, 2018	J. Jones		N.S.M.O.M.O.
	HB 166		June 19, 2018	J. Jones		N.S.M.O.M.O.
Pauline Johnson P.S.	HB 024	3	June 26, 2018	J. Jones		N.S.M.O.M.O.
	HB 102		June 26, 2018	J. Jones		N.S.M.O.M.O.
	HBL 222		June 26, 2018	J. Jones		Tear (~2") in metal cladding at rear elevation.
Tom Thompson P.S.	HB 012	8	June 21, 2018	J. Jones		N.S.M.O.M.O.
	HB 031		June 21, 2018	J. Jones		N.S.M.O.M.O.
	HB 098		June 21, 2018	J. Jones		N.S.M.O.M.O.
	HB 105		June 21, 2018	J. Jones		N.S.M.O.M.O.
	HB 124		June 21, 2018	J. Jones		N.S.M.O.M.O.
	HB 141		June 21, 2018	J. Jones		N.S.M.O.M.O.

Table 1 - Portable Classroom Preventative Maintenance Inspection No. 106 Summary

School	Portable Number	Portables on Site	Round 106 Inspection Date	Arcadis Inspector	Proposed Round 107 Inspection Date	Comments from Round 106 Inspection
	HB 148		June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
	HB 169		June 21, 2018	J. Jones		<i>N.S.M.O.M.O.</i>
Total Number of Portables		25				

Notes:
Scheduled inspection date subject to change due to availability of manpower and the facility.
N.S.M.O.M.O. = No Suspect Mould Or Moisture Observed